



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Lonpac Insured's Veh No : GBB9837J

Date of Accident : 10 February 2019

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Toh Shuk Chi @ Toh Shuk Chi Linda

Date : 12 February 2019

Estimate To Repair SLA2643J - NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-

Chassis No : JN1JANT32Z0001487

S/No	Quantity	Description	Amount
		<u>NETT ITEMS</u>	
01	1 pc	front fender with trim RH	\$ 583.40
02	1 pc	front fender top cover RH	\$ 39.00
03	1 pc	front fender inner cowling RH	\$ 81.60
04	1 pc	front fender wheel arch garnish RH	\$ 150.00
05	8 pc	front fender wheel arch garnish clips @ \$6.40	\$ 51.20
06	1 pc	front wheel rim RH	\$ 1,434.50
07	1 pc	front pillar RH	\$ 1,530.30
08	1 pc	side mirror with indicator light	\$ 1,630.10
09	1 pc	side mirror cover	\$ 141.10
10	1 pc	front door RH	\$ 1,032.90
11	1 pc	front door hinge top	\$ 56.10
12	1 pc	front door hinge bottom	\$ 56.10
13	1 pc	front door checker / arrestor	\$ 39.50
14	1 pc	front door outer moulding	\$ 157.00
15	1 pc	front door lower protector	\$ 183.90
16	1 pc	front door weatherstrip	\$ 111.50
17	1 pc	front door inner trimboard	\$ 722.50
18	1 pc	front door outer handle - chrome	\$ 142.10
19	1 pc	front door outer handle extension chrome	\$ 32.30
20	1 pc	front door regulator	\$ 94.20
21	1 pc	front door power window motor	\$ 524.40
22	1 pc	front door inner lock	\$ 166.70
23	1 pc	front door tread plate	\$ 192.80
24	1 pc	rear door RH	\$ 1,032.90
25	1 pc	rear door outer moulding	\$ 157.00
26	1 pc	rear door lower protector	\$ 112.10
27	1 pc	rear door inner trimboard	\$ 688.20
28	1 pc	rear door tread plate	\$ 192.80
29	1 pc	runningboard spoiler RH	\$ 600.00
30	1 pc	rear fender wheel arch garnish	\$ 150.00
31	8 pc	rear fender wheel arch garnish clips @ \$6.40	\$ 51.20
32	1 pc	center pillar RH	\$ 1,530.30



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Lonpac Insured's Veh No : GBB9837J

Date of Accident : 10 February 2019

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Toh Shuk Chi @ Toh Shuk Chi Linda

Date : 12 February 2019

Estimate To Repair SLA2643J - NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-
Chassis No : JN1JANT32Z0001487

S/No	Quantity	Description	Amount
33	1 pc	<u>NETT ITEMS</u> center pullar inner trim lower RH	\$ 120.50
			\$ 13,788.20
		Less 10 %	\$ 1,378.82
			\$ 12,409.38
34	1 pc	<u>SPECIAL NETT ITEMS</u> front tyre RH	\$ 300.00
			\$ 300.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 150.00
02		To transfer of both door fittings and perform water seepage test.	\$ 160.00
03		To check electrical lighting concerned.	\$ 50.00
04		To rust-proofing of the affected areas.	\$ 180.00
05		To check steering geometry and computer wheel alignment.	\$ 80.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
07		Putty and spray painting of the affected portion.	\$ 1,200.00
08		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 850.00
			\$ 2,820.00
		Total	\$ 15,529.38