

ASS. REC. BY:

REF:

CS/INC19002687/Attd307

Special Instruction:

Surveyor:

Adrian

## ASSIGNMENT (Office)

From (Person):

Daniel Koh

of

INC

Date/Time:

9:42am @ 13/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 7070U

Insured:

YN 90017

at Workshop m/s

YOU YI Automobile

Tel:

6702 1555

of

23 Kaki Bkt Ave 4 # 04-01

Policy No:

Claim No:

MT-1031762-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/2/19

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:17am @ 13/2/19

Person Contacted:

chris

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKE 7070U-CC3/AIG 12017536/Rm 1+2q2

DoA: 7/9/12

YN 90017-X

ASS. REC. BY:

REF:

## ASSIGNMENT

Adrian

Front:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKE7070U

Yr Regn: 2017, June

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus IS 200

c.c.

1998

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

41839

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTHBA1D2905052963

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / SRim / STD A/Rim or

Tyre Size:

F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

13/02/19. 1219 PM

Survey held at

You Yi

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP INC.

Lump Sum \$10,500 (Red 21976, 670%)

MV:

PV:

Nett:

RECEIVED 23 APR 2019

Date/Time, File Pass to?

1) 23/4/19 Tuptst

3)

5)

Prel. Report:

Final Report:

Date/Time, File Return to?

2)

4)

6)

Part Prices Check:

IN

OUT

Survey Fee:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

Date:

250

250

## Nivitha (LKK Auto)

**From:** Daniel Koh <daniel.koh@income.com.sg>  
**Sent:** Wednesday, 13 February 2019 1:24 PM  
**To:** 'assignments@lkkauto.com'  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 13/2/2019

Dear Veron/ Nivitha,

Resend with claim ref no and officer in charge

Daniel Koh  
Senior Admin Assistant  
Motor Insurance  
T +65 6430 7901  
[www.income.com.sg](http://www.income.com.sg)

**income**  
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

**in** with you

**From:** Daniel Koh  
**Sent:** Wednesday, 13 February 2019 9:42 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>  
**Cc:** Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>  
**Subject:** FW: TP CASES FARMED OUT TO LKK ON 13/2/2019

Dear Veron / Catherine,

Please assist to survey the vehicles as per Mr Teng's instruction :-

| S/NO | THIRD PARTY | OUR INSURED | WORKSHOP / CONTACT                    | DOA / REF / OFFICER                            |
|------|-------------|-------------|---------------------------------------|------------------------------------------------|
| 1    | SJR3431G    | GBA2291J    | YOU YI AUTOMOBILE / Chris<br>67021555 | 28-1-2019 / MT-1029869-002<br>/ David Phua     |
| 2    | ŠKE7070U    | YN9001T     | YOU YI AUTOMOBILE / Chris<br>67021555 | 11-2-2019 / MT-1031762-001<br>/ Azhari         |
| 3    | SFR1221G    | SGX8003E    | YOU YI AUTOMOBILE / Chris<br>67021555 | 2-2-2019 / MT-1030845-002 /<br>Muhammad Airwan |
| 4    | SLE1210K    | SME1674T    | YOU YI AUTOMOBILE / Chris<br>67021555 | 10-2-2019 / MT-1031369-002<br>/ Serene Lim     |
| 5    | SLZ4580L    | GBG7083D    | CHEW MOTOR / Sukyi<br>67479241        | 29-1-2019 / MT-1030426-001<br>/ Eric Tang      |

Please contact workshops.

Please ack.

Thank You

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                              |
|----------------------------|----------------------------------------------|
| Date Of Report             | 12/02/2019 10:01                             |
| Date Of Accident           | 11/02/2019 11:45                             |
| Exact Location Of Accident | SLIP ROAD OF BEDOK AVE 4 TWDS BEDOK NTH ST 5 |
| Country/State of Loss      | SINGAPORE                                    |

### DETAILS OF OWN VEHICLE

|                                                                              |                          |
|------------------------------------------------------------------------------|--------------------------|
| Vehicle Registration Number                                                  | SKE7070U                 |
| <b>Insured/Policyholder</b>                                                  |                          |
| Name Of Registered Owner                                                     | TAN BENG ENG             |
| NRIC No                                                                      | S7028276C                |
| Email Address                                                                | NOEMAIL                  |
| Mobile Phone No                                                              | (LOCAL) +65-90215150     |
| Alternative Phone No                                                         | OFFICE-60000000          |
| <b>Vehicle Particulars</b>                                                   |                          |
| Manufacturer                                                                 | LEXUS                    |
| Model                                                                        | IS200T-2.0 EXECUTIVE (A) |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE              |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                       |
| If No, Please state action to be taken                                       | THIRD PARTY              |
| Vehicle Category                                                             | PRIVATE CAR              |
| <b>Insurance Company</b>                                                     |                          |
| Name of Insurance Company                                                    | AXA INSURANCE PTE LTD    |
| Type Of Coverage                                                             | COMPREHENSIVE            |
| Fleet Policy                                                                 | NO                       |
| Policy Number                                                                | GA367726/1               |
| Cover Note Number                                                            |                          |
| <b>Driver</b>                                                                |                          |
| Name of Driver                                                               | CHONG CHEE HOW           |
| NRIC No                                                                      | S7005822G                |
| Date Of Birth                                                                | 18/02/1970               |
| Occupation                                                                   | INDOOR                   |
| Date Of Driving Pass                                                         | 04/09/2003               |
| Driving Experience                                                           | 15 YEARS AND 5 MONTHS    |
| Gender                                                                       | MALE                     |
| Mobile Number                                                                | (LOCAL) +65-90215150     |
| Fax Number                                                                   |                          |
| Contact Number                                                               |                          |
| Email Address                                                                | NOEMAIL                  |

Address 285D TOH GUAN ROAD #13-68  
 Postcode 608285  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle Involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 5

Passenger 1  
 NAME: : THANDAR LWIN  
 GENDER: : FEMALE

Passenger 2  
 NAME: : TAN KAH HONG BENJAMIN  
 GENDER: : MALE

Passenger 3  
 NAME: : WIN MOTH MOTH THEIN AUNG  
 GENDER: : FEMALE

Passenger 4  
 NAME: : S SANTHI A/P S BALA  
 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of Intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

Report please refer to Sketch Plan

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN9001T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (for/m) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Norman  
NIC/FID No.: 871218046

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary while waiting for the major Rd to clear suddenly I felt a great impact from my rear. I came out and discovered a lorry bearing YN 9001T had hit on to my rear portion of my vehicle. We exchange particulars

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Harvib  
NRIC/IN No.: 571318096

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 8276C

### Vehicle Details

Vehicle No.: SKE7070U  
Vehicle to be Exported: No  
Intended Deregistration Date: 12 Feb 2019  
Vehicle Make: TOYOTA  
Vehicle Model: LEXUS IS200T EXECUTIVE  
Primary Colour: White  
Manufacturing Year: 2017  
Engine No.: 8ARZ077829  
Chassis No.: JTHBA1D2905052963  
Maximum Power Output: 180.0 kW (241 bhp)  
Open Market Value: \$38,430.00  
Original Registration Date: 23 Jun 2017  
First Registration Date: 23 Jun 2017  
Transfer Count: 0  
Actual ARF Paid: \$45,802.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 22 Jun 2027  
PARF Rebate Amount: \$34,351.00

### Intended COE Rebate Details

COE Expiry Date: 22 Jun 2027  
COE Category: E - Open - all except motorcycle  
COE Period(Years): 10  
QP Paid: \$52,000.00  
COE Rebate Amount: \$43,477.00  
Total Rebate Amount: \$77,828.00

The information contained herein is correct as at 12 Feb 2019

OK

MV - 144,343  
- 77,828  
-----  
\$ 66,515



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.88% P.A. Lowest Interest @ Gv  
Cars Financing \$2000  
Downpayment Monthly From  
\$638  
GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted 20 results/page

4 vehicles

IS Turbo IS200t Executive

Advanced Search

|                                                                                                                                                                                                              | Make                                   | Model | Price            | Depreciation        | Reg Date           | Eng Cap         | Mileage          | Veh Type      | Status           |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|-------|------------------|---------------------|--------------------|-----------------|------------------|---------------|------------------|
| <b>Search Selection</b>                                                                                                                                                                                      | <b>IS Turbo IS200t Executive</b>       |       | Any              | Any                 | 2017               | Any             | Any              | Any           | Available        |
|                                                                                                                             | <b>Lexus IS Turbo IS200t Executive</b> |       | <b>\$143,800</b> | <b>\$14,210 /yr</b> | <b>15-Aug-2017</b> | <b>1,998 cc</b> | <b>19,411 km</b> | <b>Luxury</b> | <b>Available</b> |
| 1 Owner Agent Unit. \$2000 Republic Auto Warranty Workshop Credit. 5 Years Agent Warranty. Well Maintained. Enjoy Exclusive Interest Rate At 2.28% For Limited Time Only! Please Call/Whatsapp Wong For E... |                                        |       |                  |                     |                    |                 |                  |               |                  |
| Republic Auto                                                                                                                                                                                                |                                        |       |                  |                     |                    |                 |                  |               |                  |
| Posted: 10-Feb-2019 Tags: 2017 Lexus IS, 2017 lexus is, Lexus IS, lexus is, Lexus, IS, is, Used Lexus                                                                                                        |                                        |       |                  |                     |                    |                 |                  |               |                  |
|                                                                                                                            | <b>Lexus IS Turbo IS200t Executive</b> |       | <b>\$148,000</b> | <b>\$14,630 /yr</b> | <b>20-Sep-2017</b> | <b>1,998 cc</b> | <b>9,200 km</b>  | <b>Luxury</b> | <b>Available</b> |
| Unbelievable Flexible In House Loan. Own This Performance Inspired Sedan With Warranty Till Sep 2020, Traced Servicing History And An Assuring 160-Point Quality Inspection. Complete Your Purchase With...  |                                        |       |                  |                     |                    |                 |                  |               |                  |
| Inchcape Pre-Owned                                                                                                                                                                                           |                                        |       |                  |                     |                    |                 |                  |               |                  |
| Posted: 11-Feb-2019 Tags: 2017 Lexus IS, 2017 lexus is, Lexus IS, lexus is, Lexus, IS, is, Used Lexus                                                                                                        |                                        |       |                  |                     |                    |                 |                  |               |                  |
|                                                                                                                           | <b>Lexus IS Turbo IS200t Executive</b> |       | <b>\$145,000</b> | <b>\$14,160 /yr</b> | <b>17-Oct-2017</b> | <b>1,998 cc</b> | <b>18,000 km</b> | <b>Luxury</b> | <b>Available</b> |
| No Dealers Or Consignment Agents. Jet Black IS200T Executive Is Up For Sale. Has That Showroom Condition. Superbly Well Maintained Inside And Out. Most Importantly, Only 1 Owner. Well Taken Care. Same...  |                                        |       |                  |                     |                    |                 |                  |               |                  |
| Posted: 07-Feb-2019 Tags: 2017 Lexus IS, 2017 lexus is, Lexus IS, lexus is, Lexus, IS, is, Used Lexus                                                                                                        |                                        |       |                  |                     |                    |                 |                  |               |                  |
|                                                                                                                           | <b>Lexus IS Turbo IS200t Executive</b> |       | <b>\$139,000</b> | <b>\$13,340 /yr</b> | <b>17-Nov-2017</b> | <b>1,998 cc</b> | <b>14,000 km</b> | <b>Luxury</b> | <b>Available</b> |
| Chinese New Year Offer! Free Polishing And Inspection! Very Well Maintained By Meticulous Owner, Comes With 6 Years Extended Warranty And Free Servicing. Under Utilized And Low Mileage! Loans Availabl...  |                                        |       |                  |                     |                    |                 |                  |               |                  |
| Posted: 31-Jan-2019 Tags: 2017 Lexus IS, 2017 lexus is, Lexus IS, lexus is, Lexus, IS, is, Used Lexus                                                                                                        |                                        |       |                  |                     |                    |                 |                  |               |                  |

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used IS Turbo IS200t Executive, IS Turbo IS200t Executive Singapore, used IS Turbo IS200t Executive Singapore, used IS Turbo IS200t Executive, used vehicles Singapore or even buy used IS Turbo IS200t Executive Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

YOU YI  
23 Kaki Bukit Ave 4 (South Wing)  
#03-01 Singapore 415933

|                                                 |                     |                        |                   |
|-------------------------------------------------|---------------------|------------------------|-------------------|
| TO                                              | : NTUC INCOME       | DATE                   | : 11-Feb-19       |
| ATTENTION                                       | : MOTOR CLAIMS DEPT | JOB TYPE               | : T/P CLAIM       |
| ESTIMATE REPORT                                 | :                   |                        |                   |
| <u>OWNER'S PARTICULAR</u>                       |                     | <u>VEHICLE DETAILS</u> |                   |
| NAME                                            | :                   | VEHICLE NO             | SKE7070U          |
| ADDRESS                                         | :                   | MODEL                  | LEXUS IS200       |
| TEL. NO.                                        | :                   | CHASSIS NO             | JTHBA1D2805052963 |
| OWNER'S INSURANCE                               | :                   |                        |                   |
| POLICY NO.                                      | :                   |                        | Denise            |
| <u>ACCIDENT DETAILS</u>                         |                     | DATE                   | :                 |
|                                                 |                     | TIME                   | :                 |
| THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482 |                     |                        |                   |

### QUOTATION SUMMARY

#### CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                   | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-----------------------------------------------|-----|-----------------|------------------|
| 1   | REAR BUMPER <i>Rehnd</i>                      | 1   | \$ 989.00       | \$ 989.00        |
| 2   | REAR BUMPER LOWER TOWING COVER <i>Missing</i> | 1   | \$ 25.00        | \$ 25.00         |
| 3   | REAR BUMPER LOWER <i>Rehnd</i>                | 1   | \$ 687.00       | \$ 687.00        |
| 4   | REAR BUMPER RETAINER <i>re</i>                | 2   | \$ 99.00        | \$ 198.00        |
| 5   | REAR BUMPER REINFORCEMENT <i>Best</i>         | 1   | \$ 570.00       | \$ 570.00        |
| 6   | REAR BUMPER SPONGE <i>Cushd</i>               | 1   | \$ 254.00       | \$ 254.00        |
| 7   | REAR BUMPER SUPPORT BRACKET <i>re re</i>      | 2   | \$ 154.00       | \$ 308.00        |
| 8   | REAR BUMPER REFELCTOR <i>re re</i>            | 2   | \$ 124.00       | \$ 248.00        |
| 9   | REAR BUMPER SENSOR <i>2 pieces damaged</i>    | 4   | \$ 475.00       | \$ 1,900.00      |
| 10  | REAR BUMPER WIRE HARNESS <i>re re</i>         | 1   | \$ 489.00       | \$ 489.00        |
| 11  | REAR BUMPER AIR VENT <i>re re</i>             | 2   | \$ 58.00        | \$ 116.00        |
| 12  | BOOTLID <i>Dented</i>                         | 1   | \$ 1,659.00     | \$ 1,659.00      |
| 13  | BOOTLID OUTER GARNISH <i>re re</i>            | 1   | \$ 280.00       | \$ 280.00        |

|    |                                                      |   |             |             |      |
|----|------------------------------------------------------|---|-------------|-------------|------|
| 14 | BOOTLID INSULATOR <i>new</i>                         | 1 | \$ 1,250.00 | \$ 1,250.00 | +    |
| 15 | BOOT LID HINGE <i>Best</i>                           | 2 | \$ 180.00   | \$ 360.00   | +    |
| 16 | BOOT LID LAMP <i>lt</i>                              | 2 | \$ 857.00   | \$ 1,714.00 | 1420 |
| 17 | BOOT LID DETECTOR <i>cracked</i>                     | 1 | \$ 345.00   | \$ 345.00   | 158  |
| 18 | BOOTLID TOP LOCK <i>Repl.</i>                        | 1 | \$ 490.00   | \$ 490.00   | 385  |
| 19 | BOOTLID LOWER LOCK <i>new</i>                        | 1 | \$ 65.00    | \$ 65.00    | +    |
| 20 | BOOTLID WEATHERSTRIP <i>lt</i>                       | 1 | \$ 235.00   | \$ 235.00   | -    |
| 21 | BOOTLID LOGO                                         | 1 | \$ 63.00    | \$ 63.00    | -    |
| 22 | BOOTLID EMBLEM 'LEXLIS'                              | 1 | \$ 80.00    | \$ 80.00    | -    |
| 23 | BOOTLID EMBLEM 'IS'                                  | 1 | \$ 78.00    | \$ 78.00    | -    |
| 24 | BOOTLID EMBLEM '200'                                 | 1 | \$ 78.00    | \$ 78.00    | -    |
| 25 | BOOTLID INNER TRIM <i>new</i>                        | 1 | \$ 485.00   | \$ 485.00   | +    |
| 26 | BOOTLID STOPER <i>new</i>                            | 4 | \$ 20.00    | \$ 80.00    | +    |
| 27 | BOOTLID NUMBER PLATE LAMP <i>new</i>                 | 1 | \$ 320.00   | \$ 320.00   | +    |
| 28 | BOOTLID NUMBER PLATE LAMP GARNISH COVER <i>Repl.</i> | 1 | \$ 320.00   | \$ 320.00   | -    |
| 29 | TAILLAMP <i>Cracked</i>                              | 2 | \$ 897.00   | \$ 1,794.00 | 1540 |
| 30 | TAILLAMP LOWER BRACKET <i>new</i>                    | 2 | \$ 85.00    | \$ 170.00   | +    |
| 31 | TAILLAMP PANEL <i>Repl.</i>                          | 1 | \$ 541.00   | \$ 541.00   | +    |
| 32 | REAR FENDER RH <i>new</i>                            | 1 | \$ 1,725.00 | \$ 1,725.00 | +    |
| 33 | REAR FENDER INNER COWLING <i>new</i>                 | 2 | \$ 795.00   | \$ 1,590.00 | +    |
| 34 | REAR FENDER INNER COWLING BRACKET <i>new</i>         | 2 | \$ 95.00    | \$ 190.00   | +    |
| 35 | REAR FENDER TOP GARNISH <i>new</i>                   | 2 | \$ 340.00   | \$ 680.00   | +    |
| 36 | REAR FENDER INNER TRIM <i>2nd</i>                    | 2 | \$ 730.00   | \$ 1,460.00 | +    |
| 37 | REAR WINDSCREEN MOULDING <i>1st</i>                  | 1 | \$ 212.00   | \$ 212.00   | +    |
| 38 | REAR END PANEL <i>Dented</i>                         | 1 | \$ 780.00   | \$ 780.00   | ✓    |
| 39 | REAR END PANEL INNER <i>Repl.</i>                    | 1 | \$ 554.00   | \$ 554.00   | +    |
| 40 | REAR END PANEL TOP GARNISH <i>Repl.</i>              | 1 | \$ 398.00   | \$ 398.00   | ✓    |
| 41 | REAR END PANEL TOP GARNISH HOLDER <i>new</i>         | 1 | \$ 159.00   | \$ 159.00   | +    |
| 42 | REAR FLOOR PANEL <i>Repl.</i>                        | 1 | \$ 1,254.00 | \$ 1,254.00 | +    |
| 43 | REAR FLOOR PANEL UNDER COVER <i>torn</i>             | 1 | \$ 480.00   | \$ 480.00   | 358  |
| 44 | REAR FLOOR PANEL SIDE BOARD <i>new</i>               | 2 | \$ 210.00   | \$ 420.00   | +    |
| 45 | REAR FLOOR PANEL TOP BOARD <i>Repl.</i>              | 1 | \$ 1,080.00 | \$ 1,080.00 | 455  |
| 46 | REAR FLOOR PANEL TOP BOARD UNDER GARNISH <i>new</i>  | 2 | \$ 280.00   | \$ 560.00   | +    |
| 47 | REAR FLOOR PANEL SIDE BOX LH <i>cracked</i>          | 1 | \$ 298.00   | \$ 298.00   | -    |
| 48 | REAR FLOOR PANEL SIDE TOOLS BOX <i>cracked</i>       | 2 | \$ 450.00   | \$ 900.00   | 298  |
| 49 | REVERSE CAMERA <i>new</i>                            | 1 | \$ 1,598.00 | \$ 1,598.00 | +    |

|    |                               |   |             |             |   |
|----|-------------------------------|---|-------------|-------------|---|
| 50 | REAR ESHAUST CHROME RING      | 2 | \$ 300.00   | \$ 600.00   | + |
| 51 | REAR EXHAUST INSULATOR        | 2 | \$ 180.00   | \$ 360.00   | + |
| 52 | REAR EXHAUST HEAT SHIELD      | 1 | \$ 211.00   | \$ 211.00   | + |
| 53 | REAR EXHAUST PIPE             | 2 | \$ 1,454.00 | \$ 2,908.00 | + |
| 54 | REAR EXHAUST MOUNTING BRACKET | 2 | \$ 112.00   | \$ 224.00   | + |
| 55 | REAR EXHAUST MOUNTING         | 2 | \$ 58.00    | \$ 116.00   | + |

11920  
10728

TOTAL PRICE \$ 34,948.00  
LESS 25% 10% \$ 8,737.00  
SUB TOTAL PRICE \$ 26,211.00

| S/N | DESCRIPTION                                 | QTY | UNIT S/NETT | TOTAL S/NETT         |
|-----|---------------------------------------------|-----|-------------|----------------------|
| 1   | REAR NUMBER PLATE <i>Not Rec</i>            | 1   | \$ 50.00    | \$ 50.00             |
| 2   | REAR BUMPER CLIPS <i>x/ea</i>               | 10  | \$ 6.50     | \$ <del>65.00</del>  |
| 3   | BOOTLID SEALANT <i>rec</i>                  | 1   | \$ 80.00    | \$ 80.00             |
| 4   | BOOT LID INSULATOR CLIP <i>de</i>           | 10  | \$ 6.50     | \$ <del>65.00</del>  |
| 5   | TAILLAMP CLIPS <i>rec</i>                   | 4   | \$ 8.00     | \$ <del>32.00</del>  |
| 6   | TAILLAMP PANEL SEALANT <i>rec</i>           | 2   | \$ 60.00    | \$ 120.00            |
| 9   | REAR FENDER COWLING CLIPS <i>3/ea</i>       | 18  | \$ 6.50     | \$ 117.00            |
| 10  | REAR FENDER INNER TRIM CLIPS                | 18  | \$ 6.50     | \$ 117.00            |
| 11  | REAR END PANEL TOP GARNISH CLIPS <i>rec</i> | 6   | \$ 6.50     | \$ <del>39.00</del>  |
| 12  | REAR END PANEL INSULATION SEAL <i>rec</i>   | 1   | \$ 120.00   | \$ <del>120.00</del> |
| 13  | REAR FLOOR PANEL INSULATION SEAL <i>rec</i> | 1   | \$ 250.00   | \$ 250.00            |

140

TOTAL \$ 1,055.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

|   |                                                                                |             |      |  |
|---|--------------------------------------------------------------------------------|-------------|------|--|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS                                     | \$ 1,600.00 | 1000 |  |
| 2 | TO SPRAY PAINT AFFECTED AREA                                                   | \$ 1,500.00 | 1000 |  |
| 3 | TUFF COAT                                                                      | \$ 250.00   | 60   |  |
| 4 | WIRING CHECK                                                                   | \$ 80.00    | 20   |  |
| 5 | REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR | \$ 400.00   | 80   |  |
| 6 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                           | \$ 220.00   | 60   |  |

|    |                                                                                                |           |   |  |
|----|------------------------------------------------------------------------------------------------|-----------|---|--|
| 7  | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 550.00 | x |  |
| 8  | REAR CHASSIS ALIGNMENT                                                                         | \$ 250.00 | x |  |
| 9  | TRANSFER BOOTLID MECHANISM                                                                     | \$ 80.00  | ✓ |  |
| 10 | CONDUCT WATER LEAKAGE TEST                                                                     | \$ 80.00  | x |  |
| 11 | REMOVE AND REFIX REAR EXHAUST PIPE                                                             | \$ 200.00 | x |  |

**TOTAL**

**\$5,210.00**

2310

TOTAL PARTS COST : \$ 27,266.00  
TOTAL LABOUR COST : \$ 5,210.00  
TOTAL REPAIR COST : \$ 32,476.00

**APPROVED DETAILS**

EXCESS :  
NO. OF WORKING DAYS :  
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :  
SURVEYED BY :  
CONTACT NUMBER :  
FAX NUMBER :

Adrian King,  
h/s 13/02/19.  
OT Pays.

total: 13178  
h/s: 10.5K. ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

27718.70



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19002687/Atd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 26-04-2019



ATTN : AZHARI

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | YN 9001T       | Veh. Inspected | SKE 7070U  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT-1031762-001 | Excess (\$)    | 0.00       |
| Assign From  | DANIEL KOH     | Assign Date    | 13/02/2019 |

### 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | LEXUS IS200       | c.c          | 1998       |
| Engine No.   | HIDDEN            | Year of Reg. | 2017       |
| Chassis No.  | JTHBA1D2905052963 | Colour       | WHITE      |
| Odometer     | 41839 KM          | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

### 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 225/45 R17 | MICHELIN | 6 mm    |
| L/H Front Tyre | 225/45 R17 | MICHELIN | 6 mm    |
| R/H Rear Tyre  | 225/45 R17 | MICHELIN | 6 mm    |
| L/H Rear Tyre  | 225/45 R17 | MICHELIN | 6 mm    |

### 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

### 5. General Information

|                |                                                                                  |                     |                         |
|----------------|----------------------------------------------------------------------------------|---------------------|-------------------------|
| Accident Date  | 11/02/2019                                                                       | Inspect Date / Time | 13/02/2019 ( 12:19 PM ) |
| Survey held at | YOU YI AUTOMOBILE<br>23 KAKI BUKIT AVE 4 (SOUTH WING)<br>#04-01 SINGAPORE 415933 |                     |                         |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 7070U

| Qty | Description of Parts                    | Condition          | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------|--------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>      |                    |                           |                   |
| 1   | REAR BUMPER                             | DEFORMED           | 989.00                    | 989.00            |
| 1   | REAR BUMPER LOWER TOWING COVER          | MISSING            | 25.00                     | 25.00             |
| 1   | REAR BUMPER LOWER                       | DEFORMED           | 687.00                    | 687.00            |
| 2   | REAR BUMPER RETAINER @\$99.00           | NECESSARY          | 198.00                    | 198.00            |
| 1   | REAR BUMPER REINFORCEMENT               | BENT               | 570.00                    | 453.00            |
| 1   | REAR BUMPER SPONGE                      | CRACKED            | 254.00                    | 254.00            |
| 2   | REAR BUMPER SUPPORT BRACKET @\$154.00   | NOT NECESSARY      | 308.00                    | -                 |
| 2   | REAR BUMPER REFLECTOR @\$124.00         | NOT NECESSARY      | 248.00                    | -                 |
| 4   | REAR BUMPER SENSOR @\$475.00            | DAMAGED-2 PCS ONLY | 1,900.00                  | 560.00            |
| 1   | REAR BUMPER WIRE HARNESS                | NOT NECESSARY      | 489.00                    | -                 |
| 2   | REAR BUMPER AIR VENT @\$58.00           | NOT NECESSARY      | 116.00                    | -                 |
| 1   | BOOTLID                                 | DENTED             | 1,659.00                  | 1,450.00          |
| 1   | BOOTLID OUTER GARNISH                   | NOT NECESSARY      | 280.00                    | -                 |
| 1   | BOOTLID INSULATOR                       | NOT NECESSARY      | 1,250.00                  | -                 |
| 2   | BOOT LID HINGE @\$180.00                | BENT               | 360.00                    | 360.00            |
| 2   | BOOT LID LAMP @\$857.00                 | CUT                | 1,714.00                  | 1,420.00          |
| 1   | BOOT LID DETECTOR                       | CRACKED            | 345.00                    | 158.00            |
| 1   | BOOTLID TOP LOCK                        | DAMAGED            | 490.00                    | 385.00            |
| 1   | BOOTLID LOWER LOCK                      | NOT NECESSARY      | 65.00                     | -                 |
| 1   | BOOTLID WEATHERSTRIP                    | CUT                | 235.00                    | 235.00            |
| 1   | BOOTLID LOGO                            | NECESSARY          | 63.00                     | 63.00             |
| 1   | BOOTLID EMBLEM 'LEXLIS'                 | NECESSARY          | 80.00                     | 80.00             |
| 1   | BOOTLID EMBLEM 'IS'                     | NECESSARY          | 78.00                     | 78.00             |
| 1   | BOOTLID EMBLEM '200'                    | NECESSARY          | 78.00                     | 78.00             |
| 1   | BOOTLID INNER TRIM                      | NOT NECESSARY      | 485.00                    | -                 |
| 4   | BOOTLID STOPPER @\$20.00                | NOT NECESSARY      | 80.00                     | -                 |
| 1   | BOOTLID NUMBER PLATE LAMP               | NOT NECESSARY      | 320.00                    | -                 |
| 1   | BOOTLID NUMBER PLATE LAMP GARNISH COVER | DEFORMED           | 320.00                    | 320.00            |
| 2   | TAILLAMP @\$897.00                      | CRACKED            | 1,794.00                  | 1,540.00          |
| 2   | TAILLAMP LOWER BRACKET @\$85.00         | NOT NECESSARY      | 170.00                    | -                 |

Report Ref No. CS/INC19002687/Atd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts                               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | TAILLAMP PANEL                                     | TO REPAIR SEE LABOUR | 541.00                    | -                 |
| 1   | REAR FENDER RH                                     | NOT NECESSARY        | 1,725.00                  | -                 |
| 2   | REAR FENDER INNER COWLING @\$795.00                | NOT NECESSARY        | 1,590.00                  | -                 |
| 2   | REAR FENDER INNER COWLING BRACKET @\$95.00         | NOT NECESSARY        | 190.00                    | -                 |
| 2   | REAR FENDER TOP GARNISH @\$340.00                  | NOT NECESSARY        | 680.00                    | -                 |
| 2   | REAR FENDER INNER TRIM @\$730.00                   | NOT NECESSARY        | 1,460.00                  | -                 |
| 1   | REAR WINDSCREEN MOULDING                           | NOT NECESSARY        | 212.00                    | -                 |
| 1   | REAR END PANEL                                     | DENTED               | 780.00                    | 780.00            |
| 1   | REAR END PANEL INNER                               | TO REPAIR SEE LABOUR | 554.00                    | -                 |
| 1   | REAR END PANEL TOP GARNISH                         | DEFORMED             | 398.00                    | 398.00            |
| 1   | REAR END PANEL TOP GARNISH HOLDER                  | NOT NECESSARY        | 159.00                    | -                 |
| 1   | REAR FLOOR PANEL                                   | TO REPAIR SEE LABOUR | 1,254.00                  | -                 |
| 1   | REAR FLOOR PANEL UNDER COEVR                       | TORN                 | 480.00                    | 358.00            |
| 2   | REAR FLOOR PANEL SIDE BOARD @\$210.00              | NOT NECESSARY        | 420.00                    | -                 |
| 1   | REAR FLOOR PANEL TOP BOARD                         | DEFORMED             | 1,080.00                  | 455.00            |
| 2   | REAR FLOOR PANEL TOP BOARD UNDER GARNISH @\$280.00 | NOT NECESSARY        | 560.00                    | -                 |
| 1   | REAR FLOOR PANEL SIDE BOX LH                       | CRACKED              | 298.00                    | 298.00            |
| 2   | REAR FLOOR PANEL SIDE TOOLS BOX @\$450.00          | CRACKED              | 900.00                    | 298.00            |
| 1   | REVERSE CAMERA                                     | NOT NECESSARY        | 1,598.00                  | -                 |
| 2   | REAR EXHAUST CHROME RING @\$300.00                 | NOT NECESSARY        | 600.00                    | -                 |
| 2   | REAR EXHAUST INSULATOR @\$180.00                   | NOT NECESSARY        | 360.00                    | -                 |
| 1   | REAR EXHAUST HEAT SHIELD                           | NOT NECESSARY        | 211.00                    | -                 |
| 2   | REAR EXHAUST PIPE @\$1454.00                       | NOT NECESSARY        | 2,908.00                  | -                 |
| 2   | REAR EXHAUST MOUNTING BRACKET @\$112.00            | NOT NECESSARY        | 224.00                    | -                 |
| 2   | REAR EXHAUST MOUNTING @\$58.00                     | NOT NECESSARY        | 116.00                    | -                 |
|     | LESS 10% DISCOUNT                                  |                      | -3,494.80                 | -1,192.00         |
|     |                                                    |                      | 31,453.20                 | 10,728.00         |
|     | <b>SPECIAL NETT ITEMS</b>                          |                      |                           |                   |
| 1   | REAR NUMBER PLATE (SN)                             | NOT NECESSARY        | 50.00                     | -                 |
| 10  | REAR BUMPER CLIPS @\$6.50 (SN)                     | NECESSARY            | 65.00                     | 30.00             |

Report Ref No. CS/INC19002687/Atd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty                | Description of Parts                                                                                                              | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                  | BOOTLID SEALANT (SN)                                                                                                              | NOT NECESSARY | 80.00                     | -                 |
| 10                 | BOOT LID INSULATOR CLIP @\$6.50 (SN)                                                                                              | NECESSARY     | 65.00                     | 30.00             |
| 4                  | TAILLAMP CLIPS @\$8.00 (SN)                                                                                                       | NECESSARY     | 32.00                     | 10.00             |
| 2                  | TAILLAMP PANEL SEALANT @\$60.00 (SN)                                                                                              | NOT NECESSARY | 120.00                    | -                 |
| 18                 | REAR FENDER COWLING CLIPS @\$6.50 (SN)                                                                                            | NOT NECESSARY | 117.00                    | -                 |
| 18                 | REAR FENDER INNER TRIM CLIPS @\$6.50 (SN)                                                                                         | NOT NECESSARY | 117.00                    | -                 |
| 6                  | REAR END PANEL TOP GARNISH CLIPS @\$6.50 (SN)                                                                                     | NECESSARY     | 39.00                     | 10.00             |
| 1                  | REAR END PANEL INSULATION SEAL (SN)                                                                                               | NECESSARY     | 120.00                    | 60.00             |
| 1                  | REAR FLOOR PANEL INSULATION SEAL (SN)                                                                                             | NOT NECESSARY | 250.00                    | -                 |
|                    |                                                                                                                                   |               | 1,055.00                  | 140.00            |
|                    | <b>LABOUR</b>                                                                                                                     |               |                           |                   |
|                    | PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL, REAR END PANEL INNER AND REAR FLOOR PANEL. |               | 1,600.00                  | 1,000.00          |
|                    | TO SPRAY PAINT AFFECTED AREA.                                                                                                     |               | 1,500.00                  | 1,000.00          |
|                    | TUFF COAT.                                                                                                                        |               | 250.00                    | 60.00             |
|                    | WIRING CHECK.                                                                                                                     |               | 80.00                     | 30.00             |
|                    | REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.                                                  |               | 400.00                    | 80.00             |
|                    | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.                                                                             |               | 220.00                    | 60.00             |
|                    | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.                                  | NOT NECESSARY | 550.00                    | -                 |
|                    | REAR CHASSIS ALIGNMENT.                                                                                                           | NOT NECESSARY | 250.00                    | -                 |
|                    | TRANSFER BOOTLID MECHANISM.                                                                                                       |               | 80.00                     | 80.00             |
|                    | CONDUCT WATER LEAKAGE TEST.                                                                                                       | NOT NECESSARY | 80.00                     | -                 |
|                    | REMOVE AND REFIX REAR EXHAUST PIPE.                                                                                               | NOT NECESSARY | 200.00                    | -                 |
|                    |                                                                                                                                   |               | -                         | -                 |
|                    |                                                                                                                                   |               | -                         | -                 |
|                    |                                                                                                                                   |               | -                         | -                 |
|                    |                                                                                                                                   |               | 5,210.00                  | 2,310.00          |
| <b>GRAND TOTAL</b> |                                                                                                                                   |               | <b>37,718.20</b>          | <b>13,178.00</b>  |



|                                                                                     |  |  |           |
|-------------------------------------------------------------------------------------|--|--|-----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) |  |  | 10,500.00 |
|-------------------------------------------------------------------------------------|--|--|-----------|

Report Ref No. CS/INC19002687/Atd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.