

INS. CASE OWNER:

CC 4, MG 1900 2710, H 023/11

LKK
IDAC

Surveyor:

WSP

DOI:

ASSIGNMENT

13/2/19

Date / Time:

12/02/19

Registered in Merimen:

13/2/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKU 3247 P

Name of Insured:

Chen Chen Chen

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

3/2/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Chen Ming Sun

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLT 1908C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Glockwerke



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

18/2
New

SLT 1908C - x ; SKU 3247P - x

24/10/19 - File MMS TO HMM TO CLOS

* WI not taking a settlement amount.
Including LOR.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 22/10/19

Confirm with: Annabelle

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

Repair Cost:

S\$ 6100.00

Loss of Rental (LOR):

S\$ 700.00

(

7 days) x \$100

Loss of Use (LOU):

S\$ -

(\$

x days)

Loss of Income (LOI):

S\$ -

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

Total:

S\$ 6800.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 6800.00

Name 1:

Glockwerke

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

COPY SENT
24/10/19

REF AIG

Policy No. 13/02/19

Date 13/2/19

Estimated Value

CD / TD / WS / TP / RES / OD / RES / EVA / RV / MY

To inspect Vehicle No

SLT1908C
Glockewerke

at what address

23 buki Bukit Ave 4 #04-01

Insured

Policy No

Class No

Sum Insured

Excess

(Client's Record)

Make of Vch

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value

IIAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repair

5

days

Res.

Yes or No

Lump Sum

20

%

3 Val.

Yes or No

CA / REV / REP / 24 HRS

hpr

Vehicle IN / OUT

Date

Person Contacted

Vehicle No SLT1908C

Year 2017 Oct

Type ☒ Car / ☐ Motorcycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make

Bmw 116D.

1496

Color

White

A/C Insured / Std / NI / NA

Op Reading

29429

U/Cade Insured / Std / NI / NA

Engine

Chassis

WBA1V720905 686893

Gen Cond ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering ☒ Normal / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake ☒ Normal / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size

F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LZA ☒ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A.

0.01

13/02/19

Survey held at

Glockewerke

Des. of Damages: ☒ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TPALG.

L/S - \$6100 (Red \$6541 / 521)

Date/Time, File Path to:

☐

Pref. Report

Days Of Repair:

to

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Path to:

Survey Fee

Transportation

Add Fee:

☐

Site Trip: \$

☐

Interview: \$

☐

Technician: \$

☐

Workshop: \$

Report Format

Lump Sum / LB / FS

Page

Glockewerke

21 Kaki Bukit Road 4 #01-02 S417810

Hotline: +65 8112 6485

Email: Annabelle_lim90@hotmail.com

ESTIMATE

TAN LEE ANN ANNA
123 BEDOK RIA CRESCENT
SINGAPORE 489933

TPA16.

Ashes

Date: 11/2/2019
Vehicle No.: SLT1908C
Model: BMW F20 116D
Chassis No.: WBA1V720905G86893

PARTS AND LABOUR ASSESSMENT

DESCRIPTION OF PARTS	QTY	UNIT PRICE	TOTAL PRICE
REAR BUMPER (M SPORT BODYKIT) <i>Red</i>	1	\$1,500.00	\$1,500.00 ✓
REAR BUMPER DIFFUSER (M SPORT) <i>Red</i>	1	\$550.00	\$550.00 ✓
TOWING COVER <i>Missing</i>	1	\$60.00	\$60.00 ✓
REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$380.00	\$380.00 ✓
REAR BUMPER PDC HOLDER (SET) <i>new</i>	1	\$60.00	\$60.00 ✓
REAR BUMPER REFLECTOR <i>lit cranked</i>	2	\$90.00	\$180.00 <i>80</i>
REAR BUMPER RETAINER <i>new</i>	2	\$100.00	\$200.00 ✓
END PANEL <i>Rye</i>	1	\$620.00	\$620.00 ✓
ENG PANEL GARISH <i>new</i>	1	\$100.00	\$100.00 ✓
REAR TAIL LID <i>Red</i>	1	\$1,850.00	\$1,850.00 ✓
REAR TAIL TRIM <i>new</i>	1	\$1,000.00	\$1,000.00 ✓
STABILUS LID DAMPER <i>new</i>	2	\$50.00	\$100.00 ✓
REAR BOTH TRUNK LID HINGE <i>new</i>	2	\$150.00	\$300.00 ✓
REAR TAIL LID BMW LOGO <i>new</i>	1	\$120.00	\$120.00 ✓
REAR TAIL LID EMBLEM BUTTON <i>new</i>	1	\$250.00	\$250.00 ✓
REAR TAIL LID LOCK <i>Damaged</i>	1	\$280.00	\$280.00 ✓
REAR TAIL LID GASKET <i>new</i>	1	\$280.00	\$280.00 ✓
REAR RH TAIL LAMP INNER <i>new</i>	1	\$450.00	\$450.00 ✓
REAR LH TAIL LAMP OUTER <i>cranked</i>	1	\$500.00	\$500.00 ✓

Sub-Total before discount: \$8,780.00

5% discount: \$439.00

Sub-Total after discount: \$8,341.00

DESCRIPTION OF PARTS	QTY	UNIT PRICE	TOTAL PRICE
REAR BUMPER PDC HOLDER (SET) <i>Repacked</i>	1	\$60.00	\$60.00 *
PDC SENSOR (SET) <i>2 pieces damaged</i>	1	\$900.00	\$900.00 <i>Sub</i>
NUMBER PLATE LIGHT <i>New</i>	1	\$30.00	\$60.00 *
REVERSE CAMERA <i>Damaged</i>	1	\$1,300.00	<u>\$1,300.00</u> <i>\$80</i>
REAR BUMPER SCREW (SET) <i>new</i>	1	\$30.00	\$30.00 *
TAIL LIGHT SCREW (SET) <i>3 new</i>	1	\$10.00	\$10.00 *
TAIL LID SCREW (SET)	1	\$20.00	\$20.00 *

Sub-Total before discount: \$2,380.00

0% discount: \$0.00

Sub-Total 2: \$2,380.00

LABOUR

Diagnose, replace and repair to rectify electrical system for proper functioning (Reverse camera and PDC sensor) : \$60.00 *30*

To check fault, erase fault and factory reset functions : \$60.00 *

To provide workmanship labour to remove damage parts for assembly to new bodyparts, repair, re-construct and re-adjust structure, body alignments and damaged consistent from the accident. : \$1,000.00 *600*

To re-spray painting for change bodyparts, repair portion and where consistent from the accident : \$800.00 *600*

Labour Sub-Total: \$1,920.00

Parts and Labour Total: \$12,641.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
4/s 13/02/19

OS Pays

total: 7650.5
4/s: 6.11c

- Pre repair inspection request - SLT1908C VS SKV3247P (OI) DOA 03/02/2019

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinnul
Sent: 12/02/2019 4:00:35 PM
Attachments:  3ASZ00707.pdf

Hi,

Please refer to the enclosed request from GLOCKEWERKE.

Claim no : 7943040789SG0003
Case Owner : MING YAO LEE

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Syaza Indira Azlan
AIG
Express Claims Adjuster II, Singapore FNOI, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: glockewerke@outlook.com [mailto:glockewerke@outlook.com]
Sent: Tuesday, February 12, 2019 3:19 PM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinnul
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV3247P AND SLT1908C ON 03/02/2019

Hi Syazairdina,

Thank you for your reply. We would like to appoint Adrian Ling from LKK auto.

Thank you

Xavier Lim

From: Azlan, Syazairdina
Sent: Tue, 12 Feb 2019 06:54:29 +0000
To: glockewerke@outlook.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinnul
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV3247P AND SLT1908C ON 03/02/2019

Without Prejudice

Your Reference : SLT1908C
Our Reference : 7943040789SG0003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd

9.59am @ 13/2/19
person @ Annabelle
vehicle in
SUR @ Adrian

Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNDL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Chin, Lee-Ying
Sent: Tuesday, February 12, 2019 11:32 AM
To: Azlan, Syazairdina
Subject: FW: ACCIDENT ON 03.02.2019 BETWEEN SLT1908C AND SKV3247P ALONG CTE TOWARDS AYE BEFORE BUKIT TIMAH RD EXIT

From: Glockewerke Auto [mailto:glockewerke@outlook.com]
Sent: Tuesday, February 12, 2019 11:22 AM
To: Chin, Lee-Ying
Subject: ACCIDENT ON 03.02.2019 BETWEEN SLT1908C AND SKV3247P ALONG CTE TOWARDS AYE BEFORE BUKIT TIMAH RD EXIT

AIG: SKV3247P

PRE-REPAIR INSPECTION NOTICE

~
Dear Ms Lee,

**CLAIM BY TAN LEE ANN ANNA, NRIC NO. S1549804H
THE OWNER OF SLT1908C AGAINST OWNER/DRIVER OF SKV3247P**

We act for Tan Lee Ann Anna the owner and driver of SLT 1908C that was damaged as a result of the above accident.

Attached is our client's GIA Report of the Accident for your attention and records.

Please take note that our client's motorcar is presently located at his repairer's workshop.

MG Solution

23, Kaki Bukit Avenue 4, #04-01

Singapore 415933

Tel: 81126485/90079247

Email: glockewerke@outlook.com

Attn: Annabelle Lim/Xavier Lim

In the circumstances, kindly let us know within 2 (two) working days from your receipt of this Notice if you will be conducting a pre-repair inspection of our client's vehicle.

As provided by the NIMA Protocol, take notice that our client shall proceed to appoint his own surveyor and repair his vehicle without any further reference to you, if we do not hear from you within the next 2 (two) days.

Yours faithfully,

Xavier Lim

GLOCKEWERKE
21 KAKI BUKIT ROAD 4, #01-02
KAKI BUKIT SYNERGY
Singapore 417810

Tel: +65 8112 6485 / +65 9007 9247

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information.

If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

RE: ACCIDENT ON 03.02.2019 BETWEEN SLT1908C AND SKV3247P ALONG CTE TOWARDS AYE BEFORE BUKIT TIMAH RD EXIT

Jia Le (LKK Auto) <jiale@lkkauto.com>

Wed 12/16/2019 3:25 PM

To: Glockewerke Auto <glockewerke@outlook.com>

WITHOUT PREJUDICE

Dear Annabelle,

We refer to the above matter.

We propose settlement as follows:

1. Cost of Repair	\$ 6,100.00
2. Loss of Rental (7days x \$100)	\$ 700.00
TOTAL	\$ 6,800.00

Please confirm acceptance.

*Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6395 9767 | email: jiale@lkkauto.com | fax: 6749 4108

815 52, Paga 114 Industrial Park, Ubi Avenue 1, #02-05 | Singapore

From: Glockewerke Auto (mailto:glockewerke@outlook.com)

Sent: Thursday, 20 June 2019 4:14 PM

To: Asher Sng (LKKAuto); Jia Le (LKK Auto)

Subject: Re: ACCIDENT ON 03.02.2019 BETWEEN SLT1908C AND SKV3247P ALONG CTE TOWARDS AYE BEFORE BUKIT TIMAH RD EXIT

Dear Asher,

Can i check if you received the invoices?

Thank you

Annabelle Lim

8112 6485

From: Glockewerke Auto

Sent: Friday, June 7, 2019 4:49 PM

To: Asher Sng (LKKAuto); Jia Le (LKK Auto)

Subject: Re: ACCIDENT ON 03.02.2019 BETWEEN SLT1908C AND SKV3247P ALONG CTE TOWARDS AYE BEFORE BUKIT TIMAH RD EXIT

Dear Asher,

Xavier have left the company.

I have attached the LOD on the above.

Thank you

Annabelle

Glockewerke

8112 6485

From: Asher Sng (LKKAuto) <asher.sng@lkkauto.com>

Sent: Friday, June 7, 2019 12:25 PM

To: 'Glockewerke Auto'; Jia Le (LKK Auto)

Subject: RE: ACCIDENT ON 03.02.2019 BETWEEN SLT1908C AND SKV3247P ALONG CTE TOWARDS AYE BEFORE BUKIT TIMAH RD EXIT

WITHOUT PREJUDICE

SAVE AS TO COSTS

Hi Xavier,

We refer to the above matter.

Please forward us the full set of LOD via email for our necessary action.

Glockewerke

21 Kaki Bukit Road 4 #01-02 S417810

Hotline: +65 8112 6485

Email: Annabelle_lim90@hotmail.com

INVOICE

TAN LEE ANN ANNA
123 BEDOK RIA CRESCENT
SINGAPORE 489933

Date: 5/4/2019
Vehicle No.: SLT1908C
Model: BMW F20 116D
Chassis No.: WBA1V720905G86893

Lump Sum Invoice

Inclusive of supplying parts, spray painting and labour charges. \$6,100.00

Rental 14days (04.02.2019 - 18.02.2019) \$700.00
(Including Saturday/Sunday and also Chinese New Year)

Grand-Total: \$6,800.00

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.



Glockewerke

21 Kaki Bukit Road 4 #01-02 S417810

Hotline: +65 8112 6485

Email: Annabelle_lim90@hotmail.com

INVOICE

TAN LEE ANN ANNA
123 BEDOK RIA CRESCENT
SINGAPORE 489933

Date: 25/02/29
Vehicle No.: SLT1908C
Model: BMW F20 116D
Chassis No.: WBA1V720905G86893

PARTS AND LABOUR ASSESSMENT

DESCRIPTION OF PARTS	QTY	UNIT PRICE	TOTAL PRICE
REAR BUMPER (M SPORT BODYKIT)	1	\$1,500.00	\$1,500.00
REAR BUMPER DIFFUSER (M SPORT)	1	\$550.00	\$550.00
TOWING COVER	1	\$60.00	\$60.00
REAR BUMPER REINFORCEMENT	1	\$380.00	\$380.00
REAR BUMPER PDC HOLDER (SET)	1	\$60.00	\$60.00
REAR BUMPER REFLECTOR	1	\$90.00	\$90.00
REAR BUMPER RETAINER	2	\$100.00	\$200.00
REAR TAIL LID	1	\$1,850.00	\$1,850.00
REAR TAIL LID BMW LOGO	1	\$120.00	\$120.00
REAR TAIL LID LOCK	1	\$280.00	\$280.00
REAR LH TAIL LAMP OUTER	1	\$500.00	\$500.00

Sub-Total before discount: \$5,590.00
5% discount: \$279.50
Sub-Total after discount: \$5,310.50

DESCRIPTION OF PARTS	QTY	UNIT PRICE	TOTAL PRICE
PDC SENSOR (SET)	1	\$500.00	\$500.00
REVERSER CAMERA	1	\$1,300.00	\$580.00
REAR BUMPER SCREW (SET)	1	\$30.00	\$30.00

Sub-Total before discount: \$1,110.00
0% discount: \$0.00
Sub-Total 2: \$1,110.00

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

Glockewerke

21 Kaki Bukit Road 4 #01-02 S417810

Hotline +65 8112 6485

Email: Annabelle_jm90@hotmail.com

ESTIMATE

TAN LEE ANN ANNA
123 BEDOK RIA CRESCENT
SINGAPORE 489933

Date: 11/2/2019
Vehicle No.: SLT1908C
Model: BMW F20 116D
Chassis No.: WBA1V720905G86893

PARTS AND LABOUR ASSESSMENT

DESCRIPTION OF PARTS	QTY	UNIT PRICE	TOTAL PRICE
REAR BUMPER (M SPORT BODYKIT) <i>Red</i>	1	\$1,500.00	\$1,500.00 ✓
REAR BUMPER DIFFUSER (M SPORT) <i>Red</i>	1	\$550.00	\$550.00 ✓
TOWING COVER <i>Missing</i>	1	\$60.00	\$60.00 ✓
REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$380.00	\$380.00 ✓
REAR BUMPER PDC HOLDER (SET) <i>new</i>	1	\$60.00	\$60.00 ✓
REAR BUMPER REFLECTOR <i>LH crumb</i>	2	\$90.00	\$180.00 <i>PO</i>
REAR BUMPER RETAINER <i>new</i>	2	\$100.00	\$200.00 ✓
END PANEL <i>Bye</i>	1	\$620.00	\$620.00 ✓
ENG PANEL GARISH <i>new</i>	1	\$100.00	\$100.00 ✓
REAR TAIL LID <i>2x100</i>	1	\$1,850.00	\$1,850.00 ✓
REAR TAIL TRIM <i>new</i>	1	\$1,000.00	\$1,000.00 ✓
STABILUS LID DAMPER <i>new</i>	2	\$50.00	\$100.00 ✓
REAR BOTH TRUNK LID HINGE <i>new</i>	2	\$150.00	\$300.00 ✓
REAR TAIL LID BMW LOGO <i>new</i>	1	\$120.00	\$120.00 ✓
REAR TAIL LID EMBLEM BUTTON <i>new</i>	1	\$250.00	\$250.00 ✓
REAR TAIL LID LOCK <i>Damaged</i>	1	\$280.00	\$280.00 ✓
REAR TAIL LID GASKET <i>new</i>	1	\$280.00	\$280.00 ✓
REAR RH TAIL LAMP INNER <i>new</i>	1	\$450.00	\$450.00 ✓
REAR LH TAIL LAMP OUTER <i>crumb</i>	1	\$500.00	\$500.00 ✓

Sub-Total before discount: \$8,780.00

5% discount: \$439.00

Sub-Total after discount: \$8,341.00

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages or my personal injuries sustained in the same accident.

Glockewerke

21 Kaki Bukit Road 4 #01-02 Singapore 417810

Hotline: +65 8112 6485

Email: glockewerke@fsg.com.sg

UEN: 53373583A

Replacement Vehicle No : SJXJ044R
Accident Vehicle No : SLT1908C
Owner/Driver Name : MARK TANG SONG KANG
Address : 123 BEDOK R/A CRESCENT
S489933
Driving License No : S9125663J Date of Birth: 19.07.1991
Date Vehicle Taken : 04.02.19 Time Out : 1.00 PM
Date Vehicle Return : 18.02.19 Time In : 2.00 PM

We have been authorized by you to commence repairs and demand claims for your accident vehicle. In the event, we provide you the above said replacement vehicle for your conveniences. Upon collection of above replacement vehicle, you will be fully responsible for the following terms and conditions until the date and time of returning the above said replacement vehicle:

- Any traffic summons and parking offences.
- Accident / Losses – you have to bear the Insurance policy excess and / or compensate the repair cost / losses by yourself.
- This vehicle is to be used in Singapore only.
- Upon returning of the replacement vehicle, you must ensure that all valuables and important items are to be removed from above stated replacement vehicle. We will not be responsible of such losses.

I, FULLY UNDERSTAND AND AGREED TO BE RESPONSIBLE ON THE ABOVE TERMS AND CONDITIONS UPON RECEIVING THIS REPLACEMENT VEHICLE FOR MY CONVENIENCES AND BEAR ALL COSTS INCURRED FROM SUCH INCIDENT. I FURTHER UNDERTAKE THE REPAIRER WILL NOT BE RESPONSIBLE FOR ANY LOSS OF ANY ITEMS OR VALUABLES THAT MAY HAVE LEFT BY ME/US IN MY/OUR ACCIDENT VEHICLE WHEN I HANDED IT OVER TO THEM FOR THE PURPOSE OF REPAIRS.



Owner / Driver Signature

HP: 8328 8862

LETTER OF AUTHORITY

Name : TAN LEE ANN ANNA

Address : 123 BEDOK RIA
CRESCENT S489933

Contact No : 8328 8862

TO :

Dear Sirs,

ACCIDENT INVOLVING SLT1908C AND SKV3J47P ON 03.02.19
AT/ALONG CTE TWDS AYE BEF BUKIT TINAH RD EXIT

I/We, TAN LEE ANN ANNA, am/are the registered owner of
motor car no. SLT1908C

Please note that I have assigned all compensation monies due to me/us in the above said accident to:
GLOCKEWERKE.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to GLOCKEWERKE and forward your settlement cheque to GLOCKEWERKE whom I had
authorized to collect the said compensation monies.

Thank you



Signature of Claimant



Witness By

Glockenwerke

21 Kaki Bukit Road 4 #01-02 Singapore 417810

Hotline: +65 8112 6482

Email:

URN: 53715834

Replacement Vehicle No: 57330444
Accident Vehicle No: 5719080
Owner/Driver Name: NEERA JANG SONG HANG
Address: 123 BEDOK DIA RESIDENT
5489933
Driving License No: 591256637 Date of Birth: 19 02 1991
Date Vehicle Taken: 04 02 19 Time Out: 1 00 PM
Date Vehicle Return: 18 02 19 Time In: 3 00 PM

We have been authorized by you to commence repairs and demand claims for your accident vehicle. In the event, we provide you the above said replacement vehicle for your convenience. Upon collection of above replacement vehicle, you will be fully responsible for the following terms and conditions until the date and time of returning the above said replacement vehicle.

- Any traffic summons and parking offences.
- Accident / Losses - you have to bear the insurance policy excess and / or compensate the repair cost / losses by yourself.
- This vehicle is to be used in Singapore only.
- Upon returning of the replacement vehicle, you must ensure that all valuables and important items are to be removed from above stated replacement vehicle. We will not be responsible of such losses.

I, FULLY UNDERSTAND AND AGREE TO BE RESPONSIBLE ON THE ABOVE TERMS AND CONDITIONS. UPON RECEIVING THIS REPLACEMENT VEHICLE FOR MY CONVENIENCE AND BEAR ALL COSTS INCURRED FROM SUCH INCIDENT. I FURTHER UNDERTAKE THE REPAIRER WILL NOT BE RESPONSIBLE FOR ANY LOSS OF ANY ITEMS OR VALUABLES THAT MAY HAVE LEFT BY ME/US IN MY/OUR ACCIDENT VEHICLE WHEN I HANDED IT OVER TO THEM FOR THE PURPOSE OF REPAIRS.



Owner / Driver Signature

LETTER OF AUTHORIZATION

(Workshop)

: GLOCKENBERG

From

Name (Owner / Company)

TAN LEE ANN ANNA

Address

123 BEDOK AVE CRESCENT

S489933

NRIC No

ACCIDENT INVOLVING

SLT1908C AND SKV32470 ON 03.03.19

AT / ALONG CTE

WOODS AVE BEK BLK17 TIANH RD

We

TAN LEE ANN ANNA

am/are the registered owner of motor

car no.

SLT1908C

hereby do authorize you to commence repair to my above mentioned vehicle.

I confirm that you are hereby authorized to handle the repair of the vehicle and/or to negotiate and settle my claims, relating to the above mentioned accident, which I/we may have, against other third party/parties, or insurers, and/or to instruct lawyers on my/our behalf, to facilitate the third party claim for me/us.

You are hereby authorized to execute and/or sign my documents/discharge vouchers/agreements regarding my/our claim/case for my convenience. You are also hereby authorized to receive on my/our behalf any monies/claims, in correspondences/connection with this said claim.

I confirm that in the event of an unsuccessful claim, against the negligent party, and/or my own insurer for the damages caused to my vehicle, I agree to pay for all repair costs and any incidental expenses (including legal fees) incurred by you, or to lodge an own damage claim (only for comprehensive cover) to cover the expenses incurred.

Witness's Name

py.

Dated:

13/2/19

Witness's Signature

Owner's Signature:

Hm



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19002710/Ada3

07 OCTOBER 2019

CHU CHENG CHUAH
838 WOODLANDS STREET 82
#03-271
SINGAPORE 730838

Dear Sir/Madam,

**ACCIDENT INVOLVING SKV 3247P & SLT 1908C ALONG/AT EXPRESSWAY CTE
BEF BUKIT TIMAH ON 03/02/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLT 1908C against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: JiaLe@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

LETTER OF AUTHORITY

Name : TAN LEE ANN ANNA
Address : 123 BEDOK RIA
RESIDENT S+89933
Contact No : 8328 8862

TO

Dear Sirs,

ACCIDENT INVOLVING SL71908C AND SKV3347A ON 03.02.19
AT/ALONG CTE TWOS AYE BEF BRKIT ZINAH RD

I/We, TAN LEE ANN ANNA am/are the registered owner of
motor car no SL71908C

Please note that I have assigned all compensation monies due to me/us in the above said accident to
GLOCKWERKE.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to GLOCKWERKE and forward your settlement cheque to GLOCKWERKE whom I have
authorized to collect the said compensation monies.

Thank you


Signature of Claimant


Witness By

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, GLOCKEWERKE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,100.00 (Repair Cost), S\$700.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. SLT 1908C that was damaged pursuant to the accident which occurred on 03/02/2019 (date) along CTE TWDS AYE BEFORE BUKIT TIMAH RD EXIT (location) involving vehicle no/s SKV 3247P. This is pursuant to the inspection conducted on 13/02/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN LEE ANN ANNA ("the third party claimant") of vehicle no. SLT 1908C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLT 1908C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 22nd (day) of October (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Glockewerke

21 Kaki Bukit Road 4 #01-02 S417810

Hotline: +65 8112 6485

Email: Annabelle_lim90@hotmail.com

INVOICE

TAN LEE ANN ANNA
123 BEDOK RIA CRESCENT
SINGAPORE 489933

Date: 5/4/2019
Vehicle No.: SLT1908C
Model: BMW F20 116D
Chassis No.: WBA1V720905GE

Lump Sum Invoice

Inclusive of supplying parts, spray painting and labour charges. \$6,100.00

Rental 14days (04.02.2019 - 18.02.2019) \$1,650.00
(Including Saturday/Sunday and also Chinese New Year)

Grand-Total: \$7,750.00

Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Feb 2019 Edit Reg		12 Feb 2019 00:00 Edit Adj Rpt	S\$6,100.00 Edit Estimates	S\$6,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CHU CHENG CHUAH , ID: S1726138Z									
Main Claimant: TAN LEE ANN ANNA , ID: S1549804H									
Vehicle Reg. No.: SLT1908C		Date of Loss: 03/02/2019 16:00 - :59 [15 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7943040789SG		Policy/Cover Note No.: 2100428362 (Comprehensive)							
Vehicle Reg. No. (Insured): SKV3247P		Policy No. (Claimant): DMPG18004677							
		Excess:							
Repairer: Glockwerke (HQ) 1 KAKI BUKIT AVE 6 #01-08 AUTOBAY, 417883 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT1908C (79430407895G)

[SKV3247P]

TP

TAN LEE ANN ANNA

Feb 3 2019 4:00PM

[CHU CHENG CHUAH]

Glockewerke

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page ☐ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Photos/Images			3 per page ☐ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/19 09:04	General View	Load JPG	☒
2	04/04/19 09:04	General View	Load JPG	☒
3	04/04/19 09:04	General View	Load JPG	☒
4	04/04/19 09:04	General View	Load JPG	☒
5	04/04/19 09:04	General View	Load JPG	☒
6	04/04/19 09:04	General View	Load JPG	☒
7	04/04/19 09:04	General View	Load JPG	☒
8	04/04/19 09:04	General View	Load JPG	☒
9	04/04/19 09:04	General View	Load JPG	☒
10	04/04/19 09:04	General View	Load JPG	☒
11	04/04/19 09:04	General View	Load JPG	☒
12	04/04/19 09:04	General View	Load JPG	☒
13	04/04/19 09:04	General View	Load JPG	☒
14	04/04/19 09:04	General View	Load JPG	☒
15	04/04/19 09:04	General View	Load JPG	☒
16	04/04/19 09:04	General View	Load JPG	☒
17	04/04/19 09:04	General View	Load JPG	☒
18	04/04/19 09:04	General View	Load JPG	☒
19	04/04/19 09:04	General View	Load JPG	☒
20	04/04/19 09:04	General View	Load JPG	☒
21	04/04/19 09:04	General View	Load JPG	☒
22	04/04/19 09:04	General View	Load JPG	☒
23	04/04/19 09:04	General View	Load JPG	☒
24	04/04/19 09:04	General View	Load JPG	☒
25	04/04/19 09:04	General View	Load JPG	☒
26	04/04/19 09:04	General View	Load JPG	☒
27	04/04/19 09:04	General View	Load JPG	☒
28	04/04/19 09:04	General View	Load JPG	☒
29	04/04/19 09:04	General View	Load JPG	☒
30	04/04/19 09:04	Reinspection Photo	Load JPG	☒
31	04/04/19 09:04	Reinspection Photo	Load JPG	☒
32	04/04/19 09:04	Reinspection Photo	Load JPG	☒
33	04/04/19 09:04	Reinspection Photo	Load JPG	☒
34	04/04/19 09:04	Reinspection Photo	Load JPG	☒
35	04/04/19 09:04	Reinspection Photo	Load JPG	☒
36	04/04/19 09:04	Reinspection Photo	Load JPG	☒
37	04/04/19 09:04	Reinspection Photo	Load JPG	☒
38	04/04/19 09:04	Reinspection Photo	Load JPG	☒
39	04/04/19 09:04	Reinspection Photo	Load JPG	☒
40	04/04/19 09:04	Reinspection Photo	Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	04/04/19 09:04	Reinspection Photo		Load JPG	☒
42	04/04/19 09:04	Reinspection Photo		Load JPG	☒
43	04/04/19 09:04	Reinspection Photo		Load JPG	☒
44	04/04/19 09:04	Reinspection Photo		Load JPG	☒
45	04/04/19 09:04	Reinspection Photo		Load JPG	☒
46	04/04/19 09:04	Reinspection Photo		Load JPG	☒
47	04/04/19 09:04	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/02/19 19:28	ACKNOWLEDGEMENT EMAIL TO AIG DD 13.02.2019		Load PDF	
2	13/02/19 19:28	EMAIL FROM AIG DD 12.02.19		Load PDF	
3	13/02/19 19:28	TP GIA REPORT		Load PDF	
4	13/11/19 09:33	WORKSHOP INVOICE & LOD		Load PDF	
5	13/11/19 09:33	AUTHORISATION TO ACT FORM		Load PDF	
6	13/11/19 09:33	Release Voucher		Load PDF	
7	13/11/19 09:33	RENTAL RECEIPT		Load PDF	
8	13/11/19 09:33	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	14/02/19 15:11	OI GIA REPORT		Load PDF	
2	25/07/19 14:53	PD Claim Supp Docs		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKV3247P (Insd veh)	Model:	BMW 116D 1.5 D 5DR LED
	SLT1908C (TP veh)		EU6 (A)
Date of Accident:	03/02/2019		

Global Sum Settlement	: ☐ Yes	: ☒ No	
Repair Estimate	: \$		12,641.00
Final Repair Cost	: \$		6,100.00
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$	700.00	7 days
LTA / GIA Search Fee	: \$	0.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	6,800.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Glockewerke	: \$	6,800.00
2)		: \$	

JOANNE LEE KHANG MIN

13 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19002710/ADA3Q2

Date: 13/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100428362
 Claimant: SLT1908C Insured Vehicle No: SKV3247P
 Vehicle No: SLT1908C Nature of Claim: TP Claim No: 7943040789SG
 Date of Loss: 03/02/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT1908C
 Make & Model: BMW 116D, 1.5 D 5DR LED EU6 (A) Engine No: 30955042B37D15A
 Reg. Date: 20/10/2017 (Man. Year: 2017) Chassis No: WBA1V720905G86893
 Colour: White Odometer: 29429 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,721.00	6,420.50	4,300.50	40.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,230.00	690.00	35.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,641.00	7,650.50	4,990.50	39.48
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	12,641.00	6,100.00	6,541.00	51.74
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		6,800.00		

INSPECTION

Date of Assignment: 12/02/2019
 Date Inspected: 13/02/2019 Inspected At: Glockewerke (HQ)
 1 KAKI BUKIT AVE 6 #01-08
 AUTOBAY
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (M SPORT BODYKIT)	Deformed	1,500.00 FL	*1,500.00 FL
2	1		*REAR BUMPER DIFFUSER (M SPORT)	Deformed	550.00 FL	*550.00 FL
3	1		*TOWING COVER	Missing	60.00 FL	*60.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	380.00 FL	*380.00 FL
5	1		*SET REAR BUMPER PDC HOLDER	Necessary	60.00 FL	*60.00 FL
6	1		*REAR BUMPER REFLECTOR	N/S Cracked	180.00 FL	*90.00 FL
7	2		*REAR BUMPER RETAINER	Necessary	200.00 FL	*200.00 FL
8	1		*END PANEL	Repair	620.00 FL	*- FL
9	1		*END PANEL GARNISH	Not Necessary	100.00 FL	*- FL
10	1		*REAR TAIL LID	Dented	1,850.00 FL	*1,850.00 FL
11	1		*REAR TAIL TRIM	Not Necessary	1,000.00 FL	*- FL
12	2		*STABILUS LID DAMPER	Not Necessary	100.00 FL	*- FL
13	2		*REAR BOTH TRUNK LID HINGE	Not Necessary	300.00 FL	*- FL
14	1		*REAR TAIL LID BMW LOGO	Necessary	120.00 FL	*120.00 FL
15	1		*REAR TAIL LID EMBLEM BUTTON	Not Necessary	250.00 FL	*- FL
16	1		*REAR TAIL LID LOCK	Damaged	280.00 FL	*280.00 FL
17	1		*REAR TAIL LID GASKET	Not Necessary	280.00 FL	*- FL
18	1		*REAR RH TAIL LAMP INNER	Not Necessary	450.00 FL	*- FL
19	1		*REAR RH TAIL LAMP OUTER	Cracked	500.00 FL	*500.00 FL
20	1		*SET REAR BUMPER PDC HOLDER	Repeated	60.00 FS	*- FS
21	1		*SET PDC SENSOR	Damaged (2 PCS ONLY)	900.00 FS	*500.00 FS
22	1		*NUMBER PLATE LIGHT	Not Necessary	60.00 FS	*- FS
23	1		*REVERSE CAMERA	Damaged	1,300.00 FS	*580.00 FS
24	1		*SET REAR BUMPER SCREW	Necessary	30.00 FS	*30.00 FS
25	1		*SET TAIL LIGHT SCREW	Not Necessary	10.00 FS	*- FS
26	1		*SET TAIL LID SCREW	Not Necessary	20.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	11,160.00	6,700.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	439.00	279.50
Total Parts (\$\$)	10,721.00	6,420.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSE ,REPLACE AND REPAIR TO RECTIFY ELECTRICAL SYSTEM FOR PROPER FUNCTIONING (REVERSE CAMERA AND PDC SENSOR)	New	60.00	30.00
2	TO CHECK FAULT ,ERASE FAULT AND FACTORY REST FUNCTIONS	New	60.00	0.00
3	TO PROVIDE WORKMANSHIP LABOUR TO REMOVE DAMAGE PARTS FOR ASSE TO NEW BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ADJUST STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT FROM THE ACCIDENT	New	1,000.00	600.00
4	TO RE-SPRAY PAINTING FOR CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT FROM THE ACCIDENT	New	800.00	600.00
Gross Labour Cost (\$\$)			1,920.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >