

Adrian Nimen

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1800065855

Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 120K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 wks days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SDJ9318A Yr Regn: 2018, JuneType: ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: And; A3 SB c.c. 999Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 5739 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WA42228V2JA112406Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm

L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
------------------	----	------------------	----

D.O.A. <u>5/2/19</u>	D.O.I. <u>13/02/19</u>
----------------------	------------------------

Survey held at PremiumDes. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD AIGSDJ9318A-CC3/11619002720/Avd362DDA 6/11/1614/2/19 Revert via merimen15/2/19 Rece approved \$12,464 from Victor by merimen15/2/19 Informed Tony CIA ex \$600 by email9/5/19 Final fig \$15,210.12 (Red 8815.88, 3TB) confirmed by email

RECEIVED 28 MAR 2019

RECEIVED 24 MAY 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 24/5 - typist

2) _____

3) _____

4) _____

5) _____

6) _____

Prel. Report: _____

Final Report: _____

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

\$ + RS. \$

Photos

Others

TOTAL

Date:

20010210

View Received Message

This mail is associated with :

***SDJ9318A (3119083177SG)**

OD

Feb 5 2019 2:00PM

[TAI HWEI YEE]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/05/2019 16:43 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$15210.12) - SDJ9318A - Claim Handler: Dally Amri, Mimi Zarina

Approved:15210.12:

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Sent: Thursday, 9 May 2019 4:44 PM
To: Veron Chen (LKKAUTO)
Subject: RE: SDJ 9318A-DOA: 5/2/2019 (AIG REF: 3119083177SG)

Dear Veron

Mandate reviewed and set.

Andy Fong
AIG
Claims Technical Control Manager
Singapore | Hong Kong
AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1708|M: +(65) 9138 1785
Andy-SY.Fong@AIG.com | www.AIG.com.sg

AIG 100 | Celebrating 100 years of risk expertise, promises kept, and creating a better world. Visit 100.aig to learn more.

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. [Click here to find out more.](#)

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, May 09, 2019 4:06 PM
To: Fong, Andy-SY
Subject: [EXTERNAL] SDJ 9318A-DOA: 5/2/2019 (AIG REF: 3119083177SG)

This message is from an external sender; be cautious with links and attachments.

Dear Andy,

Kindly assist for mandate approval for the mentioned vehicle.

Best Regards,
Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer

Veron Chen (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 8 April 2019 2:35 PM
To: Veron Chen (LKKAUTO)
Subject: Re: FINAL REVISION - SDJ9318A - OD AIG - SURVEYED 13 FEB 19

Hi Veron

Please refer to Adrian for advise.

We have agreed for lock carrier replacement at 2.5 - 3 days.

Best regards - jb

On Mon, Apr 8, 2019 at 2:31 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Carrine,

According to AIG Labour to replace lock carrier at 1 - 1.5 days only to re-adjust.

Please check Supplementary Labour 2 able to re-adjust to \$750 instead of \$1500/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Saturday, 23 March 2019 5:24 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SDJ9318A - OD AIG - SURVEYED 13 FEB 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$15,210.12 @ 6 days of repairs. Additional damages re-inspected by Taufikh on 5 Mar 19.

Your early closure is well appreciated.

Best regards - jb

View Received Message

This mail is associated with :

***SDJ9318A (3119083177SG)**

OD

Feb 5 2019 2:00PM

[TAI HWEI YEE]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/03/2019 12:09 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SDJ9318A - Claim Handler: Dally Amri, Mimi Zarina

Maintained:Labour to replace lock carrier at 1 - 1.5 days only to re-adjust. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 07 Mar 2019

Preliminary Advice

Vehicle No	: SDJ9318A	Accident Date	: 05/02/2019
Make	: AUDI A3 SPORTBACK	Policy No.	: 1800065855
Assignment Date	: 14/02/2019	Excess	: S\$600.00
Date of Inspection	: 13/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,026.00	(incl.supplementary \$4129)
Revised Amount	:S\$	17,141.00	(incl.supplementary \$4129)
Check Items (Estimated)	:S\$	1,455.00	
Total	:S\$	18,596.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	54,769.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,231.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 15 February 2019 3:42 PM
To: 'Claims'; SUR
Subject: RE: SDJ 9318 A - OD CLAIM-DOA: 5/2/2019

Dear Tony,

As instructed by our client, please proceed to repair the **insured vehicle SDJ 9318A (Excess S600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 14 February 2019 12:04 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SDJ 9318 A - OD CLAIM-DOA: 5/2/2019

Dear Tony,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 13 February 2019 4:05 PM

To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: SDJ 9318 A - OD CLAIM

Dear all,

Kindly assist follow up repair approval above mention case.

Survey had carry out just nw.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199903271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SDJ9318A (3119083177SG)**

OD

Feb 5 2019 2:00PM

[TAI HWEI YEE]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 15/02/2019 14:32 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12464.00) - SDJ9318A - Claim Handler: Dally Amri, Mimi Zarina

Approved:12464.00;Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Feb 2019

Preliminary Advice

Vehicle No	: SDJ9318A	Accident Date	: 05/02/2019
Make	: AUDI A3 SPORTBACK	Policy No.	: 1800065855
Assignment Date	: 14/02/2019	Excess	: S\$0.00
Date of Inspection	: 13/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,897.00
Revised Amount	:S\$	12,464.00
Check Items (Estimated)	:S\$	1,455.00
Total	:S\$	13,919.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	54,769.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,231.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8589D
Vehicle Details	
Vehicle No.:	SDJ9318A
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Feb 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CHZ939680
Chassis No.:	WAUZZZ8V2JA112406
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,173.00
Original Registration Date:	07 Jun 2018
First Registration Date:	07 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$25,843.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2028
PARF Rebate Amount:	\$19,382.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,001.00
COE Rebate Amount:	\$35,387.00
Total Rebate Amount:	\$54,769.00

The information contained herein is correct as at 14 Feb 2019

OK

CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAI HWEI YEE
Period of Insurance : 07 Jun 2018 To 06 Jun 2020
Engine No. : CHZ 939680
Chassis No. : WAUZZZ8V2JA112406

Vehicle No. : SDJ9318A
Policy No. : 1800065855
Endorsement No. : 000000000227633
Issued Date : 13 Sep 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC Sum Insured : Market Value First Year of Registration : 2018
Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes
Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAI Hwei Yee - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES


Hire Purchase Company/Employer's Loan: NA

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1968 (Malaysia).)

0504125223

PREMIUM LEASING - \$H
261 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399640

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8945725D



Name

TAN SHU YING, VALERIE

陈淑莹

Race

CHINESE

Date of birth

18-12-1989

Sex

F

Country of birth

SINGAPORE

S8945725D

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number

S8945725D

Name

TAN SHU YING, VALERIE

Birth Date: 18 Dec 1989

Issue Date: 23 Dec 2018



0028842548



NRIC No. S8945725D



Date of issue

20-12-2004

BLK 106 BRADDELL HILL #19-27
SINGAPORE 578726

NRIC No. S8945725D

Date: 05-09-2005 No. 8300983

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 18 Dec 2008



Licence No: S8945725D

NP 426A

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/02/2019 12:16
Date Of Accident	05/02/2019 14:50
Exact Location Of Accident	CNR UPPER SERANGOON & BRADDELL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDJ9318A
Insured/Policyholder	
Name Of Registered Owner	TAI HWEI YEE
NRIC No	S1298589D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81263277
Alternative Phone No	OTHERS-81263277

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SB 1.0 TF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800065855
Cover Note Number	

Driver

Name of Driver	TAN SHU YING, VALERIE
NRIC No	S8945725D
Date Of Birth	18/12/1989
Occupation	INDOOR
Date Of Driving Pass	16/12/2009
Driving Experience	9 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96671489
Fax Number	
Contact Number	
Email Address	VALERIE_SY_TAN@PHARMACY.NHG.COM.SG

Address	BLK 10G BRADDELL HILL #19-27
Postcode	579726
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

FRONT CAR STARTED TO MOVE OFF. I TOOK MY FOOT OFF THE BRAKE. FRONT CAR STOPPED. I DID NOT BRAKE IN TIME AND HIT MY REAR OF CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA5557Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PRAVEEN
NRIC/Passport Number	
Contact Number	84227760
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 8/2/19
10.20am

Reporting Centre Personnel's Signature
Name: Nora Kwei
NRIC/TIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. Front car started to move off
2. I took my foot off the brake
3. Front car stopped
4. I did not brake in time and hit rear of car

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 8/2/19

10:20am

Reporting Centre Personnel's Signature
Name: NORA KHAI
NRIC/FIN No.:



Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD /0171/2019/GW
Date : 9-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tai Hwei Yee
Address : 10G Braddell Hill
#19-27
Singapore 579726
Telephone : HP +65 81263277
Type of Claim : Own Damage Claims
Policy No. : 1800065855
Vehicle No : **SDJ 9318 A**
Model Code : Audi A3 1.0 Sportback
Model / Year : 7/6/2018
Engine No : CHZ 939680
Chassis No : WAUZZZ8V2JA112406
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Feb-19
Place of Accident : CNR Upper Serangoon & Braddell Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDJ 9318 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer Assy.	S/N S	360.00 ✓	✓
2	To dismantle and renew front bumper, lhs front fender, bonnet and headlight. Inspect front lock carrier for damage. Re-organise front crash management components. Reinstall all parts removed.	S	2,700.00 1250 ✓	✓
3	To respray front bumper, lhs front fender and bonnet.	S	2,200.00 1650 ✓	✓
4	To carry out diagnostic check.	S/N S	192.00 ✓	✓
TOTAL LABOUR CHARGES		: S	5,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SDJ 9318 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair to m</i>	\$ 1,698.00	✓ 1358.40
2	FRONT BUMPER FIXING PARTS <i>m m</i>	\$ 170.00	+
3	RADIATOR GRILLE <i>Cracked</i>	\$ 1,301.00	✓ 1040.80
4	RADIATOR GRILLE CLOSING ELEMENT <i>Painted.</i>	\$ 174.00	? 138.80
5	AIR CONDITIONER STICKER <i>new</i>	\$ 7.00	✓ 5.12
6	SIGN "CAUTION" <i>m</i>	\$ 13.00	✓ 9.76
7	FRONT BUMPER GUIDE SECTION-LH	\$ 35.00	x
8	FRONT BUMPER GUIDE SECTION-RH	\$ 35.00	x
9	FRONT BUMPER CLOSING ELEMENT-LH	\$ 270.00	x
10	FRONT BUMPER CLOSING ELEMENT-RH	\$ 270.00	+
11	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 171.00	+
12	FRONT BUMPER COVER <i>Cracked</i>	\$ 111.00	✓ 88.80
13	FOAM FILLER PIECE <i>new m</i>	\$ 172.00	? x
14	FRONT BUMPER SIDE REINFORCMENT <i>new</i>	\$ 660.00	? x
15	FRONT FENDER-LH <i>Repair</i>	\$ 778.00	+
16	FRONT FENDER UPPER BRACKET-LH	\$ 25.00	+
17	FRONT FENDER BRACKET-LH	\$ 43.00	+
18	FRONT FENDER CLOSING ELEMENT-LH	\$ 56.00	+
19	FRONT FENDER BRACE-LH	\$ 88.00	+
20	LED HEADLIGHT-LH <i>Cracked</i>	\$ 5,029.00	✓ 4033.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 11,106.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDJ 9318 A

S/N	Parts Description		Damaged Par S/Nett
21	BONNET <i>Dented</i>	\$	2,501.00 ✓ <i>3000.80</i>
22	BONNET ATTACHMENT PARTS <i>Not New</i>	\$	149.00 ? X
23	BONNET EDGE PROTECTION <i>in</i>	\$	25.00 ✓ <i>19.92</i>
24	BONNET CATCH HOOK <i>new</i>	\$	81.00 +
25	BONNET STRIKER-LH/RH <i>3 new</i>	2 \$	200.00 +
26	BONNET CATCH HOOK	\$	58.00 +
27	FRONT NO. PLATE <i>Best</i>	S/N \$	25.00 ✓ <i>25</i>
28	SUNDRIES <i>Not New</i>	\$	300.00 ? X
TOTAL SPARE PARTS CHARGES		:	\$ 14,445.00
TOTAL LABOUR CHARGES			\$ 5,452.00
GRAND TOTAL			\$ 19,897.00 <i>24,026</i>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

23978.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 13/02/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS Pays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SDJ 9318 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Regr cut</i>	\$ 1,698.00	✓
2	FRONT BUMPER FIXING PARTS <i>in n</i>	\$ 170.00	+
3	RADIATOR GRILLE <i>cracked</i>	\$ 1,301.00	✓
4	RADIATOR GRILLE CLOSING ELEMENT <i>? CRA</i>	\$ 174.00	?
5	AIR CONDITIONER STICKER <i>in</i>	\$ 7.00	✓
6	SIGN "CAUTION" <i>n</i>	\$ 13.00	✓
7	FRONT BUMPER GUIDE SECTION-LH	\$ 35.00	+
8	FRONT BUMPER GUIDE SECTION-RH	\$ 35.00	+
9	FRONT BUMPER CLOSING ELEMENT-LH	\$ 270.00	+
10	FRONT BUMPER CLOSING ELEMENT-RH	\$ 270.00	+
11	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 171.00	+
12	FRONT BUMPER COVER <i>cracked</i>	\$ 111.00	✓
13	FOAM FILLER PIECE	\$ 172.00	?
14	FRONT BUMPER SIDE REINFORCMENT <i>?</i>	\$ 660.00	?
15	FRONT FENDER-LH <i>Regr</i>	\$ 778.00	+
16	FRONT FENDER UPPER BRACKET-LH	\$ 25.00	+
17	FRONT FENDER BRACKET-LH	\$ 43.00	+
18	FRONT FENDER CLOSING ELEMENT-LH	\$ 56.00	+
19	FRONT FENDER BRACE-LH	\$ 88.00	+
20	LED HEADLIGHT-LH <i>Cracked</i>	\$ 5,029.00	✓
SUB-TOTAL SPARE PARTS CHARGES		\$ 11,106.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Rosal - 6/3/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dep
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0171/2019/CW
5-Mar-19
CHANG
1 of 1
SDJ 9318 A
Audi A3 SPORTBACK 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. S/N	\$ 960.00	1000
2	Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,400.00	750 1250 1500
Parts			
1	FRONT LOCK CARRIER	\$ 663.00	663.00 530.00
2	LOCK CARRIER AIR GUIDE - LH	\$ 22.00	22.00 12.00
3	COOLANT	\$ 84.00	84.00 X 11
GRAND TOTAL :		\$ 4,129.00	

Signature 5/5/19

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0171/2019/GW
Date : 9-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days of repairs - ok - JB - 23 Mar 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tai Hwei Yee
Address : 10G Braddell Hill
#19-27
Singapore 579726
Telephone : HP +65 81263277
Type of Claim : Own Damage Claims
Policy No. : 1800065855
Vehicle No : **SDJ 9318 A**
Model Code : Audi A3 1.0 Sportback
Model / Year : 7/6/2018
Engine No : CHZ 939680
Chassis No : WAUZZZ8V2JA112406
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Feb-19
Place of Accident : CNR Upper Serangoon & Braddell Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDJ 9318 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, lhs front fender, bonnet and headlight. Inspect front lock carrier for damage. Re-organise front crash management components. Reinstall all parts removed.	\$	2,700.00	\$ 1,250.00
3	To respray front bumper, lhs front fender and bonnet.	\$	2,200.00	\$ 1,650.00
4	<i>Added labour charges - see attached</i>	\$	3,400.00	\$ 2,500.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
5				
	TOTAL LABOUR CHARGES	: \$	8,852.00	\$ 5,952.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SDJ 9318 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,698.00	\$ 1,358.40
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
4	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	\$ 138.80
5	AIR CONDITIONER STICKER	\$ 7.00	\$ 5.12
6	SIGN "CAUTION"	\$ 13.00	\$ 9.76
7	FRONT BUMPER GUIDE SECTION-LH	\$ 35.00	
8	FRONT BUMPER GUIDE SECTION-RH	\$ 35.00	
9	FRONT BUMPER CLOSING ELEMENT-LH	\$ 270.00	
10	FRONT BUMPER CLOSING ELEMENT-RH	\$ 270.00	
11	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 171.00	
12	FRONT BUMPER COVER	\$ 111.00	\$ 88.80
13	FOAM FILLER PIECE	\$ 172.00	
14	FRONT BUMPER SIDE REINFORCMENT	\$ 660.00	
15	FRONT FENDER-LH	\$ 778.00	
16	FRONT FENDER UPPER BRACKET-LH	\$ 25.00	
17	FRONT FENDER BRACKET-LH	\$ 43.00	
18	FRONT FENDER CLOSING ELEMENT-LH	\$ 56.00	
19	FRONT FENDER BRACE-LH	\$ 88.00	
20	LED HEADLIGHT-LH	\$ 5,029.00	\$ 4,023.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 11,106.00	\$ 6,664.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SDJ 9318 A**

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remark</u>
		<i>c/f</i>		\$ 6,664.88
21	BONNET		\$ 2,501.00	\$ 2,000.80
22	BONNET ATTACHMENT PARTS		\$ 149.00	
23	BONNET EDGE PROTECTION		\$ 25.00	\$ 19.92
24	BONNET CATCH HOOK		\$ 81.00	
25	BONNET STRIKER-LH/RH	2	\$ 200.00	
26	BONNET CATCH HOOK		\$ 58.00	
27	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
28	<i>Added parts - see attached</i>		\$ 769.00	\$ 547.52
29	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS CHARGES :			\$ 15,214.00	\$ 9,258.12
TOTAL LABOUR CHARGES			\$ 8,852.00	\$ 5,952.00
GRAND TOTAL			\$ 24,066.00	\$ 15,210.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0171/2019/GW
5-Mar-19
CHANG
1 of 1
SDJ 9318 A
Audi A3 SPORTBACK 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. S/N	\$ 1,000.00	\$ 1,000.00 ✓
2	Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,400.00 \$ 3,400.00	\$ 1,500.00 ✓ \$ 2,500.00
Parts			
1	FRONT LOCK CARRIER <i>new</i>	\$ 663.00	\$ 530.40 ✓
2	LOCK CARRIER AIR GUIDE - LH <i>old</i>	\$ 22.00	\$ 17.12 ✓
3	COOLANT <i>new</i>	\$ 84.00	
	Materials	\$ 769.00	\$ 547.52
	Labour	\$ 3,400.00	\$ 2,500.00
	Total :	\$ 4,169.00	\$ 3,047.52

Adrian Ling

Authorised Signature



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 9 May 2019 5:07 PM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SDJ9318A - OD AIG - SURVEYED 13 FEB 19

Dear Mr Boo,

Confirm repair cost of \$15,210.12 before excess \$600 and GST @ 6 days of repairs

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, 23 March 2019 5:24 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SDJ9318A - OD AIG - SURVEYED 13 FEB 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$15,210.12 @ 6 days of repairs. Additional damages re-inspected by Taufikh on 5 Mar 19.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SDJ 9318 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0171/2019/MAS

23 May 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SDJ 9318 A, Audi A3 SB 1.0 TFSI

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SDG 9318 A**, claimant, **Mdm. Tai Hwee Yee**, please find the related document per attached.

1. A copy of the Original invoice no. 85013768 – S\$15,632.83
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SDJ 9318 A



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6888 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6888 2222
Telefax: 6475 1023

UBI Service Centre
55 Ubi Road 1
Singapore 408724
Telephone: 6888 2222

Customer Service
Service Appointment
Your Breakdown Service
Email: customers.care@premiumauto.com.sg

6366 2322
9628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 15:47

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013768 Date : 14/05/2019 Order : SDJ9318A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDJ9318A (V 38204)	Regn Date: 07/06/2018	Mileage: 6231	WIP No.: 41905
Model: A3 SPORTSBACK 1.0 TFSI 8V FANG	Chassis: WAUZZZ8V2JA112406	Engine: CHZ 939680	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND HEADLIGHT. INSPECT FRONT LOCK CARRIER FOR DAMAGE, REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119838
Main Telephone: 6346 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119838
Telephone: 6346 2221
Telefax: 6475 1331

Ubi Service Centre
55 Ubi Road 1
Singapore 408711
Telephone: 6888 2333

Customer Service
Service Appointment
Breakdown Service
Email: customer.care@premiumauto.com.sg

6346 2223
6428 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 15:47

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013768 Date : 14/05/2019 Order : SDJ9318A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SDJ9318A (V 38204)	Regn Date: 07/06/2018	Mileage: 6231	WIP No.: 41905
Model: A3 SPORTSBACK 1.0 TFSI 8VFANB	Chassis: WAUZZZ8V2JA112406	Engine: CHZ 939680	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1500.00	1.00	1,500.00
X	ABV3853651AA3FZ	GRILLE Less 020%	1.00	1301.00	1,040.80
X	ABV0941773D	(A)(SK)HEADLIGHT 18. Less 020%	1.00	5029.00	4,023.20
X	ABV0805588A	CARRIER Less 020%	1.00	663.00	530.40
X	ABV0807065R GRU	(A)(SK)COVER 18.02.2 Less 020%	1.00	1698.00	1,358.40
X	ABV0823029D	HOOD Less 020%	1.00	2501.00	2,000.80
X	ABV0823126B	EDGING Less 020%	1.00	24.90	19.92
X	ABV0807217A	COVER Less 020%	1.00	111.00	88.80
X	ABK0010520A	PLATE Less 020%	1.00	12.20	9.76
X	ABV0010515A	STICKER Less 020%	1.00	6.40	5.12
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
33 Ubi Road 1
Singapore 408722
Telephone: 6386 2223
Telefax: 6471 3733

Customer Service
Service Appointment
Your Breakdown Service
(Email)
customer.care@premiumaudi.com.sg

6386 2223
6471 3733

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 15:47

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013768
Date : 14/05/2019
Order : SDJ9318A
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SDJ9318A (V 38204) Regn Date: 07/06/2018 Mileage: 6231 WIP No.: 41905
Model: A3 SPORTSBACK 1.0 TFSI 8VFBNG Chassis: WAUZZZ8V2JA112406 Engine: CHZ 939680 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	ABV0121283K	AIR DUCT	1.00	21.40	17.12
X	ABV3853949	PLATE	1.00	173.50	138.80

Parts 9,233.12
Labour 0.00
Sublet 5,977.00
Menus 0.00
Lubricant 0.00

Sub-Total 14,610.12
7% GST 1,022.71
Grand Total 15,632.83

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Signature

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SDJ 9318 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0171/2019/NK
8 February 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A3 SPORTSBACK 1.0 TF
Vehicle Chassis No. : WAUZZZ8V2JA112406
Vehicle Regn No. : SDJ 9318 A
Vehicle Mileage : _____ KM
Vehicle Owner : Mdm Tan Hwei Yee 
Certificate No. : 1800065855
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 05 February 2019
Place : Upper Serangoon & Braddell Road
Repair Cost : \$ 15,632.83
WIP No. : 41905
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte L
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 11/3

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8945725D



Name

TAN SHU YING, VALERIE

陈淑莹

Race

CHINESE

Date of birth

18-12-1989

Sex

F

Country of birth

SINGAPORE

S8945725D

REPUBLIC OF SINGAPORE DRIVING LICENCE



TAN SHU YING, VALERIE

Issued: 18 Dec 2009

Valid until: 23 Dec 2018



0028842648



NRIC No. S8945725D



Date of issue

20-12-2004

BLK 106 BRADDELL HILL #19-27

SINGAPORE 578726

NRIC No. S8945725D

Date: 05-09-2005 No: 8200985

3651315

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 18 Dec 2009



Licence No: S8945725D

NP 428A

CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAI HWEI YEE
Period of Insurance : 07 Jun 2018 To 06 Jun 2020
Engine No. : CHZ 939680
Chassis No. : WAUZZZ8V2JA112406

Vehicle No. : SDJ9318A
Policy No. : 1800065855
Endorsement No. : 00000000227633
Issued Date : 13 Sep 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAI Hwei Yee - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 406699 85662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 8338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia).

504125223

PREMIUM LEASING - SH

81 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019		14 Feb 2019 11:31 Edit Adj Rpt	S\$15,210.12 Edit Estimates	S\$15,210.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAI HWEI YEE , ID: S1298589D, Tel: +6581263277									
Vehicle Reg. No.: SDJ9318A		Date of Loss: 05/02/2019 14:00 - :59 [7 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 3119083177SG		Policy/Cover Note No.: 1800065855 (Comprehensive)							
		Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/02/2019]									
Driver/Custodian: TAN SHU YING, VALERIE (29 / Female) , NRIC: S8945725D, Tel: +6596671489 Email: VALERIE_SY_TAN@PHARMACY.NHG.COM.SG									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (09/05/2019): Alert - Adj Mandate Approved (S\$15210.12) - SDJ9318A - Claim Handler: Dally Amri... - AIG_SG (08/04/2019): Alert - Adj Mandate Maintained - SDJ9318A - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (08/03/2019): Alert - Adj Mandate Maintained - SDJ9318A - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (15/02/2019): Alert - Adj Mandate Approved (S\$12464.00) - SDJ9318A - Claim Handler: Dally Amri... - AIG_SG (14/02/2019): SDJ9318A / OD / 05/02/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDJ9318A (3119083177SG)

OD

Feb 5 2019 2:00PM

[TAI HWEI YEE]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	14/02/19 11:58	Adjuster Immediate Advice												1	Load HTM					
2	07/03/19 17:42	Adjuster Immediate Advice												1	Load HTM					
															3 per page		☒			
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	14/02/19 11:47	General View												1	Load JPG	☒				
2	14/02/19 11:47	General View												1	Load JPG	☒				
3	14/02/19 11:47	General View												1	Load JPG	☒				
4	14/02/19 11:47	General View												1	Load JPG	☒				
5	14/02/19 11:47	General View												1	Load JPG	☒				
6	14/02/19 11:47	General View												1	Load JPG	☒				
7	14/02/19 11:47	General View												1	Load JPG	☒				
8	14/02/19 11:47	General View												1	Load JPG	☒				
9	14/02/19 11:47	General View												1	Load JPG	☒				
10	14/02/19 11:47	General View												1	Load JPG	☒				
11	14/02/19 11:47	General View												1	Load JPG	☒				
12	14/02/19 11:47	General View												1	Load JPG	☒				
13	14/02/19 11:47	General View												1	Load JPG	☒				
14	14/02/19 11:47	General View												1	Load JPG	☒				
15	14/02/19 11:47	General View												1	Load JPG	☒				
16	14/02/19 11:47	General View												1	Load JPG	☒				
17	14/02/19 11:47	General View												1	Load JPG	☒				
18	14/02/19 11:47	General View												1	Load JPG	☒				
19	14/02/19 11:47	General View												1	Load JPG	☒				
20	14/02/19 11:47	General View												1	Load JPG	☒				
21	14/02/19 11:47	General View												1	Load JPG	☒				
22	14/02/19 11:47	General View												1	Load JPG	☒				
23	14/02/19 11:47	General View												1	Load JPG	☒				
24	14/02/19 11:47	General View												1	Load JPG	☒				
25	14/02/19 11:47	General View												1	Load JPG	☒				
26	14/02/19 11:47	General View												1	Load JPG	☒				
27	14/02/19 11:47	General View												1	Load JPG	☒				
28	14/02/19 11:47	General View												1	Load JPG	☒				
29	14/02/19 11:47	General View												1	Load JPG	☒				
30	14/02/19 11:47	General View												1	Load JPG	☒				
31	07/03/19 17:24	Reinspection Photo												1	Load JPG	☒				
32	07/03/19 17:24	Reinspection Photo												1	Load JPG	☒				
33	07/03/19 17:24	Reinspection Photo												1	Load JPG	☒				
34	07/03/19 17:24	Reinspection Photo												1	Load JPG	☒				

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	07/03/19 17:24	Reinspection Photo	Load JPG	☒
36	07/03/19 17:24	Reinspection Photo	Load JPG	☒
37	07/03/19 17:24	Reinspection Photo	Load JPG	☒
38	07/03/19 17:24	Reinspection Photo	Load JPG	☒
39	07/03/19 17:25	Reinspection Photo	Load JPG	☒
40	07/03/19 17:25	Reinspection Photo	Load JPG	☒
41	07/03/19 17:25	Reinspection Photo	Load JPG	☒
42	07/03/19 17:25	Reinspection Photo	Load JPG	☒
43	07/03/19 17:25	Reinspection Photo	Load JPG	☒
44	07/03/19 17:25	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/19 11:52	Singapore Accident Statement	Load PDF	
2	14/02/19 11:52	Certificate of Insurance	Load PDF	
3	14/02/19 11:52	Driver's Driving License	Load PDF	
4	14/02/19 11:53	MARK ESTIMATE	Load PDF	
5	07/03/19 17:44	SURVEYOR'S MARKING	Load PDF	
6	07/03/19 17:44	SUPPLEMENTARY	Load PDF	
7	24/05/19 12:29	Workshop Invoice	Load PDF	
8	24/05/19 12:29	Discharge Voucher	Load PDF	
9	24/05/19 12:33	Supplementary	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/02/19 15:00	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/02/19 14:50	Accident Photo	Load JPG	☒
2	08/02/19 14:50	Accident Photo	Load JPG	☒
3	08/02/19 14:50	Accident Photo	Load JPG	☒
4	08/02/19 14:50	Accident Photo	Load JPG	☒
5	08/02/19 14:50	Accident Photo	Load JPG	☒
6	08/02/19 14:50	Accident Photo	Load JPG	☒
7	08/02/19 14:50	Accident Photo	Load JPG	☒
8	08/02/19 14:50	Accident Photo	Load JPG	☒
9	08/02/19 14:50	Accident Photo	Load JPG	☒
10	08/02/19 14:50	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/02/19 14:54	Sketch Plan	Load JPG	☒
2	08/02/19 14:54	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19002720/AVD3E2

Date: 24/05/2019

REFERENCE

Insured/Claimant: TAI HWEI YEE Policy No: 1800065855
Date of Loss: 05/02/2019 Nature of Claim: OD Claim No: 3119083177SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDJ9318A**
Make & Model: AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ939680
Reg. Date: 07/06/2018 (Mon, Year, 2018) Chassis No: WAUZZZ8V2JA112406
Colour: Blue Odometer: 5739 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,076.52	9,258.12	5,818.40	38.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,852.00	5,952.00	2,900.00	32.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,928.52	15,210.12	8,718.40	36.44
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	23,328.52	14,610.12	8,718.40	37.37
+ GST 7.00/7.00% (S\$)	1,633.00	1,022.71	610.29	37.37
Nett Amount (S\$)	24,961.52	15,632.83	9,328.69	37.37

INSPECTION

Date of Assignment: 14/02/2019
Date Inspected: 13/02/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,698.00 FS	*1,358.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
4	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	174.00 FS	*138.80 FS
5	1		*AIR CONDITIONER STICKER	Necessary	7.00 FS	*5.12 FS
6	1		*SIGN CAUTION	Necessary	13.00 FS	*9.76 FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	35.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	35.00 FS	*- FS
9	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	270.00 FS	*- FS
10	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	270.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	171.00 FS	*- FS
12	1		*FRONT BUMPER COVER	Cracked	111.00 FS	*88.80 FS
13	1		*FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
14	1		*FRONT FENDER - LH	Repair	778.00 FS	*- FS
15	1		*FRONT FENDER UPPER BRACKET - LH	Not Necessary	25.00 FS	*- FS
16	1		*FRONT FENDER BRACKET - LH	Not Necessary	43.00 FS	*- FS
17	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	56.00 FS	*- FS
18	1		*FRONT FENDER BRACE - LH	Not Necessary	88.00 FS	*- FS
19	1		*LED HEADLIGHT - LH	Cracked	5,029.00 FS	*4,023.20 FS
20	1		*BONNET	Dented	2,501.00 FS	*2,000.80 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
22	1		*BONNET EDGE PROTECTION	Necessary	25.00 FS	*19.92 FS
23	1		*BONNET CATCH HOOK	Not Necessary	81.00 FS	*- FS
24	2		*BONNET STRIKER - LH/RH	Not Necessary	200.00 FS	*- FS
25	1		*BONNET CATCH HOOK	Not Necessary	58.00 FS	*- FS
26	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
27	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
28	1		*FRONT LOCK CARRIER	Cracked	530.40 FS	*530.40 FS
29	1		*LOCK CARRIER AIR GUIDE - LH	Deformed	17.12 FS	*17.12 FS
30	1		*COOLANT	Not Necessary	84.00 FS	*- FS
31	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	860.00 FS	*- FS
Total Parts (S\$)					15,076.52	9,258.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND HEADLIGHT. INSPECT FRONT LOCK CARRIER FOR DAMAGE. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	1,250.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	2,200.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE AND TRANSFER AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,000.00	1,000.00
6	RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,500.00
Gross Labour Cost (S\$)			8,852.00	5,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >