



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)
CHUI XI TAO

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPV01016927	Date of Loss:	30/01/2019
Vehicle Reg. No.:	GBF7958K	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (Insured):	CHUI XI TAO		
Make/Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Vehicle Reg. Date:	19/08/2011
Vehicle Colour:	SILVER	Chassis No:	VSKYBAM20U0022729
Engine No:	K9KF276D123386		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	30.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	3,899.80
Miscellaneous Items	0.00
Labour	1,660.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,559.80
+ GST 7.00% (S\$)	389.19
Nett Amount (S\$)	5,948.99

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Feb 2019)
Parts: N/A NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Mova Automotive Pte Ltd/GBF7958K/13/02/2019 17:26
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*SEALANT	0	0.00	*80.00 FS	
2	1		*BACK DOOR LH	10.00	0.00	*1,481.00 FN	
3	1		*BACK DOOR LOGO	10.00	0.00	*69.00 FN	
4	1		*BACK DOOR EMBLEM - NV200	10.00	0.00	*97.00 FN	
5	1		*STICKER - 70KM/H	0	0.00	*20.00 FS	
6	1		*STICKER - 5 PAX	0	0.00	*20.00 FS	
7	1		*BACK DOOR LOCK LOWER LH	10.00	0.00	*135.00 FN	
8	1		*BACK DOOR RH	10.00	0.00	*990.00 FN	
9	1		*BACK DOOR LOCK LOWER RH	10.00	0.00	*135.00 FN	
10	1		*REAR BUMPER	10.00	0.00	*790.00 FN	
11	1		*REVERSE SENSOR	0	0.00	*250.00 FS	
12	1		*REAR BUMPER REFLECTOR LH	10.00	0.00	*55.00 FN	
13	1		*REAR BUMPER REFLECTOR RH	10.00	0.00	*55.00 FN	
14	1		*REAR WEATHERSTRIP	10.00	0.00	*115.00 FN	
						Sub Total (\$\$)	4,292.00
						- Nett Item Discount on N Items (\$\$)	392.20
						Total Parts (\$\$)	3,899.80

F=Franchise part, S=SpcNett, N=NettItemDisc.

XNN
XR
NEC
XNN
BUC
XSVL
DD
XNN
?
?
XNN

Mova Automotive Pte Ltd/GBF7958K/13/02/2019 17:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO TRANSFER BACK DOOR WINDSCREEN INTO NEW DOOR LH & RH	New	200.00 60
2	TO KNOCK AND STRAIGHTEN ON END PANEL. TO REPLACE DAMAGED ITEMS. RE-ALIGN CONNECTION.	New	700.00 400
3	TO RUST PROOF ON REPAIRED AREAS	New	80.00 30
4	TO SPRAY PAINT ON REPAIRED AREAS	New	600.00 500
5	TO REINSTALL REVERSE SENSOR & DIAGNOSE FUNCTION	New	80.00 40
Gross Labour Cost (S\$)			1,660.00

Mova Automotive Pte Ltd/GBF7958K/13/02/2019 17:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >