

ASS. REC. BY:

REF: CS/SMO19002758/Avd3n2 Special Instruction:

Surveyor:

merimen

ASSIGNMENT (Office)

From (Person): Thelma Choo of SMO Date/Time: 14/12/19 @ 8:58am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 6309D Insured: PC4201E

at Workshop m/s SM Automotive Tel: 67479241

of 756 Juncy weef st 74 # 12.60

Policy No: D18M1SCBU000583 Claim No: CM1D1900850

Sum Insured: Excess:

Make of Vch: D.O.A. 12/2/2019
(Client's Record)CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement

Date/Time: 10:27am @ 14/12/19 Person Contacted: Sukyi Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 6309D - NA/MSG19002616/13 D.O.A. 12/2/19
	PC4201E - NA/MSG19002616/13 D.O.A. 12/2/19
18/2/19	Informed Thelma pending workshop est via merimen
15/3/19	Adrian lump sum 8000 (Red: 16535.80! 67%)

RCE SMO

CONSENT

Form Date 15/2/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SKZ 6309D

At Work-shop no:

SM Automotive

of

1 Kaki Bkt Ave 6 # 01-43

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Secn:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

TP Sampr.

MV: 60.5K
PV: 52.3K
Nett: 8.2K.

RECEIVED 18 MAR 2019

Veh No: SKZ6309D. In Poss: 2016 Jan.

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Volkswagen Jetta.

c.e. 1390

Colour:

White.

AC:

Insured / Std / NI / NA

Sp Reading:

67858.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVW 2221626M00 9051

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16.

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

15/02/19.

Survey held at

SM.

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to:

18/3 Typist

Date/Time: File Return to:



Preli. Report



Final Report

Days Of Repair:

6

Resurvey No. of Trip:

Add Fee:



Site Insp. (\$)



Interview (\$)



Tech. Trng (\$)



Weekend (\$)

Survey Fee:

Transportation

1. 500.00

2. 100.00

3. 100.00

4. 100.00

TOTAL

450
10

460

Report Format:

Lump Sum / L.B.E.C

TP

8000/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2019		14 Feb 2019 08:58 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SEVILAI TRANSPORT PTE. LTD., Co. Reg. No.: 201003530D		
Main Claimant:	CHOO SWEE SOON		
Vehicle Reg. No.:	SKZ6309D	Date of Loss:	12/02/2019 18:00 - :59
Claim Type:	TP / CMTD1900850	Policy/Cover Note No.:	D18MTSCBU000583 (Comprehensive)
Vehicle Reg. No. (Insured):	PC4201E	Policy No. (Claimant):	
		Excess:	
Repairer:	SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60, 640756 Kaki Bukit - Tel: 67479241		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/02/2019]		
Adj Asg. Remarks:	PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SKZ6309D (CMTD1900850)
[PC4201E]**

TP
CHOO SWEE SOON
Feb 12 2019 6:00PM
[SEVILAI TRANSPORT PTE. LTD.]
SM Automotive

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/02/2019 17:37 PM.
To ThelmaChoo
Subject TP SURVEY SKZ 6309D

Dear Thelma,

Please be informed that we have inspected the vehicle SKZ 6309D on 15/2/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.



☐ Volkswagen Jetta GP 1.4A TSI \$52,800 \$7,720 /yr 24-Jun-2015 1,390 cc 29,000 km Sedan Available

1 Owner Only With Low Mileage Done At 29000KM. Flexible Loan Package And Low Insurance Payment.

Ka-Hup Vehicles Trading



Posted: 26-Jan-2019

Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen Jetta, jetta, Used Volkswagen

PREMIUM AD



☐ Volkswagen Jetta GP 1.4A TSI \$64,800 \$9,430 /yr 30-Jun-2015 1,390 cc 56,000 km Sedan Available

Highline
4 Free Agent Service With 4 Years Of Free Roadside Assistance 1 Owner White Jetta With Nice 3 Digit Number And New Road Tax. Showroom Condition, Low Mileage And Well Maintained. View To Believe And Ma...



Posted: 01-Feb-2019

Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen Jetta, jetta, Used Volkswagen

DIRECT OWNER



☐ Volkswagen Jetta GP 1.4A TSI \$57,900 \$7,620 /yr 31-Jul-2015 1,390 cc 50,000 km Sedan Available

1 Owner Only! High ARFI High ParFI Low Depre! 100% Low Genuine KM Done! Full VW Agent Service Records To Prove Till Current! New Tyres! Upgraded Touchscreen Andriod Play KitKat Processor Audio System,...



Posted: 20-Jan-2019

Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen Jetta, jetta, Used Volkswagen



Free Valuation by sgCarMart Quotz

Trading-in your Car? Make a better informed decision by getting your Car accurately valued with Quotz, based on SG's largest car database, sgCarMart. Get notified via Phone, SMS, Email. Sell your Car for more - Get your Free Valuation Today.

Find out more!



☐ Volkswagen Jetta GP 1.4A TSI \$61,800 \$8,010 /yr 21-Aug-2015 1,390 cc 38,000 km Sedan Available

Free Service! Lowest Interest Rate In Town! Genuine Mileage! Call Our Friendly Sales Adviser For A Non Obligation Chat.

ABWIN Bus Pte Ltd



Posted: 14-Feb-2019

Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen Jetta, jetta, Used Volkswagen

PREMIUM AD



☐ Volkswagen Jetta GP 1.4A TSI \$88,800 \$11,870 /yr 19-Oct-2015 1,390 cc 70,000 km Sedan Available

From 1.98%. Maintained By Volkswagen. 100% Genuine Mileage. Well Maintained.

Privilege Motors Pte Ltd



Posted: 27-Jan-2019

Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen Jetta, jetta, Used Volkswagen



☐ Volkswagen Jetta GP 1.4A TSI \$59,500 \$7,440 /yr 23-Oct-2015 1,390 cc 32,339 km Sedan Available

1 Owner Only, Low Mileage Done, Like New And Asking Cheap, Call Now For More Information, Loan Trade In And Scrap Services Available, You May View, Test Drive By Today, Call Now.



Posted: 14-Feb-2019

Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen Jetta, jetta, Used Volkswagen



☐ Volkswagen Jetta GP 1.4A TSI \$59,800 \$7,620 /yr 29-Oct-2015 1,390 cc 48,800 km Sedan Available

Selling At Scrap Value! Highest COE Value In The Market! 1 Owner Only! Full Agent Servicing History! High Loan Available. Extremely Well Maintained In It's Original Condition. Very Good Deal Not To Be...

Car (S) Pte Ltd



Posted: 13-Feb-2019

Tags: 2015 Volkswagen Jetta, 2015 volkswagen jetta, Volkswagen Jetta, volkswagen jetta, Volkswagen Jetta, jetta, Used Volkswagen

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Jetta, Jetta Singapore, used Jetta Singapore, used Jetta, used vehicles Singapore or even buy used Jetta Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 67961

Vehicle Details

Vehicle No.: SKZ6309D
Vehicle to be Exported: No
Intended Deregistration Date: 13 Feb 2019
Vehicle Make: VOLKSWAGEN
Vehicle Model: JETTA GP 1.4 TSI 90 A/T HL
HID 1634G5

Primary Colour: White
Manufacturing Year: 2015
Engine No.: CAXF82966
Chassis No.: WVVZZZ16ZGM009051
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$21,584.00
Original Registration Date: 28 Jan 2016
First Registration Date: 28 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$22,218.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Jan 2026
PARF Rebate Amount: \$16,663.00

Intended COE Rebate Details

COE Expiry Date: 27 Jan 2026
COE Category: A - Car up to 1600cc & 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$51,301.00
COE Rebate Amount: \$35,676.00
Total Rebate Amount: \$52,339.00

The information contained herein is correct as at 13 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2019 13:14
Date Of Accident	12/02/2019 18:20
Exact Location Of Accident	JALAN BUROH ROUND ABOUT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ6309D
Insured/Policyholder	
Name Of Registered Owner	CHOO SWEE SOON
NRIC No	S1296796I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90113726
Alternative Phone No	OTHERS-90113726

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28680082 AVW
Cover Note Number	

Driver

Name of Driver	CHOO SWEE SOON
NRIC No	S1296796I
Date Of Birth	23/09/1958
Occupation	INDOOR
Date Of Driving Pass	24/11/1983
Driving Experience	35 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90113726
Fax Number	
Contact Number	OTHERS-90113726
Email Address	NOEMAIL

Address	224 WESTWOOD AVENUE #10-15
Postcode	648356
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4201E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG JALAN PER CAKIS (ROUND ABOUT) ON THE RIGHT LANE OF 2 LANE, AS I WAS TRAVELLING AT THE ROUND ABOUT, I NOTICED ONE UNKNOWN M/LORRY SIGNO RIGHT AND WANTED TO SWITCH LANE, WHEN NOTICED THAT MOTOR LORRY WANTED TO CHANGE LANE, I SLOWED DOWN MY VEHICLE AND WANTED TO GIVE WAY TO THE SAID LORRY, I SLOWED DOWN MY VEHICLE TO STOP WHEN SUDDENLY ONE M/BUS PC 4201E CAME FROM MY REAR AND COLLIDED TO THE REAR PORTION OF MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

13/02/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

13/02/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Sampo
Veron

WVWZZZ16ZGM009051

Accident date: 12/02/2019

Estimated repair cost for vehicle no: SKZ6309D VOLKSWAGEN JETTA GP 1.4 A '16

CHASSIS: WVWZZZ16ZGM009051

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,875.45 → 1450
2	2	Rear Boot Lid Hinge <i>2 new</i>	\$126.85	\$253.70 +
3	2	Rear Boot Lid Shock Absorber	\$136.60	\$273.20 +
4	1	Rear Boot Lid Emblem Logo		\$115.75 ✓
5	1	Rear Boot Lid Jetta Logo <i>2 new</i>		\$82.10 ✓
6	1	Rear Boot Lid Tsi Logo		\$61.85 ✓
7	2	Rear Boot Lid Side Reflector <i>cut</i>	\$280.15	\$560.30 ✓
8	1	Rear Boot Lid Number Plate <i>no new</i>		\$50.00 +
9	2	Rear Boot Lid Number Plate Lamp <i>no new</i>	\$82.90	\$165.80 +
10	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$181.05 ✓
11	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$323.85 ✓
12	1	Rear Boot Lid Inner Trim Board <i>cracked</i>		\$220.75 ✓
13	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 ✓
14	2	Rear Tail Lamp <i>cracked</i>	\$410.80	\$821.60 ✓
15	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
16	2	Rear Tail Lamp Panel <i>Repair</i>	\$157.95	\$315.90 +
17	1	Rear Bumper <i>Deformed</i>		\$1,366.35 ✓
18	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
19	2	Rear Bumper Side Retainer <i>new</i>	\$110.40	\$220.80 ✓
20	2	Rear Bumper Side Reflector <i>new</i>	\$66.55	\$133.10 +
21	1	Rear Bumper Lower Lid <i>cracked</i>		\$656.75 ✓
22	1	Rear Bumper Reinforcement <i>Best</i>		\$606.05 ✓
23	1	Rear Bumper Top Beam <i>cracked</i>		\$102.15 ✓
24	4	Rear Bumper Reverse Sensor <i>2 pieces damaged</i>	\$208.85	\$835.40 410.
25	2	Rear Fender <i>Repair</i>	\$1,758.05	\$3,516.10 +
26	2	Rear Fender Inner Trim Board <i>2 new</i>	\$296.65	\$593.30 +
27	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00 +
28	1	Rear End Panel <i>Dented</i>		<u>\$1,266.00</u> 962

29	1	Rear End Panel Top Garnish <i>cracked</i>		\$145.75 ✓
30	1	Rear Spare Tyre Panel <i>2 qts</i>		\$1,101.25 ✗
31	1	Rear Spare Tyre Panel Top Cover <i>2 qts</i>		\$339.15 ✓
32	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00 ✗
33	2	Rear Exhaust		\$1,027.65 \$2,055.30 ✗
34	2	Rear Exhaust Mounting		\$84.00 \$168.00 ✗
35	1	Rear Exhaust Aluminium Cover		\$191.05 ✗
36	1	Rear Centre Exhaust		\$970.00 ✗
37	1	Rear Windscreen Moulding		\$105.00 ✗

8758.25

Subtotal :- \$20,375.80

8320.33

Labour charges

To remove & refit cushion & trim board	\$280.00 <i>60</i>
To remove & refit reverse sensor	\$180.00 <i>60</i>
To remove & refit rear & center exhaust	\$380.00 ✗
To remove & refit rear windscreen	\$120.00 ✗
Gum <i>m</i>	\$50.00 ✗
To check wiring	\$100.00 <i>30</i>
Towing fee	\$100.00 ✗
Tuff kote	\$150.00 <i>50</i>
Panel beating	\$1,400.00 <i>800</i>
Spray painting	\$1,400.00 <i>800</i>

1800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$4,160.00

Total:- \$24,535.80

Adrian Lj *total 10120.33*
f/s 15/02/19. h/s 8K
06 hrs. *8K*

Nett Value: 8K.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002758/AVD3N2

Date: 19/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000583
Claimant Vehicle No :	SKZ6309D	Insured Vehicle No :	PC4201E
Date of Loss:	12/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900850

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ6309D		
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 HL HID 1634G5 (A)	Engine No:	CAXF82966
Reg. Date:	28/01/2016 (Man. Year: 2015)	Chassis No:	WWWZZZ16ZGM009051
Colour:	White	Odometer:	67858 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	20,425.80	8,303.24	12,122.56	59.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	1,800.00	2,310.00	56.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,535.80	10,103.24	14,432.56	58.82
Approved Total (Overridden) (\$\$)		8,000.00		
Nett Amount (\$\$)	24,535.80	8,000.00	16,535.80	67.39

INSPECTION

Date of Assignment:	14/02/2019		
Date Inspected:	15/02/2019	Inspected At:	1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883 REPAIRER :SM Automotive (HQ)
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2019)
Parts:	143	VOLKSWAGEN JETTA GP 1.4 TSI 90 HL HID 1634G5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ6309D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,875.45 F	*1,450.00 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	253.70 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	273.20 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	115.75 F	*115.75 FL
5	1		*REAR BOOT LID JETTA LOGO	Necessary	82.10 F	*82.10 FL
6	1		*REAR BOOT LID TSI LOGO	Necessary	61.85 F	*61.85 FL
7	2		*REAR BOOT LID SIDE REFLECTOR	Cut	560.30 F	*560.30 FL
8	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	165.80 F	*- FL
10	1		*REAR BOOT LID INNER LOCK	Damaged	181.05 F	*181.05 FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	323.85 F	*323.85 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	220.75 F	*220.75 FL
13	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	52.00 F	*52.00 FL
14	2		*REAR TAIL LAMP	Cracked	821.60 F	*821.60 FL
15	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
16	2		*REAR TAIL LAMP PANEL	Repair	315.90 F	*- FL
17	1		*REAR BUMPER	Deformed	1,366.35 F	*1,366.35 FL
18	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	220.80 F	*220.80 FL
20	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	133.10 F	*- FL
21	1		*REAR BUMPER LOWER LID	Cracked	656.75 F	*656.75 FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	606.05 F	*606.05 FL
23	1		*REAR BUMPER TOP BEAM	Cracked	102.15 F	*102.15 FL
24	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Damaged (2 Pcs only)	835.40 F	*410.00 FL
25	2		*REAR FENDER	Repair	3,516.10 F	*- FL
26	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	593.30 F	*- FL
27	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
28	1		*REAR END PANEL	Dented	1,266.00 F	*962.00 FL
29	1		*REAR END PANEL TOP GARNISH	Cracked	145.75 F	*145.75 FL
30	1		*REAR SPARE TYRE PANEL	Repair	1,101.25 F	*- FL
31	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	339.15 F	*339.15 FL
32	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
33	2		*REAR EXHAUST	Not Necessary	2,055.30 F	*- FL
34	2		*REAR EXHAUST MOUNTING	Not Necessary	168.00 F	*- FL
35	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	191.05 F	*- FL
36	1		*REAR CENTRE EXHAUST	Not Necessary	970.00 F	*- FL
37	1		*REAR WINDSCREEN MOULDING	Not Necessary	105.00 F	*- FL
38	1		*GUM	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,425.80 8,740.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			- List Item Discount on L Items 0.00/5.00% (S\$)		0.00	437.01
			Total Parts (S\$)		20,425.80	8,303.24
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	180.00	60.00
3	TO REMOVE & REFIT REAR & CENTER EXHAUST	New	380.00	0.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
5	TO CHECK WIRING	New	100.00	30.00
6	TOWING FEE	New	100.00	0.00
7	TUFF KOTE	New	150.00	50.00
8	PANEL BEATING	New	1,400.00	800.00
9	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (\$\$)			4,110.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >