

REP es/FCI/9002763/UTd3/02

Surveyor

ASSIGNMENT (Office)

CWS

From (Person)

Joanne Yang

of

FCI

Date/Time

11:39 am 14/12/19

Estimated Cost

Bill to

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLN1281H

Insured

SHC8917S

at Workshop m/s

Kah Motor

Tel

81006306

of

15 ubi Road 4

Policy No.

Claim No.

D19001067MFST

Sum Insured

Excess

Make of Veh

D.O.A

11/02/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement

Date/Time

12:54pm 8/12/19

Person Contacted

Any

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLN1281H-X

SHC8917S-CS/MSG15060429/H/v/b/c3

Don: 6/1/15

7/3/19 @ 2:40pm - renews preli advice via email.

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLN1281H*at Workshop m/s *Deh motor*

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *736*

IBAC Accident Report Consistent? : Yes or No

GIA / PR Seen. Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

*LTA 56903*Veh No: *SLN1281H* Yr Regn: *4,17*Type: *M* Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *blonde mobilio* c.c. *1497*Colour: *white* A/C: Insured / Std / NI / NASp. Reading: *26509* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *M R H DD 48706 P 000 458*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *185/65R15*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front


Rear

R/Bal. *7* mm R/Bal. *7* mmL/Bal. *7* mm L/Bal. *7* mmD.O.A. *11/4/19* D.O.I. *4/3/19*

Survey held at

Des. of Damages: *Rear* / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 13 MAR 2019

Date/Time, File Pass to?

1) *11/3 Typist*

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report
Days Of Repair: *4*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: *TP*Lump Sum / I.B.I. (\$ *4994.27*)

170
50
50
50
320

MOTOR SURVEY ASSIGNMENT

Date	13-02-2019	Our Ref No. D19001067MFSH
Accident Date	11-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8917S	Third Party Vehicle. SLN1281H
Survey Location	15 UBI ROAD 4	
Contact Person.	ARY CHUA WAI NGEE	
Contact No.	81006306/ 81006306	Fax No. 67480770
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 7 March 2019 2:40 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001067MFSH/1
Attachments: PRELI ADVISED SLN 1281H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLN 1281H**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 14 February 2019 12:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001067MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 14 February 2019 11:38 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2017 Toyota Wish 1.8 with very low mileage of 13K.



As good as new. Borneo Motor warranty. High trade in. Price Neg! Call us now. Speedo Motoring StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

Honda Mobilio

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Mobilio		Any	Any	2017	Any	Any	Any	Available
	Honda	Honda Mobilio 1.5A RS i-VTEC Luxe	\$75,800	\$8,300 /yr	24-Feb-2017	1,497 cc	38,214 km	MPV	Available
Very Stylish And Rare Honda Mobilio. Spacious Rear Space And Accident Free! 1 Owner Only! Accident-Free! Call Now For Enquiry! Buy With A Peace Of Mind! Full/High Loan Available. Mayfair Motoring Posted: 25-Feb-2019 Tags: 2017 Honda Mobilio, 2017 honda mobilio, Honda Mobilio, honda mobilio, Honda, Mobilio, mobilio, Used Honda									
	Honda	Honda Mobilio 1.5A RS i-VTEC Luxe	\$76,800	\$8,550 /yr	13-Jan-2017	1,497 cc	57,968 km	MPV	Available
1 Owner, Full Agent Maintain, 5 Years Warranty By Kah Motor, View To Believe, Drive With Peace Of Mind! High Trade In And Flexible High Loan Available, Please Call/SMS Our Sales Consultant For Viewing... Accendore Autolution Pte Ltd Posted: 22-Feb-2019 Tags: 2017 Honda Mobilio, 2017 honda mobilio, Honda Mobilio, honda mobilio, Honda, Mobilio, mobilio, Used Honda									
	Honda	Honda Mobilio 1.5A RS i-VTEC Luxe	\$74,666	\$8,160 /yr	23-Feb-2017	1,497 cc	26,000 km	MPV	Available
Owned This Car With 95% Loan Stated. Monthly At \$1,288. 5 Years Warranty From Date Of First Registration, Free Servicing Till 60000Km Mileage, Spacious And Fuel Efficient MPV, Excellent Condition Insl... Creative Auto Posted: 12-Feb-2019 Tags: 2017 Honda Mobilio, 2017 honda mobilio, Honda Mobilio, honda mobilio, Honda, Mobilio, mobilio, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Mobilio, Honda Mobilio Singapore, used Honda Mobilio Singapore, used Honda Mobilio, used vehicles Singapore or even buy used Honda Mobilio Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3387D

Vehicle Details

Vehicle No.: SLN1281H

Vehicle to be Exported: No

Intended Deregistration Date: 05 Mar 2019

Vehicle Make: HONDA

Vehicle Model: MOBILIO SV 1.5 CVT

Primary Colour: White

Manufacturing Year: 2016

Engine No.: L15Z12874853

Chassis No.: MRHDD4870GP000458

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$19,735.00

Original Registration Date: 24 Apr 2017

First Registration Date: 24 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$19,735.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Apr 2027

PARF Rebate Amount: \$14,801.00

Intended COE Rebate Details

COE Expiry Date: 23 Apr 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$51,765.00

COE Rebate Amount: \$42,102.00

Total Rebate Amount: \$56,903.00

The information contained herein is correct as at 04 Mar 2019

OK



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref.No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLN1281H
Chassis No : MRHDD4870GP000458
Model : MOBILIO YM 2016
Owner's Name : GOH ZHEN QUAN
Ins Policy No. : 17-MU004687-R00
Date of Accident : 11/2/2019

Document No. : SQT19000692 Page 1
Date : 12. Feb 2019
Customer No. : WZF002
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15Z12874853
Date | Time : 12. Feb 2019 6:59:22 PM
Surveyor Name : DID : +65 6846 5673
Survey Date : HP : +65 8100 6306
Authorisation Date : Email : anychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 721)						
	OWNER: GOH ZHEN QUAN						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 11/2/2019@19.00PM						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED						
	TP VEH: SHC8917S - HYUNDAI/I40/BLUE/TAXI						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
75725-TRD-T00	EMBLEMRR.I VTEC	1	12.20	25	9.15	0.64	9.79
75722-TE8-K00	EMBLEM SETRR.MOBILIO	1	18.80	25	14.10	0.99	15.09
75723-TE7-K90	EMBLEMRR.RS	1	17.80	25	13.35	0.93	14.28
33551-TE7-T01	LAMP UNITL.	1	205.70	25	154.27	10.80	165.07
34155-TE7-T11	LIGHT ASSY.L.LID	1	67.50	25	50.62	3.54	54.16
73225-TE7-K00	RUBBER AWINDSHIELD DAMPER	1	18.60	25	13.95	0.98	14.93
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
71501-TE7-K90ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
71593-TE7-K01	SPACERR.RR.BUMPER SIDE	1	28.50	25	21.37	1.50	22.87
71598-TE7-K01	SPACERL.RR.BUMPER SIDE	1	28.50	25	21.37	1.50	22.87
71502-TE7-K90	MOLDING,RR.BUMPER	1	112.40	25	84.30	5.90	90.20
90107-SMG-E02	BOLTTAILGATE LOCK	1	2.00	25	1.50	0.11	1.61
66100-TE7-K20ZZ	PANEL COMP,RR.SILL	1	314.70	25	236.02	16.52	252.54
74440-TE7-K01	WEATHERSTRIPTAILGATE	1	64.70	25	48.52	3.40	51.92
68100-TRD-K10ZZ	TAILGATE COMP	1	1125.00	25	843.75	59.06	902.81
Sum Item					1977.94	138.47	2,116.41

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SLN1281H
 Chassis No : MRHDD4870GP000458
 Model : MOBILIO YM 2016
 Owner's Name : GOH ZHEN QUAN
 Ins Policy No. : 17-MU004687-R00
 Date of Accident : 11/2/2019

Document No. : SQT19000692
 Date : 12. Feb 2019
 Customer No. : WZF002
 Svc Advisor : ARY CHUA WAI NGEE
 Engine No : L15Z12874853
 Date | Time : 12. Feb 2019 6:59:22 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	40.00	20	40.00	2.80	42.80
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	X	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	100	140.00	9.80	149.80
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	160.00	130	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	X	250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM (N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION (N)	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	11X	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00	380	550.00	38.50	588.50
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1800.00	900	1800.00	126.00	1926.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	2800.00	1120	2800.00	196.00	2996.00
Sum Labor					7440.00	520.80	7,960.80

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,417.94 659.27 10,077.21

Total (Inclusive of GST) 10,077.21

LIK Auto Consultancy notice notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/2/2019 7:34:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: ****3387D / GOH ZHEN QUAN
Chassis No: MRHDD4870GP000458
License No: SLN1281H
Mileage: 265110
Engine No: L15Z12874853

Document No: SVO19013718
Printed By: ARYCHUA
Order Date: 4. March 2019
Order Time: 6:59:22 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	
						Amount	GST
	SUPPLIMENTARY ITEM PARTS & LABOR						
75701-TE7-K00	EMBLEM H	1	18.40	25	13.80	0.97	14.77
	SUM PARTS:				13.80	0.97	14.77
	TOTAL SGD				13.80	0.97	14.77

Total Payable (SGD)

14.77

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: MRHDD4870GP000458
License No: SLN1281H
Mileage: 265110
Engine No: L15Z12874853

Document No: SVO19013718
Printed By: ARYCHUA
Order Date: 4. March 2019
Order Time: 6:59:22 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 72237)							
	OWNER: GOH ZHEN QUAN							
	OWNER INSURER: TOKIO MARINE INSURANCE LTD							
	ACC DATE: 11/2/2019@19.00PM							
	SURVEYED BY: MARCUS CHUA(LKK) 4/3/2019@10.10AM							
	REF NO: D19001067MFSH							
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED							
	TP VEH: SHC8917S - HYUNDAI/I40/BLUE/TAXI							
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20	
75725-TRD-T00	EMBLEMRR.I VTEC	1	12.20	25	9.15	0.64	9.79	
75722-TE8-K00	EMBLEM SETRR.MOBILIO	1	18.80	25	14.10	0.99	15.09	
75723-TE7-K90	EMBLEMRR.RS	1	17.80	25	13.35	0.93	14.28	
73225-TE7-K00	RUBBER A WINDSHIELD DAMPER	1	18.60	25	13.95	0.98	14.93	
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57	
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01	
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51	
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10	
71501-TE7-K90ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11	
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77	
71502-TE7-K90	MOLDING,RR.BUMPER	1	112.40	25	84.30	5.90	90.20	
68100-TRD-K10ZZ	TAILGATE COMP	1	1,125.00	25	843.75	59.06	902.81	
	SUM PARTS:				1,444.27	101.10	1,545.37	
BOSUN	0760	1	20.00		20.00	1.40	21.40	
	SUNDRIES							
BML02I	0760	1	100.00		100.00	7.00	107.00	
	INSPECT RR LIGHTING MECHANISMS.							
	PERFORM WATER							
	TEST.(N)							
BA02R	0760	1	130.00		130.00	9.10	139.10	
	REMOVE & INSTALL REVERSE							
	SENSORS-4 PCS (N)							
BG02D	0760	1	300.00		300.00	21.00	321.00	
	REMOVE & INSTALL RR. WINDSCREEN.							
	(N)							
BOMISC1	0760	1	300.00		300.00	21.00	321.00	
	RESET VEHICLE SMART KEY							
	ACCESS/ENTRY SYSTEM(N)							
BOMISC1	0760	1	300.00		300.00	21.00	321.00	
	REMOVE & INSTALL REVERSE CAMERA							
	& CALIBRATION(N)							
BKTG02R	0760	1	380.00		380.00	26.60	406.60	
	REMOVE & TRANSFER ITEMS TO NEW							
	TAILGATE. ADJUST &							
	ALIGN TAILGATE.(N)							
BP03R	EXT-YBH	1	900.00		900.00	63.00	963.00	
	SPRAY PAINTING ON REPAIRED OR							
	REPLACED AREAS.(3P)							
BKRP02S	0760	1	1,120.00		1,120.00	78.40	1,198.40	

W.D=4

**HONDA****SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: MRHDD4870GP000458
License No: SLN1281H
Mileage: 265110
Engine No: L15Z12874853

Document No: SVO19013718
Printed By: ARYCHUA
Order Date: 4. March 2019
Order Time: 6:59:22 PM
Service Advisor: ARY CHUA WAI NGEE

STRAIGHTEN ALIGN RR PANEL &
RENEW DAMAGE PARTS.

SUM LABOUR:	3,550.00	248.50	3,798.50
TOTAL SGD	4,994.27	349.60	5,343.87

Total Payable (SGD) **5,343.87**

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002763/Utd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8917S	Veh. Inspected	SLN 1281H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001067MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA MOBILIO (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHDD4870GP000458	Colour	WHITE	
Odometer	26509	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	7 mm	
L/H Front Tyre	185/65 R15	DUNLOP	7 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	7 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/02/2019	Inspection Date	04/03/2019	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 1281H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	EMBLEMRR.I VTEC (SN)	NECESSARY	9.15	9.15
1	EMBLEM SETRR MOBILIO (SN)	NECESSARY	14.10	14.10
1	EMBLEMRR.RS (SN)	NECESSARY	13.35	13.35
1	LAMP UNITL (SN)	NOT NECESSARY	154.27	-
1	LIGHT ASSY,L LID (SN)	NOT NECESSARY	50.62	-
1	RUBBER A WINDSHIELD DAMPER (SN)	NECESSARY	13.95	13.95
2	RUBBERRR QTR W/SHIELD (SN)	NECESSARY	14.55	14.55
4	FASTENER BW/SHIELD (SN)	NECESSARY	15.90	15.90
2	FASTENER B (SN)	NECESSARY	7.95	7.95
2	FASTENER AW/SHIELD (SN)	NECESSARY	5.70	5.70
1	FACERR BUMPER (SN)	DENTED / DEFORMED	347.77	347.77
8	CLIP BUMPER (SN)	NECESSARY	13.80	13.80
1	SPACERR RR BUMPER SIDE (SN)	NOT NECESSARY	21.37	-
1	SPACERL RR BUMPER SIDE (SN)	NOT NECESSARY	21.37	-
1	MOLDING,RR BUMPER (SN)	SCRATCHED	84.30	84.30
1	BOLTTAILGATE LOCK (SN)	NOT NECESSARY	1.50	-
1	PANEL COMP RR SILL (SN)	TO REPAIR SEE LABOUR	236.02	-
1	WEATHERSTRIP TAILGATE (SN)	NOT NECESSARY	48.52	-
1	TAILGATE COMP (SN)	DENTED / BENT	843.75	843.75
1	SUNDRIES (SN)	NECESSARY	40.00	20.00
1	BODY JOINT SEALANT (SN)	NOT NECESSARY	100.00	-
1	EMBLEM H (ADDITIONAL)(SN)	NOT NECESSARY	13.80	-
			2,131.74	1,464.27
LABOUR				
	BODY UNDERSIDE COATING.	NOT NECESSARY	100.00	-
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		140.00	100.00
	REMOVE & INSTALL REVERSE SENSOR-4 PCS.		160.00	130.00

Report Ref No. CS/FCI19002763/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL RR WINDSCREEN.		350.00	300.00
	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM.		350.00	300.00
	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION.		350.00	300.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.	NOT NECESSARY	450.00	-
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST.		550.00	380.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P).		1,800.00	900.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF PANEL COMP RR SILL.		2,800.00	1,120.00
			7,300.00	3,530.00
	GRAND TOTAL		9,431.74	4,994.27
RECOMMENDED COST OF REPAIRS				4,994.27

Report Ref No. CS/FCI19002763/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.