

Number

ANS REC IV

REP 03 / FC119002765 / R1 vd3n2

Special Instruction

Surveyor
CWS

~~Jayrich~~
Sithera

ASSIGNMENT (Office)

From (Person)

of

Rep

Date/Time

10:15am @ K1/2/19

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FZ1784G

Insured

SHC 7204Y

at Workshop n/s

Primerio Koenig

Tel:

81611427

of

20 Blk Batok Crescent # 01-19

Policy No:

Claim No:

D19001013MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

9/2/19

CA / REV / REP / REV 24 HRS

cup

H.O.D. Endorsement

Date/Time:

12:40pm @ K1/2/19

Person Contacted:

Raj

Vehicle

(IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SH FZ1784G - X
	SHC 7204Y - CS / MSG 18009400 / R1 vd3n2 DUA: 22/8/18
25/2/19	Email preli revised to FC1
26/3/19	LS \$ 1700 confirmed by email (Red 1763.80, 51/19) MV: \$ 5K (Est) LTA: \$ 568 NV: \$ 4432

John

REF:


5564A

COB XP124: 2020/mar

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **FZ 1784G**
 at Workshop no/s: **PRIMERO RACING**
 of: **20, bucket motor cassette**
 Insured: **FCU**
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **FZ 1784G** Yr Regn: **2005 APR**
 Type: M.Gar / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **HONDA WAVE 125R A** c.c: **125**
 Colour: **BLACK** A/C: Insured / Std / NI / NA
 Sp Reading: **58855** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **NF125MP0032556**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Modi: Nil / Rim / STD A/Rim or _____
 Tyre Size: F: **70/90-17**
 R: **80/90-17**



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: **SK**
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **MAXXIS**
 Front: _____ Rear: _____
 R/Bal. **3** mm R/Bal. **3** mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. **09/02/19** D.O.I. **15/02/19**
 Survey held at **PRIMERO RACING**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Body
 The U/C / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	Rasul, PLS check repair limit & see my remark.
	<i>[Signature]</i> 22/2

RECEIVED 26 MAR 2019

Date/Time, File Pass to? Preli. Report
 Final Report

Days Of Repair: **4**
 Resurvey No. of Trip: **1**

Date/Time, File Return to?
2) xob - typist

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Report Format: **CWS**
 Lump Sum / L.B.I: (\$) **1700p**

Survey Fee:	130
Transportation	50
) S+RS: SI	50
) Photos	44
) Other	
TOTAL	374



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001013MFSH

Our Ref: CS/FCI19002765/R1vd3

Date : 25/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FZ 1784G


We thank you for your instruction on 14/2/2019

Please be informed that we had conducted the inspection of the above mentioned 14/2/2019 at the premises of M/s PRIMERO RACING and have the following to report:-

Workshop Estimate Amount	: S\$3,463.80
Revised Estimate Amount	: S\$1,928.92
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	12-02-2019	Our Ref No. D19001013MFSH
Accident Date	09-02-2019	Claim Type. Third Party
Insured Vehicle	SHC7204Y	Third Party Vehicle. FZ1784G
Survey Location	20 BUKIT BATOK CRESCENT ENTERPRISE CENTRE #01-19	
Contact Person.	RAJ	
Contact No.	62623305/ 81611427	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIMERO RACING	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Tuesday, 26 March 2019 2:09 PM
To: Primero Racing Claims -
Cc: Veron Chen (LKKAUTO)
Subject: RE: FZ 1784G DOA : 09/02/19

Hi Raj,

As spoken, finalise amount of \$ 1,700 / 4 days lump sum is confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Primero Racing Claims - [mailto:primeroracingclaims@gmail.com]
Sent: Monday, 25 February, 2019 2:03 PM
To: Veron Chen (LKKAUTO)
Cc: Rasul (LKKAUTO); SUR
Subject: Re: FZ 1784G DOA : 09/02/19

I don't agree.


Please re look at the estimate as it is very low for us to do a claim.

Once again wishing you a fantastic day ahead.

For any other information, please do not hesitate to contact us further. We look forward to hearing from you soon.

Best Regards,

Raj Kumar | Director
Primero Racing
[+65 81611427](tel:+6581611427)



www.facebook.com/Primero
www.primororacing.com

Primero Racing Singapore

20 Bukit Batok Crescent
Enterprise Centre #01-19
Singapore 658080

Monday to Friday: 12PM to 10PM
Saturday: 10AM to 8PM

T:+65 62623305

Do follow our Facebook Page, www.facebook.com/Primero for constant updates on promotions and upcoming giveaways

The information contained in this email message is **CONFIDENTIAL** and may also be taken as **LEGALLY PRIVILEGED** and you are hereby notified that any use, review, dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please notify the sender immediately by email.

Primero Racing (including all of its subsidiaries, associates, affiliates and successors) does not hold itself out as a legal opinion and should not be relied upon as such. Any business, legal or tax consultancy provided is based on a non-prejudice basis. You may obtain your own independent legal and tax advice, if so required, or to assume, the risk of any action taken.

On Mon, Feb 25, 2019 at 8:57 AM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Raj,

WITHOUT PREJUDICE

Offer Lump Sum \$1500/- @ 4 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto)
Sent: Wednesday, 20 February 2019 9:02 AM
To: Primero Racing Claims - <primeroracingclaims@gmail.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FZ 1784G DOA : 09/02/19

Hi Raj,

I've checked the estimate and I realized that the estimate got no labour and spray paint

Kindly re-do the estimate and include the labour and spray paint

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 25 February 2019 9:04 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001013MFSH/1, FZ 1784G
Attachments: FZ 1784G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FZ 1784G
Date of survey: 15/2/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 February 2019 12:42 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001013MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 14 February 2019 10:15 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001013MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5564A
Vehicle Details	
Vehicle No.:	FZ1784G
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	WAVE 125R A
Primary Colour:	Yellow
Manufacturing Year:	2005
Engine No.:	NF125MPE0032556
Chassis No.:	NF125MP0032556
Maximum Power Output:	-
Open Market Value:	\$1,688.00
Original Registration Date:	29 Apr 2005
First Registration Date:	29 Apr 2005
Transfer Count:	6
Actual ARF Paid:	\$254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2020
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,427.00
COE Rebate Amount:	\$568.00
Total Rebate Amount:	\$568.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Feb 2019

OK



Primero Racing
 20 Bukit Batok Crescent
 #01-19, Enterprise Centre
 Singapore 658080
 Tel: 62623305 Mobile: 81611427

Survey Estimate
 Email: primeroracingclaims@gmail.com
 Surveyor: LKK AUTO CONSULTANTS PTE LTD

X

Name of Owner:
 Vehicle No.:
 Vehicle Make/Model/Year:
 Address of Owner:

MOHAMED RIFHAN (T0025564A)
 FZ1784G
 HONDA WAVE 125 R
 C/O 20 Bukit Batok Crescent, #01-19 Enterprise Centre
 S(658080)

S/N	Items/Services	Amount
1	Front Rim Repair	320
2	Front Tyre Shaft SCB	45
3	Front Tyre Bolt SCB	8
4	Fork Assembly SCB	250
5	Steering Stem X	220
6	Front License Plate PA	10
7	Front Fender BPO	55
8	IU Unit SCB	155.8
9	Left Side Cover BPO	85
10	Right Side Cover X	85
11	Handlebar PA	85
12	Balancer MIS	20
13	Left Mirror SCB	45
14	Front Panel Cover SCB	45
15	Speedometer Cover X	55
16	Speedometer Panel X	35
17	Front Kappa Rack SCB X	85
18	Panel Cover 1 SCB	65
19	Panel Cover 2 PA	60
20	Footrest Bracket BPO	95
21	Footpeg with Rubber CA	80
22	Pillion Bracket BPO	90
23	Pillion Footpeg MIS	40
24	Swingarm Repair	400
25	Seat CA	100
26	Rear Left Side Cover SCB	85
27	Pillion Handle SCB	80
28	Box SCB	120
29	Box Rack SCB	80
30	Rear License Plate X	15

Handwritten notes:
 22/2/19
 Resurvey
 Hp 90010068
 4 days
 4/5
 15/02/19 @ 1420
 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by Insurance Company

REMARKS:

Acknowledged by Repairer
 Signature:
 Date:

Sub Total: 2913.8
 Labour (5 Days): 350
 Total Cost of Repair: 3263.8

Handwritten note: too high



Primero Racing
 20 Bukit Batok Crescent
 #01-19, Enterprise Centre
 Singapore 658080
 Tel: 62623305 Mobile: 81611427

Survey Estimate
 Email: primoracingclaims@gmail.com
 Surveyor: LKK AUTO CONSULTANTS PTE LTD

Name of Owner:
 Vehicle No.:
 Vehicle Make/Model/Year:
 Address of Owner:

MOHAMED RIFHAN (T0025564A)
 FZ1784G
 HONDA WAVE 125 R
 C/O 20 Bukit Batok Crescent, #01-19 Enterprise Centre
 S(658080)

S/N	Items/Services	Amount
1	Front Rim repair ✓	320 X
2	Front Tyre Shaft sca ✓	45 ✓
3	Front Tyre Bolt sca ✓	8 ✓
4	Fork Assembly sca ✓	250 ✓
5	Steering Stem ? Rbt ✓	220 ✓
6	Front License Plate Rt ✓	10 ✓
7	Front Fender Bro ✓	55 ✓
8	IU Unit sca ✓	155.8 ✓
9	Left Side Cover Bro ✓	85 ✓
10	Right Side Cover X Svc ✓	85 X
11	Handlebar ? Rt ✓	85 ✓
12	Balancer M.S ✓	20 ✓
13	Left Mirror sca ✓	45 ✓
14	Front Panel Cover sca ✓	45 ✓
15	Speedometer Cover X ✓	55 X
16	Speedometer Panel X Svc ✓	35 X
17	Front Kappa Rack X ✓	85 X
18	Panel Cover 1 sca ✓	65 ✓
19	Panel Cover 2 DE ✓	60 ✓
20	Footrest Bracket Bro ✓	95 ✓
21	Footpeg with Rubber cut ✓	80 ✓
22	Pillion Bracket Bro ✓	90 ✓
23	Pillion Footpeg M.S ✓	40 ✓
24	Swingarm repair ✓	400 X
25	Seat cut ✓	100 ✓
26	Rear Left Side Cover sca ✓	85 ✓
27	Pillion Handle sca ✓	80 ✓
28	Box sca ✓	120 ✓
29	Box Rack sca ✓	80 ✓
30	Rear License Plate X M ✓	15 X
31	Labour (Spray)	200 150

1918.80
 10%
 1726.92

400

1726.92
 400.00
 2126.92
 20%
 1701.53
 45-1700

4 days

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

REMARKS:
 Acknowledged by Repairer
 Signature:
 Date:

Sub Total: 3113.8
 Labour (5 Days): 350 250
 Total Cost of Repair: 3463.8



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002765/R1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-04-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7204Y	Veh. Inspected	FZ 1784G
Policy No.		Coverage (\$)	0.00
Claim No.	D19001013MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	14/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA WAVE 125R A	c.c	125
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	NF125MP0032556	Colour	BLACK
Odometer	58855	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90-17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MAXXIS	3 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/02/2019	Inspection Date	15/02/2019
Survey held at	PRIMERO RACING 1 BUKIT BATOK CRESENT #04-34 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FZ 1784G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RIM	TO REPAIR SEE LABOUR	320.00	-
1	FRONT TYRE SHAFT	SCRATCHED	45.00	45.00
1	FRONT TYRE BOLT	SCRATCHED	8.00	8.00
1	FORK ASSEMBLY	SCRATCHED	250.00	250.00
1	STEERING STEM	BENT	220.00	220.00
1	FRONT LICENSE PLATE	BENT	10.00	10.00
1	FRONT FENDER	BROKEN	55.00	55.00
1	IU UNIT	SCRATCHED	155.80	155.80
1	LEFT SIDE COVER	BROKEN	85.00	85.00
1	RIGHT SIDE COVER	SERVICEABLE	85.00	-
1	HANDLEBAR	BENT	85.00	85.00
1	BALANCER	MISSING	20.00	20.00
1	LEFT MIRROR	SCRATCHED	45.00	45.00
1	FRONT PANEL COVER	SCRATCHED	45.00	45.00
1	SPEEDOMETER COVER	SERVICEABLE	55.00	-
1	SPEEDOMETER PANEL	SERVICEABLE	35.00	-
1	FRONT KAPPA RACK	SERVICEABLE	85.00	-
1	PANEL COVER 1	SCRATCHED	65.00	65.00
1	PANEL COVER 2	DEFORMED	60.00	60.00
1	FOOTREST BRACKET	BROKEN	95.00	95.00
1	FOOTPEG WITH RUBBER	CUT	80.00	80.00
1	PILLION BRACKET	BROKEN	90.00	90.00
1	PILLION FOOTPEG	MISSING	40.00	40.00
1	SWINGARM	TO REPAIR SEE LABOUR	400.00	-
1	SEAT	CUT	100.00	100.00
1	REAR LEFT SIDE COVER	SCRATCHED	85.00	85.00
1	PILLION HANDLE	SCRATCHED	80.00	80.00
1	BOX	SCRATCHED	120.00	120.00
1	BOX RACK	SCRATCHED	80.00	80.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LICENSE PLATE LESS 10% DISCOUNT	NOT NECESSARY	15.00	-
			-	-191.88
			2,913.80	1,726.92
	LABOUR			
	LABOUR (SPRAY).		200.00	150.00
	LABOUR INCLUSIVE OF THE REPAIR OF FRONT RIM AND SWINGARM.		350.00	250.00
			550.00	400.00
	GRAND TOTAL		3,463.80	2,126.92
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/FC119002765/R1vd3n2

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$568.00=NETT VALUE: \$4,432.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.