

000000

INS. CASE OWNER:

CC⁶ /AIG1900 2882, Ueb27

LKK:

IDAC:

Surveyor:

mhring

DOI:

ASSIGNMENT

4/2/19

Date / Time:

14/2/19

Registered in Meriten:

4/2/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMP 1A44P

Name of Insured:

ROSLAW BIN HUSSEIN

Insured Tel No.:

HP:

Claim No.:

47521503046

Policy No.:

1500172720

Make / Model:

MPV

Excess Sec II :SS

D.O.A:

12/2/19

Place of Accident:

57 UBI AVE1

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MUHAMMAD PREHAN BIN RIZWAN

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SEM 24753



INSRS:
WSP:
Tel:
Liability:
RMKS:

Hode
w/h



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SEM 24753 - 4 SMP 1A44P - X
15/2/19 CAUSED O/D (CONFERRED ACCIDENT). DID MAKE A STOP TURN INTO THE MAIN ROAD HTY TO REM. INCIDENT TP CLAIM ADDED TO SERVE TWO PAPERS FROM NED BURE.
EMAIL WSP LAMANN CLEAR.

28/11/19
Khandan

File pass to Shy Rei to close.

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	PHONE 8/2/19
After call Itr to OI:	
Documentation Check List: Handler Typist	
Notification Itr (if non-pickup)	☐
After call Itr to OI:	☒
Authorisation To Act:	☒
Release Voucher:	☒
Final Repair Bill:	☒
Car Rental Invoice:	☒
Towing Invoice:	☒
LTA / GIA:	☒
Medical Bill:	☐
PIR:	☐
Mandate/Reject Instruction:	☐
LOD:	☒
Payment Breakdown Form:	☐
Post-Repair Photos:	☐
Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	415	SS 2,500	(4 days) Reduction: 44 %	Email ☐ Call ☐
--------------	-----	----------	---------------------------	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
------------------	------------	---------------	---

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	9	If NO or B 28, Ass. Lia:
------------------	-------	-----------------------------------	---	--------------------------

Repair Cost:	(w/last)	SS 2,675.00	ON TUE 12/11/19 1400 MAIN ROAD HTY TP
--------------	----------	-------------	---------------------------------------

Loss of Rental (LOR):	SS	(- days)
-----------------------	----	-----------

Loss of Use (LOU):	SS	360 (S 60 x 6 days)
--------------------	----	---------------------

Loss of Income (LOI):	SS	(S x days)
-----------------------	----	------------

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐	[Tick only one]		
---	-----------------	--	--

GIA/LTA Search	SS	2.00
----------------	----	------

Medical:	SS	-
----------	----	---

Disbursement:	SS	-	(e.g. Tow/ Independent)
---------------	----	---	-------------------------

Legal Cost	SS	-
------------	----	---

Total:	SS	3,037	Global Sum SS:
--------	----	-------	----------------

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
---------------	------------	---------------	--

Payee 1:	SS	3,037	Name 1: HOCK WAH MOTOR WORKSHOP PTE LTD
Payee 2: (Strike if N.A.)	SS		Name 2:
Payee 3: (Strike if N.A.)	SS		Name 3:

HOCK WAH MOTOR WORKSHOP PTE LTD

101-102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

TO: 20081003013
FIRST HIAE (S) PTE LTD
NO 53 UBI AVENUE 1
05-12 PAYA UBI INDUSTRIAL PARK
SINGAPORE
TEL: 81390855 FAX:
PH:
ATTN:

ESTIMATE BILL

Number: EB00005054
Date: 13/02/2019
Case No: AD00010256
Vehicle No: SKM2475B
Chassis: MNTBBAB17Z000965
Year of Mfr: 2013
Policy No:
Model: NISSAN SYLPHY 1.6 CVT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT DOOR RH <i>3.550 839.50</i>	1.0	876.40	10	788.76
2	FRONT DOOR TOP STICKER RH <i>re</i>	1.0	27.30	10	24.57
3	FRONT DOOR INNER LOCK RH <i>re/shold</i>	1.0	231.10	10	207.99
4	FRONT DOOR PROTECTOR MOULDING RH <i>re</i>	1.0	191.80	10	172.62
5	REAR DOOR RH <i>2/2nd 689.50</i>	1.0	876.40	10	788.76
6	REAR DOOR TOP STICKER RH <i>re</i>	1.0	27.30	10	24.57
7	REAR DOOR HINGE TOP RH <i>re</i>	1.0	56.10	10	50.49
8	REAR DOOR HINGE BOTTOM RH <i>re</i>	1.0	56.10	10	50.49
9	FRONT DOOR INNER RUBBER RH <i>re</i>	1.0	85.30	10	76.72
10	FRONT DOOR HANDLER SENSOR LOCK <i>shutted.</i>	1.0	96.70	10	87.03
11	ROCKER PANEL REAR STICKER <i>re</i>	1.0	88.10	10	79.29
Nett Price - Parts Sub Total					2,351.34
12	REAR DOOR PILLAR CENTER PILLAR RH - REPAIR <i>re X</i>	1.0			
13	FRONT DOOR PILLAR CENTER PILLAR RH - REPAIR <i>re X</i>	1.0			
14	ROCKER PANEL RH - REPAIR <i>re X</i>	1.0			
15	REAR FENDER RH - REPAIR <i>re X</i>	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					2,351.34
16	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0 <i>re</i>	800.00
17	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0 <i>re</i>	900.00
18	ANTI-RUST COATING	1.0	250.00	0 <i>re</i>	250.00
Labour 1 Sub Total					1,950.00
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED TWO AND CENTS FORTY-THREE ONLY					0.00
Less Excess					
SUBTOTAL					4,301.34
GST 7.00%					301.09
TOTAL					4,602.43

Date of accident : 12/02/2019 05:20 PM. Place : EXIT OF 53 PAYA UBI INDUSTRIAL PARK

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 200810030D

FIRST HIACE (S) PTE LTD
NO 53 UBI AVENUE 1
05-12 PAYA UBI INDUSTRIAL PARK
SINGAPORE
TEL : 81390855 FAX :
PH :
ATTN :

ESTIMATE BILL

Number : EB00005088
Date : 19/02/2019
Case No : AD00010236
Vehicle No : SKM2475B
Chassis : MNTBBAB17Z0009634
Year of Mfr : 2013
Policy No
Model : NISSAN SYLPHY 1.6
CVT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR DOOR PROTECTOR MOULDING RH	1.0	172.40	10	155.16
	Nett Price - Parts Sub Total				155.16
	Parts Total				155.16
					7- 2449
					107
					2204.10
					144- 1380.00
					3584.10
					4/5 302
					2508.87
SINGAPORE DOLLARS : ONE HUNDRED SIXTY-SIX AND CENTS TWO ONLY			Less Excess		0.00
			SUBTOTAL		155.16
			GST 7.00%		10.86
			TOTAL		166.02

Date of accident : 12/02/2019 05:20 PM. Place : EXIT OF 53 PAYA UBI INDUSTRIAL PARK

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

0030D

Vehicle Details

Vehicle No:

SKM2475B

Vehicle First Exported:

No

Intended Registration Date:

15 Feb 2019

Vehicle Make:

NISSAN

Vehicle Model:

SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR

Primary Colour:

Red

Manufacturing Year:

2013

Engine No:

HR16993168A

Chassis No:

MNTBBAB17Z0009634

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$14,872.00

Original Registration Date:

12 Feb 2014

First Registration Date:

12 Feb 2014

Transfer Count:

1

Actual Cash Paid:

\$9,872.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Feb 2024

PARF Rebate Amount:

\$6,910.00

Intended COE Rebate Details

COE Expiry Date:

11 Feb 2024

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period (Years):

10

QP Price:

\$71,564.00

COE Rebate Amount:

\$35,719.00

Total Rebate Amount:

\$42,629.00

The information contained herein is correct as at 15 Feb 2019

OK

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4.
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

302

TO : 200810030D
FIRST HIACE (S) PTE LTD
NO 53 UBI AVENUE 1
05-12 PAYA UBI INDUSTRIAL PARK
SINGAPORE
TEL: 81390855 FAX:
PH:
ATTN:

ESTIMATE BILL

Number : EB00005084
Date : 13/02/2019
Case No : AD00010236
Vehicle No : SKM2475B
Chassis: MNTBBAB17Z0009634
Year of Mfr 2013
Policy No
Model : NISSAN SYLPHY 1.6
CVT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT DOOR RH	1.0	876.40	10	788.76
2	FRONT DOOR TOP STICKER RH	1.0	27.30	10	24.57
3	FRONT DOOR INNER LOCK RH	1.0	231.10	10	207.99
4	FRONT DOOR PROTECTOR MOULDING RH	1.0	191.80	10	172.62
5	REAR DOOR RH	1.0	876.40	10	788.76
6	REAR DOOR TOP STICKER RH	1.0	27.30	10	24.57
7	REAR DOOR HINGE TOP RH	1.0	56.10	10	50.49
8	REAR DOOR HINGE BOTTOM RH	1.0	56.10	10	50.49
9	FRONT DOOR INNER RUBBER RH	1.0	85.30	10	76.77
10	FRONT DOOR HANDLER SENSOR LOCK	1.0	96.70	10	87.03
11	ROCKER PANEL REAR STICKER	1.0	88.10	10	79.29
Nett Price - Parts Sub Total					2,351.34
12	REAR DOOR PILLAR CENTER PILLAR RH - REPAIR	1.0			
13	FRONT DOOR PILLAR CENTER PILLAR RH - REPAIR	1.0			
14	ROCKER PANEL RH - REPAIR	1.0			
15	REAR FENDER RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					2,351.34
16	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
17	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
18	ANTI-RUST COATING	1.0	250.00	0	250.00
Labour 1 Sub Total					1,950.00
SINGAPORE DOLLARS : FOUR THOUSAND SIX HUNDRED TWO AND CENTS FORTY-THREE ONLY					
Less Excess					0.00
SUBTOTAL					4,301.34
GST 7.00%					301.09
TOTAL					4,602.43

Date of accident : 12/02/2019 05:20 PM. Place : EXIT OF 53 PAYA UBI INDUSTRIAL PARK

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

Date:

AUTHORISED SIGNATURE

Khanchna (LKK Auto)

From: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>
Sent: Monday, 18 November 2019 3:55 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: TP CLAIM_ SKM2475B & SMF1994P _DOA:14/02/2019 ***LKK
REF:CC6/AIG19002782/Ueb3

Dear Khanchna

Refer to the loss of use matter.

Please re-consider the day of loss of use at 6 days as the above mention vehicle could not be driven after the accident and our client actually incurred more loses during this period. Due to your insured negligence, my client had suffered loss of income also. Thus, kindly consider at least \$360.00 for loss of use.

Thank you.

Best Regards

Anysia Foo

Senior Claims Advisor

Hock Wah Motor Workshop Pte Ltd

Blk 3011 Bedok North Avenue 4 | #01-2008/2010/2012/2014 | Singapore 489977

Tel: 6441 5655 | Fax: 6243 8121 | Website: www.hockwah.com.sg

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Tuesday, 12 November, 2019 10:04 AM
To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: TP CLAIM_ SKM2475B & SMF1994P _DOA:14/02/2019 ***LKK
REF:CC6/AIG19002782/Ueb3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

Please let us know the status of our offer dated 30/9/2019.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 30 September 2019 3:29 PM
To: Hock Wah Motor Pte Ltd
Cc: Admin A
Subject: RE: TP CLAIM_SKM2475B & SMF1994P_DOA:14/02/2019 ***LKK
REF:CC6/AIG19002782/Ueb3

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 2,675.00
2. Loss of Use (4 days x \$60.00)	\$ 240.00
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 2,917.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Sent: Monday, 30 September 2019 2:02 PM

To: Hock Wah Motor Pte Ltd <motor@hockwah.com.sg>; Khanchna (LKK Auto) <khanchna@lkkauto.com>

Subject: RE: TP CLAIM_SKM2475B & SMF1994P_DOA:14/02/2019 ***LKK

REF:CC6/AIG19002782/Ueb3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2019 Edit Reg		14 Feb 2019 00:00 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	ROSLAN BIN HUSSAIN, ID: S2071379H	
Main Claimant:	FIRST HIACE (S) PTE LTD, Co. Reg. No.: 200810030D	
Vehicle Reg. No.:	SKM2475B	Date of Loss: 12/02/2019 17:00 - :59 [60 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4352950803SG	Policy/Cover Note No.: 1800123930 (Comprehensive)
Vehicle Reg. No. (Insured):	SMF1994P	Policy No. (Claimant): 50096399777-01
	Excess:	
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 25/02/2019]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKM2475B (4352950803SG)
[SMF1994P]

TP

FIRST HIACE (S) PTE LTD

Feb 12 2019 5:00PM

[ROSLAN BIN HUSSAIN]

Hock Wah Motor Workshop Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print		
1	14/02/19 18:18	Chassis Number		Load JPG	☒	
2	14/02/19 18:19	Odometer Reading		Load JPG	☒	
3	14/02/19 18:19	General View		Load JPG	☒	
4	14/02/19 18:19	General View		Load JPG	☒	
5	14/02/19 18:19	General View		Load JPG	☒	
6	14/02/19 18:19	General View		Load JPG	☒	
7	14/02/19 18:19	General View		Load JPG	☒	
8	14/02/19 18:19	General View		Load JPG	☒	
9	14/02/19 18:19	General View		Load JPG	☒	
10	14/02/19 18:19	General View		Load JPG	☒	
11	14/02/19 18:19	General View		Load JPG	☒	
12	14/02/19 18:19	General View		Load JPG	☒	
13	14/02/19 18:19	General View		Load JPG	☒	
14	14/02/19 18:19	General View		Load JPG	☒	
15	14/02/19 18:19	General View		Load JPG	☒	
16	14/02/19 18:19	General View		Load JPG	☒	
17	14/02/19 18:19	General View		Load JPG	☒	
18	14/02/19 18:19	General View		Load JPG	☒	
19	14/02/19 18:19	General View		Load JPG	☒	
20	14/02/19 18:19	General View		Load JPG	☒	
21	14/02/19 18:19	General View		Load JPG	☒	
22	14/02/19 18:19	General View		Load JPG	☒	
23	14/02/19 18:19	General View		Load JPG	☒	
24	14/02/19 18:19	General View		Load JPG	☒	
25	14/02/19 18:19	General View		Load JPG	☒	
26	14/02/19 18:19	General View		Load JPG	☒	
27	14/02/19 18:19	General View		Load JPG	☒	
28	14/02/19 18:19	General View		Load JPG	☒	
29	14/02/19 18:19	General View		Load JPG	☒	
30	14/02/19 18:19	General View		Load JPG	☒	
31	14/02/19 18:19	General View		Load JPG	☒	
32	14/02/19 18:19	General View		Load JPG	☒	
33	14/02/19 18:19	General View		Load JPG	☒	
34	14/02/19 18:19	General View		Load JPG	☒	
35	14/02/19 18:19	General View		Load JPG	☒	
36	14/02/19 18:19	General View		Load JPG	☒	
37	14/02/19 18:19	General View		Load JPG	☒	
38	14/02/19 18:19	General View		Load JPG	☒	
39	14/02/19 18:19	General View		Load JPG	☒	
40	14/02/19 18:19	General View		Load JPG	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	14/02/19 18:19	General View	 Load JPG	☒
42	14/02/19 18:19	General View	 Load JPG	☒
43	14/02/19 18:19	General View	 Load JPG	☒
44	14/02/19 18:19	General View	 Load JPG	☒
45	14/02/19 18:19	General View	 Load JPG	☒
46	14/02/19 18:19	General View	 Load JPG	☒
47	14/02/19 18:19	General View	 Load JPG	☒
48	14/02/19 18:19	General View	 Load JPG	☒
49	14/02/19 18:19	General View	 Load JPG	☒
50	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
51	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
52	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
53	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
54	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
55	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
56	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
57	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
58	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
59	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
60	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
61	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
62	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
63	19/02/19 18:12	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/19 15:48	TP ESTIMATE- MARKED	 Load PDF	
2	14/02/19 15:48	TP GIA REPORT	 Load PDF	
3	30/09/19 14:53	LETTER TO OI	 Load PDF	
4	10/12/19 09:21	WORKSHOP INVOICE	 Load PDF	
5	10/12/19 09:21	AUTHORISATION TO ACT FORM	 Load PDF	
6	10/12/19 09:21	Release Voucher	 Load PDF	
7	10/12/19 09:21	LOD	 Load PDF	
8	10/12/19 09:21	GIA SEARCH	 Load PDF	
No	Finalized On	ATG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/02/19 14:19	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMF1994P (Insd veh)	Model:	NISSAN SYLPHY 1.6 CVT
	SKM2475B (TP veh)		ABS D/AIRBAG 2WD 4DR
Date of Accident:	12/02/2019		(A)

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	4,768.46
Final Repair Cost	:	\$	2,675.00
Loss of Use	:	\$	360.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,037.00

6.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hock Wah Motor Workshop Pte Ltd	:	\$ 3,037.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19002782/UKB3Q2

Date: 10/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800123930
Claimant
Vehicle No : SKM2475B **Insured Vehicle No :** SMF1994P
Date of Loss: 12/02/2019 **Nature of Claim:** TP **Claim No:** 4352950803SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM2475B
Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) **Engine No:** HR16993168A
Reg. Date: 12/02/2014 (Man. Year: 2013) **Chassis No:** MNTBBAB17Z0009634
Colour: Red **Odometer:** 50513 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 **Rear Tyre Size:** 195/60 R16
Front Left Side: Yokohama 6 mm **Rear Left Side:** Yokohama 6 mm
Front Right Side: Yokohama 6 mm **Rear Right Side:** Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,506.50	2,204.10	302.40	12.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,380.00	570.00	29.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,456.50	3,584.10	872.40	19.58
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	4,456.50	2,500.00	1,956.50	43.90
+ GST 7.00/7.00% (S\$)	311.96	175.00	136.96	43.90
Nett Amount (S\$)	4,768.46	2,675.00	2,093.46	43.90
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,037.00		

INSPECTION

Date of Assignment: 14/02/2019

Date Inspected: 14/02/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
 (Bedok)
 Blk 3011, Bedok Industrial Park E.,
 #01-2008/2010/2012
 Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Badly Dented	876.40 FL	*839.50 FL
2	1		*FRONT DOOR TOP STICKER RH	Necessary	27.30 FL	*27.30 FL
3	1		*FRONT DOOR INNER LOCK RH	Twisted / Shorted	231.10 FL	*231.10 FL
4	1		*FRONT DOOR PROTECTOR MOULDING RH	Bent	191.80 FL	*191.80 FL
5	1		*REAR DOOR RH	Dented / Bent	876.40 FL	*689.50 FL
6	1		*REAR DOOR TOP STICKER RH	Necessary	27.30 FL	*27.30 FL
7	1		*REAR DOOR HINGE TOP RH	Not Necessary	56.10 FL	*- FL
8	1		*REAR DOOR HINGE BOTTOM RH	Not Necessary	56.10 FL	*- FL
9	1		*FRONT DOOR INNER RUBBER RH	Necessary	85.30 FL	*85.30 FL
10	1		*FRONT DOOR HANDLER SENSOR LOCK	Shorted	96.70 FL	*96.70 FL
11	1		*ROCKER PANEL REAR STICKER	Necessary	88.10 FL	*88.10 FL
12	1		*REAR DOOR PILLAR CENTER PILLAR RH (NPA)	Repair	0.00 FS	*- FS
13	1		*FRONT DOOR PILLAR CENTER PILLAR RH (NPA)	Repair	0.00 FS	*- FS
14	1		*ROCKER PANEL RH (NPA)	Repair	0.00 FS	*- FS
15	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
16	1		*REAR DOOR PROTECTOR MOULDING RH	Scratched	172.40 FL	*172.40 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	2,785.00	2,449.00
- List Item Discount on L Items 10.00/10.00% (S\$)	278.50	244.90
Total Parts (S\$)	2,506.50	2,204.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	800.00
3	ANTI -RUST COATING	New	250.00	80.00
Gross Labour Cost (S\$)			1,950.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >