



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

<b>Customer</b> : MS FIRST CAPITAL INSURANCE 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b> : SQT19000879 <span style="float: right;">Page 1</span>
<b>Registration No</b> : SLJ1176A	<b>Date</b> : 24. Feb 2019
<b>Chassis No</b> : JHMGK5850HX200872	<b>Customer No.</b> : WZF002
<b>Model</b> : JAZZ 1.5VTIR CVT 17YM	<b>Svc Advisor</b> : LIM CHOU SIONG
<b>Owner's Name</b> : LOW HAN SONG, CLARENCE	<b>Engine No</b> : L15B31190620
<b>Ins Policy No.</b> :	<b>Date   Time</b> : 24. Feb 2019 5:32:03 PM
<b>Date of Accident</b> : 8/2/2019	<b>Surveyor Name</b> : MARCUS (L.K.K.)
	<b>Survey Date</b> : 15/2/2019
	<b>Authorisation Date</b> : 14/2/2019

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72171) OWNER: LOW HAN SONG, CLARENCE OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD ACC DATE: 8/2/2019 SURVEYED BY: MARCUS (L.K.K.) DATE: 15/02/2019 @ 09:30AM REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA4370E SUPPLEMENTARY LABOUR & PARTS						
38389-T5R-A01	COVER.L.FR.ANTENNA <i>ADD</i>	1 <i>CAE</i>	18.70	25	14.02	0.98	15.00
					<b>Sum Item</b>	<b>14.02</b>	<b>0.98</b>
							<b>15.00</b>

Survey By	_____						
Date & Time	_____				<b>Total Amount</b>	14.02	0.98
Excess	_____				<b>Total (Inclusive of GST)</b>		<b>15.00</b>
Status	_____						
Signature	_____						

Printed on 24/2/2019 5:37:05 PM  
 This is a computer generated invoice. No signature is required.  
 Part prices are subjected to change without notice.  
 The above estimated cost of repair do not include any unforeseen damages.  
 GST Amount is calculated from individual line(s)