

Tauhinu

REF:

CC3/A19/9002844/TIVD302

Vehicle No.

OK

Form Date
Estimated Cost
TP / WS / TP RES / OD RES / EVA / INV / MV

Inspected Vehicle No.
Workshop No.
Insured
Policy No. 1800041244
Claims No.
Sum Insured Excess 1600
(Client's Record)
Make of Veh.

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: 9132K
IDAC Accident Report Consistent? : Yes or No
GIA / PR Seen Consistent? : Yes or No
Est. Repairs: 8 days Res: Yes or No
Lump Sum: % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: Person Contacted:
Vehicle: IN / OUT

Vehicle: SLX96095
Type: M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: And 194
Colour: Black A/C Insured / Std / NI / NA
Sp. Reading: 8580 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: WA422ZF46J4131065
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60R16
R: 7
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Gutbuster
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 9/2/19 D.O.L. 14/2/19
Survey held at Premium Alexander
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Frt N/S
The UIC / Chassis frame / Body Structure affected due to collision

Date: Time Action / Instruction
15/7/19 @ 1:43pm SLX 96095 X
revert to Victor via Merimen.

15/2/19 Rece approved \$16,441 from Victor by merimen
15/2/19 Informed George CIA ex TBC by email
13/3/19 Informed Sheila vehicle ex \$1600 by email

8/5/19 final fig \$17,148.76 (Red 11002.24, 3910) confirmed by email

RECEIVED 12 APR 2019

Date/Time: File Pass to? ☐ : Proli. Report
1) ☐ : Final Report

Days Of Repair: 8
Resurvey No. of Trip: 1

Survey Fee	200
Transportation	
1. S - RT - 10	
2. H - 10	
3. Fuel	10
4. Other	
5. Total	210

24/5- typist

Report Format: merimen
Lump Sum / LB: 17,148.76

Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Fuel: \$
☐ Workshop: \$

View Received Message

This mail is associated with :

***SLX9609S (4908764235SG)**

OD

Feb 9 2019 12:00PM

[LIM JIA HUI , EUGENE (LIN JIAHUI)]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/05/2019 14:18 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$17148.76) - SLX9609S - Claim Handler: Dally Amri, Mimi Zarina

Approved:17148.76:

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 March 2019 5:21 PM
To: 'Claims Dept'; Shiau Chan (LKKAUTO)
Cc: SUR
Subject: RE: OD CLAIMS FOR SLX 9609 S -DOA: 9/2/2019

Dear Sheila,

Vehicle excess \$1600/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 13 March 2019 5:16 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR SLX 9609 S

Hi Shiau Chan ,

How much is the excess ?

Thank You.

Best Regards,
Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 209902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shiau Chan (LKKAuto) [<mailto:siewsc@lkkauto.com>]
Sent: Tuesday, 19 February 2019 1:10 PM
To: Claims
Cc: SUR
Subject: RE: OD CLAIMS FOR SLX 9609 S

Dear Sheila,

Please refer to the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 19 February 2019 12:31 PM
To: 'Claims' <claims@premiumauto.com.sg>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: OD CLAIMS FOR SLX 9609 S

Hi Shiau Chan ,

Kindly advise on approval status.

Thank You.

Best Regards,

Sheila M Ismail

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902773W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Friday, 15 February 2019 2:22 PM

To: 'Shiau Chan (LKKAUTO)'; 'SUR'; 'assignments'; 'Admin-D (LKKAUTO)'

Cc: 'Claims'

Subject: RE: OD CLAIMS FOR SLX 9609 S

Dear Shiau Chan,

Please find attached the requested documents.

Thank you.

Best regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199802271W)

281 Alexandra Road Singapore 159938

p. +65 6388 2223 d. +65 66900293 f. +65 64751023

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Friday, February 15, 2019 1:27 PM

To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>;

Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: RE: OD CLAIMS FOR SLX 9609 S

Dear George,

Kindly provide us the certificate of insurance and driver's driving license copy of above vehicle.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Wednesday, 13 February 2019 10:41 AM

To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIMS FOR SLX 9609 S

Dear Nivitha,

As spoken over the phone , kindly arrange survey on 14th of Feb @230pm.

Address : 281 Alexandra Road Singapore 159938

Attached is the GIA for your reference.

Thank you.

Best regards,
George Wong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 189902271W)

281 Alexandra Road Singapore 159938

p. +65 6388 2223 d. +65 66900293 f. +65 64751023

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SLX9609S (4908764235SG)**

OD

Feb 9 2019 12:00PM

[LIM JIA HUI , EUGENE (LIN JIAHUI)]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 15/02/2019 17:19 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$16441.00) - SLX9609S - Claim Handler: Dally Amri, Mimi Zarina

Approved:16441.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 15 Feb 2019

Preliminary Advice

Vehicle No	: SLX9609S	Accident Date	: 09/02/2019
Make	: AUDI A4	Policy No.	:
Assignment Date	: 15/02/2019	Excess	: S\$0.00
Date of Inspection	: 14/02/2019	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,151.00
Revised Amount	:S\$	16,441.00
Check Items (Estimated)	:S\$	7,002.00
Total	:S\$	23,443.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	132,000.00
COE / PARF Rebate	:S\$	63,588.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,412.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8134F
Vehicle Details	
Vehicle No.:	SLX9609S
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	CVK057022
Chassis No.:	WAUZZZF46JA131065
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,425.00
Original Registration Date:	18 Apr 2018
First Registration Date:	18 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$38,795.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2028
PARF Rebate Amount:	\$29,096.00
Intended COE Rebate Details	
COE Expiry Date:	17 Apr 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,605.00
COE Rebate Amount:	\$34,492.00
Total Rebate Amount:	\$63,588.00

The information contained herein is correct as at 15 Feb 2019

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM JIA HUI, EUGENE (LIN JIAHUI)
Period of Insurance : 18 Apr 2018 To 17 Apr 2019
Engine No. : CVK 057022
Chassis No. : WAUZZZF46JA131065

Vehicle No. : SLX9609S
Policy No. : 1800041244
Endorsement No. :
Issued Date : 26 Apr 2018

ABOUT THE COVER

Make/Model : AUDI A4 Sedan 2.0 TFSI S tronic
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM JIA HUI, EUGENE (LIN JIAHUI) - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 85 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125276

PREMIUM LEASING -SCS
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159038

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Stephany Loh

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8708134F**

Name: **LIM JIA HUI, EUGENE**
LIN JIAHUI

Date of Birth: **31 Mar 1987**

Issue Date: **16 Oct 2015**

SG 50

002483872F



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8708134F

Name: **LIM JIA HUI, EUGENE**
(LIN JIAHUI)
林家輝

Race: **CHINESE**

Date of birth: **31-03-1987**

Country/Place of birth: **SINGAPORE**

Sex: **M**

S8708134F





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg **16 Oct 2015**

Licence No: S8708134F

NP 428A



S869604

5869604

S8708134F

Date of issue
09-02-2018

Address
APT BLK 1G CANTONMENT ROAD
#19-75
SINGAPORE 085701




SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/02/2019 17:04
Date Of Accident	09/02/2019 12:00
Exact Location Of Accident	BASEMENT CARPARK OF PINNACLE @DUXTON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX9609S
Insured/Policyholder	
Name Of Registered Owner	LIM JIA HUI , EUGENE (LIN JIAHUI)
NRIC No	S8708134F
Email Address	EUGENELIMJIAHUI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90079692
Alternative Phone No	OFFICE-90079692

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800041244
Cover Note Number	

Driver

Name of Driver	LIM JIA HUI , EUGENE (LIN JIAHUI)
NRIC No	S8708134F
Date Of Birth	31/03/1987
Occupation	INDOOR
Date Of Driving Pass	16/10/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90079692
Fax Number	
Contact Number	OFFICE-90079692
Email Address	EUGENELIMJIAHUI@GMAIL.COM

Address	APT BLK 1G CANTONMENT ROAD #19-75
Postcode	085701
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ACCIDENTALLY HIT ONTO PILLAR OF BASEMENT CAR PARK WHILE LOOKING FOR PARKING.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name: James Robert Sankarasingh
NRIC/IN No: 9278749



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accidentally hit onto pillar of basement car-park while looking for parking.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Wahid Khan S. Chaudhary*
NRIC/ID No: *Q298745A*



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0198/2019/GW
Date : 14-Feb-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Lim Jia Hui, Eugene (Lin JiaHui)
Address : Apt Blk 1G Cantonment road
#19-75
Singapore 085701
Telephone : HP +65 90079692
Type of Claim : Own Damage Claims
Policy No. : 1800041244
Vehicle No : **SLX 9609 S**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : 18-04-18
Engine No : CVK 057022
Chassis No : WAUZZZF463A131065
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 09-Feb-19
Place of Accident : Basement Carpark of Pinnacle @ Duxton

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 9609 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washery assy and front parking aid.	S/N	\$ 480.00 ^{with} ✓	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vaccum/regas and to pressurise cooling system.	S/N	\$ 1,000.00 ?	✓
3	To dismantle lhs fornt door panel trim. To remove and reinstall all wing mirror assy.	S/N	\$ 300.00 ✓	✓
4	To dismantle and renew front bumper, lhs front fender and lhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	500	\$ 3,900.00 ¹²⁵⁰ 2750	
5	To respray front bumper, lhs front fender, bonnet and lhs front door. ✓		\$ 3,000.00 [✓] 2200 ✓	
6	To renew lhs front rim. To carry out wheel alignment.	S/N	\$ 280.00 X	
7	To carry out diganostic check.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	\$ 9,152.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9609 S

S/N	Parts Description		Damaged Parts & Prices S/Nett
1	FRONT BUMPER	S	1,999.00 <i>de</i> ✓ 1599.30
2	FRONT BUMPER FIXING PARTS	S	258.00 <i>na</i> ✓ X <i>nn</i>
3	FRONT BUMPER SECURING STRIP	S	32.00 <i>na</i> ✓ 25.44
4	FRONT BUMPER GRILLE-CENTER	S	178.00 X <i>nn</i>
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	S	191.00 <i>na</i> ✓ 150.40
6	FRONT BUMPER AIR GUIDE-LH	S	56.00 ? X <i>nn</i>
7	RADIATOR GRILLE	S	1,227.00 <i>cm</i> ✓ 981.60
8	FRONT BUMPER AIR GUIDE GRILLE-LH	S	123.00 ?
9	FOAM FILLER PIECE	S	113.00 ? } X <i>nn</i>
10	FRONT BUMPER CARRIER	S	733.00 ?
11	FRONT BUMPER BRACKET-LH	S	207.00 ?
12	FRONT BUMPER GUIDE SECTION-LH	S	33.00 ? 26.08 <i>de</i> ✓
13	FRONT BUMPER COVER	S	116.00 X
14	SIGN * CAUTION *	S	13.00 X
15	AIR CONDITIONER STICKER	S	7.00 X
16	FRONT BUMPER SUPPORT	S	26.00 ? } X <i>nn</i>
17	FRONT BUMPER BRACKET LOCK CARRIER	S	125.00 ?
18	FRONT SENSOR	2 S	462.00 ?
19	FRONT SEAL RING	4 S	12.00 <i>na</i>
20	FRONT FENDER-LH	S	700.00 <i>bt</i> ✓ 559.60
TOTAL SPARE PARTS CHARGES		:	\$ 6,611.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved.
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9609 S

S/N	Parts Description	Damaged Parts & Prices	
		S/	Nett
21	FRONT FENDER ATTACHMENT PARTS	\$	183.00 <i>de ✓ X un</i>
22	FRONT FENDER CLOSING ELEMENT-LH	\$	45.00 <i>? 36 de ✓</i>
23	FRONT FENDER BRACKET-LH	\$	32.00 <i>? 25.20 h/ ✓</i>
24	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH	\$	45.00 <i>? 35.60 de ✓</i>
25	FRONT FENDER UPPPRT BRACKE-LH	\$	29.00 <i>? X un</i>
26	FRONT FENDER BRACE-LH	\$	107.00 <i>? X un</i>
27	FRONT WHEEL HOUSING LINER-LH	\$	223.00 <i>de ✓ 178.40</i>
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH	\$	82.00 <i>de ✓ 65.52</i>
29	FRONT WHEEL SPOILER-LH	\$	66.00 <i>? 50.32 de ✓</i>
30	FRONT WHEEL SPOILER END PLATE-LH	\$	32.00 <i>? X un</i>
31	FRONT STONE CHIP GUARD-LH	\$	46.00 <i>? X un</i>
32	FRONT FENDER COVER-LH	\$	28.00 <i>? 22.54 de ✓</i>
33	FRONT FENDER TOP COVER-LH	\$	21.00 <i>? 16.16 de ✓</i>
34	LED HEADLIGHT -LH	\$	7,087.00 <i>de ✓ 5669.60</i>
35	LED POWER MODULE	\$	716.00 <i>?</i>
36	LED HEADLIGHT CONTROL UNIT	\$	685.00 <i>?</i>
37	LED HEADLIGHT LIFT CYLINDER-LH	\$	192.00 <i>?</i>
38	WASH WATER RESERVOIR	\$	135.00 <i>?</i>
39	FANFARE -HIGH TONE	\$	37.00 <i>?</i>
40	SPRING SHACKLE-LH	\$	26.00 <i>?</i>
TOTAL SPARE PARTS CHARGES		\$	9,817.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9609 S

S/N	Parts Description	Damaged Parts & Prices S/Nett	
41	LOCK CARRIER WITH MOUNTING	S	928.00 ? 743.00 ✓
42	READY MIX COOLANT 1.5 LTR	4 S	84.00 ?
43	FRONT AIR GUIDE-LH	S	25.00 ?
44	FRONT INNER AIR DUCT	S	11.00 ?
45	FRONT UPPRT AIR DUCT	S	15.00 ?
46	FRONT LOWER AIR DUCT	S	19.00 ?
47	FRONT ALUMINIUM RIM-RH	S	651.00 X u? ✓
48	RUBBER VALVE	S	13.00 X u? ✓
49	FRONT NO. PLATE	S	25.00 ne 25 ✓
50	SUNDRIES	S	800.00 ? 14.40 ✓
TOTAL SPARE PARTS CHARGES		:	\$ 18,999.00
TOTAL LABOUR CHARGES			\$ 9,152.00
GRAND TOTAL			\$ 28,151.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

15/2/19

Name	:	Taylor 97495269
Surveyed Date	:	- Apr 04/11/9 Not Authorise
Authorised Date	:	
Excess Cost	:	Doing before paint
Liability	:	
Remarks	:	See what is on of days

MV\$132K.

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

LKK Auto Consultants

Name: _____
Address: _____
City: _____
State: _____
Zip: _____
Phone: _____
Fax: _____
E-mail: _____
Website: _____

Signature: _____
Date: _____

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0198/2019/GW
Date : 14-Feb-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian, Taufikh
8 days exclude 1 Sunday - ok
jb 10 Apr 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Lim Jia Hui, Eugene (Lin JiaHui)
Address : Apt Blk 1G Cantonment road
#19-75
Telephone : Singapore 085701
Type of Claim : HP +65 90079692
Policy No. : Own Damage Claims
Vehicle No : 1800041244
Model Code : **SLX 9609 S**
Model / Year : Audi A4 Sedan 2.0 TFSI
Engine No : 18/4/2018
Chassis No : CVK 057022
Mileage : WAUZZZF463A131065
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Feb-19
Place of Accident : Basement Carpark of Pinnacle @ Duxton

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 9609 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washery assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vaccum/regas and to pressurise cooling system.	S/N \$ 1,000.00	\$ 1,000.00
3	To dismantle lhs front door panel trim. To remove and reinstall all wing mirror assy.	S/N \$ 300.00	\$ 300.00
4	To dismantle and renew front bumper, lhs front fender and lhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. (Added 3 days for lock carrier replacement)	\$ 3,900.00	\$ 2,750.00
5	To respray front bumper, lhs front fender, bonnet and lhs front door.	\$ 3,000.00	\$ 2,200.00
6	To renew lhs front rim. To carry out wheel alignment.	S/N \$ 280.00	
7	To carry out diganostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 9,152.00	\$ 6,922.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9609 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT BUMPER	\$ 1,999.00	\$ 1,599.20
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	FRONT BUMPER SECURING STRIP	\$ 32.00	\$ 25.44
4	FRONT BUMPER GRILLE-CENTER	\$ 178.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 191.00	\$ 152.40
6	FRONT BUMPER AIR GUIDE-LH	\$ 56.00	
7	RADIATOR GRILLE	\$ 1,227.00	\$ 981.60
8	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 123.00	
9	FOAM FILLER PIECE	\$ 113.00	
10	FRONT BUMPER CARRIER	\$ 733.00	
11	FRONT BUMPER BRACKET-LH	\$ 207.00	
12	FRONT BUMPER GUIDE SECTION-LH	\$ 33.00	\$ 26.08
13	FRONT BUMPER COVER	\$ 116.00	
14	SIGN ' CAUTION '	\$ 13.00	
15	AIR CONDITIONER STICKER	\$ 7.00	
16	FRONT BUMPER SUPPORT	\$ 26.00	
17	FRONT BUMPER BRACKET LOCK CARRIER	\$ 125.00	
18	FRONT SENSOR	2 \$ 462.00	
19	FRONT SEAL RING	4 \$ 12.00	
20	FRONT FENDER-LH	\$ 700.00	\$ 559.60
TOTAL SPARE PARTS CHARGES		\$ 6,611.00	\$ 3,344.32

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9609 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>		
		S/Nett		
		c/f	\$	3,344.32
21	FRONT FENDER ATTACHMENT PARTS	\$	183.00	
22	FRONT FENDER CLOSING ELEMENT-LH	\$	45.00	\$ 36.00
23	FRONT FENDER BRACKET-LH	\$	32.00	\$ 25.20
24	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH	\$	45.00	\$ 35.60
25	FRONT FENDER UPPPRT BRACKE-LH	\$	29.00	
26	FRONT FENDER BRACE-LH	\$	107.00	
27	FRONT WHEEL HOUSING LINER-LH	\$	223.00	\$ 178.40
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH	\$	82.00	\$ 65.52
29	FRONT WHEEL SPOILER-LH	\$	66.00	\$ 52.32
30	FRONT WHEEL SPOILER END PLATE-LH	\$	32.00	
31	FRONT STONE CHIP GUARD-LH	\$	46.00	
32	FRONT FENDER COVER-LH	\$	28.00	\$ 22.24
33	FRONT FENDER TOP COVER-LH	\$	21.00	\$ 16.16
34	LED HEADLIGHT -LH	\$	7,087.00	\$ 5,669.60
35	LED POWER MODULE	\$	716.00	
36	LED HEADLIGHT CONTROL UNIT	\$	685.00	
37	LED HEADLIGHT LIFT CYLINDER-LH	\$	192.00	
38	WASH WATER RESERVOIR	\$	135.00	
39	FANFARE -HIGH TONE	\$	37.00	
40	SPRING SHACKLE-LH	\$	26.00	
TOTAL SPARE PARTS CHARGES		\$	9,817.00	\$ 9,445.36

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9609 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
		<i>c/f</i>	\$ 9,445.36
41	LOCK CARRIER WITH MOUNTING	\$ 928.00	\$ 742.00
42	READY MIX COOLANT 1.5 LTR	4 \$ 84.00	
43	FRONT AIR GUIDE-LH	\$ 25.00	
44	FRONT INNER AIR DUCT	\$ 11.00	
45	FRONT UPPRT AIR DUCT	\$ 15.00	
46	FRONT LOWER AIR DUCT	\$ 19.00	
47	FRONT ALUMINIUM RIM-RH	\$ 651.00	
48	RUBBER VALVE	\$ 13.00	
49	FRONT NO. PLATE	\$ 25.00	\$ 25.00
50	SUNDRIES	\$ 800.00	\$ 14.40
	TOTAL SPARE PARTS CHARGES	\$ 18,999.00	\$ 10,226.76
	TOTAL LABOUR CHARGES	\$ 9,152.00	\$ 6,922.00
	GRAND TOTAL	\$ 28,151.00	\$ 17,148.76

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 8 May 2019 2:57 PM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SLX9609S - OD AIG - SURVEYED 14 FEB 19 - TAUFIKH

Dear Mr Boo,

Confirm repair cost of \$17,148.76 before excess \$1600 and GST @ 8 days of repairs

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 10 April 2019 4:48 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLX9609S - OD AIG - SURVEYED 14 FEB 19 - TAUFIKH

Hi Adrian, Taufikh and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$17,148.76@8 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLX 9609 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0198/2019/MAS

23 May 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLX 9609 S, Audi A4 Sedan 2.0 TFSI

With reference to the above-mentioned vehicle, no. **SLX 9609 S**, claimant, **Mr. Lim Jia Hui, Eugene**, please find the related document per attached.

1. A copy of the Original invoice no. 85013767 – S\$16,637.17
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLX 9609 S

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Main Telephone: 6386 2222
Main Telefax: 6471 3733

Alexander Service Centre
281 Alexandra Road
Singapore 159908
Telephone: 6386 2222
Telefax: 6475 1023

UBI Service Centre
95 Ubi Road 1
Singapore 408721

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2222
6826 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 1 15:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85813767 Date : 14/05/2019 Order : SLX96095 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX96095 (V 37245) Regn Date: 18/04/2018 Mileage: 10114 WIP No.: 42450
Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF46JA131065 Engine: CVK 057022 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1500.00	1.00	-1,500.00
C	01500000	M: 6BH TO CARRY OUT DIAGNOSTIC CHECK.	1.28	150.00	192.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	400.00	1.00	400.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REBAG AND TO PRESSURISE COOLING SYSTEM	1000.00	1.00	1,000.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	300.00	1.00	300.00
S	BODYWORK	M: TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	2750.00	1.00	2,750.00
Sub-Total					
7% GST					
Grand Total					



Customer Service	
Service Appointment	6346 1323
CE	
24-hour Breakdown Service	9828 1233
Email	CUSTOMER.CARE@STONMILLMOTOR.COM

Page 2 15:36

BST Reg. No. 153902271W

Grand Total

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
201 Alexandra Road
Singapore 159939
Main Telephone: 6346 2223
Main Telefax: 6471 2233

Alexandra Service Centre
201 Alexandra Road
Singapore 159939
Telephone: 6346 2223
Telefax: 6471 2233

UBi Service Centre
55 Ubi Road 1
Singapore 408722

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6346 2223
6828 1219

INS TAX INVOICE

Company Reg. No: 199902271W

GST Reg. No. 199902271W

Page 3 15:36

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013767
Date : 14/05/2019
Order : SLX96095
Term : 30

Account: A0006 (T @)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLX96095 (V 37245) Regn Date: 18/04/2018 Mileage: 10114 WIP No.: 42450
Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF46JA131065 Engine: CVK 057022 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A8W0090629	ATT.PARTS	Less 020%	1.00	65.52	65.52
X	A8W0021467	BRACKET	Less 020%	1.00	25.20	25.20
X	A8W0021469	BRACKET	Less 020%	1.00	35.60	35.60
X	A8W0007283	(SH) GUIDE	Less 020%	1.00	26.08	26.08
X	A8W0023745	COVER	Less 020%	1.00	16.16	16.16
X	A8W0021091	PLATE	Less 020%	1.00	36.00	36.00
X	A8W0007277	STRIP	Less 020%	1.00	25.44	25.44
X	A8W0020581C	COVER	Less 020%	1.00	22.24	22.24
X	AN 0161857	POP-RIVET	Less 020%	6.00	14.40	14.40

Parts 10,201.76
Labour 217.00
Sublet 5,730.00
Menus 0.00
Lubricant 0.00

Sub-Total 15,548.76

7% GST 1,088.41

Grand Total 16,637.17

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLX 9609 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0198/2019/KK
13TH March 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF46JA131065
Vehicle Regn No. : SLX 9609 S
Vehicle Mileage : 9083 KM
Vehicle Owner : Mr. Lim Jia Hui, Eugene(Lin Jia Hui)
Certificate No : 1800041244
Own Damage Excess : \$ 1712.00 (Inclusive 7%GST)
Accident Date : 09/02/2019
Place : Basement Carpark Of Pinnacle@ Duxton
Repair Cost : \$ 16,637.17
WIP No. : 42450
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 13/3/19

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8708134F**

LIM JIA HUI, EUGENE
林 家 輝

Valid Date: 31 Mar 1987
Valid Date: 16 Oct 2015

002483872F

SG 50

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8708134F

LIM JIA HUI, EUGENE
(LIN JIAHUI)
林 家 輝

Race: **CHINESE**
Date of birth: **31-03-1987**
Country/Place of birth: **SINGAPORE**

Sex: **M**

S8708134F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 16 Oct 2015

Licence No: S8708134F

NP 428A

5869604

S8708134F

09-02-2018

APT BLK 1Q CANTONMENT ROAD
#19-75
SINGAPORE 085701

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM JIA HUI, EUGENE (LIN JIAHUI)
Period of Insurance : 18 Apr 2018 To 17 Apr 2019
Engine No. : CVK 057022
Chassis No. : WAUZZZF46JA131065

Vehicle No. : SLX9609S
Policy No. : 1800041244
Endorsement No. :
Issued Date : 26 Apr 2018

ABOUT THE COVER

Make/Model	AUDI A4 Sedan 2.0 TFSI S tronic			
Engine Capacity/Tonnage	1,984.00 CC	Sum Insured	: Market Value	First Year of Registration
Driver Restriction	: NA	Off Peak Car	: No	Insuring with COE/PARE
				: Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these hearings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM JIA HUI, EUGENE (LIN JIAHUI) - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center: Add: 35 Ubi Road 1 Singapore 408699 63662333

For other Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 180), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

0504125276

PREMIUM LEASING -SCS
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Steffany Luth

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2019 13:40		15 Feb 2019 13:35 Edit Adj Rpt	S\$17,148.76 Edit Estimates	S\$17,148.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM JIA HUI , EUGENE (LIN JIAHUI), ID: S8708134F, Tel: +6590079692, Email: EUGENELIMJIAHUI@GMAIL.COM								
Vehicle Reg. No.:	SLX9609S	Date of Loss:	09/02/2019 12:00 - :59 [9 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4908764235SG	Policy/Cover Note No.:	(Comprehensive)						
		Excess:	S\$1,600.00						
Reparer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/02/2019]								
Driver/Custodian:	LIM JIA HUI , EUGENE (LIN JIAHUI) (31 / Male) , NRIC: S8708134F, Tel: +6590079692 Email: EUGENELIMJIAHUI@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (08/05/2019): Alert - Adj Mandate Approved (S\$17148.76) - SLX9609S - Claim Handler: Dally Amri... - AIG_SG (15/02/2019): Alert - Adj Mandate Approved (S\$16441.00) - SLX9609S - Claim Handler: Dally Amri...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX9609S (4908764235SG)
 OD
 Feb 9 2019 12:00PM
 [LIM JIA HUI , EUGENE (LIN JIAHUI)]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports											1 per page		☒	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	15/02/19 13:42		Adjuster Immediate Advice								1	Load HTML		
Photos/Images											3 per page		☒	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	15/02/19 13:38		Odometer Reading								1	Load JPG	☒	
2	15/02/19 13:38		General View								1	Load JPG	☒	
3	15/02/19 13:38		General View								1	Load JPG	☒	
4	15/02/19 13:38		Chassis Number								1	Load JPG	☒	
5	15/02/19 13:38		General View								1	Load JPG	☒	
6	15/02/19 13:38		General View								1	Load JPG	☒	
7	15/02/19 13:38		General View								1	Load JPG	☒	
8	15/02/19 13:38		General View								1	Load JPG	☒	
9	15/02/19 13:38		General View								1	Load JPG	☒	
10	15/02/19 13:38		General View								1	Load JPG	☒	
11	15/02/19 13:38		General View								1	Load JPG	☒	
12	15/02/19 13:38		General View								1	Load JPG	☒	
13	15/02/19 13:38		General View								1	Load JPG	☒	
14	15/02/19 13:38		General View								1	Load JPG	☒	
15	15/02/19 13:38		General View								1	Load JPG	☒	
16	15/02/19 13:38		General View								1	Load JPG	☒	
17	15/02/19 13:38		General View								1	Load JPG	☒	
18	15/02/19 13:38		General View								1	Load JPG	☒	
19	15/02/19 13:38		General View								1	Load JPG	☒	
20	15/02/19 13:38		General View								1	Load JPG	☒	
21	15/02/19 13:38		General View								1	Load JPG	☒	
22	15/02/19 13:38		General View								1	Load JPG	☒	
23	15/02/19 13:38		General View								1	Load JPG	☒	
24	15/02/19 13:38		General View								1	Load JPG	☒	
25	15/02/19 13:38		General View								1	Load JPG	☒	
26	15/02/19 13:38		General View								1	Load JPG	☒	
27	15/02/19 13:38		General View								1	Load JPG	☒	
28	15/02/19 13:38		General View								1	Load JPG	☒	
29	15/02/19 13:38		General View								1	Load JPG	☒	
30	15/02/19 13:38		General View								1	Load JPG	☒	
31	15/02/19 13:38		General View								1	Load JPG	☒	
32	15/02/19 13:38		General View								1	Load JPG	☒	
33	03/05/19 14:50		Reinspection Photo								1	Load JPG	☒	
34	03/05/19 14:50		Reinspection Photo								1	Load JPG	☒	
35	03/05/19 14:50		Reinspection Photo								1	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
37	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
38	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
39	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
40	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
41	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
42	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
43	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
44	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
45	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
46	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
47	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
48	03/05/19 14:50	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/19 13:37	Singapore Accident Statement	 Load PDF	
2	15/02/19 13:37	ESTIMATE	 Load PDF	
3	15/02/19 14:25	Driver's Driving License	 Load PDF	
4	15/02/19 14:26	Certificate of Insurance	 Load PDF	
5	24/05/19 12:52	Workshop Invoice	 Load PDF	
6	24/05/19 12:52	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/02/19 17:59	Accident Statement	 Load HTM	
2	12/02/19 18:33	Addendum Sheet	 Load JPG	☒
3	12/02/19 18:33	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/02/19 17:46	Accident Photo	 Load JPG	☒
2	11/02/19 17:46	Accident Photo	 Load JPG	☒
3	11/02/19 17:46	Accident Photo	 Load JPG	☒
4	11/02/19 17:46	Accident Photo	 Load JPG	☒
5	11/02/19 17:46	Accident Photo	 Load JPG	☒
6	11/02/19 17:46	Accident Photo	 Load JPG	☒
7	11/02/19 17:46	Accident Photo	 Load JPG	☒
8	11/02/19 17:46	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/02/19 17:38	Sketch Plan	 Load JPG	☒
2	11/02/19 17:38	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19002844/T1VD3E2

Date: 24/05/2019

REFERENCE

Insured/Claimant: LIM JIA HUI, EUGENE (LIN JIAHUI)

Policy No:

Date of Loss: 09/02/2019

Nature of Claim: OD Claim No: 4908764235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX9609S	Engine No:	CVK057022
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Chassis No:	WAUZZZF46JA131065
Reg. Date:	18/04/2018 (Man. Year: 2018)	Odometer:	8580 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$132,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,999.00	10,226.76	8,772.24	46.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,152.00	6,922.00	2,230.00	24.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,151.00	17,148.76	11,002.24	39.08
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	26,551.00	15,548.76	11,002.24	41.44
+ GST 7.00/7.00% (S\$)	1,858.57	1,088.41	770.16	41.44
Nett Amount (S\$)	28,409.57	16,637.17	11,772.40	41.44

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 14/02/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,999.00 FS	*1,599.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Necessary	32.00 FS	*25.44 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	178.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	191.00 FS	*152.40 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	56.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,227.00 FS	*981.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	123.00 FS	*- FS
9	1		*FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
10	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
11	1		*FRONT BUMPER BRACKET - LH	Not Necessary	207.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Deformed	33.00 FS	*26.08 FS
13	1		*FRONT BUMPER COVER	Not Necessary	116.00 FS	*- FS
14	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
15	1		*AIR CONDITIONER STICKER	Not Necessary	7.00 FS	*- FS
16	1		*FRONT BUMPER SUPPORT	Not Necessary	26.00 FS	*- FS
17	1		*FRONT BUMPER BRACKET LOCK CARRIER	Not Necessary	125.00 FS	*- FS
18	2		*FRONT SENSOR	Not Necessary	462.00 FS	*- FS
19	4		*FRONT SEAL RING	Not Necessary	12.00 FS	*- FS
20	1		*FRONT FENDER - LH	Bent	700.00 FS	*559.60 FS
21	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
22	1		*FRONT FENDER CLOSING ELEMENT - LH	Deformed	45.00 FS	*36.00 FS
23	1		*FRONT FENDER BRACKET - LH	Bent	32.00 FS	*25.20 FS
24	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT - LH	Deformed	45.00 FS	*35.60 FS
25	1		*FRONT FENDER UPPPRT BRACKE - LH	Not Necessary	29.00 FS	*- FS
26	1		*FRONT FENDER BRACE - LH	Not Necessary	107.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	223.00 FS	*178.40 FS
28	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH	Necessary	82.00 FS	*65.52 FS
29	1		*FRONT WHEEL SPOILER - LH	Deformed	66.00 FS	*52.32 FS
30	1		*FRONT WHEEL SPOILER END PLATE - LH	Not Necessary	32.00 FS	*- FS
31	1		*FRONT STONE CHIP GUARD - LH		46.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*FRONT FENDER COVER - LH	Not Necessary Deformed	28.00 FS	*22.24 FS
33	1		*FRONT FENDER TOP COVER - LH	Deformed	21.00 FS	*16.16 FS
34	1		*LED HEADLIGHT - LH	Cracked	7,087.00 FS	*5,669.60 FS
35	1		*LED POWER MODULE	Not Necessary	716.00 FS	*- FS
36	1		*LED HEADLIGHT CONTROL UNIT	Not Necessary	685.00 FS	*- FS
37	1		*LED HEADLIGHT LIFT CYLINDER - LH	Not Necessary	192.00 FS	*- FS
38	1		*WASH WATER RESERVOIR	Not Necessary	135.00 FS	*- FS
39	1		*FANFARE - HIGH TONE	Not Necessary	37.00 FS	*- FS
40	1		*SPRING SHACKLE - LH	Not Necessary	26.00 FS	*- FS
41	1		*LOCK CARRIER WITH MOUNTING	Cracked	928.00 FS	*742.00 FS
42	4		*READY MIX COOLANT 1.5 LTR	Not Necessary	84.00 FS	*- FS
43	1		*FRONT AIR GUIDE - LH	Not Necessary	25.00 FS	*- FS
44	1		*FRONT INNER AIR DUCT	Not Necessary	11.00 FS	*- FS
45	1		*FRONT UPPRT AIR DUCT	Not Necessary	15.00 FS	*- FS
46	1		*FRONT LOWER AIR DUCT	Not Necessary	19.00 FS	*- FS
47	1		*FRONT ALUMINIUM RIM - RH	Not Necessary	651.00 FS	*- FS
48	1		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
49	1		*FRONT NO. PLATE	Necessary	25.00 FS	*25.00 FS
50	1		*SUNDRIES	Necessary	800.00 FS	*14.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **18,999.00** **10,226.76**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHERY ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,000.00	1,000.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL ALL WING MIRROR ASSY	New	300.00	300.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,900.00	2,750.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR	New	3,000.00	2,200.00
6	TO RENEW LHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			9,152.00	6,922.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >