OD TP / W	Bill to: STTP RESTOR RESTEVATING I MYTCS
To Impect Ve	303 T 4D
at Workshop a	ryele + caminge Ind. Tel 91865112
of	188 pandon toup
Folicy bee	Claim No. S9 MOIDWA
Sum heared	Excess: \$500.00
Make of Veh (Client's Record	DOA 13/2/19
	RED: A RESULTATION
Date/Time	Income and the
Date/True	Action/Instruction (~) Estimate thek/comment on mechanical Issue
	8DS78D-CC+1ASM19002861/693 DOA:1312/2019
18/2/19	

Menu

FINAL ASSESSMENT

Type

Question

Message

WE HAD RECEIVED FINAL REPAIRER INVOICE AND DV. PLEASE LET US HAVE YOUR FINAL ASSESSMENT AND TAX INVOICE FOR PAYMENT

Reply * Dear Yvonne, Noted with thanks. Best Regards Veron Chen

Cancel Reply

Reply Now



51 UHI AVE 1, 801-25 PAYA UHI INDUSTRIAL PARK, SINGAPORE 408933. TEL ; (065) 62563561. FAX ; (065) 62564515

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 5/4/2019

Survey details

Date of loss	13/2/2019	
Date of appointment	14/2/2019	
Date of survey	15/2/2019	
Location of survey	CYCLE & CARRIAGE INDUSTRIES PTE LTD	

Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	SDS 78D	
Make and Model	MERCEDES BENZ E250	
Date of registration	2/9/2011	
Excess	\$500	
Market Value	\$71,000.00	
Parf Rebate	\$48,118.00	
Nett Loss	\$22,882.00	

Repair details

Initial Estimate	\$30,810.71 (INCL.SUPPLEMENTARY \$891.06

Proposed/Revised repair cost:

Parts	\$8,270.85
"Check items (Estimated)	
Labour	\$4,542.00
Total	\$12,812.85 (INCL.SUPPLEMENTARY \$891.06)
Lump Sum (Estimated)	

Number of days of repair 6	days
------------------------------	------

Remarks:

The vehicle sustained damages at the front portion and o/s body

Damages Consistent Repair Cost Economical

Menu.

New Message

Type *



Message

Subject *

SDS 78D-SUPPLEMENTARY

Message *

Dear Yvonne,

We have received supplementary from repairer .Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair.

Best Regards.

Veron Chen

Cancel

Veron Chen (LKKAuto)

From:

Alan Quek <alan.quek@cyclecarriage.com.sg>

Sent:

Tuesday, 19 February 2019 9:21 AM

To:

Veron Chen (LKKAuto); SUR

Cc:

Rasul (LKKAuto)

Subject:

RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron,

LUM SUM where got supplementary or add on. Anything above the repair limit we will absorb the cost.

Your Sincerely

Alan Quek Service Advisor Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd 188 Pandan Loop Service Center Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Tuesday, 19 February 2019 9:12 AM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan.

As instructed by our client, please proceed to repair the insured vehicle SDS 78D Lump Sum repair not exceeding \$22,000/- or which ever lower (Excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

18

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek <alan.quek@cyclecarriage.com.sg>

Sent: Monday, 18 February 2019 3:31 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com >; SUR < sur@lkkauto.com >

Cc: Rasul (LKKAuto) < Rasul@lkkauto.com > Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron,

Attached is the letter. Kindly assist to authorise repair and LUM SUM repair amount agree by AXA. Thank you.

Your Sincerely

Alan Quek
Service Advisor
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 18 February 2019 1:40 PM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan.

Refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek <alan.quek@cyclecarriage.com.sg>

Sent: Monday, 18 February 2019 1:30 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com >; SUR < sur@lkkauto.com >

Cc: Rasul (LKKAuto) < Rasul@lkkauto.com > Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron,

You may consider LUM SUM repair at \$22K, I may forward me the LUM SUM agreement form, I will get your insured to sign and forward back to you.

Your Sincerely

Alan Quek
Service Advisor
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 18 February 2019 1:26 PM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan,

Kindly check vehicle able to repair at part by part not exceeding \$22,000/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Veron Chen (LKKAuto)-

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 19 February 2019 9:12 AM

To:

'Alan Quek'; SUR Rasul (LKKAuto)

Cc: Subject:

RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan,

As instructed by our client, please proceed to repair the insured vehicle SDS 78D Lump Sum repair not exceeding \$22,000/- or which ever lower (Excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek <alan.quek@cyclecarriage.com.sg>

Sent: Monday, 18 February 2019 3:31 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Rasul (LKKAuto) < Rasul@lkkauto.com>
Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron.

Attached is the letter. Kindly assist to authorise repair and LUM SUM repair amount agree by AXA. Thank you.

Your Sincerely

Alan Quek
Service Advisor
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 18 February 2019 1:40 PM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan,

Refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek <alan.guek@cyclecarriage.com.sg>

Sent: Monday, 18 February 2019 1:30 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Rasul (LKKAuto) < Rasul@lkkauto.com> Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron,

You may consider LUM SUM repair at \$22K, I may forward me the LUM SUM agreement form, I will get your insured to sign and forward back to you.

Your Sincerely


Alan Quek Service Advisor Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd 188 Pandan Loop Service Center Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 18 February 2019 1:26 PM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan.

Kindly check vehicle able to repair at part by part not exceeding \$22,000/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

invalid -Menu

AUTHORIZE

Type

Question

Message

Please proceed to authorize

Reply

LKK AUTO CONSULTANTS PTE LTD (OD) .

New Message

Type *



Message

Subject *

IA SUBMITTED FOR SDS 78D

Message *

Dear Yvonne,

Please be informed that IA submitted. We have Not Authorize repair. Pending repair cost from repairer.

According to surveyor, at time of assessement, there were no signs of mechanical failure. Brakes are working, no signs of leakages, tyres are in working conditions. Thanks Veron Chen

Cancal



51 UBLAVE 1, #01-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 400933 TEL : (003) 62563561 FAX : (008) 62564313

Immediate Advice

To: AXA Insurance Pte Ltd

Date:18/2/2019

Survey details

Date of loss	13/2/2019
Date of appointment	14/2/2019
Date of survey	15/2/2019
Location of survey	CYCLE & CARRIAGE INDUSTRIES PTE LTD

Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	SDS 78D	
Make and Model	MERCEDES BENZ E250	
Date of registration	2/9/2011	
Excess	\$500	
Market Value	\$71,000.00	
Parf Rebate	\$48,118.00	
Nett Loss	\$22,882.00	

Repair details

Initial Estimate	\$29,789.65	

Proposed/Revised repair cost:

Parts	\$7,308.28	
"Check items (Estimated)	\$17,001.41	
Labour	\$4,412.00	
Total	\$28,721.65	
Lump Sum (Estimated)		

Number of days of repair	6 days

Remarks:

The vehicle sustained damages at the fron portion and o/s body.

Damages Consistent

Pending repair cost from repairer



Ser e Request Details

7.4

3, 2019

ate

4, 2019

1, 2019

me

CONSULTANTS PTE OTP (DD)

135

ige.

d survey and authorize

15

ép

perform service

Iformation

phicle Registration

i. A.

Contact/Insured

AUH WO:

GARDENS, #10-02, +19957, Singapore

ndler

ine

61

@@axa.com.se

Instruction

00

	1	Invoicing		Documents	As esment	Metrics	Notes	
	alle							
					0			
SINT			2/14	4/19 4:38 PM				
			ANG	3 Yvonne				
			MEC	HANICAL ISSUE				
			Made	sc comment on m	echanical issue, T	hanks		

Sec.

VISHNU B THAM Shekhar

From: Allin Quek <alan.quek@cyclecarriage.com.sg>

Sent: Thursday, February 14, 2019 2:46 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey

Subject SDS/BD Own Policy Claim

Attach ent. mg-214144227-0001.pdf, SDS78D.PDF

Categories: SHEICHAR

Dear Officer

Car is in 188 Fandan Loop Cycle & Carriage, kindly arrange for own policy claim survey. Thank you.

Your

Alan

Servi

Merca 3 3 3 3 3 4 5 6 7

Cycle Industries Press

188 P Service Cente

Tel: 6 DID: 9186 5117 872 1272

Web- mercedes-benz



tional Journeys



CYCL RIAGE

4

the environment. ______ this e-mail.

DISCLAIM Re-This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly professed. If you have received this email in error, please notify us immediately by return email and destroy the maginal message. Any views expressed are those of the individual sender, and not necessarily the views of views of views and views expressed are those of the individual sender, and not necessarily views of v

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	5428F	
Vehicle Details		
Vehicle No.:	SDS78D	
Vehicle to be Exported:	No	
Intended Deregistration Date:	28 Feb 2019	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	E 250	
Primary Colour:	Silver	
Manufacturing Year:	2011	
Engine No.:	27186030235618	
Chassis No.:	WDD2120472A448668	
Maximum Power Output:	150.0 kW (201 bhp)	
Open Market Value:	\$52,881.00	
Original Registration Date:	02 Sep 2011	
First Registration Date:	02 Sep 2011	
Transfer Count:	2	
Actual ARF Paid:	\$52,881.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	01 Sep 2021	
PARF Rebate Amount:	\$31,728.00	
Intended COE Rebate Details	un acceptual	
COE Expiry Date:	01 Sep 2021	
COE Category:	E - Open Category	
COE Period(Years):	10	
QP Paid:	\$65,490.00	
COE Rebate Amount:	\$16,390.00	
Total Rebate Amount:	\$48,118.00	
The information contained berein is correct as at 14 Feb 201	19	

The information contained herein is correct as at 14 Feb 2019

OK



Login Sign up

New Cars

Sell My Car

Directory

Products

Insurance

Articles

Farum

Resources

Learn from Jim Rogers Free

Signup to our online sun Free and limited - don't

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!



Speedo Motoring

YONG LEE SENG MOTOR PTE LTD

Browse by Category

14 vehicles

Post in Ad

e250

Ways of Selling

Search Selection

e250

Advertiser Logis

Model

Any

Depreciation Aru

2011

Eng Cap

Mileage

Veh Type

Avuilable

▼ 20 results/page

Mercedes-Benz E-Class E250 CGI Avantgarde

\$62,800

\$13,800 /yr

21-Sep-2011

1,796 cc

158,000 km

Sort by Date Posted

Luxury

Anu

Available

Section 2

Well Maintained And Its Only 1 Owner Carl High Paper Rebate To Minimize Your Losses, Bank/ In-house Loan Packages Available. Call Me For Viewing

Ka-Hup Vehicles Trading France 12-Feb-2019

Mercedes-Banz E-Class E250

01-Jan-2011

1.795 cc

137,000 km

Availlable

Control Section 1

CGI Avantgarde

\$59,888

Plercoties-Borz, E250, e250, Used Mercedes-Bend

\$17,250 /vr

Laboury

Posted 11-Feb-2019

Tagi: 2011 Mercedes-Benz E250, 2011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

Tags: 2011 Mercedos-Benz E290, 2011 manosties-benz e250, Mercedos-Benz E250, mercedos-benz e250,

Mercedes-Benz E-Class E250

\$58,800

\$15,930 Art

04-Mar-2011

1.796 cm

91,000 km

Available

CGI Coupe

Sports

Welcome, Purchase Comes With Official Warranty Certificat...

Footed: 11-Feb-2019 Tags: 2011 Mercades-Benz E250, 2011 monades-benz e250, Mercades-Benz E250, monades-benz e250, Marcades-Benz, E250, e250, Used Mercades-Benz

High Lisan Available, Price Stated Above Is Actual Selling Price, Low Mileages, Good For Further CDE Renewal, Accident-Free, STA Evaluation Are

COE)

Mercedes-Benz E-Class E250 CGI Cabriolet (New 10-yr

\$105,800

\$10,570 AT

21-Feb-2011

1.796 cc

94,000 km

Sports

Available

Very Worthy Buy, Only \$10500 Per Year For A E250 Cabriolet, Option For Non Renew CDE, Very Mice Condition With Accident Free, Immediate Transfer When Delivery Buy With Worries Free.

Grande Auto Credit Posted: 10-Feb-2019

Tags: 2011 Morcedes-Benz E250, 3011 mercedes-benz e250, Mercedes-Benz E250, mercedes-benz e250, Mercedes-Benz, E250, e250, Used Mercedes-Benz

GET YOUR RENEWAL

LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Mercedes-Benz E-Class E250

\$66,900

\$16,490 /yr

29-Apr-2011

118,698 km

Available

(We Assure 100% Genuine Mileage,) Original Condition, Beautiful White Cabriolet Mercedes Benz E250 AMG. This Sporty Car Always Give You An Attractive And Charming Look, Very Well Maintained. Accident-...

Festes 09-Feb-2019 Tags: 3011 Mercedes-Benz £250, 2011 marcedes-Benz Mercedes-Benz £250, e250, Used Mercedes-Benz ies-Beez £250, 2011 marcedes-berz e250; Hercodes-Berz £250, marredes-berz e250.



Mercedes-Benz E-Class E250 CGI Avantgarde

\$57,800

31-Mar-2011

1,796 cc

78,000 km

Limitry

Available

Rare High Specification Option Unit With Only 1 Careful Owner, Exterior And Interior Well Groomed By Prestige Retailer, 100% Major And Minor Accident Free With. 6 Months Road Tax And Servicing Done Bu...

\$14,000 /уг

Poetad DR-Feb-2019 Tags: 2011 Process and EMR. 1411 merceles-benz 6250, merceles-benz

https://www.sgcarmart.com/used_cars/listing.php?MOD=e250&PRC=0&DEP=0&RGD=2011&VEH=0&AVL=2

1.4

real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All picos and other information displayed on sigCarMart.com are gathered from sources and based on algorithms that are believed by sigCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sigCarMart.com does not assume any responsibility for errors or unisseems or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2019 sgCarMart. All rights reserved.

AXA INTRANCE PTE LTD 8 Sh enth Way, #24-01 AXA TOW, Singapore 068811 Cust on #Centre #01-21 Tel:1 800804888 Fax:-Websiteww.axa.com.sg GST Returation Number: 199903512M custometare@axa.com.sg



CERTIFICATE OF INSURANCE

■ bttor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Ruks and Compensation) Rules. 1960 ■ Road Transport Act. 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO.

: VPA/P1976298

Account No. : 14077

(01)

Cwerage

: Comprehensive

Sum Insured

: Market Value At The Time Of Loss

Name of Policy Holder

: CHIA CHEOW HUA

Vehicle Registration No. : SDS78D

Period of Insurance

: From 02/09/2018 To 01/09/2019 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

(a) The Policyholder

The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner

(b) Any other person who is driving on the Policyholder's order or with his permission Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

Basic Own Damage Excess

: SGD 500.00

An Additional Excess is applicable as follows: S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver. S\$5,000.00 for Undeclared Young and Inexperienced Driver. (Please refer to your policy on the terms & conditions)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Alfa Credit Pte Lui

bull are a second

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOGIRR2 on 22/08/2018

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or distroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and emorsement etc.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 21 Aug 1990

FOR C&C USE ONLY



NP 428A

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Irritimation provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to rep udite policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Anylalse reporting may be referred to the Police for investigation.
- 6. This eport will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for arc#niving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

	ACCIDENT STATEMENT	
Date Of Report	14/02/2019 13:56	
Date Of Accident	13/02/2019 17:15	
Exact Location Of Accident	MARINE PARADE	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Ve hide Registration Number	SDS78D	

Instituted/Dal	Indendos	

Insured/Policyholder

Name Of Registered Owner CHIA CHEOW HUA

NRIC No S1655428F Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-98007888 Alternative Phone No. OFFICE-98007888

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model E250

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No. Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number VPA/P1976298

Cover Note Number

Driver

Name of Driver EE HOCK SENG ANDREW

NRIC No S1612280G Date Of Birth 26/08/1963 Occupation INDOOR Date Of Driving Pass 21/08/1990

Driving Experience 28 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91810939

Fax Number Contact Number

EMail Address NOEMAIL Address.

BLK 1 AMBER GARDENS #10-02

Postode

439957

W as triver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehide

.

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Ro ad Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

7 NO

Number of vehicles (Milluding own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

am bulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes,Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I ACCIDENTLY HIT ONTO RIGHT SIDE KERB WALL DAMAGING MY BOTH RIGHT TYRES. I APPLIED MY BRAKE BUT MY CAR MORE FORWARD AND COLLIDED CAR B (SGS6938Y). CAR B FRONT COLLIDED CAR C (SHD8829H) REAR. NO ONE WAS INJURE AND WE EXCHANGE PARTICULAR.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGS6938Y

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

MR CHRIS

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

SKETCH PLAN

IM PORTANT NOTICE

- 30

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (IV) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

Driver's Signature


(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name: Alan awk

NRIC/FIN No.:



() I accidently hit outo right side kend wall damaging my both right types.
(2) I apply my brake but my can more formant and callided (B) vehicle.
(3°B) rehicle frat collided (c) rehicle hear.
(9No one was injure and we excharge particular

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature Date & Time

Driver's Signature

(if driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name: Alan (

NRIC/FIN No .:

Quek



AXA INSURANCE SINGAPORE PTE LTD

1800-880 4888 (Within Singapore)
(65) 6880 4888 (International)

(65) 6338 2522

www.axa.com.sg

Letter of Authorisation for Lump Sum Repair

I, [Name] [NRIC] <u>CHIA CHEOW HUA</u>, the owner of vehicle [no.]
 SDS 78D ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.

- The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorisation for lump sum repair for the Vehicle.
- 3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
- 4. I am aware that AXA Insurance Singapore Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorised.

Signed and acknowledged by:

Signature of policyholder

Date: 18-02-19

Name and signature of workshop personnel including workshop stamp Date:



ESTIMATE FOR SDS78D

Cycle & Carriage Industries Pte Limited

Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Ms Chia Cheow Hua

Blk 1 Amber Gardens #10-02

Singapore 439957

64400878

2

Vehicle & Document Information

WIP No

Reg No/Reg Date Date In/Mileage

Chassis No Engine No

Make/Model

Colour/Trim

30873

SDS78D

/ 02/09/2011

- 1- 0

WDD2120472A448668

27186030235618

MB/E 250 CGI SEDAN (W212)

027 775 Iridium sil/ 042 201 Black

Account No	Terms	Date/Time Prin	nted	CSE	Operator				
WCV31535	CRDVCH	14/02/2019/	14:35	AQ	305 / Alan Quek Ai Lur	1			
		Descriptio	n of Good	s / Services		Qty	Unit Price	Disc%	Amount
DATE IN	/EXCESS DATE SURVE		98 // 13- // TBA	-02-2019	FFICIAL	TA	XX II	٧V	OICE
BY/AUTHR A BPILAB	IZED ON	:				1	2	0.10	380.00
USE XENT		K CONTROL UNI	ITS & RES	SET MEMORY T	0	3/6	2		
S BPNSUB	SETTINGS.	NE II			2 71	11	-		Mes/ 60.00
	PC REG. P	LATE WITH HOU	USING.NET	TT	7 1/1 /	1 7			. /
THE RESERVE AND ADDRESS OF THE PARTY OF THE	ORDER NO:				~ 181 PM	0			7.3 05900
S BPNSUB	TRANSCER	1PC FRONT RIG	CUT TYPE	E IDC BEAD	18/11/1				7.2 968.00
RIGHT TY		IFC FROM KI	ant time	a trusten	111/2/11-				67
A BPILAB	116			12/	11810				540.00
	& CONDUCT	WHEEL ALIGNME	ENT NETT	- //	D		anci	117	100
A BPILAB				7) 12			xan (gl	wh).	1910 2480.00
	INSTALL F	RONT SUSPENS	TON & WHI	EEL BASE					120.00
A BPILAB			origin as					100	120.00
	ADLAMP, WIT	TH FOCUS ADJUS	STHEM! . WI	11				100	/CVC 1920.00
A BPILAB	DEDLACE E	RONT BUMPER I	E DEMOVE	FRONT SUPPO	DT:				
4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	PONENTS &		a hinori	Thom: Joire				1	
A BPIRES	a sincinia a	100000000000000000000000000000000000000							1200.00
	FRONT BUMP	PER & FRONT BO	ONNET						/
S BPNTOW									
	11 - 11 - 11 - 11 - 11	ROM MARINE PAR	RADE RD	TO PLSC					130
	NG DOLLEY								
WO: 160:	PP	41				1.00	1105.12	00.00	1105.12
M LH/F HEA	SECTION ST.	ca!				1.00	1105.12		1105.12
M RH/F HEA		ex/				1.00	1183.82	00.00	1183.82
M DARTATAL						4 1 9 9	16.47		16.47

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quota, This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or demaged parts are discovered after work has started and needed for repairs or replacement. However, should this occurwe would advise you. Flease be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or choque. You must also agree to pay full amount for renowal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128376 Tel: 6777 E388 Fax: 6779 5383 www.mercedes-benz.com.sg



ESTIMATE FOR SDS78D

Cycle & Carriage Industries Pte Limited Authorised Desler Company No. 196400367W GST Reg No. MR-#500111-X

Ms Chia Cheow Hua

Blk 1 Amber Gardens #10-02 Singapore 439957

64400878

Vehicle & Document Information WIP No

30873

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

/ 02/09/2011 SDS78D

0 - 0 -

WDD2120472A448668

27186030235618

MB/E 250 CGI SEDAN (W212)

027 775 Iridium sil/ 042 201 Black


M. BONNET STAR 84	Account No	Terms	Date/Time Printed	CSE	Operator				
BONNET STAR 1,00	WCV31535	CRDVCH	14/02/2019/ 14:35	AQ	305 / Alan Quek	Ai Lun			
M BIDNNET SEAL (## 1.00 21.20 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1449.20 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1469.24 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.00 1669.20 00.0				s / Services			LEGISLA CONTRACTOR		Amount
M FRT BUMPER GARNISHA M HA/F BUMPER GARNISHA M CT/F BASIC MOUNTING FOR BUMPER GARNISHA M FRT CROSS MEMBER GARNISHA M FRT C	M BONNET ST			61.00	PERMIS				101.50
LH/F BUMPER GARNISHA 1.00				NO	4/8				21.20
RH/F BUNDER GARNISH	FRT BUMP	ER DE	11.		Mine				1469.24
CT/F BASIC MOUNTING FOR BUMPER Sw. Lh/F BASIC MOUNTING FOR BUMPER 1.00 70.54 00.00 70.54 00.00 110.24 00.00 110.24 00.00 110.24 00.00 110.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.00 120.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.24 00.2	H LH/F BUMP	PER GARNIS	HA -		1 11				85.83 85.83
RH/F BASIC MOUNTING FOR BUMPER RH/F PASIC MOUNTING FOR BUMPER RH/F BASIC MAPPER RH/F BA	H KH/F BUM	PER GARNIS	e con number 144	0	1 11.0			1000 1100 1000 1000	74.92
RH/F BASIC MOUNTING FOR BUMPER 1 TO 100 70.54 00.00 CT/F PARKING SENSOR SEAL 7 CT/F PARKING SENSOR SEAL 7 LICENSE PLATE BASE CA 1.00 184.82 00.00 ET/F PARKING SENSOR SEAL 7 LICENSE PLATE BASE CA 1.00 184.82 00.00 ET/F BASIC MEEEL 1.00 71.55 00.00 FRT CROSS MEMBER 7 FRT END SUPPORT MEMBER 7 FRT END SUPPORT MEMBER 7 FRT END SUPPORT MEMBER CLAMP RH/F DISC WHEEL 1.00 609.02 00.00 RH/F DISC WHEEL 1.00 609.02 00.00 RH/F SHOCK-ABSORBER 7 FRT TORSION BAR 7 RH/F SHOCK-ABSORBER 7 FRT TORSION BAR 7 RH/F STEERING KNUCKLE 7 RH/F STEERING KNUCKLE 7 RH/F STEERING KNUCKLE 7 RH/F MHEEL HUB 8 RH/F STEERING KNUCKLE 7 RH/F BALL JOINT 7 RH/F TRUST ARM 1.00 1261.19 00.00 RH/F TRUST ARM 1.00 143.81 00.00 RH/F TRUST ARM BUSHING 7 STEERING ASSEMBLY 7 Confirmed & accepted by Nett 29.7 Confirmed & accepted by	I LIVE BAS	IC MOUNTIN	C FOR BUMPER A SE	c (/.	111			Company of the second second	70.54
CT/F IMPACT ABSORBER CA CT/F PARKING SENSOR CT/F PARKING SENSOR SEAL			d run dunren .		suc				70.54
CT/F PARKING SENSOR SEAL CT/F PARKING SENSOR SEAL LICENSE PLATE BASE CT/F BOTTOM GRILLE FRT CROSS MEMBER FRT CROSS MEMBER FRT END SUPPORT MEMBER FRT END SUPPORT MEMBER FRT END SUPPORT MEMBER FRT END SUPPORT MEMBER FRT TORSION BAR RH/F DISC WHEEL TOO RH/F SHOCK-ABSORBER FRT TORSION BAR RH/F STEERING KNUCKLE RH/F STEERING KNUCKLE RH/F STEERING KNUCKLE RH/F BALL JOINT RH/F BALL JOINT RH/F TRUST ARM TOO RH/F TRUST ARM TOO RH/F STEERING ASSEMBLY AID OUCK CT/F BOTTOM GRILLE TOO TOO TOO TOO TOO TOO TOO			o toll boile bit	1	in amionis			2011/01/01/01	110.24
CT/F PARKING SENSOR SEAL LICENSE PLATE BASE 100.00 LICENSE PLATE BASE 200.00 LICENSE 200.00 LICENSE PLATE BASE 200.00 LICENSE 200.00 LICENSE 200.00 LICENSE PLATE 200.00 LICENSE 20			200	1 +	4 1001-00				1421.68
LICENSE PLATE BASE 1.00 184.82 00.00	CT/F DAD	VING SENSO	D SEAL & 7 AM		10			G1453 1537 3 3 5 5 1	28.72
## FRT CROSS MEMBER ## 1.00	H I TENSE	DI ATE BASE	.01		1 James			3 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1	184.82
FRT CROSS MEMBER 87 7 8 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CT/F BOT	TOM COTILE	# 2. CAL	75	10 may			T 121.7 (45.17.1)	71.55
FRT END SUPPORT MEMBER CLAMP FRT END SUPPORT MEMBER CLAMP RH/F DISC WHEEL RH/F DISC WHEEL RH/F SHOCK-ABSORBER FRT TORSION BAR RH/F TORSION BAR RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER FRT TORSION BAR RH/F SHOCK-ABSORBER FRT TORSION BAR RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER FRT TORSION BAR RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER RH/F TORSION BAR RH/F SHOCK-ABSORBER	The state of the s		701/	-55	1111111111			100	546.09
RRI/F DISC WHEEL RRI/F DISC WHEEL RRI/F SHOCK-ABSORBER RRI/F SHOCK-ABSORBER RRI/F STEERING KNUCKLE RRI/F HIBEL HUB RRI/F STEERING KNUCKLE RRI/F HIBEL HUB RRI/F STEERING KNUCKLE RRI/F LOWER ARM 1.00 109.57 00.00 1.00 1261.19 00.00 1.00 747.27 00.00 1.00 502.50 00.00 RRI/F RRIST ARM 1.00 502.50 00.00 RRI/F TRUST ARM 1.00 517.64 00.00 RRI/F TRUST ARM BUSHING STEERING ASSEMBLY 7 Confirmed & accepted by Nett 29.7				-11	1 / 1/19 BITH			And the same of the same	155.54
RH/F DISC WHEEL RH/F SHOCK-ABSORBER RH/F TORSION BAR RH/F TORSION BAR ROD RH/F STEERING KNUCKLE RH/F STEERING KNUCKLE RH/F HEEL HUB RH/F TRUST ARM RH/F TRUST ARM STEERING ASSEMBLY Alan Quek Cycle & Carriage Industries Fie Ltd Hody Care & Repair Center DID: 6771 4377 HP: 9186 5112 Fax: 68721272 Empili elanary state; yelcarriage cornes Nett 29,7				- // /	2/05/15/6/210	1.00			42.09
RH/F SHOCK-ABSORBER RH/F SHOCK-ABSORBER RH/F TORSION BAR ROD RH/F TORSION BAR ROD RH/F STEERING KNUCKLE RH/F STEERING KNUCKLE RH/F LOWER ARM RH/F LOWER ARM RH/F LOWER ARM RH/F TRUST ARM RH/F TRUST ARM BUSHING STEERING ASSEMBLY 7 Confirmed & accepted by RH/F Olick RH/F RUST ARM RH/F TRUST ARM BUSHING RH/F RUST ARM RUSHING RH/F RUST ARM RH/F RUST				2 17		1.00			609.02
RH/F TORSION BAR ROD 7 RH/F STEERING KNUCKLE 7 RH/F STEERING KNUCKLE 7 RH/F WHEEL HUB 7 RH/F LOWER ARM 7 RH/F LOWER ARM 7 RH/F TRUST ARM 7 RH/F TRUST ARM 8USHING 7 RH/F TRUST ARM BUSHING 7 RH/F TR				2) 0	1	1.00			609.02
## RH/F TORSION BAR ROD ### RH/F STEERING KNUCKLE ### RH/F WHEEL HUB ### RH/F WHEEL HUB ### RH/F LOWER ARM ### RH/F LOWER ARM ### RH/F LOWER ARM ### RH/F TRUST ARM ### RH/F TRUST ARM BUSHING ### RH/F TRUST ARM BUSHING ### BUSHING ### RH/F TRUST ARM BUSHING ### BUSHING ### RH/F TRUST ARM BUSHING ### RH/F TRUST ARM BUSHING ###	M RH/F SHOO	CK-ABSORBE	R 7	1	en by pour	1.00		00.00	856.0
## RH/F TORSION BAR ROD ### RH/F STEERING KNUCKLE ### RH/F WHEEL HUB ### RH/F WHEEL HUB ### RH/F LOWER ARM ### RH/F LOWER ARM ### RH/F LOWER ARM ### RH/F TRUST ARM ### RH/F TRUST ARM BUSHING ### RH/F TRUST ARM BUSHING ### BUSHING ### RH/F TRUST ARM BUSHING ### BUSHING ### RH/F TRUST ARM BUSHING ### RH/F TRUST ARM BUSHING ###				Ka	7-6	1.00			479.05
Alan Quek Oyer & Carriage Industries Pie Ltd Hody Care & Repair Center DID: 6777 4377 HP: 9186 5112 Fax: 6872 1272 Emails elan making y sleet mings corner Confirmed & accepted by Nett 29,7			000			1.00			109.57
Alan Quek Oyer & Carriage Industries Pie Ltd Hody Care & Repair Center DID: 6777 4377 HP: 9186 5112 Fax: 6872 1272 Emails elan making y sleet mings corner Confirmed & accepted by Nett 29,7				T	1001-111V	1.00	1261.19	00.00	1261.19
Alan Quek Oyer & Carriage Industries Pie Ltd Hody Care & Repair Center DID: 6777 4377 HP: 9186 5112 Fax: 6872 1272 Emails elan making y sleet mings corner Confirmed & accepted by Nett 29,7			10.0	1	ACCID. 30	1.00		00.00	747.27
Alan Quek Cycle & Carriage Industries Pie Ltd Hody Care & Repair Center DID: 6777 4377 HP: 9186 5112 Fax: 6872 1272 Emails elangraking y sleet mings cornes Nett 29,7					20 004	1.00		00.00	502.50
M STEERING ASSEMBLY 7. 1.00 111.45 00.00 8012.26 00.00 8 1.00 8012.26 00.00 8 1.00 8012.26 00.00 8 1.00 8012.26 00.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1.00 8 1					Double	1.00	143.81	00.00	143.8
Alan Quek Oyer & Carriage Industries Pie Ltd Hody Care & Repair Center DID: 6777 4377 HP: 9186 5112 Fax: 6872 1272 Emails elan making y sleet mings corner Confirmed & accepted by Nett 29,7	A RH/F TRUS	ST ARM ?			Chrani	1.00	517.64	00.00	517.64
Afan Quek Cycle & Carriage Industries Pie Ltd Hody Care & Repair Center DID: 6771 4377 1(P: 9186 5112 Fax: 6672 1272 Email: alanguakida yakut magazamas Confirmed & accepted by Nett 29,7			HING -			1.00	111.45	00.00	111.45
Alan Quek Cycle & Carriage Industries Pie Ltd Hody Care & Repair Center DID: 6771 4377 1(P: 9186 5112 Fax: 6672 1272 Email: alanguakida yakumaga zomag Confirmed & accepted by Nett 29,7	The second secon		_			1.00	8012.26	00.00	8012.26
Confirmed & accepted by Nett 29,7			DID: 6	Cycle & Carriag Hody Care 6 771 4377 HP: 9	pe Industries Pie Lid & Repair Center 7186 5112 Faxt 6872 12	172	30,810.	71	
Nett 29,7	Confirmed &	accepted by							
		made Marian S				7% G	ST on 29		29,789.65 2085.28
Total Payable 31,8							200 12	100	31,874.93

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Flease be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or chaque. The must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber small or other repair requiring

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



the removal of the windscreen.



ESTIMATE FOR SD\$78D

Finalization

Cycle & Carnage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. M9-6300111-X

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811 068811 63387288

WIP No Reg No/Reg Date

Date In/Mileage

Engine No

Colour/Trim

30873

SDS78D

MB/E 250 CGI SEDAN (WZ12)

Vehicle & Document Information

027 775 Iridium s11/ 042 201 Black

/ 02/09/2011

19/02/2019/-82232-WDD2120472A448668 Chassis No 27186030235618

Make/Model

Date/Time Printed CSE Operator Account No Terms

305 / Alan Ouek At Lun 20 /02 /2010 / 21.35

CS100001	Cash	29/03/2019/ 21:35	305 / Alan Quek Al	Lun			
a Surviva	DESCRIPTION DE	Description of Goods / S	orvices Control of the Control	Oty	Unit Price	Disc%	Amount
DATE IN	NO ACC DAT WEXCESS DATE SURV	EY:15-02-2019 // LKK RASU	OFFICIAL	TA	II XA	VV	DICE
A BPILAB USE XEN		:LKK VERON // 19-02-201 CK CONTROL UNITS & RESET		25		0.10	380.0
S BPNSUB	D SETTINGS	-NET	~ ~	11 11	1	- 1	60.0
	1 PC NO PL	ATE	7 1	11 1			503500
S BPNSUB			~ [N 12]	U			672.0
SUPPLY A BPILAB	& INSTALL	2 PCS MICHELIN NEW TYRES	MINIM				540.0
	& CONDUCT	WHEEL ALIGNMENT NETT	201111111111111111111111111111111111111			- 1	
A BPILAB			11 11770				120.0
	EADLAMP WI	TH FOCUS ADJUSTMENT MET	11 2			- 1	1440.0
A BPILAB REMOVE ASSY CO	& REPLACE	FRONT BUMPER & REMOVE FRO	NT SUPPORT				1440.0
A BPIRES						- 1	1200.0
	FRONT BUY	PER A FRONT BONNET	a control of the state of the state of the	hii nasansad	NEW YORK PLOY	Stylens in	Comments
	T TOWING F	ROM MARINE PARADE RD TO P	LSC			10.7	130.0
WO: 160	1303						-500.0
X BPNEXC	CE EXCESS					- 1	-300.0
X LH/F HE	men militarian			1.00	1105.12		1105.1
X RH/F H				1.00	1105.12		1105.1
X RADIATO	R GRILLE			1.00	1183.82		1183.8
And the second second	R GRILLE	SRACKET		1.00	16.47		16.4
X BONNEY				1.00	101.50	F. C.	101.
X BONNET	SEAL			1.00	21.20	00.00	21.


Confirmed & accepted by

Authorized signatory and company stamp

Validity of this satisate is 14 days from date of quote. This is a computer generated document, so atgnature is required. extincted thats torted are, entireling (3), we would recrise that the above notinees to beset of our teleful temperature and may be tended any application parts or labour which may be retained after repair more has desembled. Seagriculty mans or discount parts are discounted ofter working granted and pended for repairs or replacement. Season, should this occur. we would advise you. Finese be informed that a deposit of SOE of the above extincts to payable before commencement of the work. Fayment for this may be made in cash, credit card ar chaque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertant breakage to the course of renewing the public seal or other repair requiring the renoval of the windscreen.

> Pandan Loop Service Center 198 Pandan Loop Singapore 12ft378 Tel: 6777 8388 Fax: 6779 5383 w.mercedes-benz.com.eg





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SDS78D

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811 068811 63387288

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

30873

/ 02/09/2011 SDS78D

19(02/2019/-82231-WDD2120472A448668

27186030235618

MB/E 250 CGI SEDAN (WZ12)

027 775 Iridium sil/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator				
CS100001	Cash	29/03/2019/ 21:35		305 / Alan Quek A	i Lun			
		Description of Goo	ods / Services		Qty	Unit Price	Disc%	Amount
X CT/F BOTT X FRT CROSS X RH/F DISC X RH/R DISC X BRACKET	CC MOUNTINGET ABSORB PLATE BASE FOM GRILLE MEMBER WHEEL WHEEL ABSORBER B	H NOT A	ALCOHOL: UNKNOWN	FFICIA	1.00	1459 24 85.83 85.83 74.92 110.24 184.82 71.55 546.09 609.02 609.02 39.16 29.56 30.96 127.50	00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00	74.93 110.24 184.83 71.55 546.05 609.03 39.11 29.56 61.93
X PLUG	DLAMP PANE BAFFLE BN DOK		91	Ann	1.00 1.00 1.00 1.00 1.00 1.00 2.00	8.20 264.38 74.32 35.86 74.70 163.26 6.10	00.00 00.00 00.00 00.00 00.00 00.00	8.2 254.3 74.3 35.8 74.7 163.2 12.2

Asan Quek

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272 Email: alan.mak@cyclecarriags.com.sg

Confirmed & accepted by

Nott

12,312.85

7% GST on 12312.85

861.90

Total Payable

13,174.75

Authorized signatory and company stamp

Validity of this estimate is 16 days from date of quete. This is a computer generated document, as signature is required.

Estimated costs quoted are sactuding GST. We would meeting that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be recurrent after regula were has communed. Exceptionally were or emand parts are discovered after work has started and mended for regains in reclaration. Newson, should this documbe world series you. Please be informed that a deposit of the above extincts to popula before connecement of the work. Payment for this may be made in each, credit card or shows, for mich also agree to pay full amount for renowal of the windscreen in the event of inchestant breakage to the course of recoving the rubber seal or other requiring the removal of the windscreen.

> Pandan Loop Service Center 166 Pandan Loop Singapore 128378 Tel: 6777 8389 Fax: 6779 5383 www.mercedes-benz.com.sg



Cycle & Carriage Industries Pte Limited Authorized Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SDS78D

SUPPLEMENTA /

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811 068811 63387288

Rep No/Reg Date

Date In/Milesge

Chassis No.

Engine No.

Colour/Trim

27186030235618 MB/E 250 CGI SEDAN (W212)

30873

SDS78D

027 775 Iridium sil/ 042 201 Black

/ 02/09/2011

Vehicle & Document Information

19(02/2019/~82231~ g

WDD2120472A448668

WIP No

Make/Model

Account No	Terms	Date/Time Printed CS	SE	Operator			
CS100001	Cash	29/03/2019/ 21:34		305 / Alan Quek At Lun			
		Description of Goods / Ser	rvices	Qty	Unit Price	Disc%	Amount

OFFICIAL TAX INVOICE POLICY NOTACO DATE DRIVE THYEXCESS

DATE IN/DATE SURVEY:15-02-2019 // LKK RASUL :LKK VERON // 19-02-2019 BY/AUTHRIZED ON

BRACKET

SUPPORT ABSORBER BRACKET

BONNET HOOK

TOP FAN SHROUD

PEUD

LH/F HEADLAMP PANEL

TOP AIR BAFFLE

GUIDE SIGN

SAFETY HOOK

AIR DUCT

ROTARY CATCH

.00 1,00 200 1.00 1.00 1.00 2.00

27.50 00.00 8.20 00.00 264.38 00.00 74.32 00:00 35.86 00.00 74,70 00.00 163.26 00.00 6.10 00.00

39.16 00.00

29.55 00.00

30.96 00.00

CRA/ 74.32 M 74.70 CAN 163.26 12.20

39.16 CAR 29.56 M 61.92

CRA/127.50

ALC 8.20

M/ 264.38

SUPPLEMENTA. /

Alan Quck Cycle & Carriage Industries Pte Ltd. Body Care & Repair Center DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: ulan.quek@cyclecariage.com.sg.

Confirmed & accepted by

Nett

891.06

7% GST on

891.06

62.37

Total Payable

953.43

Authorized signatory and company stamp

valisity of this estimate is 14 days from date of quote, This is a computer generated document, as eignature is required, Estimated coats quoted are excluding GST. We would mention that the shows actions is head on our intifal inspection and does not include required after repair work has cummenced. Occasionally were or damaged parts are discovered after work has started and needed for repairs or replacement. However, showld this occur, we would advise you. Please he informed that a depualt of 60% of the above extinuis is payable before comsencement of the work. Payment for this may be made in cash, credit card or chapts. You must also agree to pay full amount for ranges of the winderroom in the event of inadvertent breakage in the course of redewing the rubber seed or other repair requiring the removal of the windstreen.

Pandan Loop Service Center 188 Pandon Loop Singapore 128376 Tel: 6777 8358 Fax: 6779 5383 www.mercedes-benz.com.st

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Friday, 5 April 2019 2:12 PM

To:

'Dennis Yap'; Rasul (LKKAuto); Alan Quek; SUR

Subject:

RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan.

Confirmed finalize amount \$12,812.85 before excess \$500 @ 6 working days.

Kindly forward invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Dennis Yap <dennis.yap@cyclecarriage.com.sg>

Sent: Thursday, 4 April 2019 5:57 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Alan Quek <alan.quek@cyclecarriage.com.sg>

Cc: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Rasul,

Photos as requested

With thanks & best regards
Dennis Yap
Technical Executive
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center

TEL: 67778388 | DID 67714434 | HP 94506582 Wedsite: www.mercedes-benz.com.sg

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]

Sent: Thursday, 4 April, 2019 5:41 PM

To: Alan Quek; Dennis Yap Cc: Veron Chen (LKKAuto)

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Alan,

Kindly forward to me the supplementary and check item damage photos

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





LKK Save the Earth Print only when necessary

From: Alan Quek [mailto:alan.guek@cyclecarriage.com.sg]

Sent: Tuesday, 19 February, 2019 9:21 AM

To: Veron Chen (LKKAuto); SUR

Cc: Rasul (LKKAuto)

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron,

LUM SUM where got supplementary or add on. Anything above the repair limit we will absorb the cost.

Your Sincerely

Alan Quek Service Advisor Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd 188 Pandan Loop Service Center Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Tuesday, 19 February 2019 9:12 AM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan,

As instructed by our client, please proceed to repair the insured vehicle SDS 78D Lump Sum repair not exceeding \$22,000/- or which ever lower (Excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek <alan.guek@cyclecarriage.com.sg>

Sent: Monday, 18 February 2019 3:31 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com >; SUR < sur@lkkauto.com >

Cc: Rasul (LKKAuto) < Rasul@lkkauto.com > Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron,

Attached is the letter. Kindly assist to authorise repair and LUM SUM repair amount agree by AXA. Thank you.

Your Sincerely

Alan Quek
Service Advisor
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

00



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 18 February 2019 1:40 PM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan,

Refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek <alan.quek@cyclecarriage.com.sg>

Sent: Monday, 18 February 2019 1:30 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com >; SUR < sur@lkkauto.com >

Cc: Rasul (LKKAuto) < Rasul@lkkauto.com > Subject: RE: SDS 78D-DOA: 13/2/2019 (AXA OD)

Hi Veron,

You may consider LUM SUM repair at \$22K, I may forward me the LUM SUM agreement form, I will get your insured to sign and forward back to you.

Your Sincerely

Alan Quek
Service Advisor
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

Treasure Military



Exceptional Journeys





Please consider the environment before printing this e-mail.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 18 February 2019 1:26 PM

To: Alan Quek; SUR Cc: Rasul (LKKAuto)

Subject: SDS 78D-DOA: 13/2/2019 (AXA OD)

Dear Alan,

Kindly check vehicle able to repair at part by part not exceeding \$22,000/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.