



AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 Shenton Way #07-16
Singapore 079120

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : **SLN4736T**
CHASSIS NO : KPT30B1USGP105403
ENGINE NO : 67391002034397
MAKE / MODEL : SSANGYONG TIVOLI 1.6D 6AT 2WD ESP E5
DATE OF ACCIDENT : 02.02.2019 @ 01:30HRS
YOUR INSURED VEHICLE NUMBER : SLG9261A

Resue
Hp 90010068
3 days
L/S
19/02/19 @ 1555
Resueing after repair

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
FRONT BUMPER UPPER <i>SCA</i>	1pc	\$ 898.00	\$ 898.00
FRONT BUMPER LOWER LH <i>SCA</i>	1pc	\$ 350.00	\$ 350.00
FRONT BUMPER CLIPS <i>SCA</i>	1set	\$ 30.00	\$ 30.00
FRONT LH BUMPER SIDE RETAINER <i>X</i>	1pc	\$ 45.00	\$ 45.00
FRONT BUMPER SPONGE <i>?</i>	1pc	\$ 115.00	\$ 115.00
	Total	\$	1,438.00
	ADD 10%	\$	143.80
	TOTAL PARTS	\$	1,581.80

LABOUR CHARGES

TO REMOVE, REPLACE & REPAIR ALL DAMAGES PARTS DUE TO ACCIDENT	\$	1,050.00 <i>350</i>
TO SPRAY PAINT ON THE AFFECTED AREAS DUE TO THE ACCIDENT	\$	300 <i>300</i>
TOTAL LABOUR	\$	1,350.00

SUB TOTAL \$ 2,931.80

LABOUR : \$350 per day
SPRAY PAINT : \$300 per panel

Prepared By : -

RAJ

Motor Claims

TEL: 6571 9635 FAX : 6278 5535

EMAIL: lynn@motorway.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are subject to "without Prejudice" basis
- No illegal modification allowed
- Supplemental claims are subject to resurveyed and is subject to the Motorway Insurance Company

Acknowledged:

Signature:

Date: