

Surveyor
CWS

Kenneth

ASSIGNMENT (Office)

From (Person)

Eileen Lee

of

FCI

Date/Time

5:05pm @ 14/2/19

Estimated Cost

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLE 310/D

Insured

SHC8018L

at Workshop n/a

Boeki Auto

Tel

64521574

of

Blk 10, Sin Ming Ind. Est. Sec-C #01-12

Policy No.

Claim No.

019001058MFSTH

Sum Insured

Excess:

Make of Veh.

(Client's Record)

D.O.A

6/2/19

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement

15/2/19

Date/Time

5:30pm @ 14/2/19

Person Contacted

Anna

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

20/2-@12:10pm Replied via email.

ISS. REC. BY:

REF: F021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Boeki

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

23K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

DS

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCE 31010

Yr Regn:

12, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

c.c

1797

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

230284

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZG E20 0039745

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

8/12/19

D.O.A.

15/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

L124 85507 Cabernet (Red: 0574.27, 65%)

MV: 23,000/-

CTA: 8 14781-

NV: 88224-

RECEIVED 21 FEB 2019

Date/Time, File Pass to?

21/2/2019

Date/Time, File Return to?

2)

☐

: Prell. Report

☒

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + R/S. \$

Fictos

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

50507

4x15 = 60

170 + 60

50

50

21

351



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001058MFSH

Date: 20/2/2019

Our Ref: CS/FCI19002918/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 3101D

Please be informed that we had conducted the inspection of the abovementioned vehicle
15/2/2019 at the premises of M/s Boeki Auto have the following to report: -

Workshop Estimate Amount	: S\$ <u>14,624.27</u>
Revised Estimate Amount	: S\$ <u>6,253.26</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-02-2019	Our Ref No. D19001058MFSH
Accident Date	06-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8018L	Third Party Vehicle. SLE3101D
Survey Location	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-12	
Contact Person.	ANNA CHUA	
Contact No.	64521574/ 98766876	Fax No. 64521576
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BOEKI AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 20 February 2019 12:10 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001058MFSH/1
Attachments: PRELI ADVISED SLE 3101D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLE 3101D**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 15 February 2019 11:00 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001058MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 14 February 2019 5:05 PM
To: ASSIGNMENTS@LKKAUTO.COM

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No.: M4-0006529-2

Print Date/Time : 12 Feb 2019 / 15:12:02

Receipt Date/Time : 12 Feb 2019 / 15:12:02

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190212-002240

Previous Receipt No.:

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHC8018L

As at 06 Feb 2019/11:30:00

Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED

1 Insurance Enquiry - SHC8018L
Enquiry Fee
20190212151053055497

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

TP Search For SLE3101D

TP19-004

Paid By

xxxxxxxxxxxx8261 Credit Card:
Visa/MasterCard

Total	7.45
Cash Change	0.00
Tendered Amount	7.45
Excess Refundable Amount	0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

INFORMATION REQUESTED

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT, THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

**Business Profile (Company) of ASCENDANT CARS & RENTAL PTE. LTD.
(201425372K)**

Date: 12/02/2019

The Following Are The Brief Particulars of :

Registration No.	201425372K
Company Name.	ASCENDANT CARS & RENTAL PTE. LTD.
Former Name if any	
Incorporation Date.	28/08/2014
Company Type	EXEMPT PRIVATE COMPANY LIMITED BY SHARES
Status	Live Company
Status Date	28/08/2014
Principal Activities	
Activities (I)	RENTING AND LEASING OF PRIVATE CARS WITHOUT OPERATOR (77101)
Description	
Activities (II)	PASSENGER LAND TRANSPORT N.E.C. (EG PRIVATE CARS FOR HIRE WITH OPERATOR AND TRISHAWS) (49219)
Description	

Capital

Issued Share Capital (AMOUNT)	Number of Shares *	Currency	Share Type
80000	80000	SINGAPORE, DOLLARS	ORDINARY

* Number of Shares includes number of Treasury Shares

Paid-Up Capital (AMOUNT)	Number of Shares	Currency	Share Type
80000		SINGAPORE, DOLLARS	ORDINARY

COMPANY HAS THE FOLLOWING ORDINARY SHARES HELD AS TREASURY SHARES

Number Of Shares	Currency
------------------	----------

Authentication No. : G19092710A

INFORMATIONAL DOCUMENTS

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

**Business Profile (Company) of ASCENDANT CARS & RENTAL PTE. LTD.
(201425372K)**

Date: 12/02/2019

Registered Office Address : 780D WOODLANDS CRESCENT
#15-63
WOODLANDS DEW
SINGAPORE (734780)

Date of Address : 26/06/2018

Date of Last AGM : 30/06/2016

Date of Last AR : 29/07/2016

FYE As At Date of Last AR : 31/12/2015

Audit Firms**NAME****Charges**

Charge No.	Date Registered	Currency	Amount Secured	Chargee(s)
------------	-----------------	----------	----------------	------------

Officers/Authorised Representative(s)

Name	ID	Nationality	Source of Address	Date of Appointment
Address		Position Held		
GUAN ZHIJIE	S9171653D	SINGAPORE CITIZEN	OSCARS	05/07/2016
683B EDGEDALE PLAINS #06-697 WATERWAY VIEW SINGAPORE (822683)		Director		
VINCENT RAJ S/O ARUNAN	S8226651H	SINGAPORE CITIZEN	ACRA	05/07/2016
302 WOODLANDS STREET 31 #04-269 SINGAPORE (730302)		Director		
CHOO YONG SOON (ZHU YONGSHUN)	S8606514B	SINGAPORE CITIZEN	OSCARS	28/08/2014
780D WOODLANDS CRESCENT #15-63 WOODLANDS DEW SINGAPORE (734780)		Director		
CHOO YONG SOON (ZHU YONGSHUN)	S8606514B	SINGAPORE CITIZEN	OSCARS	28/08/2014

Authentication No. : G19092710A

INFORMATION AT GLANCE

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

Business Profile (Company) of **ASCENDANT CARS & RENTAL PTE. LTD.**
(201425372K)

Date: 12/02/2019

Officers/Authorised Representative(s)

Name	ID	Nationality	Source of Address	Date of Appointment
Address		Position Held		
780D WOODLANDS CRESCENT #15-63 WOODLANDS DEW SINGAPORE (734780)		Secretary		

Shareholder(s)

Name	ID	Nationality/Place of Incorporation/Origin	Source of Address	Address Changed
Address				
1 CHOO SER LEONG	S2548504A	SINGAPORE CITIZEN	ACRA	
330 WOODLANDS AVENUE 1 #12-445 SINGAPORE (730330)				
Ordinary(Number)	Currency			
20000	SINGAPORE, DOLLARS			
2 VINCENT RAJ S/O ARUNAN	S8226651H	SINGAPORE CITIZEN	ACRA	
302 WOODLANDS STREET 31 #04-269 SINGAPORE (730302)				
Ordinary(Number)	Currency			
60000	SINGAPORE, DOLLARS			

Authentication No. : G19092710A

INFORMATION RESOURCES

WHILST EVERY ENDEAVOR IS MADE TO ENSURE THAT INFORMATION PROVIDED IS UPDATED AND CORRECT. THE AUTHORITY DISCLAIMS ANY LIABILITY FOR ANY DAMAGE OR LOSS THAT MAY BE CAUSED AS A RESULT OF ANY ERROR OR OMISSION.

**Business Profile (Company) of ASCENDANT CARS & RENTAL PTE. LTD.
(201425372K)**

Date: 12/02/2019

Abbreviation

UL - Local Entity not registered with ACRA

UF - Foreign Entity not registered with ACRA

AR - Annual Return

AGM - Annual General Meeting

FS - Financial Statements

FYE - Financial Year End

OSCARS - One Stop Change of Address Reporting Service by Immigration & Checkpoint Authority

Note :

- The information contained in this Business Profile is extracted from lodgements filed by this entity with ACRA.
- The list of officers for this entity is available for online authentication within 30 days from the date of purchase of this Business Profile. Please scan the QR code available on the last page of this profile to access the authentication page. For more information, please visit www.acra.gov.sg

FOR REGISTRAR OF COMPANIES AND BUSINESS NAMES
SINGAPORE

RECEIPT NO. : ACRA190212115531

DATE : 12/02/2019

This is computer generated. Hence no signature required.



Authentication No. : G19092710A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8606514B**



Name

CHOO YONG SOON
(ZHU YONGSHUN)

朱 勇 順

Race

CHINESE

Date of birth

18-03-1986

Sex

M

S8606514B

Country/Place of birth

SINGAPORE



5613069



NRIC No. **S8606514B**




Expiry of license

31-05-2016

APT BLK 780D WOODLANDS CRESCENT #16-63
SINGAPORE 734760

NRIC No: S8606514B

Date: 01/04/2018



> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

S372K

Vehicle Details

Vehicle No.:

SLE3101D

Vehicle to be Exported:

Yes

Intended Deregistration Date:

11 Feb 2019

Vehicle Make:

TOYOTA

Vehicle Model:

WISH 1.8S A

Primary Colour:

Silver

Manufacturing Year:

2009

Engine No.:

2ZR0516599

Chassis No.:

ZGE200039745

Maximum Power Output:

106.0 kW (142 bhp)

Open Market Value:

\$25,599.00

Original Registration Date:

17 Dec 2009

First Registration Date:

17 Dec 2009

Transfer Count:

1

Actual ARF Paid:

\$25,599.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

16 Dec 2019

PARF Rebate Amount:

\$12,799.00

Intended COE Rebate Details

COE Expiry Date:

16 Dec 2019

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$17,905.00

COE Rebate Amount:

\$1,379.00

Total Rebate Amount:

\$14,178.00

The information contained herein is correct as at 11 Feb 2019

OK

PLEASE ARRANGE TO SURVEY VEHICLE AT
BLK 10 SIN MING IND ESTATE SECTOR C
#01-12
SINGAPORE 575645

Anna Chua
BOEKI AUTO PTE LTD
TEL: 6452 1574
FAX: 6452 1576
H/P: 9876 6876

Date : 12.02.2019

To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

Owner : ASCENDANT CARS & RENTAL PTE LTD

Owner Insurance : NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate Number : 5090240588-01

Accident Date 06.02.2019

Vehicle Number : SLE3101D

Make & Model : TOYOTA WISH 1.8 S (A)

*Not withair
L1 Pny B355ok
Resony After Paint
5 days*

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	BONNET <i>861.10</i>	<i>Bul</i> \$ 1,177.51	—
1	BONNET HINGE LH	\$ <i>R</i> 88.50	X
1	BONNET HINGE RH	\$ <i>R</i> 88.50	X
1	BONNET INSULATOR	\$ <i>Sm</i> 597.54	X
10	BONNET INSULATOR CLIPS	\$ <i>Sm</i> 50.00	X
1	BONNET LOGO <i>48.00</i>	\$ <i>Sm</i> 96.80	✓
1	BONNET LOCK <i>127.50</i>	<i>D.I</i> \$ 267.54	—
1	FRONT GRILLE BASE C/W CHROME <i>327.10</i>	<i>CM</i> \$ 338.61	—
6	FRONT GRILLE CLIPS	<i>m</i> \$ 30.00	—
1	FRONT SUPPORT PANEL <i>1178.05</i>	<i>Bul</i> \$ 1,786.90	✓
1	FRONT SUPPORT PANEL TOP GARNISH	<i>Sm</i> \$ 157.81	X
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	<i>mm</i> \$ 50.00	X
1	HEADLAMP LH	<i>Sm</i> \$ 918.97	X
1	HEADLAMP RH	<i>mjm</i> \$ 918.97	✓
1	FRONT BUMPER <i>491.60</i>	<i>R</i> \$ 718.13	—
1	FRONT BUMPER RETAINER LH	<i>D.I</i> \$ 98.30	—
1	FRONT BUMPER RETAINER RH	<i>D.I</i> \$ 98.30	—
1	FRONT BUMPER BRACKET LH	<i>R</i> \$ 118.84	X
1	FRONT BUMPER BRACKET RH	<i>R</i> \$ 118.84	X
1	FRONT BUMPER REINFORCEMENT <i>384.20</i>	<i>B</i> \$ 456.57	✓
1	FRONT BUMPER LOWER CENTRE GRILLE TOP	<i>Sm</i> \$ 489.80	X
1	FRONT BUMPER LOWER CENTRE GRILLE BOTTOM	<i>Sm</i> \$ 228.81	X
1	FRONT BUMPER FOGLAMP LH	<i>Sm</i> \$ 388.10	X
1	FRONT BUMPER FOGLAMP RH	<i>Sm</i> \$ 388.10	X

PAGE : 1

Date : 12.02.2019

To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

Owner : ASCENDANT CARS & RENTAL PTE LTD

Owner Insurance : NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate Number : 5090240588-01

Accident Date 06.02.2019

Vehicle Number : SLE3101D

Make & Model : TOYOTA WISH 1.8 S (A)

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
10	FRONT BUMPER CLIPS	<i>Ne</i> \$ 50.00	✓
1	AIR CON CONDENSER	<i>Btl Pr</i> \$ 1,187.90	✓
1	AIR CON FAN MOTOR	<i>Pr</i> \$ 486.90	X
1	AIR CON FAN BLADE	<i>Pr</i> \$ 338.84	X
1	AIR CON PIPE (COND TO DRIER)	<i>Pr</i> \$ 588.90	X
1	AIR CON PIPE (COND TO COMP)	<i>Pr</i> \$ 598.51	X
1	RADIATOR	<i>Pr</i> \$ 1,748.59	X
1	RADIATOR TOP BRACKET LH	<i>Pr</i> \$ 75.80	X
1	RADIATOR TOP BRACKET RH	<i>Pr</i> \$ 75.80	X
1	RADIATOR HOSE TOP	<i>Pr</i> \$ 74.86	X
1	RADIATOR HOSE BOTTOM	<i>Pr</i> \$ 71.40	X
1	RADIATOR FAN MOTOR	<i>Pr</i> \$ 478.92	X
1	RADIATOR FAN BLADE	<i>Pr</i> \$ 175.90	X
1	RADIATOR FAN COWLING	<i>Pr</i> \$ 348.60	X
1	FRONT FENDER LH	REPAIR	
1	FRONT FENDER RH	REPAIR	
Sub Total		\$ 15,972.36	
Discount 25% on Parts		\$ 3,993.09	
		\$ 11,979.27	
Special Nett Item			
1	FRONT NUMBER PLATE & HOLDER	<i>Pr</i> \$ 45.00	✓
1	AIRCON GAS	\$ 60.00	20L
1	FRONT BUMPER PARKING SENSOR	<i>Pr</i> \$ 220.00	2005m
Sub Total		\$ 325.00	

PAGE : 2

Date : 12.02.2019

To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

Owner : ASCENDANT CARS & RENTAL PTE LTD

Owner Insurance : NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate Number : 5090240588-01

Accident Date 06.02.2019

Vehicle Number : SLE3101D

Make & Model : TOYOTA WISH 1.8 S (A)

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
Labour & Misc			
1	LABOUR TO FACILITATE REPAIR	\$ 1,000.00	6001
1	R & R AC CONDENSER INCLUDING TOP UP GAS	\$ 120.00	1001
1	R & R FRONT BUMPER PARKING SENSOR	\$ 60.00	501
1	TO CHECK & RECONNECT ALL NECESSARY WIRINGS	\$ 60.00	201
1	TO RUST PROOF ON AFFECTED AREAS	\$ 80.00	601
1	TO SPRAY PAINT ON AFFECTED AREAS	\$ 1,000.00	8801
Sub Total		\$ 2,320.00	
Grand Total		\$ 14,624.27	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19002918/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8018L	Veh. Inspected	SLE 3101D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001058MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	14/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ZGE200039745	Colour	METALLIC SILVER	
Odometer	230284	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	7 mm	
L/H Front Tyre	205/55 R16	PIRELLI	7 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/02/2019	Inspection Date	15/02/2019	
Survey held at	BOEKI AUTO PTE LTD BLK 176 SIN MING DRIVE #02-15 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 3101D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BUCKLED	1,177.51	861.10
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	88.50	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	88.50	-
1	BONNET INSULATOR	SERVICEABLE	597.54	-
10	BONNET INSULATOR CLIPS	NOT NECESSARY	50.00	-
1	BONNET LOGO	NECESSARY	96.80	48.00
1	BONNET LOCK	DISTORTED	267.54	127.50
1	FRONT GRILLE BASE C/W CHROME	CRACKED	338.61	327.10
6	FRONT GRILLE CLIPS	NECESSARY	30.00	30.00
1	FRONT SUPPORT PANEL	BUCKLED	1,786.90	1,178.05
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	157.81	-
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	NOT NECESSARY	50.00	-
1	HEADLAMP LH	SERVICEABLE	918.97	-
1	HEADLAMP RH	MTG CRACKED	918.97	918.97
1	FRONT BUMPER	BENT	718.13	491.60
1	FRONT BUMPER RETAINER LH	DISTORTED	98.30	98.30
1	FRONT BUMPER RETAINER RH	DISTORTED	98.30	98.30
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	118.84	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	118.84	-
1	FRONT BUMPER REINFORCEMENT	BENT	456.57	394.20
1	FRONT BUMPER LOWER CENTRE GRILLE TOP	SERVICEABLE	489.80	-
1	FRONT BUMPER LOWER CENTRE GRILLE BOTTOM	SERVICEABLE	228.81	-
1	FRONT BUMPER FOGLAMP LH	SERVICEABLE	388.10	-
1	FRONT BUMPER FOGLAMP RH	SERVICEABLE	388.10	-
10	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	AIR CON CONDENSER	BENT / PUNCTURE	1,187.90	1,187.90
1	AIR CON FAN MOTOR	SERVICEABLE	486.90	-
1	AIR CON FAN BLADE	SERVICEABLE	338.84	-

Report Ref No. CS/FCI19002918/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON PIPE (COND TO DRIER)	SERVICEABLE	588.90	-
1	AIR CON PIPE (COND TO COMP)	SERVICEABLE	598.51	-
1	RADIATOR	SERVICEABLE	1,748.59	-
1	RADIATOR TOP BRACKET LH	TO REPAIR SEE LABOUR	75.80	-
1	RADIATOR TOP BRACKET RH	TO REPAIR SEE LABOUR	75.80	-
1	RADIATOR HOSE TOP	SERVICEABLE	74.86	-
1	RADIATOR HOSE BOTTOM	SERVICEABLE	71.40	-
1	RADIATOR FAN MOTOR	SERVICEABLE	478.92	-
1	RADIATOR FAN BLADE	SERVICEABLE	175.90	-
1	RADIATOR FAN COWLING	SERVICEABLE	348.60	-
1	FRONT FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-3,993.09	-1,452.76
			11,979.27	4,358.26
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE & HOLDER (SN)	BENT	45.00	45.00
1	FRONT BUMPER PARKING SENSOR (SN)	DENTED	220.00	200.00
			265.00	245.00
	LABOUR			
	AIRCON GAS.		60.00	20.00
	LABOUR TO FACILIATE REPAIR.INCLUSIVE OF THE REPAIR OF BONNET HINGE LH,BONNET HINGE RH,FRONT BUMPER BRAKET LH,FRONT BUMPER BRAKET RH,RADIATOR TOP BRACKET LH,RADIATOR TOP BRACKET RH,FRONT FENDER LH AND FRONT FENDER RH.		1,000.00	600.00
	R&R AC CONDENSER INCLUDING TOP UP GAS.		120.00	100.00
	R&R FRONT BUMPER PARKING SENSOR.		60.00	50.00
	TO CHECK & RECONNECT ALL NECESSARY WIRINGS.		60.00	20.00
	TO RUST PROOF ON AFFECTED AREAS.		80.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON AFFECTED AREAS.		1,000.00	880.00
			2,380.00	1,730.00
GRAND TOTAL			14,624.27	6,333.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,050.00

Report Ref No. CS/FC119002918/Ktd3n2

MARKET VALUE: \$23,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,178.00=NETT VALUE: \$8,822.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.