

INSURANCE

INS. CASE OWNER:

CC 48111900

2474, J [unclear] s3

LKK:

IDAC:

Surveyor:

HGJ

DOI:

ASSIGNMENT

latman

Date / Time:

14/1/19
18/1/19

Registered in Meritum:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 5064H

Claim No.:

MU1902262

Name of Insured:

LTOL

Policy No.:

MLOMOD15

Insured Tel No.:

HP:

Make / Model:

HUMMER

Excess Sec II :SS

D.O.A.:

17/1/19

Place of Accident:

TL DEP HALL

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN THIAM SENG

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SKM 31510



INSRS:
WSP:
Tel:
Liability:
RMKS:

Hua Hong



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
15/1/19	Non-Reporting ltr (1st):	
15/1/19	Non-Reporting ltr (2nd):	
15/1/19	Non-Reporting ltr (Final):	
15/1/19	Notification ltr (if non-pickup):	
15/1/19	Call OI:	
15/1/19	After call ltr to OI:	
15/1/19	Documentation Check List:	Handler Typist
15/1/19	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Payment Breakdown Form:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Post-Repair Photos:	<input checked="" type="checkbox"/> <input type="checkbox"/>
15/1/19	Others:	<input checked="" type="checkbox"/> <input type="checkbox"/>

15/1/19 - Liability mandate approved. Pending finalized.

17/1/19 - Rec COR to TP (Pending LOD)

17/1/19 - File pass PT type report.

17/1/19 - Pending mandate approval

18/1/19 - settle by #3319 as per TP LOD, file pass to send BV.

OPENING DOOR.

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: [Signature]

Repair Cost: S\$ 2900/- (4 days) Reduction: EXOR 50 @ 45

FINAL SETTLEMENT Date/Time: Confirm with: Email: Call:

Final Liability: S\$ 100 (Agreed / Assessed) BOLA S/N No.: 26

Repair Cost: (w/est) S\$ 2679.00

Loss of Rental (LOR): S\$ 642.00 (4 days) X \$160.50 (w/est)

Loss of Use (LOU): S\$ - (5 x days)

Loss of Income (LOI): S\$ - (5 x days)

LOR only [checked] LOU only [] LOR + LOU [] LOR + LOI [] [Tick only one]

GIA/LTA Search: S\$ -

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/Independent)

Legal Cost: S\$ -

Total: S\$ 3319.00 Global Sum S\$:

FINAL PAYMENT Date/Time: Confirm with: Email: Call:

Payee 1: S\$ 3319.00 Name 1: Hua Hong Private Limited

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

COPY SENT 22/1/2020

Hwee die

III

19/2/19


SKM 3151D

19 Feb 2014

WRETT RESOURCES / ENA / TRV / MV
 Make / Model / No SKM 3151D
 Reg / Reg No Hua Hong
 25 D Sungai Kadut Street 1
 Date / Time
 Class / No
 Condition / Remarks
 Driver's License
 Make of Vch
 10:30am @ owner waiting

Type: Car / Cycle / Bus / Van / Lorry / Taxi / Public Motor / Truck / Trailer or
 Make Mercedes
 Color Black
 Chassis No L05346
 Engine No
 Catio WDD2120342A921738
 Gear Const Good / Fair / Poor / Burnt
 Steering Normal / Jammed / Locked / Burnt or
 Brake Normal / Jammed / Locked / Burnt or
 Blot Nil / STD A/Rim or
 Tyre Size F: 245/40 R18
 R: -

(Vehicle Condition)
 Remarks: The vehicle had commenced its repair at the time of inspection.



BS / DON / EXNOVA / GY / FS / LIZA / MIC / OHTSU SUMI / TOYO / YOKO or
 Front
 RRW 6 mm
 LRW 6 mm
 D.O.A. 13/2/19
 Survey held at Hua Hong

Net or Market Value
 R/W, Accident Report Consistent? Yes or No
 R/W, P/P Seen Consistent? Yes or No
 Est. Repair 4 days Res: Yes or No
 Est. Cost 20 % 3 Val: Yes or No
 COV / REV / REP / 24HRS / up
 Date Person Contacted Vehicle: IN / OUT

Dist. of Damages: FR / Rear / ORS / UIC / Rooftop or
 Has UIC / Chassis frame / Body Structure affected due to collision

US \$2500/- (Verify with Bryan)

(Red = \$2018.40 / 45%)

(Make use of Form by) Prel. Report
 Final Report

Days Of Repair:
 Resurvey No. of Trip:

Report Format
 Camp Site / ID / etc

Add Fee: Site Insp. 15
 Interview 15
 For a Fee 15
 Other 15

Survey Fee:
 Inspection:



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street | Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

15 February 2019

HHTPClaims19-14

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SKM 3151 D & SHA 5064 H ON 13/02/2019 ALONG CHANGI AIRPORT T1 NEAR DEPARTURE DOOR 3 AT 1055 HRS

Insured : HUA HONG PTE. LTD.
Vehicle Registration No : SKM 3151 D
Vehicle Make : MERCEDES-BENZ
Vehicle Model : E200 SEDAN (R18)
Vehicle Chassis No : WDD2120342A921738
Policy No : 5087272209-01
Date of Accident : 13/02/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Door (LH) <i>DI</i>		\$ 1,820.00 ✓
2	1	Rear Door Protector (LH) <i>NEC</i>		\$ 145.00 ✓
				\$ 1,965.00
			Less 10%	\$ (196.50)
				\$ 1,768.50
3	1	Rear Sport Rim (LH) <i>Repair</i>	NETT	\$ 950.00 ✗
		To dismantle & change rear LH door, knocking & pull straight rear LH fender and all area affected by accident		\$ 750 900.00 ✓
		To perform wire checking		\$ 20.00 ✓
		To dismantle & refit rear cushion seat, inner trim to facilitate repair		\$ 50 100.00 ✓
		To dismantle & refit rear RH door fitting and mechanism to new door		\$ 50 60.00 ✓
		To dismantle & refit rear LH sport rim		\$ 20.00 ✓
		To perform 4 wheel alignment		\$ 60 100.00 ✓
		To spray rear LH door, rear LH fender and touch up rear bumper	<i>500</i>	\$ 450 600.00 ✓
				\$ 4,518.50
			7% GST	\$ 316.30
			Total	\$ 4,834.80

Signature

Authorised by Claims Dept
Mrs Tan @ 9639 9195

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten:
Hwee Jie - LKK
19/2/19
L/S 4days

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 14 February 2019 1:36 PM
To: Jerleen Tang; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: yvonne@huahong.com.sg; Pooi Chin Han Daniel
Subject: RE: Accident Involving SKM 3151 D & SHA 5064 H on 13/2/2019 along Changi Airport T1 Near Departure Door 3

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKM3151D and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

10:20 am @ 15/2/19
VNY
jerleen

From: Jerleen Tang [mailto:jerleen@huahong.com.sg]
Sent: 14 February, 2019 11:33 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: yvonne@huahong.com.sg
Subject: RE: Accident Involving SKM 3151 D & SHA 5064 H on 13/2/2019 along Changi Airport T1 Near Departure Door 3

Dear Gabriel

We choose LKK Auto Consultants Pte Ltd

Thank you.

Regards
Jerleen Tang
Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | W. huahong.com.sg
f in

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Thursday, 14 February 2019 9:47 AM

To: Jerleen Tang <jerleen@huahong.com.sg>

Cc: yvonne@huahong.com.sg

Subject: RE: Accident Involving SKM 3151 D & SHA 5064 H on 13/2/2019 along Changi Airport T1 Near Departure Door 3

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Jerleen Tang [<mailto:jerleen@huahong.com.sg>]

Sent: 13 February, 2019 5:04 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: yvonne@huahong.com.sg

Subject: Accident Involving SKM 3151 D & SHA 5064 H on 13/2/2019 along Changi Airport T1 Near Departure Door 3

Dear Sir/Mdm

Kindly advise liability for this accident case.

Our insured claiming third party. GIA report as per attached.

Should you have any clarification, please contact us @ 6661 9688.

Thank you.

Regards

Jerleen Tang

Claims Department



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1 SINGAPORE 729332

T. 6661 9688 | F. 6661 9699 | W. huahong.com.sg



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.
Registration No. 198703792-K

Print Received Message

This mail is associated with :

***SKM3151D (MCT19020362)**
[SHA5064H]

TP

HUA HONG PTE LTD

Feb 13 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Hua Hong Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 25/09/2019 17:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3317.00) - SKM3151D - Claim Handler: Pooi Chin Han Daniel

Approved:3317.00:Request TP WS to issue Tax invoice for Repairs in III's favour

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019 Edit Reg		14 Feb 2019 00:00 Edit Adj Rpt	\$92,500.00 Edit Estimates	\$92,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	HUA HONG PTE LTD , Co. Reg. No.: 200900309M								
Vehicle Reg. No.:	SKM3151D	Date of Loss:	13/02/2019 00:00 - :59 [59 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19020362	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHA5064H	Policy No. (Claimant):	5087272209-01						
		Excess:							
Repairer:	Hua Hong Pte Ltd (Sungei Kadut) 25D Sungei Kadut Street 1, 729332 Sungei Kadut - Tel: 6760 8815 / 6760 0539								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 27/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (25/09/2019): Alert - Adj Mandate Approved (\$3317.00) - SKM3151D - Claim Handler: Pool Chin H... III_SG (25/02/2019): Alert - Adj Mandate Approved (\$0.00) - SKM3151D - Claim Handler: Pool Chin Han ... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKM3151D (MCT19020362)
[SHA5064H]
TP
HUA HONG PTE LTD
Feb 13 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hua Hong Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
2	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
3	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
4	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
5	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
6	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
7	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
8	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
9	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
10	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
11	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
12	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
13	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
14	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
15	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
16	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
17	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
18	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
19	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
20	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
21	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
22	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
23	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
24	17/09/19 15:18	General View			Load JPG	<input checked="" type="checkbox"/>	
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	18/02/19 14:37	EMAIL FROM III DD 14022019			Load PDF		
2	22/02/19 15:11	TP GIA REPORT			Load PDF		
3	25/02/19 10:08	TP ESTIMATE- MARKED			Load PDF		
4	17/09/19 15:17	LOD			Load PDF		
5	23/09/19 14:26	WORKSHOP INVOICE			Load PDF		
6	31/01/20 11:37	DISCHARGE VOUCHER			Load PDF		
7	31/01/20 11:37	RENTAL RECEIPT			Load PDF		
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print		
1	19/02/19 09:13	Singapore Accident Statement			Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19002974/JGS3Q2

Date: 31/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No : SKM3151D Insured Vehicle No : SHA5064H
 Date of Loss: 13/02/2019 Nature of Claim: TP Claim No: MCT19020362

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM3151D
 Make & Model: MERCEDES-BENZ E200 (R18), 2.0 (A) Engine No: 27492030121885
 Reg. Date: 19/02/2014 (Man. Year: 2013) Chassis No: WDD2120342A921738
 Colour: Black Odometer: 105346 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,718.50	1,768.50	950.00	34.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,450.00	350.00	19.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,518.50	3,218.50	1,300.00	28.77
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	4,518.50	2,500.00	2,018.50	44.67
+ GST 7.00/7.00% (S\$)	316.30	175.00	141.30	44.67
Nett Amount (S\$)	4,834.80	2,675.00	2,159.80	44.67
+ Car Rental (4.0 x S\$160.50/day) (S\$)		642.00		
Nett Liability (S\$)		3,317.00		

INSPECTION

Date of Assignment: 14/02/2019
 Date Inspected: 19/02/2019 Inspected At: Hua Hong Pte Ltd (Sungei Kadut)
 25D Sungei Kadut Street 1
 Singapore 729332
 Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 23 Sep 2019)	
Parts:	N/A	MERCEDES-BENZ E200 (R18) 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM3151D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR DOOR (LH)	Dented	1,820.00 FL	*1,820.00 FL	
2	1		*REAR DOOR PROTECTOR (LH)	Necessary	145.00 FL	*145.00 FL	
3	1		*REAR SPORT RIM (LH)	Repair	950.00 FS	*- FS	
					Sub Total (\$\$)	2,915.00	1,965.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	196.50	196.50
					Total Parts (\$\$)	2,718.50	1,768.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & CHARGE REAR LH DOOR ,KNOCKING & PULL STRAIGHT REAR LH FENDER AND ALL AREA AFFECTED BY ACCIDENT	New	900.00	750.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO DISMANTLE & REFIT REAR CUSHION SEAT ,INNER TRIM TO FACILITATE REPAIR	New	100.00	50.00
4	TO DISMANTLE & REFIT REAR RH DOOR FITTING AND MECHANISM TO NEW DOOR	New	60.00	50.00
5	TO DISMANTLE & REFIT REAR LH SPORT RIM	New	20.00	20.00
6	TO PERFORM 4 WHEEL ALIGNMENT	New	100.00	60.00
7	TO SPRAY REAR LH DOOR ,REAR LH FENDER AND TOUCH UP REAR BUMPER	New	600.00	500.00
Gross Labour Cost (\$\$)			1,800.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >