

**JKS MOTOR WORKS PTE LTD**

8 KAKI BUKIT AVENUE 4, #03-45, Premier @ Kaki Bukit, Singapore, 415875

Company Reg & GST No. : 201407714K

TEL: 67026828 FAX: 6702 6829

EMAIL: admin@jksmotorworks.com.sg

Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD**QUOTATION : JKSQUOTE074****DATE : 14-Feb-19****REF NO :****VEH NO :** TAMPINES AVE 4 NEAR JUNYUN PRIMARY SCHOOL
BUS STOP ON 14 FEB 2019 @ 7:30**VEHICLE NO :** SLW8250D
MAKE/MODEL : TOYOTA MARKX
CHASSIS : GRX1203069260
ENGINE NO : 4GR0535268
REG. DATE : 26-Jul-09
CAPACITY : 2.5CC
MILEAGE :**ESTIMATE FOR : SLW8250D TOYOTA MARKX**

Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 25%)	
SPARE PARTS					
1 BUMPER REAR	1	PC	750.00	562.50	RX
2 BUMPER RETAINER REAR LH & RH	2	PCS	356.40	267.30	?
3 BUMPER BRACKET	2	PCS	322.40	241.80	? BRV
4 TAIL LIGHT LH & RH	2	PCS	756.40	567.30	?
5 END PANEL REAR	1	PC	780.20	585.15	? RX
6 END PANEL TOP GARNISH	1	PC	378.10	283.58	NNX
7 REAR BOOT	1	PC	980.20	735.15	NNX
8 REAR BOOT INNER TRIM	1	PC	571.20	428.40	NNX
9 EMBLEM 'MARK X'	1	PC	80.00	60.00	NNX
10 EMBLEM '250G'	1	PC	60.00	45.00	NNX
11 EMBLEM 'LEXUS'	1	PC	60.00	45.00	NNX
12 WEATHERSTRIP	1	PC	200.00	150.00	NNX
NETT ITEMS					
13 REVERSE SENSOR	1	SET	300.00	300.00	?
LABOUR					
LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY, REMOVE & REPLACE REAR DAMAGE PARTS AS LISTED ABOVE					
14	1.00	SRV	1,200.00	1,200.00	400.00
15 TO APPLY PUTTY AND SPRAY PAINT ON REAR PORTION AFFECTED AREAS	1.00	SRV	1,200.00	1,200.00	600.00
16 TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS	1.00	SRV	120.00	120.00	60.00
17 TO APPLY ANTI RUST COATING ON REPAIR / REPLACED PANELS	1.00	SRV	200.00	200.00	NNX

**JKS MOTOR WORKS PTE LTD**

8 KAKI BUKIT AVENUE 4, #03-45, Premier @ Kaki Bukit, Singapore, 415875

Company Reg & GST No. : 201407714K

TEL: 67026828 FAX: 6702 6829

EMAIL: admin@jksmotorworks.com.sg

Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD**QUOTATION : JKSQUOTE074****DATE : 14-Feb-19****REF NO :****VEH NO :** TAMPINES AVE 4 NEAR JUNYUN PRIMARY SCHOOL
BUS STOP ON 14 FEB 2019 @ 7:30VEHICLE NO : SLW8250D
MAKE/MODEL : TOYOTA MARKX
CHASSIS : GRX1203069260
ENGINE NO : 4GR0535268
REG. DATE : 26-Jul-09
CAPACITY : 2.5CC
MILEAGE :**ESTIMATE FOR : SLW8250D TOYOTA MARKX**

Description	Qty	UOM	Repaire's Estimate	Revised Amount (Less 25%)
SPARE PARTS				
✓ 1 BUMPER REAR	1	PC	750.00	562.50
✓ 2 BUMPER RETAINER REAR LH & RH	2	PCS	356.40	267.30
3 BUMPER BRACKET	2	PCS	322.40	241.80
✓ 4 TAIL LIGHT LH & RH	2	PCS	756.40	567.30
✓ 5 END PANEL REAR	1	PC	780.20	585.15
6 END PANEL TOP GARNISH	1	PC	378.10	283.58
7 REAR BOOT	1	PC	980.20	735.15
8 REAR BOOT INNER TRIM	1	PC	571.20	428.40
9 EMBLEM 'MARK X'	1	PC	80.00	60.00
10 EMBLEM '250G'	1	PC	60.00	45.00
11 EMBLEM 'LEXUS'	1	PC	60.00	45.00
12 WEATHERSTRIP	1	PC	200.00	150.00
NETT ITEMS				
✓ 13 REVERSE SENSOR	1	SET	300.00	300.00
LABOUR				
14 LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY REMOVE & REPLACE REAR DAMAGE PARTS AS LISTED ABOVE	1.00	SRV	1,200.00	1,200.00
15 TO APPLY PUTTY AND SPRAY PAINT ON REAR PORTION AFFECTED AREAS	1.00	SRV	1,200.00	1,200.00
16 TO CHECK ALL WIRINGS AND LIGHTS FUNCTION AND FOCUS	1.00	SRV	120.00	120.00
17 TO APPLY ANTI RUST COATING ON REPAIR / REPLACED PANELS	1.00	SRV	200.00	200.00

Supplementary:
Sensor