

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Fax: 64815390

ESTIMATE OF REPAIR

XE1667J Pg 1/1

Veh # : XE1667J Model : SCANIA P360CB6X4MHZ (27/4/2016)

Date Of Accident: 6/2/2019 3P : SMG941T (AIG)

Location : TAMPINES EXPRESSWAY

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$
<u>List Items</u>				
1 pc	Fuel tank (Aluminium) <i>dd ✓</i>		6000	9,090.00
2 pcs	Fuel tank bracket (Lower) <i>? bf ✓</i>		700	1,200.00
2 pcs	Fuel tank bracket (Upper) <i>? bf ✓</i>		500	900.00
2 pcs	Fuel tank stand bracket (Lower) <i>? bf ✓</i>		500	900.00
1 pc	Air-tank (Front) <i>? d1 ✓</i>		1700	3,110.00
Sub-Total			9400	15,200.00
<u>Nett Items</u>				
1 pc	Rear n/s guard (LTA Approved) <i>bt ✓</i>		1800	3,200.00
3 pcs	Rear n/s guard bracket <i>bt ✓</i>		1400	2,400.00
2 pcs	Rear n/s guard bracket (Upper) <i>bt ✓</i>		200	300.00
1 pc	Rear n/s guard block bracket <i>bt ✓</i>		1000	1,800.00
1 set	Rear n/s guard Yellow/Black sticker <i>nk ✓</i>		150	200.00
Sub-Total			4550	7,900.00
<u>Labour</u>				
1	To remove and refit n/s guard. <i>1200</i>	<i>1350</i>		2,800.00
2	To remove and refit fuel tank including bleeding. <i>400 ✓</i>			900.00
3	To remove and refit air-tank including checking leakage. <i>300 ✓</i>	<i>photo</i>		700.00
Sub-Total		<i>4550</i>		4,400.00
Total			16000	27,500.00
After -20%			<i>4/5 12800</i>	22,000.00

** 1500 for labour.*

Chan San Choon

Director

DipEng, AAE MIMI, MSAE(Aust), AFMIA



(heavy vehicles, marine vessels)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary (work) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

8778 1999

24 hr accident call



Tanjim 27495719
WP' 19/2/19 E1045
** Resurvey after repair 06 days. 06 days*
** To check price parts*
Sur @ lkkauto.com