

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 17:10

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014262	Account: A0006 (T 0)
		Date : 18/09/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
		Order : SMH2956H	
		Term : 30	

Regn No: SMH2956H (V 40477)	Regn Date: 18/01/2019	Mileage: 13928	WIP No.: 43071
Model: A4 SEDAN 2.0 TFSI 8W2ADG	Chassis: WAUZZZF47KN000866	Engine: CVK 072219	Dept: U
You have been assisted by :- UB-Nora (11)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR AND AIR CHARGED COOLER.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1000.00	1.00	1,000.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT. CUT OUT AND REWELD LHS FRONT FENDER TOP SUPPORT.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	3000.00	1.00	3,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,LHS FRONT FENDER, BONNET,LHS FRONT FENDER TOP SUPPORT AND LHS FRONT DOOR	2475.00	1.00	2,475.00
S	BODYWORK	M: TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0853887E	(A) (SK) SPOILER 25/02	Less 020%	1.00	65.40
X	A8W0941773A	(SK) HEADLIGHT	Less 020%	1.00	7087.00
					5,669.60

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 2 17:10

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014262	Account: A0006 (T 0)
	Date : 18/09/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SMH2956H	
	Term : 30	

Regn No: SMH2956H (V 40477) Regn Date: 18/01/2019 Mileage: 13928 WIP No.: 43071
Model: A4 SEDAN 2.0 TFSI 8W2ADG Chassis: WAUZZZF47KN000866 Engine: CVK 072219 Dept: U
You have been assisted by :- UB-Nora (11)

		Details		Qty	Unit Price	Amount
X	A8W0821105A	(A) (SK) FENDER 25/02/	Less 020%	1.00	699.50	559.60
X	A8W0821171A	WHEEL HOUS	Less 020%	1.00	223.00	178.40
X	A8W0805594	(SK) CARRIER	Less 020%	1.00	927.50	742.00
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	21.00	67.20
X	A8W0823029A	HOOD	Less 020%	1.00	2554.00	2,043.20
X	A8W0807065D GRU	COVER	Less 020%	1.00	1999.00	1,599.20
X	A8W0601025EF	(V) (G) RIM 16" CX1 25	Less 020%	1.00	651.00	520.80
X	A4E0260749B	WASHER	Less 020%	1.00	4.50	3.60
X	A8W0821467	BRACKET	Less 020%	1.00	31.50	25.20
X	A8W0821469	BRACKET	Less 020%	1.00	44.50	35.60
X	A8W0821135C	SUPPORT	Less 020%	1.00	107.00	85.60
X	A8W0807283	(SK) GUIDE	Less 020%	1.00	32.60	26.08
X	A8W0823745	COVER	Less 020%	1.00	20.20	16.16
X	A8W0821091	(A) (SK) PLATE 25/02/1	Less 020%	1.00	45.00	36.00
X	A8W0823125	(SK) PROTECTION	Less 020%	1.00	24.90	19.92
X	A8W0823126	PROTECTION	Less 020%	1.00	24.70	19.76
X	A8W0820581C	COVER	Less 020%	1.00	27.80	22.24
X	A3D0260749C	WASHER	Less 020%	2.00	4.00	6.40
X	A4E0260749C	WASHER	Less 020%	1.00	4.20	3.36
X	A5Q0298403C	INSERT	Less 020%	1.00	227.00	181.60
X	A8W0853823B 9B9	STONEGUARD	Less 020%	1.00	45.80	36.64
X	A8W0816738Q	PIPE	Less 020%	1.00	475.50	380.40
X	A8W0807681B 9B9	GRILL	Less 020%	1.00	122.50	98.00
X	A8W0853833	SPOILER	Less 020%	1.00	31.30	25.04
X	AN 0161857	POP-RIVET	Less 020%	6.00	3.00	14.40
X	AN 0161857	POP-RIVET	Less 020%	6.00	3.00	14.40
X	AN 10347204	BOLT	Less 020%	2.00	1.50	2.40
X	A8W0823124	PROTECTION	Less 020%	1.00	24.70	19.76

Parts 12,504.88
Labour 0.00
Sublet 7,727.00
Menus 0.00
Lubricant 0.00



Sub-Total 19,431.88
7% GST 1,360.23
Grand Total 20,792.11

Received by

For & on behalf of
Premium Automobiles Pte Ltd