

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9141B

AAD1902-138

*Not Authorized
Resurvey By paint*

Vehicle No.:	SHD 9141B
Chassis No.:	JTDKB3FU003079215
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	16.2.2019
Third Party Insurer :	III
Date of Registration :	17/1/2019

	PART	LIST
1	1 REAR BUMPER SIDE LH	\$ <i>SL</i> 232.00 X
2	1 REAR FENDER LH	\$ <i>N</i> 817.50 X
3	1 REAR BUMPER	\$ <i>msjcm</i> 458.60 ✓
4	1 REAR BUMPER RE-INFORCEMENT	\$ <i>N</i> 318.80 X
5	1 REAR BUMPER TOWING COVER	\$ <i>SL</i> 14.70 X
6	1 REAR BUMPER UNDER COVER (BLACK)	\$ <i>SL</i> 552.60 X
7	1 REAR BUMPER SIDE RETAINER LH	\$ <i>D11</i> 112.70 ✓
8	1 REAR BUMPER SIDE RETAINER RH	\$ <i>SL</i> 112.70 X
		<hr/>
		\$ 2,619.60
		25% \$ 654.90
		<hr/>
		\$ 1,964.70

Special Nett

1	1 REAR WHEEL RIM	\$ <i>SL</i> 1,570.55 X
2	1 REAR WHEEL RIM COVER	\$ <i>SL</i> 175.80 X
3	1 CLIP, REAR FENDER LINER	\$ <i>na</i> 22.00 X
4	1 REAR DOOR STICKER '6555-3333'	\$ <i>na</i> 80.00 <i>base</i>

TOTAL \$ 1,848.35**TOTAL PARTS \$ 3,813.05****LABOUR**Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *6601*

Trans-cab Auto Services Pte Ltd

AAD1902-138

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9141B

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>400d</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>~</i> 170.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>↪</i> 170.00	X
To transfer of Door fittings, attachments and perform water seepage test.	\$	<i>↪</i> 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	<i>↪</i> 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>↪</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00	X
TOTAL	\$	7,070.00	

Over All Total \$ 12,847.75

(PART-BY-PART) Repair Days *10 DAYS*
2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: