

ASS. REC. BY

REP

CS/SMO19003322/ud3

n2

Special Instruction

Surveyor  
Meimien

Marius

ASSIGNMENT (Office)

From (Person)

Thelma Chao

of

SMO

Date/Time

21/2/19 @ 4:20pm

Estimated Cost

Bill to

OD / ☒ WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLP 1482J

Insured

GBP 5086T

at Workshop n/a

Fastech Auto

Tel:

67465405

of

1 Kaki Blk Ave 6 # 01-46

Policy No:

D18MTPCVE 00404

Claim No:

CMTD 1901015

Sum insured

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

20/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:31pm 21/2/19

Person Contacted:

Nancy

Vehicle

OUT

Date/Time

Action/Instruction (✓) Estimate

27/2/19 @ 5pm Informed Thelma Chao, we are pending estimate from repairer.  
06/3/19 @ 4:37pm revised to Thelma Chao via Meimien.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

SMD /

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 MAR 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 12/3 turnish

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$

MER-TP

3500

350  
10

360

**Note: This document has not been finalised.**

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 06 Mar 2019

## Preliminary Advice

Insured Vehicle No	: GBF5076T	Accident Date	: 20/02/2019
TP Vehicle No	: SLP1482J	Assignment Date	: 21/02/2019
Make	: TOYOTA ALLION	Est. Duration of Repair	: 3.00
Date of Inspection	: 21/02/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	10,377.30
Revised Amount	:S\$	4,383.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,383.60
Lump Sum Repair	:S\$	3,500.00

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2019		21 Feb 2019 16:20 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	<b>HONG MEI ENTERPRISES</b> , Co. Reg. No.: 23204600W		
Main Claimant:	<b>JASON NG CONG RONG</b> , ID: S8340967C		
Vehicle Reg. No.:	<b>SLP1482J</b>	Date of Loss:	20/02/2019 00:00 - :59
Claim Type:	<b>TP / CMTD1901015</b>	Policy/Cover Note No.:	D18MTPCVE004014 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>GBF5076T</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Fastech Auto Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Thelma Choo</b> - 6322 4681]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 04/03/2019]</b>		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Friday, 22 February 2019 5:00 PM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** VEHICLE SLP 1482J (YOUR REF: CMTD1901015)

This mail is associated with :

**\*SLP1482J (CMTD1901015)**

**[GBF5076T]**

TP

JASON NG CONG RONG

Feb 20 2019 12:00AM

[HONG MEI ENTERPRISES]

Fastech Auto Pte Ltd

Dear Thelma,

Please be informed that we have inspected the vehicle SLP 1482J on 21/02/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance


Articles

Forum

Resources

CHEAPEST CAR

INSURANCE RENEWAL



\$

Choice of \$0 excess

Option of any workshop

GET A CHEAPER QUOTE NOW!

Toyota Allion

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » William Lee Car Aircon Engineering » Toyota Allion 1.5A (COE till 09/2023)

Resources

Car Buying

Car Selling


Car Ownership


Car Aftermarket

On The Move

Lifestyle

Car Tyres





D&S TREASURES  
PRIVATE CLIENT

Compare

Toyota Allion 1.5A (COE till 09/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$31,000

Depreciation

\$6,740 /yr

Reg Date

29-Sep-2008  
(4yrs 7mths 7days COE left)

Manufactured

2008

Mileage

-

Transmission

Auto

Engine Cap

1,496 cc

Road Tax

\$750 /yr

Power

81.0 kW (108 bhp)  
View specs of the Toyota Allion (2007-2012)

Curb Weight

1,200 kg

Features

1.5L DOHC VVT-i Engine, CVT Automatic Transmission, SRS Airbags, Auto Climatic Aircon Control, Knockdown Rear Seats, Keyless Entry.

Accessories

Full Factory Fitted Accessories, Leather Seat, Etc.

Description

Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

COE

\$16,170

OMV

\$14,652

ARF

\$14,652

Dereg Value

\$14,885 as of today (change)

No. of Owners

3

Type of Veh

Mid-Sized Sedan

Category

COE Car

Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 28-Dec-2018 | Last Updated on: 19-Feb-2019

Tags: Toyota Allion, toyota allion, 2008 Toyota Allion, 2008 toyota allion, Toyota, Allion, allion, Used Toyota

Upfront Payment

» more Financial info

Transfer Fee

\$25


Down Payment




\$9,300 (change)




Maximum 70% Loan

1st Instalment

\$462







Location Map

Seller Information

Company

William Lee Car Aircon Engineering  
» dealer's pricelist  
» 19 vehs sold | 27 vehs available

Address

61 Ubi Avenue 2 #08-04B  
Search cars nearby this location

Location

Automobile Megamart

Office No

63821006

Contact Person(s)

Keith

98290368

Erik

96812139


Ben


98274488

Shen Qiang

94557994

Useful Services

 Afraid of lemons? Request to have this car evaluated professionally.  
Vehicle Evaluation

 Find out the market value for your car. Get a free Car Valuation.  
Free Valuation

https://www.sgcarmart.com/used\_cars/info.php?ID=778633&DL=2191

21-Feb-19

**> Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 0967C

### Vehicle Details

Vehicle No.: SLP1482J  
Vehicle to be Exported: No  
Intended Deregistration Date: 21 Feb 2019  
Vehicle Make: TOYOTA  
Vehicle Model: ALLION 1.5 A  
Primary Colour: Silver  
Manufacturing Year: 2008  
Engine No.: 1NZD112481  
Chassis No.: NZT2603029205  
Maximum Power Output: 81.0 kW (108 bhp)  
Open Market Value: \$14,168.00  
Original Registration Date: 29 Aug 2008  
First Registration Date: 29 Aug 2008  
Transfer Count: 2  
Actual ARF Paid: \$9,174.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 28 Aug 2023  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$17,099.00  
COE Rebate Amount: \$15,453.00  
**Total Rebate Amount: \$15,453.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Feb 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/02/2019 12:11
Date Of Accident	20/02/2019 09:35
Exact Location Of Accident	PICKERING ST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP1482J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JASON NG CONG RONG
NRIC No	S8340967C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91867974
Alternative Phone No	OFFICE-91867974

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ALLION
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103624429
Cover Note Number	

### Driver

Name of Driver	JASON NG CONG RONG
NRIC No	S8340967C
Date Of Birth	22/12/1983
Occupation	INDOOR
Date Of Driving Pass	30/04/2004
Driving Experience	14 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91867974
Fax Number	
Contact Number	OFFICE-91867974
EMail Address	NOEMAIL



Address	APT BLK 212 PETIR ROAD #04-465
Postcode	670212
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF5076T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	JASON NG CONG RONG
------	--------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLP1482J

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

APT BLK 212 PETIR ROAD #04-465

Postcode

670212

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTES


1. Please report correctly the details of the accident to SPCED within the stipulated period.
2. The form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible and without misrepresentation or withholding of material facts. Material misstatements committed to constitute fraudulent claims.
4. The insurer's acceptance of this form by insurance company is not an admission of policy liability on the part of the insurance company.
5. SPCED report may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Report Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and final copies of the report will for a fee be made available upon application by the insured.
7. On the receipt of this report to the insurers, you must inform the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA):

I/We (insured/insureds), agree and consent that:

- a. I/We (insured/insureds) and the General Insurance Association of Singapore (GIA) provide permission to collect, use, process and disclose my personal data/personal information (referred to as "Personal Information") and any other personal information collected or made possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Attorney General of Singapore and any relevant government agency (such as the police), for the purposes of:
  - i. processing, handling and/or dealing with my claims (including the settlement of the claims and any necessary investigations relating to the claims);
  - ii. investigating the accident and/or my claims;
  - iii. handling my claim or dealing with my insurer(s) and/or responding to any enquiries by me;
  - iv. settling my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which may involve disclosure of certain personal data about me to bring about delivery of the same as well as on the part of the insurer(s) involved (mail packages); and/or
  - v. complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- b. Insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, process and/or process my Personal Information for one or more of the above Purposes, and
- c. Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.
- d. My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- e. The Personal Information collected under (c) above may be shared and disclosed:
  - i. to the insurer and/or any other third parties that assist in evaluating, investigating, controlling or managing traffic, regulatory enforcement and government agencies as reasonably required for the purposes stated; or
  - ii. complying with requirements under any regulatory laws or court orders.

  
Driver's Signature

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name  
(NIC/PIN No.)

## Sketch Plan #2

SKETCH PLAN

A SLP1483  
B EBF5076T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling straight, CAR B already changed lane to first lane, suddenly he apply brake and cut into my lane and collided into my right portion of vehicle.

### DECLARATION

We declare the foregoing particulars are true in every respect.

  
Driver's Signature  
Date & Time

Driver's Signature  
(If driver is not the sole accident)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/PPN No:

FASTECH AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46/48/50 AUTOBAY  
SINGAPORE 417883

VEHICLE NO:SLP 1482J

QTY	PARTICULAR			
1 PCS	REAR DOOR O/S	1345.10	3045.00	\$1,455.10
1 PCS	REAR DOOR OUTER HANDLE O/S		11	\$322.50 X
1 PCS	REAR DOOR OUTER GLASS MOULDING O/S		11	\$145.80 X
1 PCS	REAR DOOR INNER LOCK O/S	399.50	241/shed	\$499.20
1 PCS	REAR DOOR INNER TRIM BOARD O/S		11	\$799.10 X
1 SET	REAR DOOR INNER TRIM BOARD CLIPS O/S		11	\$50.00 X
1 PCS	REAR DOOR GLASS REGULATOR O/S		11	\$299.20 X
1 PCS	REAR FENDER O/S		11	\$911.10 X
1 PCS	REAR BUMPER	745.10	cut/turn	\$1,251.10
1 SET	REAR BUMPER CLIPS		11	\$50.00
1 PCS	REAR SHOCK ABSORBER O/S		11	\$699.10 X
1 PCS	REAR WHEEL HUB & BEARING O/S		2x2	\$545.10
1 PCS	REAR SPORT RIM O/S		sent cut	\$850.00 4505.2
				\$7,877.30
	LABOUR CHARGES:			
	TO CHECK WIRING			\$50.00 20
	TO DISMANTLE & REFIX REVERSE SENSOR			\$80.00 50
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE			\$150.00 120
	TO TRANSFER REAR DOOR MECHANISM			\$100.00 60
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY			\$120.00 80
	TO DISMANTLE & REFIX REAR WINDSCREEN		un	\$120.00 X
	TO CONDUCT WHEEL ALGNMENT			\$100.00 60
	TO SPRAY RUST PROOFING			\$100.00 50
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$800.00 580
	TO PUTTY & SPRAY PAINTING			\$880.00 600
			TO	\$10,377.30

Not Authorised  
LKK  
2/58 3500  
327.  
21/2/19

(257)

P-30.84.8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003322/UQD3N2

Date: 13/03/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE004014
Claimant Vehicle No :	SLP1482J	Insured Vehicle No :	GBF5076T
Date of Loss:	20/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1901015

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLP1482J	Engine No:	1NZD112481
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603029205
Reg. Date:	29/08/2008 (Man. Year: 2008)	Odometer:	277985 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,877.30	2,763.60	5,113.70	64.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,620.00	880.00	35.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,377.30</b>	<b>4,383.60</b>	<b>5,993.70</b>	<b>57.76</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>(S\$)</b>	<b>10,377.30</b>	<b>3,500.00</b>	<b>6,877.30</b>	<b>66.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>726.41</b>	<b>245.00</b>	<b>481.41</b>	<b>66.27</b>
<b>Nett Amount (S\$)</b>	<b>11,103.71</b>	<b>3,745.00</b>	<b>7,358.71</b>	<b>66.27</b>

## INSPECTION

Date of Assignment:	21/02/2019	
Date Inspected:	21/02/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2019)
<b>Parts:</b> 143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLP1482J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR DOOR O/S	Badly Dented	1,455.10 F	*1,345.10 FL
2	1	*REAR DOOR OUTER HANDLE O/S	Not Necessary	322.50 F	*- FL
3	1	*REAR DOOR OUTER GLASS MOULDING O/S	Not Necessary	145.80 F	*- FL
4	1	*REAR DOOR INNER LOCK O/S	Twisted/Shorted	499.20 F	*399.50 FL
5	1	*REAR DOOR INNER TRIM BOARD O/S	Not Necessary	799.10 F	*- FL
6	1	*SET REAR DOOR INNER TRIM BOARD CLIPS O/S	Not Necessary	50.00 F	*- FL
7	1	*REAR DOOR GLASS REGULATOR O/S	Not Necessary	299.20 F	*- FL
8	1	*REAR FENDER O/S	Repair	911.10 F	*- FL
9	1	*REAR BUMPER	Cut/Torn	1,251.10 F	*745.10 FL
10	1	*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
11	1	*REAR SHOCK ABSORBER O/S	Not Necessary	699.10 F	*- FL
12	1	*REAR WHEEL HUB & BEARING O/S	Damaged	545.10 F	*545.10 FL
13	1	*REAR SPORT RIM O/S	Bent/Cut	850.00 FS	*450.00 FS
				<b>Sub Total (\$\$)</b>	<b>7,877.30 3,534.80</b>
				<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00 771.20</b>
				<b>Total Parts (\$\$)</b>	<b>7,877.30 2,763.60</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE	New	150.00	120.00
4	TO TRANSFER REAR DOOR MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
8	TO SPRAY RUST PFOOFING	New	100.00	50.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	800.00	580.00
10	TO PUTTY & SPRAY PAINTING	New	880.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,500.00</b>	<b>1,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >