



SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4  
Singapore 757705  
Tel: 65 6362 3422  
Fax: 65 6368 7420

### SMRT Vehicle Repair Estimate

Group : **Buses / Taxis / Private Car**

Reg. No. : PC 6199 R

Make / Mo : MITSUBISHI FUSO ROSA

Chassis : BE641JK30367

Name of D : BUS-PLUS SERVICES PTE LTD

Date/Time of Accident : 08-01-2019 / 16:30HRS

Surveyor is Required YES / NO

If Yes, VICOM / LKK / AIS / Others

MSIG : \_\_\_\_\_

Vehicle is Towed BY YES / NO

Date / Time : \_\_\_\_\_

Accident reporting c 09-01-19 16:10

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any :

THIRD PARTY CLAIM

Ref. No. 8RS/01/19/3002

Reg. Date : 16/9/2017

Mileage \_\_\_\_\_

Rental/Replacement Vehicle : Yes / No

The damages on the vehicle are as indicated in the following diagram :



Signed : \_\_\_\_\_

Date : \_\_\_\_\_

Accident Repair Job Card No. : \_\_\_\_\_

Date Prepared : \_\_\_\_\_

Summary of Repair Estimates

Repair Complete : \_\_\_\_\_

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges : \$ 500.00

\$ -

Total Spray Painting Charges : \$ 400.00

\$ -

Total Material Charges : \$ 2,225.77

\$ -

Other Charges : \$ 210.00

\$ -

**TOTAL** : \$ 3,335.77

\$ -

Lump Sum Repair, if any : \_\_\_\_\_

No. of Repair Days : [ 4 ] days

[ 4 ] days

Signature : Prepared by: \_\_\_\_\_

Adjusted by: Rasul - LKK

QN No. \_\_\_\_\_ Invoice No. \_\_\_\_\_

Signed : \_\_\_\_\_

Date : \_\_\_\_\_

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign hydraulic, and aligned all parts	\$ <del>500.00</del>	300
<b>Total Labour Cost</b>	\$ 500.00	\$ -

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	
To respray affected areas	\$ <del>400.00</del>	400
<b>Spray Painting</b>	\$ 400.00	

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Page ( )

Job Scope	Quotation from ARC	
To remover /refit wiring check	\$ 60.00	30
To remove/replace Advertisement sticker	\$ 150.00	100
<b>Total Other Costs</b>	\$ 210.00	

**Part 4 - Spare Parts / Material Usage**

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	Cost Price (\$)	COST LESS 10%	Final Price (\$)	Repair (R) Replace ( / )	Not given (X) Repair (R) Replace ( / )
1	FRONT BUMPER	1	\$ 1,588.97	10%	\$ 1,430.07	Repair	
2	FRONT BUMPER ADVERTISEMENT STICKER	1	\$ 450.00	10%	\$ 405.00	re-	
3	FRONT BUMPER SIDE BRACKET LH	1	\$ 113.60	10%	\$ 102.24	X	
4	FRONT SIDE LAMP LH	1	\$ 205.16	10%	\$ 184.64	??	
5	FRONT SIDE DOOR SIGNAL LAMP LH	1	\$ 115.35	10%	\$ 103.82	X	
<b>TOTAL MATERIALS</b>			\$ 2,473.08	-	\$ 2,225.77		

Surveyor Remark:

Pass - 17p 90010068  
 4 days  
 P/P  
 22/07/19 @ 1525