

HWA SENG SPRAY PAINTING CO
 160 Sin Ming Drive
 #05-11 Sin Ming Autocity
 SINGAPORE 575722
 (COMPANY REGISTRATION NO. 09574400B)
 TEL : 64533100
 FAX : 62669932

Date of Accident. 16/02/2019
 Your Insured
 Vehicle number: SMG2378G

ESTIMATE REPAIR COSTS TO BMW X1 REG. NO. SKP 6797 E


		SS\$	
1pc	Left Front Door	1380.00	✓
1pc	Door Rubber Body	180.00	✓
1pc	Door Power Window Regulator	310.00	✓
1pc	Power Window Motor	340.00	✓
1pc	Emblem '5 Drive'	50.00	✓
1pc	Emblem '20i'	58.00	✓
1pc	N/S side skirt	550.00	X
		2868.00	
Less : 10%		286.80	
		2581.20	

LABOUR & MISC CHARGES

Panel Knocking	500.00	400
Spray Painting	1000.00	660
Tuff Kote	250.00	30
Labour to transfer door trim & attach part	200.00	60
TOTAL	4531.20	

NOT Authorized
 1. B. I
 Reimbursement
 4 days

HWA SENG SPRAY PAINTING COMPANY



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: