

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19003368/Jpa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH		Date: 11-05-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 5933U	Veh. Inspected	SHB 296H
	Policy No.	P1923095	Coverage (\$)	0.00
	Claim No.	S9M01EML	Excess (\$)	0.00
	Assign From		Assign Date	22/02/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JTDKN36U805746866	Colour	MAROON
	Odometer	498026	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	20/02/2019	Inspection Date	22/02/2019
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD		
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			