

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 27 Mar 2019

Preliminary Advice

Vehicle No	: SME9645A	Accident Date	: 16/02/2019
Make	: BLUECAR BLUECAR	Policy No.	: 29112616MCY
Assignment Date	: 20/03/2019	Excess	: S\$2,000.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12 Singapore 539315		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,735.60
Revised Amount	:S\$	2,130.00
Check Items (Estimated)	:S\$	243.00
Total	:S\$	2,373.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	38,501.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,499.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.