



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

4/3/19
@
09:00am

119013963

4/3/19

Marcus 4/3/19 11:50

SU019013963

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLK5182A
Chassis No : MRHGM6660HP000478
Model : CITY 1.5SV CVT 2017
Owner's Name : LI SHAOYAN
Ins Policy No :
Date of Accident : 21/2/2019

Document No. : SGT19000852
Date : 22. Feb 2019
Customer No. : WZ1007
Svc Advisor : LIEW THYE WEI
Engine No : L15Z14114322
Date | Time : 22. Feb 2019 8:58:45 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

YS
Chen

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LI SHAO YAN OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 21/2/19 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHC3992G						
71101-T9A-T00ZZ	FACEFR.BUMPER	1	459.80	25	344.85	24.14	368.99
91505-TM8-003	CLIP,BUMPER	13	2.30	25	22.42	1.57	23.99
71198-T9A-T00	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71193-T9A-T00	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71140-T9A-T00	BEAMR.FR.BUMPER UPPER	1	27.50	25	20.62	1.44	22.06
71102-T9A-T50	GARNISHR.FR.FOGLIGHT	1	23.60	25	17.70	1.24	18.94
33100-T9A-T01	HEADLIGHT ASSY,R	1	324.10	25	243.07	17.01	260.08
	Sum Item				664.26	46.50	710.76
BOSUN	SUNDRIES	1	30.00	10	30.00	2.10	32.10
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		80.00	5.60	85.60
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	900.00		900.00	63.00	963.00
BP02R	SPRAY PAINTING ON BUMPER AND RIGHT FRONT FENDER.	1	1300.00		1300.00	91.00	1391.00
	Sum Labor				2310.00	161.70	2471.70

Survey By
Date & Time
Excess

Marcus 4/3/19 10:30
Not Authorised
The job before painting
3 dy.

21/2
2168.14

LKK Auto Consultants hence notify the Repairer of the following:
Total (Inclusive of GST) 3,182.46
Total Amount 2,974.26 208.20 3,182.46
To be done before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
No illegal compensation(s) is allowed
• Any claim(s) must be resurveyed and is subject to final approval from Insurance Company
A. 3.19
Signature: 11/5/19
Date: P 12

7/3/2019.

Page 1/1



①

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS CHUA

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 3 DAYS.

Customer:	WZIO07 / INDIA INTERNATIONAL	Document No:	SVO19013963
Chassis No:	MRHGM6660HP000478	Printed By:	TWLEW
License No:	SLK5182A	Order Date:	4. March 2019
Mileage:	23824	Order Time:	11:24:33 AM
Engine No:	L15Z14114322	Service Advisor:	LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72271)						
	OWNER: LI SHAO YAN						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 21/2/19						
	SURVEYED BY: MERCUS (LKK)						
	DATE: 25/2/19 @ 10.30AM						
	REF NO: CC4/III19003386/Uja3						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHC3992G						
71101-T9A-T00ZZ	FACEFR.BUMPER	1	459.80	25	344.85	24.14	368.99
91505-TM8-003	CLIP.BUMPER	13	2.30	25	22.42	1.57	23.99
71193-T9A-T00	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
33100-T9A-T01	HEADLIGHT ASSY,R	1	324.10	25	243.07	17.01	260.08
	SUM PARTS:				618.14	43.27	661.41
BOSUN	0760	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BML01I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BKBH01S	EXT-YJ	1	560.00		560.00	39.20	599.20
	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.						
BP02R	EXT-YBH	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON BUMPER AND RIGHT FRONT FENDER.						
	SUM LABOUR:				1,550.00	108.50	1,658.50
	TOTAL SGD				2,168.14	151.77	2,319.91
	Total Payable (SGD)						2,319.91

GST Amount is calculated from individual line(s)