

ASS. REC. BY:

REF: CS/FCI 1900339/End 304 Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Menina chia

of

FCI

Date/Time: 6:22pm @ 21/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

YN 88884

Insured:

SHA 0954Y

at Workshop in/s

Detail Lab

Tel:

9844 8533

of

8 kaki Bkt Ave 4 #02/03

Policy No:

Claim No:

019000860MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/02/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11:33am @ 22/2/19

Person Contacted:

Benedict

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

YN 88884 - NS/INC100/8891/Dg1

DUA: 19/9/2010

SHA 954Y - NS/TNC11005054/Hln

DUA: 16/3/11

27/2/19

Informed FCI pending est from repairer

26/3/19

Email preli revised to FCI

26/3/19

LS \$700 Confirmed by email (Ref 4063, 851)

REF: FCI

VEHICLE

From: Date: 26/2/19
 Estimated Cost
 OD: TPRES / TPRES / ODRES / EVA / INV / MV
 To inspect Vehicle No: **YN 8888H**
 at Workshop No: **Detail Lab**
 at **8 kaki Bkt Ave 4 #02-03/04**
 Insured
 Policy No.
 Claim No.
 Sum Insured
 (Client's Record)
 Make of Veh:

Excess:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report. Consistent? : Yes or No

GIA / PR Seen. Consistent? : Yes or No

Est. Repairs. days Res.: Yes or No

Lump Sum. % 3 Val.: Yes or No

GA / REV / REP. / 24 HRS **lap**

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: **YN 8888H** at Regn: **9/09/14**
 Type: Car / M Cycle / Bus / Van / Truck / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Mitsubishi Canter** C.C. **2998**
 Color: **White** A/C: Insured / Std / Nil / NA
 Sp. Reading: **31711** T/Radio: Insured / Std / Nil / NA
 Eng No.
 C.No.: **FEB 21EA 00954**
 Gen. Cond. Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod.: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **195/85 R15**
 R: **61**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: Rear
 R/Bal: **7** mm R/Bal: **7** mm
 L/Bal: **7** mm L/Bal: **7** mm
 D.O.A. **1/2/19** D.O.I. **26/2/19**
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflop or
Rear RH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 MAR 2019

Date/Time: File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time: File Return to?

26/3- typist

Report Format:

Lump Sum / L.B.I. (\$) **CWS**
700fDays Of Repair: **2**Resurvey No. of Trip: **-**

Add Fee:

☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Insp. (\$)
☐ Weekend (\$)

Survey Fee:

Transportation

1. S. P. S.

1. Photos

1. Other

Total

139
50
24
209



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000860MFSH

Our ref: CS/FCI190339/Evd3

Date : 26/3/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. YN 8888H


We thank you for your instruction on 21/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/2/2019 at the premises of M/s DETAIL LAB and have the following to report:-

Workshop Estimate Amount	: S\$4,763.00
Revised Estimate Amount	: S\$700.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

STEVE CHEN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-02-2019	Our Ref No. D19000860MFSH
Accident Date	01-02-2019	Claim Type. Third Party
Insured Vehicle	SHA0954Y	Third Party Vehicle. YN8888H
Survey Location	8 KAKI BUKIT AVE 4#02-03/04 PREMIER @ KAKI BUKIT	
Contact Person.	MR BENEDICT YAP	
Contact No.	63855510/ 98448533	Fax No. 0
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	DETAIL LAB	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 26 March 2019 4:16 PM
To: 'CWS Motor Claims'
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000860MFSH/1, YN 8888H
Attachments: PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle YN 8888H
Date of survey: 26/2/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 27 February 2019 3:23 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000860MFSH/1, YN 8888H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle YN 8888H on 26/2/2019

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 22 February 2019 11:41 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000860MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 21 February 2019 6:22 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San <MerinaChia@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000860MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 27 February 2019 3:23 PM
To: 'CWS Motor Claims'
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000860MFSH/1, YN 8888H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle YN 8888H on 26/2/2019

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 22 February 2019 11:41 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000860MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 21 February 2019 6:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San

<MerinaChia@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000860MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com



AVIVA

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



2.38% P.A. Low Interest @ GV
Finance. \$0 Admin Fees. \$1500
Downpayment Monthly \$468
GV Credit Pte Ltd StarAd



Browse by Category ▼

« Back (1 2) Next »

Sort by Date Posted ▼

20 results/page

26 vehicles

Mitsubishi Canter

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Canter		Any	Any	2014	Any	Any	Any	Availabl
	Mitsubishi	Fuso Canter FEB21	\$39,800	\$7,260 /yr	21-Aug-2014	2,998 cc	-	Truck	Availabl
Fuel Type: Diesel 1 Owner! In Good Condition! Cheapest In Town, Reliable 14 Feet Lorry You Can Trust! Full Loan Available! High Trade-In Price! Trusted Partner For Your Commercial Vehicle Needs!									
ABWIN Bus Pte Ltd Posted: 26-Feb-2019 Tags: 2014 Mitsubishi Fuso, 2014 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEB71	\$48,800	\$8,860 /yr	29-Aug-2014	2,998 cc	-	Truck	Availabl
Fuel Type: Diesel We Provide Up To 100% In-house Loan And Low Insurance Quotation. For More Enquiries Please Contact Us!									
ABWIN (1994) Pte Ltd Posted: 26-Feb-2019 Tags: 2014 Mitsubishi Fuso, 2014 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEA01	\$39,800	\$7,810 /yr	31-Mar-2014	2,998 cc	109,817 km	Truck	Availabl
Fuel Type: Diesel Think One Automobile & Trading									
Posted: 25-Feb-2019 Tags: 2014 Mitsubishi Fuso, 2014 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Mitsubishi	Fuso Canter FEA01	\$38,800	\$6,940 /yr	30-Sep-2014	2,998 cc	-	Truck	Availabl
Fuel Type: Diesel FEA01 Auto Box 7.5 Feet For Sale. 1 Owner Only, Tip Top Condition, No Need Say So Much Come And See And You Will Know How Good Is The Lorry. Trade In High Loan Available. Door Step Viewing Can Be Arra...									
ABWIN (1994) Pte Ltd Posted: 25-Feb-2019 Tags: 2014 Mitsubishi Fuso, 2014 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									
	Ralliart Emblem Chrome Colour Emblem. More info about this product								
	Mitsubishi	Fuso Canter FEB21	\$43,500	\$8,170 /yr	23-Jun-2014	2,998 cc	-	Truck	Availabl
Fuel Type: Diesel In House Finance Available.									
Posted: 25-Feb-2019 Tags: 2014 Mitsubishi Fuso, 2014 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi									

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9601W
Vehicle Details	
Vehicle No.:	YN8888H
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	4P10B30164
Chassis No.:	FEB21EA00954
Maximum Power Output:	-
Open Market Value:	\$30,562.00
Original Registration Date:	09 Sep 2014
First Registration Date:	09 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$1,529.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Sep 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$29,933.00
COE Rebate Amount:	\$16,569.00
Total Rebate Amount:	\$16,569.00

The information contained herein is correct as at 26 Feb 2019

OK

Vehicle Estimate

Page: 1/1

Supplier: _____

Vehicle No.:

YN88884.

Attention to: _____

DETAIL LAB	
Person-in-charge:	
Chassis No.:	
Year:	

Make & Model:

Mitsubishi
 Canter

	Parts/Description	Qty	Unit Price (\$)
1	Tail Board Assy. X R	1 PC	
2	RH Tail Board Hook Assy. X R	1 PC	
3	Tail Board end stopper RH. /	1 PC	
4	RH Tail Lamp Assy. X	1 Jlt	
5	RH Tail Board stopper Hinge. X	1 PC	
6	REAR Reinforcement Beam. X	1 Jlt	
7	RH Tail Lamp Panel	1 PC	
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20	labon.		
21	Panel Repair		
22	Spray Painting		
23	Check wiring & electrical system.		
24	Remove & install Tail Board		
25	Remove / install Reinforcement Beam Rr		
26			
27			
28			
29	LKK Auto Consultants hence notify the Repairer of the following:		
30	• To resurvey before/after spray painting		
31	• To display damaged part(s) during resurvey		
32	• Parts prices are subject to confirmation		
33	• Third party survey is on a "Without Prejudice" basis		
34	• No illegal modification(s) is allowed		
35	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
36	Acknowledged by Repairer		

Signature:
 Date:
 Date:

Vehicle Estimate

Page: 1/1

Supplier: _____

Vehicle No.:

YN8888H.

Attention to: _____

DETAIL LAB	
Person-in-charge:	
Chassis No.:	
Year:	

Make & Model:

Mitsubishi
 Canter

Parts/Description	Qty	Unit Price (\$)
1 Tail Board Assy. x R	1 PC	1350.00 X
2 RH Tail Board Hook Assy. x R	1 PC	385.00 X
3 Tail Board End Stopper RH. / DD	1 PC	58.00 /
4 RH Tail Lamp Assy. x NN	1 set	385.00 X
5 RH Tail Board Stopper Hinge. x NN	1 PC	235.00 X
6 Rear Reinforcement Beam x NN	1 set	685.00 X
7 RH Tail Lamp Panel / DD	1 PC	185.00 /
8		
9		243
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20 Labor.		
21 Panel Repair		450.00 300
22 Spray Painting		450.00 300
23 Check wiring & electrical system.		80.00 30
24 Remove & install Tail Board		250.00 X
25 Remove / install Reinforcement Beam Rr		250.00 X
26		630
27		
28		4763
29		
30		
31		
32		
33		
34		
35		
36		

- LK to Consultants hence notify the insurer of the following:
- To survey before/after spray painting
 - To pay damaged part(s) during resurvey
 - Prices are subject to confirmation
 - The survey is on a "Without Prejudice" basis
 - No modification(s) is allowed
 - S. 35 Item(s) must be removed and
 - is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

873
 L/S - 698.4
 = 700

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 26 March 2019 4:09 PM
To: 'benedict yap'
Cc: SUR
Subject: RE: YN 8888H-DOA: 1/2/2019

Dear Sir,

Noted with thanks.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: benedict yap <detail.lab@gmail.com>
Sent: Tuesday, 26 March 2019 3:49 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: YN 8888H-DOA: 1/2/2019

Hi Veron

I confirm the Offer Lump Sum at \$700 @ 2 days COR.

Thanks

On Tue, Mar 26, 2019 at 3:26 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$700/- @ 2 days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--
Should you require further queries or clarifications, please do not hesitate to contact me.

Best Regards

Ben Yap
Detail Lab
Swissvax Singapore
mobile: 9844 8533

Veron Chen (LKKAuto)

From: benedict yap <detail.lab@gmail.com>
Sent: Friday, 15 March 2019 5:23 PM
To: Steve Chen (LKK Auto)
Subject: Workshop Estimate YN8888H
Attachments: YN8888Hestimate.PDF

Dear Steve

For your perusal - workshop estimate YN8888H

--

Should you require further queries or clarifications, please do not hesitate to contact me.

Best Regards

Ben Yap
Detail Lab
Swissvax Singapore
mobile: 9844 8533

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003391/Evd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 954Y	Veh. Inspected	YN 8888H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000860MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	21/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	FEB21EA00954	Colour	WHITE	
Odometer	317111	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/85 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	195/85 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	195/85 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/02/2019	Inspection Date	26/02/2019	
Survey held at	DETAIL LAB BLK 8 KAKI BUKIT AVE 4 #02-03/04 PREMIER @ KB SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8888H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL BOARD ASSY	TO REPAIR SEE LABOUR	1,350.00	-
1	RH TAIL BOARD HOOK ASSY	TO REPAIR SEE LABOUR	385.00	-
1	TAIL BOARD END STOPPER RH	DENTED	58.00	58.00
1	SET RH TAIL LAMP ASSY	NOT NECESSARY	385.00	-
1	RH TAIL BOARD STOPPER HINGE	NOT NECESSARY	235.00	-
1	SET REAR REINFORCEMENT BEAM	NOT NECESSARY	685.00	-
1	RH TAIL LAMP PANEL	DENTED	185.00	185.00
			3,283.00	243.00
	<u>LABOUR</u>			
	PANEL REPAIR, INCLUSIVE OF THE REPAIR OF TAIL BOARD ASSY AND RH TAIL BOARD HOOK ASSY.		450.00	300.00
	SPRAY PAINTING.		450.00	300.00
	CHECK WIRING & ELECTRICAL SYSTEM.		80.00	30.00
	REMOVE & INSTALL TAILBOARD.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL REINFORCEMENT BEAM RR.	NOT NECESSARY	250.00	-
			1,480.00	630.00
	GRAND TOTAL		4,763.00	873.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			700.00

Report Ref No. CS/FCI19003391/Evd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.