

BY:

Adrian

REP CS/CTI 1900 3452 / And 3<sup>rd</sup>

Special Instruction

IN (cont)

Chong Boon Sun

ASSIGNMENT (Office)

CTI

Date/Time: 28/2/19 @ 11:19am

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLW 96964

Insured:

at Workshop no/s

Sheng Ji Hui

Tel:

91119222

of

2 Kaki Bukit Ave 2 # 01-36

Policy No:

OMPEN 3072391800

Claim No:

SNM19 D200 48201

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

(Client's Record)

D.O.A

21/01/2019

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:30am @ 28/2/19

Person Contacted:

Mr. Tan

Vehicle

(IN) OUT

Date/Time	Action/Instruction (←) Estimate
	SLW 96964 - CS/CTI 1900/1922 / Dvd3 D.O.A. 24/1/2019
28/2/19 @ 4:30pm	report to Chong Boon Sun via Meimien.
28/07/19 @ 12:01pm	Mfred informed C/A on L9 basis @ ex: \$1500 via Meimien.
28/07/19 @ 2:28pm	Informed Mr Low C/A on L9 basis @ ex: \$1500 by email. US \$ 12700, 7 days. (Per \$ 14766.80, 54%)

ASS. REC. BY:

REP:

# ASSIGNMENT

Adrian

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLW9696U Yr Regn: 2014 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Macan c.c 1984

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 55794 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WP122295 ZFLB12789

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/40R20

R: 275/40R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 25/02/19

Survey held at Sheng Li Lai

Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD China

RECEIVED 27 OCT 2019

MV: 175K

PV: 112.5K

Nett: 62.5K

Date/Time, File Pass to?

1) Mio Purisa

3) \_\_\_\_\_

5) \_\_\_\_\_

Prel. Report

Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

4) \_\_\_\_\_

6) \_\_\_\_\_

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

\_\_\_ S + RS, \_\_\_ SI

Photos

Others

TOTAL

Date:


## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Submitted	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019		25 Feb 2019 11:19 Assign				<b>New Assignment</b> <input type="button" value="Cancel Case"/>

Main	Reference	Claim Details	Documents	<input type="button" value="Show All"/>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	MR LAU ZENGBIN, ID: S8239008A								
Vehicle Reg. No.:	SLW9896U	Date of Loss:	24/01/2019 18:00 - :59						
Claim Type:	OD / SNM19D200482C01	Policy/Cover Note No.:	DMPCSN3072391800 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222								
Handling Insurer:	China Shipping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/03/2019]								
Driver/Custodian:	NG WUAN CHIN (HUANG WAN JUN) (36 / Female), NRIC: S8204483C, Tel: +6593252324 Email: NOEMAIL								
Adj Assg. Remarks:	survey revert								
<b>ASSOCIATED MAIL RECEIVED</b>				<input type="button" value="View All"/> <input type="button" value="Compose Case Mail"/>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>				<input type="button" value="View All"/> <input type="button" value="Search Tasks"/> <input type="button" value="Create New Task"/> <input type="button" value="Complete"/>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Monday, 25 February 2019 11:23 AM  
**To:** assignments  
**Subject:** FW: SLW9696U - Clarifications of the Delay

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 25 February 2019 11:22 AM  
**To:** Sheng Li Lai <slshenglilai@gmail.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: SLW9696U - Clarifications of the Delay

Dear Sir,

We have allowed OD claim and have appointed LKK.

Dear LKK,

Please refer Merimen.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208184E

DD: 63866171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

Disclaimer:

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Chong Boon Sen  
**Sent:** Monday, 25 February, 2019 11:05 AM  
**To:** 'Sheng Li Lai' <[shenglilai@gmail.com](mailto:shenglilai@gmail.com)>  
**Subject:** RE: SLW9696U - Clarifications of the Delay

Dear Mr Low,

Noted with thanks.

Am looking at matter now.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-03 Springleaf Tower

Singapore 079909

Co. Reg. No. 200230434E

DIC: 3836171

Fax: 67244173

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.cntaiping.com](http://www.cntaiping.com)

*Disclaimer:*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in an agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or in part, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

From: Sheng Li Lai [mailto:[slshenglilai@gmail.com](mailto:slshenglilai@gmail.com)]

Sent: Monday, 25 February, 2019 11:04 AM

To: Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

Subject: SLW9696U - Clarifications of the Delay

Hi Boonsen,

As spoken on the phone earlier on, I will be explaining why the estimate took longer than 14 days. The accident took place on the 24th January and reporting was done the next day afternoon. However, due to Chinese New Year, both workshops and suppliers are closed. In addition, there was some misunderstanding over the Number Plate as the retained plate was not updated on the original Certificate of Insurance.

Subsequently, we have provided you the official LTA letter as a proof of verification on the registered number plate.

Hence, I will sincerely like to apologise for the delay of SLW 9696 U and hope that your side can consider this claim and proceed accordingly. Thank you.

Best Regards,

Mr Low

SHENG LI LAI

Kaki Bukit Autohub

2 Kaki Bukit Ave 2 #01-36

Singapore 417921

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 27 February 2019 2:28 PM  
**To:** sllshenglilai@gmail.com  
**Cc:** SUR  
**Subject:** RE: CHINA-OD VEHICLE SLW 9696U (DOA: 24/01/2019)

Dear Mr Low,

Re-send.

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SLW 9696U at repair cost on Lump Sum Basis (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 27 February 2019 2:14 PM  
**To:** sllshenglilai@gmail.com  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** CHINA-OD VEHICLE SLW 9696U (DOA: 24/01/2019)

Dear Mr Low,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SLW 9696U (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 27 February 2019 2:14 PM  
**To:** sllshenglilai@gmail.com  
**Cc:** SUR  
**Subject:** CHINA-OD VEHICLE SLW 9696U (DOA: 24/01/2019)

Dear Mr Low,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SLW 9696U (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### Claim Audit

AUDIT TRAIL				By
No.	On	Audit	Remarks	[I] Chong Boon Sen
1	25 Feb 2019 11:18	Cim Veh Model Changed	(203486) PORSCHE MACAN 2.0 PDK (A). Reg No: SLW9696U. Policy No: DMPCSN3072391800. Acct Date: 2019/01/24. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Sheng Li Lai (KAKI BUKIT). Ins.Status => Incoming Claim. Created from SAS:MANA119012250	[I] Chong Boon Sen
2	25 Feb 2019 11:18	Cim Created		[I] Chong Boon Sen
3	25 Feb 2019 11:19	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):survey revert	[I] Chong Boon Sen
4	25 Feb 2019 11:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/06	[I] Chong Boon Sen
5	25 Feb 2019 11:19	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
6	25 Feb 2019 11:24	Assignment 1st Accessed		[A] Nivitha Govindasamy
7	25 Feb 2019 14:58	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Nivitha Govindasamy
8	25 Feb 2019 16:16	Adj Rpt Initiated		[A] SHIAU CHAN
9	25 Feb 2019 16:16	Cim Dtl Modified	JPJ Reg. Date: -> 2014/12/09.	[A] SHIAU CHAN
10	25 Feb 2019 16:16	Cim Details Notified		[A] SHIAU CHAN
11	25 Feb 2019 16:22	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/06	[A] SHIAU CHAN
12	25 Feb 2019 16:30	Adj Mandate Request	Cur.Req:27858.88:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. THE VEHICLE REPAIR ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	27 Feb 2019 12:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/06. Mandate Remarks: Please proceed to authorize repairs at \$22,250.00 (LUMP SUM) BEFORE Excess of \$1,500.00. RE-INSPECTION OF VEHICLE REQUIRED.	[I] Alfred Toh
14	27 Feb 2019 12:01	Adj Mandate Set	Approved:22250.00:Please proceed to authorize repairs at \$22,250.00 (LUMP SUM) BEFORE Excess of \$1,500.00. RE-INSPECTION OF VEHICLE REQUIRED.Reinsp:Adj d ecides.	[I] Alfred Toh

Date From  Date To  Audit Type  Go

**ACTIVITY**

No record

**Merimen Billing for this case - Transaction History**

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2067504	25/02/2019 16:16	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLW9696U		10.70

Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 25 Feb 2019

### Preliminary Advice

Vehicle No	: SLW9696U	Accident Date	: 24/01/2019
Make	: PORSCHE MACAN	Policy No.	: DMPCSN3072391800
Assignment Date	: 25/02/2019	Excess	: S\$1,500.00
Date of Inspection	: 25/02/2019	Est. Duration of Repair	: 7.00
Inspection At	: SHENG LI LAI (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT SINGAPORE 417921		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,466.80
Revised Amount	:S\$	7,700.00
Check Items (Estimated)	:S\$	20,158.80
Total	:S\$	27,858.80
Lump Sum Repair	:S\$	22,250.00

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	112,454.00
Salvage Value	:S\$	
Margin for Repair	:S\$	62,546.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/01/2019 16:54
Date Of Accident	24/01/2019 18:00
Exact Location Of Accident	UPP BUKIT TIMAH RD TWDS CHOA CHU KANG RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW9696U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MR LAU ZENGBIN
NRIC No	S8239008A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91252324
Alternative Phone No	OFFICE-91252324
<b>Vehicle Particulars</b>	
Manufacturer	PORSCHE
Model	MACAN 2.0 A/T ABS D/AIRBAG AWD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3072391800
Cover Note Number	
<b>Driver</b>	
Name of Driver	NG WUAN CHIN (HUANG WAN JUN)
NRIC No	S8204483C
Date Of Birth	04/02/1982
Occupation	INDOOR
Date Of Driving Pass	07/03/2007
Driving Experience	11 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93252324
Fax Number	
Contact Number	OFFICE-93252324
E-Mail Address	NOEMAIL

Address	95 PAVILION CIRLCE
Postcode	658535
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO STATEMENT.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SHD4329K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LOH YEOW SENG
NRIC/Passport Number	S1337088E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: :
	GENDER: :

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA):**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers, lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agent(s) (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected (under (a) above) may be shared, disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Person's Signature  
Name  
NRIC/IN No.



**Accident Sketch Plan**

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE.  
SUDDENLY VEHILCE B JAMMED BRAKE. I COULDN'T BRAKE MY VEHICLE IN  
TIME AND HIT ONTO VEHICLE B REAR PORTION.

Others

Nicole

Enquire Vehicle Registration Details

NRIC/Passport/Company Cert No	S8239008A
Owner ID Type	Singapore NRIC
Owner Name	LAU ZENGBIN (LPU ZENGBIN)
Registered Address	66 CHESTNUT AVENUE #14-11 SINGAPORE 679520
Mailing Address	
Birth Date	09 Dec 1962
Vehicle No	SLW9696U
Previous Vehicle No	SLZ30815
Effective Date of Ownership	14 Nov 2018
Original Regn Date	04 Dec 2014
Registration Date	04 Dec 2014
Year of Manufacture	2014
Vehicle Type	Passenger Motor Car
Vehicle Scheme	-
Vehicle Attachment 1	No Attachment
Vehicle Attachment 2	-
Vehicle Attachment 3	-
Vehicle Make	PORSCHE
Vehicle Model	MACAN 2.0 A/T ABS D/AIRBAG AWD
Primary Colour	White
Secondary Colour	-
Passenger Capacity	4
Chassis No	WP1ZZZ95ZF1B12789
Engine No	0B4834
Engine Capacity / Power Rating	1996 cc /
Maximum Power Output	174.0 kW (233 bhp)
Fuel Type	Petrol
Max Unladen Weight	1940 kg
Maximum Laden Weight	2445 kg
Open Market Value	\$67,995.00
PARF Eligibility	Yes
PARF Eligibility Expiry Date	03 Dec 2024
Minimum PARF Benefit	\$47,195.00
No. of Transfers	2
Co Label No	1125158671
COE No	2014110103000023R
COE Expiry Date	03 Dec 2024
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Registration Category	B - Car above 1600cc or 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium	\$72,180.00
Actual QP Paid	\$72,180.00
QP (Regn Cat)	\$72,180.00
DPG Cash Rebate Eligibility	No
QP during COE Bidding Exercise	\$72,180.00
Additional Registration Fee Rate	First \$20,000.00 (100%), next \$30,000.00 (140%), next \$17,995.00 (180%)
Actual ARF Paid	\$94,391.00
Vehicle Lifespan Expiry Date	No Lifespan
CO2 Emission	166.00 (g/km)
CEV/VES Rebate Utilised Amount	
CO Emission	
HC Emission	

Others

Replace Vehicle No. (Confirmation)

Vehicle No. To Be Replaced	S, Z30815
Vehicle Make	PORSCHE
Vehicle Model	MACAN 2.0 A/T ABS D/A/PRAG AWD
Chassis No.	WP12ZZ95ZFL812789
Engine No.	094834
Motor No.	
Replace With	S0W9696U
Expiry Date	15 Nov 2018

Note:

Upon successful replacement of the vehicle registration number:

- You are required to change the physical number plate(s) on the existing vehicle and display the newly replaced vehicle registration number by 18 Nov 2018. Please print and produce the receipt at the workshop as proof of approval from the LTA to change your vehicle number plate(s).
- Please visit our website at [www.onemotoring.com.sg](http://www.onemotoring.com.sg) if you have any queries.

Previous

Print

Confirm

Cancel

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9008A
Vehicle Details	
Vehicle No.:	SLW9696U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	PORSCHE
Vehicle Model:	MACAN 2.0 A/T ABS D/AIRBAG AWD
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	084834
Chassis No.:	WP1ZZZ95ZFLB12789
Maximum Power Output:	174.0 kW (233 bhp)
Open Market Value:	\$67,995.00
Original Registration Date:	04 Dec 2014
First Registration Date:	04 Dec 2014
Transfer Count:	2
Actual ARF Paid:	\$94,391.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2024
PARF Rebate Amount:	\$70,793.00
Intended COE Rebate Details	
COE Expiry Date:	03 Dec 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$72,180.00
COE Rebate Amount:	\$41,661.00
<b>Total Rebate Amount:</b>	<b>\$112,454.00</b>

The information contained herein is correct as at 25 Feb 2019

OK

New Cars

**Used Cars**

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



2.38%P.A Low Interest@Gv  
Finance, \$0 Admin Fees, \$1500  
Downpayment Monthly \$468  
Gv Credit Pte Ltd StarAd



**PRIME MOTOR & LEASING**

(SIANG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.



Browse by Category Save Search Print Sort by Date Posted 20 results/page

8 vehicles

**Search** Macan

Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Macan	Any	Any	2014	Any	Any	Any	Available
------------------	-------	-----	-----	------	-----	-----	-----	-----------



<input type="checkbox"/>	<b>Porsche Macan S 3.0A PDK</b>	<b>\$189,800</b>	<b>\$25,660 /yr</b>	<b>03-Jul-2014</b>	<b>2,997 cc</b>	<b>108,300 km</b>	<b>SUV</b>	<b>Available</b>
--------------------------	---------------------------------	------------------	---------------------	--------------------	-----------------	-------------------	------------	------------------

18"Macan S Wheel, Mobile Phone Prep + BT, Fully Maintained & Serviced By Stuttgart, 5 Years Warranty Till July 2019, Please Call For More Details And View By Appointment! Buy With Assurance From Porsche...

Porsche Pre-Owned Centre

Posted: 30-Jan-2019 Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche



<input type="checkbox"/>	<b>Porsche Macan 2.0A PDK</b>	<b>\$183,800</b>	<b>\$25,450 /yr</b>	<b>08-Sep-2014</b>	<b>1,984 cc</b>	<b>48,500 km</b>	<b>SUV</b>	<b>Available</b>
--------------------------	-------------------------------	------------------	---------------------	--------------------	-----------------	------------------	------------	------------------

Extremely Well Maintained! Fully Serviced By Agent! Under 5 Years Warranty By Agent! View To Believe! Up To 90% Financing Possible! Trade In Welcome! In House Finance Interest As Low As 2.48%! Call/SM...

Think One Automobile & Trading

Posted: 22-Feb-2019 Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche

**PREMIUM AD**



<input type="checkbox"/>	<b>Porsche Macan Turbo 3.6A PDK</b>	<b>\$278,800</b>	<b>\$35,100 /yr</b>	<b>26-Sep-2014</b>	<b>3,604 cc</b>	<b>30,000 km</b>	<b>SUV</b>	<b>Available</b>
--------------------------	-------------------------------------	------------------	---------------------	--------------------	-----------------	------------------	------------	------------------

Panoramic Roof, Porsche Active Suspension Management, Sports Exhaust, Full Leather Agate Grey, Reverse Camera Inc Front/Rear Park Assist, Cruise Control, 19" Macan Turbo Design Wheels, Sport Steering,...

Porsche Pre-Owned Centre

Posted: 15-Feb-2019 Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche



<input type="checkbox"/>	<b>Porsche Macan S 3.0A PDK</b>	<b>\$189,800</b>	<b>\$24,970 /yr</b>	<b>09-Oct-2014</b>	<b>2,997 cc</b>	<b>78,000 km</b>	<b>SUV</b>	<b>Available</b>
--------------------------	---------------------------------	------------------	---------------------	--------------------	-----------------	------------------	------------	------------------

Full Agent Serviced Records With 5 Years Warranty And Free Maintenance Package By Stuttgart Auto, Upgraded 20" RS Spyder Design Wheels, Navigation System, Bluetooth Tel/Audio, Power Tailgate And Etc, ...

Posted: 17-Feb-2019 Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche



**New Porsche Macan S gets more features**

Using the Macan S as its starting point, the Porsche Exclusive Manufaktur has equipped a model with a wide range of additional features.

Read this article



<input type="checkbox"/>	<b>Porsche Macan Turbo 3.6A PDK</b>	<b>\$245,800</b>	<b>\$29,740 /yr</b>	<b>17-Oct-2014</b>	<b>3,604 cc</b>	<b>49,000 km</b>	<b>SUV</b>	<b>Available</b>
--------------------------	-------------------------------------	------------------	---------------------	--------------------	-----------------	------------------	------------	------------------

Highly Spec. 19" Macan Turbo Wheel. With Navigation And Bluetooth, Front And Rear Park Assist With Reversing Camera, Buy With Peace Of Mind At Porsche Pre-Owned Center. Trade In Welcome. With Existing...

Porsche Pre-Owned Centre

Posted: 10-Jan-2019 Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche



<input type="checkbox"/>	<b>Porsche Macan Diesel S 3.0A PDK</b>	<b>\$183,800</b>	<b>\$23,760 /yr</b>	<b>03-Nov-2014</b>	<b>2,967 cc</b>	<b>84,000 km</b>	<b>SUV</b>	<b>Available</b>
--------------------------	--	------------------	---------------------	--------------------	-----------------	------------------	------------	------------------

**Fuel Type:** Diesel (Euro 5 Engine and Above)

Tip Top Interior Exterior With Low Mileage! View To Believe! Frequent Service At Agent And Still Under Agent Warranty. Car Is Wrapped, Original Paintwork Intact. Contact Our Professional Sales Team To...

Car Search

Posted: 04-Jan-2019 Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche

**PREMIUM AD**

3402752314D H515087

**Compare**

<input type="checkbox"/>	<b>Porsche Macan 2.0A PDK</b>	<b>\$173,800</b>	<b>\$22,890 /yr</b>	<b>12-Nov-2014</b>	<b>1,984 cc</b>	<b>90,000 km</b>	<b>SUV</b>	<b>Available</b>
--------------------------	-------------------------------	------------------	---------------------	--------------------	-----------------	------------------	------------	------------------



One Of The Most Outstanding Posh SUV In Our Lot Now! A Luxurious Feel Of The Posh And Full Stars Level Of Comfort. A Fully Maintained & Serviced By Stuttgart Since Day One, All Records Available Store...

PREMIUM AD



Posted: 23-Feb-2019

Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche



Porsche Macan 2.0A PDK

\$182,000

\$24,460 /yr

28-Nov-2014

1,984 cc

42,000 km

SUV

Available

Asking Only \$182K. This Is A Special Indent Unit From Stuttgart. Special Color Combination That I Paid Additional \$15k Including Other Add On Features. Very Low Mileage Of 42K KM. Still Under Agent 5 Y...

GREAT OWNER



Posted: 20-Feb-2019

Tags: 2014 Porsche Macan, 2014 porsche macan, Porsche Macan, porsche macan, Porsche, Macan, macan, Used Porsche

Save this search criteria, to get email alerts whenever a match is found.

Save Search

For old advertisements, view Expired ads

20 results/page

[Home](#) | 
 [New Cars](#) | 
 [Used Cars](#) | 
 [Sell My Car](#) | 
 [Directory](#) | 
 [Products](#) | 
 [Insurance](#) | 
 [Article](#) | 
 [Forum](#) | 
 [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & DPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Macan Singapore, used Macan Singapore, used Macan, used vehicles Singapore or even buy used Macan Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



[About Us](#) | 
 [Careers](#) | 
 [Contact Us](#) | 
 [Sitemap](#) | 
 [Terms of Service](#) | 
 [Privacy Policy](#) | 
 [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

# 昇利来 SHENG LI LAI



Kaki Bukit Auto Hub 2 Kaki Bukit Ave 2 #01-36  
Singapore 417921  
Tel: 6842 0302 Fax: 6746 0295

## Estimate

M/s **China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909

Date : 19.02.2019

Vehicle No : **SLW 9696U** was SLZ 3081S

Make/ Model : Porsche Macan

Chassis No : WP1ZZZ95ZFLB12789

Acc. Date : 24.01.19

Policy No : DMPCSN3072391800

Your Ref :

Tel: 6389 6111 (main)

Fax: 6222 1033

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

S/n.	Qty	Particulars	Unit Price	Amount
<b>Materials</b>				
1	1 pc	Frt Bonnet <i>Dented</i>	\$ 3,000.00	\$ 3,000.00 ✓ 2100
2	2 pc	Frt Bonnet Hinge (L/RH) <i>for m.</i>	\$ 150.00	\$ 300.00 +
3	2 pc	Frt Bonnet Damper (L/RH)	\$ 110.00	\$ 220.00 +
* 4	2 pc	Frt Bonnet Weatherstrip (L/RH) <i>seen</i>	\$ 35.00	\$ 70.00 +
5	2 pc	Frt Top Bonnet Hook <i>seen</i>	\$ 55.00	\$ 110.00 +
6	1 pc	Frt Bonnet Porsche Logo <i>seen</i>	\$ 220.00	\$ 220.00 +
* 7	2 pc	Frt Bonnet Mechanism Lock (L/RH) <i>seen</i>	\$ 120.00	\$ 240.00 +
8	2 pc	Headlamp Assy (L/RH) <i>RH cracked.</i>	\$ 3,200.00	\$ <del>6,400.00</del> ? 2700
9	2 pc	Headlamp Rim Moulding (L/RH) <i>for m.</i>	\$ 100.00	\$ 200.00 ✓
10	1 pc	Frt Bumper Assy <i>Dented</i>	\$ 950.00	\$ 950.00 ✓
11	20 pc	Frt Bumper Clips <i>m</i>	\$ 3.00	\$ 60.00 ✓
12	2 pc	Frt Bumper Side Holder (L/RH) <i>m</i>	\$ 100.00	\$ 200.00 ✓
13	1 pc	Frt Bumper Tow Hook Cover <i>Missing</i>	\$ 55.00	\$ 55.00 ✓
14	1 pc	Frt Bumper Reinforcement <i>Best</i>	\$ 375.00	\$ 375.00 ✓
15	2 pc	Frt Bumper Reinforcement Bracket (L/RH) ? <i>m</i>	\$ 120.00	\$ 240.00 ✓
16	2 pc	Frt Bumper Lower Foglamp (L/RH) <i>RH missing</i>	\$ 500.00	\$ 1,000.00 <i>500</i>
17	2 pc	Frt Bumper Signal Lamp (L/RH) <i>RH cracked</i>	\$ 375.00	\$ <del>750.00</del> ? 375.
18	1 pc	Frt Bumper No. Plate Garnish <i>missing</i>	\$ 100.00	\$ 100.00 ✓
19	1 pc	Frt Bumper Lower Air Grille <i>cracked.</i>	\$ 200.00	\$ 200.00 ✓
20	2 pc	Frt Bumper Side Air Duct Garnish (L/RH) <i>RH del.</i>	\$ 100.00	\$ 200.00 <i>100</i>
21	2 pc	Frt Bumper Side Film Garnish (L/RH) <i>RH seen</i>	\$ 80.00	\$ 160.00 <i>80</i>
22	1 pc	Frt Center Grille <i>cracked.</i>	\$ 350.00	\$ 350.00 ✓
23	1 pc	Frt Center Grille Inner Garnish <i>cracked</i>	\$ 350.00	\$ 350.00 ✓
24	1 pc	Frt Center Grille Inner Air Duct <i>cracked.</i>	\$ 350.00	\$ 350.00 ✓
25	1 pc	Frt Bumper PDC (RH) - parking distance sensor <i>Miss</i>	\$ 280.00	\$ 280.00 ✓
26	2 pc	Frt Lower Air Grille Inner Side Air Duct (L/RH) <i>for m</i>	\$ 240.00	\$ 480.00 ✓
27	1 pc	Frt Bumper Under Shield <i>for m</i>	\$ 250.00	\$ 250.00 ✓
28	8 pc	Frt Bumper Under Shield Clips <i>new</i>	\$ 3.00	\$ 24.00 ✓
29	1 pc	Radiator Assy <i>Dented</i>	\$ 300.00	\$ 300.00 ✓
30	1 pc	Radiator Top Hose <i>for m</i>	\$ 175.00	\$ 175.00 +
31	1 pc	Radiator Lower Hose	\$ 200.00	\$ 200.00 +
32	2 pc	Radiator Top Bush Mounting <i>new</i>	\$ 5.00	\$ 10.00 ✓
33	1 pc	Radiator Auxillary Fan Assy <i>for m</i>	\$ 680.00	\$ 680.00 ✓

34	1 pc	Radiator Fan ECU	NEW
35	1 pc	Aircon Condenser	Best
36	1 pc	Aircon Liquid Pipe	NEW
37	1 pc	Aircon Aluminium Pipe	NEW
38	1 pc	Aircon Discharge Hose	NEW
39	1 pc	Horn	NEW
40	1 pc	Turbo Inter Cooler	Painted
41	2 pc	Turbo Pipe (L/RH)	NEW
42	1 pc	Radiator Support Panel Assy	Body
43	1 pc	Radiator Spare Tank Return Pipe	NEW

11584  
13321.60

\$	320.00	\$	320.00	X
\$	1,450.00	\$	1,450.00	✓
\$	300.00	\$	300.00	X
\$	450.00	\$	450.00	X
\$	450.00	\$	450.00	X
\$	120.00	\$	240.00	X
\$	150.00	\$	150.00	✓
\$	350.00	\$	700.00	X
\$	275.00	\$	275.00	✓
\$	55.00	\$	55.00	X
Total :		\$	22,889.00	
Plus 20% :		\$	4,577.80	
Total Parts :		\$	27,466.80	

Labour

- 1 To remove, rearrange electrical wirings, check lightings
- 2 To remove, replace aircon parts, vacuum & refill aircon gas.
- 3 To remove, replace turbo parts, retro fit.
- 4 To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.
- 5 To putty and respray painting on affected area.

\$	120.00	50
\$	200.00	150
\$	400.00	200
2600		
\$	1,800.00	1200, 1400
\$	1,500.00	600, 800
Total Labour :	\$	4,020.00

**Grand Total : \$ 27,466.80**

31486.804



Sheng Li Lai  
H/P: 91119222

Adrian Lim,  
H/S 25/02/19.  
07 Days  
Excess \$1500.  
Not Authorised.  
Total: 15921.60  
L/S 12.7K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Feb 2019		25 Feb 2019 11:19 <a href="#">Edit Adj Rpt</a>	<b>S\$12,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$12,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	MR LAU ZENGBIN, ID: S8239008A		
Vehicle Reg. No.:	SLW9696U	Date of Loss:	24/01/2019 18:00 - :59 [49 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D200482C01	Policy/Cover Note No.:	DMPCSN3072391800 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/03/2019]		
Driver/Custodian:	NG WUAN CHIN (HUANG WAN JUN) (36 / Female), NRIC: S8204483C, Tel: +6593252324 Email: NOEMAIL		
Adj Asg. Remarks:	survey revert		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>CHINA_TAIPING (27/02/2019): Alert - Adj Mandate Approved (S\$22250.00) - SLW9696U - Claim Handler: Chong Boon...</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			



## Claim Documents

\*SLW9696U (SNM19D200482C01)  
 OD  
 Jan 24 2019 6:00PM  
 [MR LAU ZENGBIN]  
 Sheng Li Lai

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▾

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/01/19 17:04	<b>Accident Statement</b>	Load HTM	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 16:22	<b>Adjuster Immediate Advice</b>	Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
17	25/01/19 17:01	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	25/02/19 16:43	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
4	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	25/02/19 16:43	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
15	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
16	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
17	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
18	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
19	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
20	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
21	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
22	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
23	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
24	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
25	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
26	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
27	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
28	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
29	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
30	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
31	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
32	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
33	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
34	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
35	25/02/19 16:43	General View	Load JPG	<input checked="" type="checkbox"/>
36	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
68	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
71	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
72	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
75	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
76	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
77	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	21/10/19 16:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/02/19 11:20	repair estimate	Load PDF	
2	25/02/19 11:20	od contact details	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/01/19 17:02	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 17:02	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 17:02	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 17:02	Others [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	25/01/19 17:02	Others [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 16:29	ESTIMATE	Load PDF	

### Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/01/19 17:04	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/01/19 17:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 17:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 17:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 17:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
5	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
6	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
7	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
8	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
9	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
10	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
11	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
12	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
13	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
14	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
15	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
16	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>
17	25/01/19 17:01	<b>Accident Photo</b>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	25/01/19 17:02	<b>Accident Sketch Plan</b>	Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 17:02	<b>Accident Sketch Plan</b>	Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 17:02	<b>Accident Sketch Plan</b>	Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 17:02	<b>Others</b>	Load JPG	<input checked="" type="checkbox"/>
5	25/01/19 17:02	<b>Others</b>	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI19003452/AQD3S2  
Date: 23/10/2019

### REFERENCE

Insured/Claimant: MR LAU ZENGBIN Policy No: DMPCSN3072391800  
Date of Loss: 24/01/2019 Nature of Claim: OD Claim No: SNM19D200482C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW9696U** Engine No: 084834  
Make & Model: PORSCHE MACAN, 2.0 PDK (A) Chassis No: WP1ZZZ95ZFLB12789  
Reg. Date: 04/12/2014 (Man. Year: 2014) Odometer: 55794 km  
Colour: White  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$175,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 295/40 R20 Rear Tyre Size: 295/40 R20  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,466.80	13,321.60	14,145.20	51.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	2,600.00	1,420.00	35.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>31,486.80</b>	<b>15,921.60</b>	<b>15,565.20</b>	<b>49.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,700.00</b>		
<b>- Excess (S\$)</b>	1,500.00	1,500.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>29,986.80</b>	<b>11,200.00</b>	<b>18,786.80</b>	<b>62.65</b>

### INSPECTION

Date of Assignment: 25/02/2019  
Date Inspected: 25/02/2019 Inspected At: Sheng Li Lai (KAKI BUKIT)  
NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB  
KAKI BUKIT  
Singapore 417921  
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2019)	
<b>Parts:</b> M1-SUV	PORSCHE MACAN 2.0 PDK (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW9696U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRT BONNET</b> (WCP)	Dented	3,000.00 F	*2,100.00 F
2	2		<b>*FRT BONNET HINGE (L/RH)</b> (WCP)	Not Necessary	300.00 F	*- F
3	2		<b>*FRT BONNET DAMPER (L/RH)</b> (WCP)	Not Necessary	220.00 F	*- F
4	2		<b>*FRT BONNET WEATHERSTRIP (L/RH)</b> (WCP)	Not Necessary	70.00 F	*- F
5	2		<b>*FRT TOP BONNET HOOK</b> (WCP)	Not Necessary	110.00 F	*- F
6	1		<b>*FRT BONNET PORSCHE LOGO</b> (WCP)	Not Necessary	220.00 F	*- F
7	2		<b>*FRT BONNET MECHANISM LOCK (L/RH)</b> (WCP)	Not Necessary	240.00 F	*- F
8	1		<b>*HEADLAMP ASSY (L/RH)</b> (WCP)	O/s Cracked	6,400.00 F	*2,700.00 F
9	2		<b>*HEADLAMP RIM MOULDING (L/RH)</b> (WCP)	Not Necessary	200.00 F	*- F
10	1		<b>*FRT BUMPER ASSY</b> (WCP)	Deformed	950.00 F	*950.00 F
11	20		<b>*FRT BUMPER CLIPS</b> (WCP)	Necessary	60.00 F	*60.00 F
12	2		<b>*FRT BUMPER SIDE HOLDER (L/RH)</b> (WCP)	Necessary	200.00 F	*200.00 F
13	1		<b>*FRT BUMPER TOW HOOK COVER</b> (WCP)	Missing	55.00 F	*55.00 F
14	1		<b>*FRT BUMPER REINFORCEMENT</b> (WCP)	Bent	375.00 F	*375.00 F
15	2		<b>*FRT BUMPER REINFORCEMENT BRACKET (L/RH)</b> (WCP)	Not Necessary	240.00 F	*- F
16	1		<b>*FRT BUMPER LOWER FOGLAMP (L/RH)</b> (WCP)	O/s Missing	1,000.00 F	*500.00 F
17	1		<b>*FRT BUMPER SIGNAL LAMP (L/RH)</b> (WCP)	O/s Cracked	750.00 F	*375.00 F
18	1		<b>*FRT BUMPER NO. PLATE GARNISH</b> (WCP)	Missing	100.00 F	*100.00 F
19	1		<b>*FRT BUMPER LOWER AIR GRILLE</b> (WCP)	Cracked	200.00 F	*200.00 F
20	1		<b>*FRT BUMPER SIDE AIR DUCT GARNISH (L/RH)</b> (WCP)	O/s Deformed	200.00 F	*100.00 F
21	1		<b>*FRT BUMPER SIDE FILM GARNISH (L/RH)</b> (WCP)	O/s Necessary	160.00 F	*80.00 F
22	1		<b>*FRT CENTER GRILLE</b> (WCP)	Cracked	350.00 F	*350.00 F
23	1		<b>*FRT CENTER GRILLE INNER GARNISH</b> (WCP)	Cracked	350.00 F	*350.00 F
24	1		<b>*FRT CENTER GRILLE INNER AIR DUCT</b> (WCP)	Cracked	350.00 F	*350.00 F
25	1		<b>*FRT BUMPER PDC (RH) - PARKING DISTANCE SENSOR</b> (WCP)	Missing	280.00 F	*280.00 F
26	2		<b>*FRT LOWER AIR GRILLE INNER SIDE AIR DUCT (L/RH)</b> (WCP)	Not Necessary	480.00 F	*- F
27	1		<b>*FRT BUMPER UNDER SHIELD</b> (WCP)	Torn	250.00 F	*250.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	8		*FRT BUMPER UNDER SHIELD CLIPS (WCP)	Necessary	24.00 F	*24.00 F
29	1		*RADIATOR ASSY (WCP)	Dented	300.00 F	*300.00 F
30	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	175.00 F	*- F
31	1		*RADIATOR LOWER HOSE (WCP)	Not Necessary	200.00 F	*- F
32	2		*RADIATOR TOP BUSH MOUNTING (WCP)	Necessary	10.00 F	*10.00 F
33	1		*RADIATOR AUXILLARY FAN ASSY (WCP)	Not Necessary	680.00 F	*- F
34	1		*RADIATOR FAN ECU (WCP)	Not Necessary	320.00 F	*- F
35	1		*AIRCON CONDENSER (WCP)	Bent	1,450.00 F	*1,450.00 F
36	1		*AIRCON LIQUID PIPE (WCP)	Not Necessary	300.00 F	*- F
37	1		*AIRCON ALUMINIUM PIPE (WCP)	Not Necessary	450.00 F	*- F
38	1		*AIRCON DISCHARGE HOSE (WCP)	Not Necessary	450.00 F	*- F
39	1		*HORN (WCP)	Not Necessary	240.00 F	*- F
40	1		*TURBO INTER COOLER (WCP)	Dented	150.00 F	*150.00 F
41	2		*TURBO PIPE (L/RH) (WCP)	Not Necessary	700.00 F	*- F
42	1		*RADIATOR SUPPORT PANEL ASSY (WCP)	Damaged	275.00 F	*275.00 F
43	1		*RADIATOR SPARE TYRE RETURN PIPE (WCP)	Not Necessary	55.00 F	*- F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>22,889.00</b>	<b>11,584.00</b>
<b>+ Margin on L,N Items 20.00/15.00% (S\$)</b>	<b>4,577.80</b>	<b>1,737.60</b>
<b>Total Parts (S\$)</b>	<b>27,466.80</b>	<b>13,321.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS.	New	120.00	50.00
2	TO REMOVE, REPLACE AIRCON PARTS, VACUUM & REFILL AIRCON GAS.	New	200.00	150.00
3	TO REMOVE, REPLACE TURBO PARTS, RETRO FIT.	New	400.00	200.00
4	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.	New	1,800.00	1,400.00
5	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.	New	1,500.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>4,020.00</b>	<b>2,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >