

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0021574
Chow I-Ruh

Page: 1 of 3
Your ref: TP-SLQ 8920K AXA
Job No: 70262
Our ref: 19.02.19
Payment:
Date: 22/2/2019

Attn

Vehicle No: SKR 9417Y
Vehicle Model : Toyota Wish
Accident on ...: 21/2/2019

Not Authorized
Resurvey B4 painting
6 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear tailgate	1,175.91	25.00	<i>As</i> 881.93
1.00	Pc	Rear tailgate lock	361.60	25.00	<i>Tm</i> 271.20
1.00	Pc	Rear tailgate chrome moulding	239.10	25.00	<i>CPM</i> 179.33
1.00	Pc	Rear tailgate weatherstrip	302.60	25.00	<i>Cr</i> 226.95
1.00	Pc	Rear bumper	491.90	25.00	<i>R1</i> 368.93
1.00	Pc	Rear bumper bracket LH	48.44	25.00	<i>R1</i> 36.33
1.00	Pc	Rear bumper side holder LH (short)	40.40	25.00	<i>M1</i> 30.30
1.00	Pc	Rear end panel	453.90	25.00	<i>R1</i> 340.43
1.00	Pc	Rear end panel inner (lower)	139.20	25.00	<i>R1</i> 104.40
1.00	Pc	Rear end panel top garnish	<i>Mgem</i> 253.19	25.00	189.89
1.00	Pc	Rear keyless sensor	144.20	25.00	<i>Red</i> 108.15
1.00	Pc	Rear logo emblem	70.24	25.00	<i>Ne</i> 52.68
1.00	Pc	Rear Valve Matic emblem	35.49	25.00	<i>Ne</i> 26.62
1.00	Pc	Rear bumper inner shield RH	63.90	25.00	<i>CPM</i> 47.93
4.00	Pcs	Rear bumper lower clips	3.50	25.00	<i>Ne</i> 10.50
1.00	Set	Rear windscreen mouldings	125.42	25.00	<i>Ne</i> 94.07

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0021574
Chow I-Ruh

Page 2 of 3
Your ref. TP-SLQ 8920K AXA
Job No. 70262
Our ref 19.02.19
Payment
Date 22/2/2019

Attn

Vehicle No SKR 9417Y
Vehicle Model : Toyota Wish
Accident on ... 21/2/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Nett item:					
1.00	Pc	Rear Elegance emblem	50.00		50.00 ✓
1.00	Set	Rear parking sensor (Original)	160.50		160.50 7
Special nett item:					
1.00	Pc	Rear number plate	35.00		35.00 ✓
Labour & Misc:					
1.00		To check + erase fault codes	60.00		60.00 7
1.00		To dismantle + refix rear fender inner trim garnish (x2) + 3rd row seat, etc	140.00		140.00 120
1.00		To apply anti rust chemical	120.00		120.00 60
1.00		To transfer rear tailgate top spoiler	40.00		40.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0021574
Chow I-Ruh

Page 3 of 3
Your ref. TP-SLQ 8920K AXA
Job No. 70262
Our ref 19.02.19
Payment
Date 22/2/2019

Attn

Vehicle No SKR 9417Y
Vehicle Model : Toyota Wish
Accident on ... 21/2/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To transfer rear reversing camera + cable	40.00		40.00 ✓
1.00		To dismantle + refix rear windscreen	140.00		140.00 120
1.00		To supply sealant	40.00		40.00 ✓
1.00		To straighten rear body including cutting and welding, to knock dents on rear luggage panel and renew of parts	900.00		900.00 800
1.00		To spray paint	1,100.00		1,100.00 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-T

GST 7.00%

Total

5,795.14

405.66

6,200.80

S\$

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."