1300019		CC 3/011 1900	35 13 1	M2054/100	2
INS. CASE OWNER:	Aux	ASSIGNM DOI:		Date / Time	75/7/19
Surveyor:		_		Registered in Merimen:	
Pre-assign / CCU / I	FTE	17			
Insured Vehicle No.	STB 5753		Claim No.		
Name of Insured	ONG CHOON	PENG	Policy No.		
0 0	7.7	1.00	A PARENT PROPERTY.	0	
Insured Tel No	H	1111114	Make / Model		
Excess Sec II :88	^	O.A :	Place of Accid	ent :	
Is driver the owner?	(YES / NO) N	sture of Accident		a	
If NO, Driver Name Driver Tel N		(V/L(YES)/NO)	Of GIA REPO Insured Liabili	RT: YES / NO ; TP GIA ty: % Fins	REPORT (YES / NO
Mto Gazza			1 - tm 11/24 2 - 2 - 111 (A.1)	200	
2482024	$\lambda \longrightarrow$				
DNSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP; Tel: Liability: RMKS:
Date/Time	Cabo Cara A di				
PRELIMINARY ADVICE	CRUSO of NO RESPONSE.	Sent By:		STAGE Non-Reporting ltr (1st) Non-Reporting ltr (2nd) Non-Reporting ltr (Final): Nonfication ltr (if non-pic Call OI: After call ltr to OI: Pocumentation Check I Notification ltr (if non-pic After call ltr to OI: Authorisation ltr (if non-pic After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice LTA / GIA Medical Bill: PIR. Mandate/Reject Instruct LOD Payment Breakdown Fo	ist: Handler Typist icap)
TREESTE VARIABLE	Date Fine.	trum try		Others:	
FINALIZATION	Date/Time:	Confirm with:		Confirm by: Aut.	
Company of the Compan	S\$1,850 (3	days) Reduction: 70	54	THE RESERVE AND ADDRESS OF THE PARTY OF THE	nil - Cali
FINAL SETTLEMENT		Confirm with Stephengyl-		Email - Call	
Final Liability:		Assessed) BOLA S/N No. :	9	If NO or B 28, Ass. Lin	11
Repair Cost: (a)(a)	8\$1,979.50		by Totall esto	NIPM ROPO,	
Loss of Rental (LOR): Loss of Use (LOU):	S\$ 630.38 (6	days) x +103,38			
Loss of Income (LOI):	S\$ " (\$ x S\$ " (\$ x	days)		1 00000	**************************************
LOR only _ LOU only	100	R + LOI Tick only one	1	Memo	ASIE
GIA/L/TA Search	553.00	K - DOIL Thek only one	4.		41-67
Medical	5\$ -			1) Claim status: Norma	l/Reject/Private Settle
Disbursement	55 -	(e.g. Tow/ Independer	it)	2) Report Format:	Ty
Legal Cost	SS -				+4=0
Total:		Global Sum SS: 2,500.40			
FINAL PAYMENT		Confirm with: Inflowers		Email Call	
Payee 1:	\$\$3,600.00	Name 1: Remot Autonom	W SERVICES PTE		
Payee 2: (Strike if N.A.)		Name 2:		-	
Payes 3: (Strike if N.A.)	SS	Name 3:			

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.; (065) 62563561 FAX: (065) 62564315

Your ref:

TBA

Date: 05.03.2019

Our ref:

CC3/CTI19003573/K1ea3

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 8034B

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on <u>25.02.2019</u> at the premises of M/s <u>Premier Automotive Services Pte Ltd - Changi</u> and have the following to report:

: S\$	6,127.60	
: S\$	2,257.10	
: S\$	275.40	
: S\$	2,532.50	
: S\$	- (es	it.)
: S\$	- (es	it.)
: S\$	- (es	it.)
	: S\$: S\$: S\$: S\$: S\$ 2,257.10 : S\$ 275.40 : S\$ 2,532.50 : S\$ - (es

Description of Damage:

The vehicle sustained damages at the

O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

3.0 days

Yours faithfully,

KALVIN ANG

Licensed Appraiser

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D CHZMA

25-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8034 B

1 pc	o/s head tamp × 500	s	1,028.00
1 pc	Front bumper emblem / ***	\$	44.00
1 pc	Front bumper X Mars	\$	531.00
2 pcs	Front bumper n/s & o/s side retainer @\$16.00 4/3× 6/4 ×	S	32.00
1 pc	Front o/s fender	\$	384.00
1 pc	Front o/s fender inner shield	\$	120.00
1 pc	Front o/s door	\$	791.00
1 pc	Front o/s door regulator	\$	290.00
2 pcs	Front o/s door regulator Front o/s door hinges @ \$34.00 LKK Auto Consultants hence notify the Repairer of the Consultants	_5	68.00
1 pc	Front o/s rim × the Repairer of the following:	5	246.00
1 pc	Ols wing mirror assy X Mark . To deplay dumined	s	590.00
	Parts prices are subject to continuous Third parts subject to continuous	\$	4,124.00
	Third party survey is on a 1 more 10% time. No stepal modificational isLess 10% time.	5	412.40
	Supplementary territory manufactures and and a subject to final approval from insurance to manufacture.	\$	3,711.60
S/NETT	Acknowledged by Repairer		
1 set	Front o/s fender inner shield clips & Square:	\$	28.00
1 set	Front bumper clips × ha	\$	48.00
1 pc	Tyre Kalis (CRY	\$	30.00
1 pc	Tyre × MARIE (CICY	s	200.00
1 pc	a/s door stickers / 15/3/9 10504	s	100.00
	Sundry Nu 3A,	s	5000
	To check wheel alignment Affer Rear offe	\$	88:00 + 1
	To dismantle / refit inner components of the front o/s door		
	onto new shell door	\$	159:00 50
	To dismantle / refit the inner garnishes, inner linings, inner		_
	trims, cushion seat, carpet, etc to facilitate repairs.	\$	189:00
	To labour charge for dismantle and renew the accident		X **
	damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	50000
			70.
	To putty and spray painting on front bumper, front o/s fender, front o/s door, o/s wing mirror cover	\$	80000
	To apply rustproofing on the repaired and replaced panels.	\$	150:00 5
		\$	6,127.60
	14/1/19		

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

1 45/12 /3h.

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

30 Dec 2015 / 08:54:00

Receipt No.:

AACCK001-AX239-151230-000008

Asset Type:

Vehicle

Transaction Amount

\$68,909.00

Asset ID:

SHB8034U

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type

01.02 Register New Vehicle (AA)

Business Transaction Reference No.:

20151230085400687804

Vehicle No.

SHB8034U

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3

Vehicle Scheme:

Taxi (Company)

First Registration Date

30 Dec 2015

Original Registration

30 Dec 2015

Date Vehicle Make:

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5658139

Engine No:

D4FDFH314465

Motor No.:

Trailer Chassis No.:

Propellant:

Diesel

1685

4

Passenger Capacity:

Engine Capacity

Power Rating:

Unladen Weight:

Maximum Laden Weight:

1584 2050

Primary Color.

Silver

Secondary Color:

Manufacturing Year:

2015

Open Market Value:

\$22,359.00

Minimum PARF Benefit \$13,981.00

PARF Eligibility:

No. of Transfer.

Effective Ownership Date/Time

30 Dec 2015 08:54:00

COE No

2015123001003574R

COE Expiry Date

29 Dec 2023

COE Bid Category

Actual OP/PQP Paid

Amount:

\$45,466.00

Lifespan Expiry Date:

29 Dec 2023

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D CHZMA


25-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8034 B

1 pc	o/s head lamp X	S	1,028.00
1 pc	Front bumper emblem /	S	44.00
1 pc	Front bumper X MPS	s	531.00
2 pcs	Front bumper n/s & o/s side retainer @\$16.00 1/3x 6/4 1	S	32.00
1 pc	Front o/s fender	S	384.00
1 pc	Front o/s fender inner shield 🗶	S	120.00
1 pc	Front o/s door	S	791.00
1 pc	Front o/s door regulator ?	S	290.00
2 pcs	Front o/s door hinges @ \$34.00 X	s	68.00
1 pc	Front o/s rim the Repairor of the following: To resurvey before also deep pressing:	5	246.00
1 pc	O/s wing mirror assy X (***) *To display damaged parties deep permiting *Parts prices are to make the property.	\$	590.00
	Parts prices are suffect to restrict to a service and a service are suffect to a service and a service are suffect to a service and a service are suffered as a service are suffered as a service and a service are suffered as a servi	\$	4,124.00
		\$	412.40
	Supplementary disease and LESS TOW Subject to final approval four-research	\$	3,711.60
S/NETT	Acknowledged by Repairer	-90	
1 set	Front o/s fender inner shield clips 🗶 Strature:	\$	28.00
1 set	Front bumper clips	\$	48.00
1 pc	Front o/s fender sticker X	\$	30.00
1 pc	Tyre ×	, \$	200.00
1 pc	Tyre × o/s door sticker / 10/5/9 105	12 s	100.00
	Sundry 3 A	s	50.00
	a His	,	92.00
	To check wheel alignment After Par place	. \$	80.00 +
	To dismantle / refit inner components of the front o/s door onto new shell door	\$	150.00 so
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180:00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	400 600:00
	To putty and spray painting on front bumper, front o/s fender, front o/s door, o/s wing mirror cover	s	800.00
		1040.00	
	To apply rustproofing on the repaired and replaced panels.	\$	150:00 5

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.





REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1204496H





LEE POH NGUAN

李保源 Asse CHINESE Date of Berl Ser 22-10-1955 M County of Berly SINGAPORE







VOCATIONAL LICENCE

ipejice No. 81204496H ame LEE POH NGUAN

ssue Date /1 28/4/2011

Please visit www.lta.gov.sg to check the status of this vocational licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(E

PASS DATE

Class 3 Motor Cars and Meter Tractors the weight of

31 Mar 1976

Class 4

which unladen does not exceed 2500 killograms Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 killograms

13 Oct 1983





NRC™ S1204496H

Bleed Group. Date of name

O+ 31-03-1992

APT BLK 23B SERANGOON AVENUE 2 #10-31 SINGAPORE 1955 NP 426A



This card is not transferable and is the property of the Land Transpo Authority (LTA). It must be surrendered to LTA on request. If found, pleareturn to LTA, 10 Sin Ming Drive, Singapore 575701.

Type Description

Issue Date

02 TAXI VL

21/11/1986



Text size + ...

Enquire Transaction History

Transaction History Details

Log Date/Time:

30 Dec 2015 / 08:54:00

Receipt No.:

AACCK001-AX239-151230-000008

Asset Type:

Vehicle

Transaction Amount:

\$68,909.00

Asset ID:

SHB8034U

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

01.02 Register New Vehicle (AA)

Business Transaction

Reference No.:

20151230085400687804

Vehicle No.:

SHB8034U

Vehicle Type:

H10 - Public Transport Taxi (Molor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 30 Dec 2015

Original Registration

30 Dec 2015

Date:

Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5658139

Engine No:

D4FDFH314465

Motor No.:

Trailer Chassis No.:

Propellant: Diesel

Passenger Capacity:

Engine Capacity: 1685

Power Rating:

Unladen Weight:

Maximum Laden

1584 2050

4

Weight: Primary Color:

Silver

Secondary Color:

Manufacturing Year: 2015

Open Market Value:

\$22,359.00

Minimum PARF Benefit: \$13,961.00

PARF Eligibility:

No, of Transfer:

Effective Ownership Date/Time:

30 Dec 2015 08:54:00

COE No:

2015123001003574R

COE Expiry Date

29 Dec 2023

COE Bid Category.

Actual QP/PQP Paid

\$45 466.00

Lifespan Expiry Date:

29 Dec 2023



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5107202885-000030

Cover : Third Party

Index mark and Registration Number of Vehicle

: SHB8034U

Chassis Number

: KNAGM414MF5668139

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 01 Feb 2019

4. Expiry Date of Insurance

: 31 Jan 2020

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

- 6. Limitations as to Use*
 - (a) Use as a Taxi.
 - (b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled
 - Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: \$\$3,500

INSURE WITH COE

: N/A

HIRE PURCHASE COMPANY

: UNITED OVERSEAS BANK LIMITED

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987

Agency

: HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue

: 01 Feb 2019 09:37 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorisad Officer

Chief Executive

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443 TEL: 65446671 FAX: 62141511 CO. REG: 200707743D GST REG: 200707743D

Our Ref: SHB8034U/SR

WITHOUT PREJUDICE

25 March 2019

(By Email Only)

Attn: The Motor Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Dear Sir/Madam

ACCIDENT INVOLVING SHB8034U AND SJB5755T ALONG COLLEGE ROAD @ SGH BLK 7 ON 22.02.2019

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHB8034U, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: SJB5755T at the material time of the accident with the driver of our client's vehicle, Mr. Lee Poh Nguan.

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: SJB5755T, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair (Incl. GST)	\$	1,979.50
(2) Loss of Rental – 6 Days @\$103.38 per day	\$	620.28
(Inc PRI, Weekend + 3 days) (3) GIA Search fee	S	2.00
(3) GIA Scaleir Ice	S	2,601.78

A copy of each of the following supporting documents is enclosed:

- GlA report & sketch plan of SHB8034U
- (2) Driver's I/C and Driving License
- (3) Final repair bill
- (4) Vehicle Registration card, Certificate of Insurance, Certification Letter
- (5) Check In/Out Voucher
- (6) GIA search
- (7) Scene Video

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443

TEL: 65446671 FAX: 62141511 CO. REG: 200707743D GST REG: 200707743D

Our Ref: SHB8034U/SR

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,

Claims Department - Shafawati Md Rabu

Email: shafawati.rabu@premiertaxi.com

DID: 64100946

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client - Premier Taxis Pte Ltd



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108

Our Ref: CC3/CTI19003573/K1ea3

24 JUL 2019

ONG CHOON PENG BLK 441 SIN MING AVENUE #07-419 SINGAPORE 570441

Dear Sir/Madam,

ACCIDENT INVOLVING SJB 5755T AND SHB 8034U ON 22/02/2019

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: ashersng@lkkauto.com

c.c. China Taiping Insurance (Singapore) Pte Ltd (Motor Claims Dept)

WITHOUT PREJUDICE

China Taiping Insurance (Singapore) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909

Attn: The Motor Claims Department

Dear Sir/Madam,

ACCIDENT INVOLVING SHB8034U AND SJB5755T ALONG COLLEGE ROAD @ SGH BLK 7 ON 22.02.2019

We, Premier Taxis Pte Ltd, the registered owner of vehicle No: SHB8034U. We, hereby authorize the said workshop, M/s Premier Automotive Services Pte Ltd to execute sign discharge voucher/Indemnity forms and all necessary documents in connection with and arising out of the above claim, and collect all compensation monies due to us from you or any other party, regarding the said accident.

Thank You.

Premier Taxis Pte Ltd

Authorized Signatory

20(8/1) Date

mis Sci. lement excludes any bodily injuries arising out of :: . above said accident and participation to respectly damage only

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN3039981906

Claim No :

Claimant : PREMIER TAXIS PTE LTD

: \$\$2,600.00

DOLLARS TWO THOUSAND AND SIX HUNDRED ONLY

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHB 8034U Insured Vehicle No. : 5JB 5755T

Date of Loss

: 22/02/2019

Place of Accident

: COLLEGE ROAD @ SGH BLK 7

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name

: ONG CHOON PENG

Driver Name

: ONG CHOON PENG

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PIE. LTD.

(1) Global Sum

2,600.00 \$\$

. . SS 2,600.00

Claimant Name: PREMIER TAXYS PTE

NRIC No : 200304975H

Signature



OFFICE: 23 Changi South Avenue 2 #01-02 S(486443) TEL: 65436676 / 65436689 FAX: 62141511 CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

TAX INVOICE

DATE

21-Mar-2019

PAGE

1 OF 1

PREMIER TAXIS PTE LTD 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443

ITEM	Description QTY U.PRIC		AMOUNT
(FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8034 U	47	\$ 1,850,00
	TOTAL LUMPSUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR GST @ GRAND TO	7% \$	129.50

for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



28 February 2019

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Lee Poh Nguan of NRIC Number S1204496H is a registered driver of SHB8034U. Lee Poh Nguan is paying daily rental rate of \$103.38 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

Kellie Poh

Administration Manager

Prepared By: Hasnah

PREMIER TAXIS PTE LTD
23 Changi South Avenue 2
803-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 0330
aven, premieriasi.com
Co. Reg. No. 20030497354

PREMIER

VEH NO.	
VEN NO.	JOB NO.

CHECK IN / OUT VOUCHER

DRIVER'S NAME LEE	POH NO	SUAN	CHIRE	RJ IN	DICATE AREA	OF DAMAGE HERE:
NRIC \$ 1 20 4		HANDPHONE Q	0 26 8 2 45			EAR
TAXI REGN NO. S H &			K0Z			
ANY TORREST TORONOMICS AND A BARBOTTON AND AND ADMINISTRATION ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATI	MEIN 9 4 4 0	DATE OUT	TIME OUT	7		
S 8 1 1 2 6	FUEL IN E 1/4 1/2 3/4 F	KILOMETRES OU		FI		
YES I ACKNOWELDGE AND CONTRACT THE SAME IS IN GOOD CONJUNCTION WITH THE CHECK PONDORIVER'S NAME ORIVER'S SIGNATURE / D.	NO ONFIRM THAT I HAVE COD CONDITION AND COESSORIES / ITE TERM RENTAL AG (IN	D D M M Y E EXAMINED THE A ID TO MY SATISFAC MS LIST ABOVE. TH REEMENT. CH DRIVER'S NAME	ORMEROR VEHICLE COLLECT Y H H M M BOVE SAID VEHICLE /	ND COT		
CHECKED IN BY PREMIER'S AUTHORISED SERVICE / REPAIRS DON		OHECKED OUT BY	IORISED WORKSHOP)	1 – Lig 2 – Sa 3 – Lig 4 – Sa	MARKINGS ht Dent rious Dent ht Scratch rious Scratch	5 - Damaged 6 - Chip 7 - Crack 8 - Peeling
D SERVICING D	OTHERS: ACCIDENT: DATE /	нимм	DRIVER'S REMARK	1		



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-19-029414

Date of Request:

25/02/2019

Your Ref No:

Online Purchase

Premier Automotive Services Pte Ltd 23 Changi South Ave 2 #01-02 Singapore 486443

Dear Sir/Madam,

Enquiry Date

25/02/2019

Enquiry By

GARY SHI GUO RONG

TP Vehicle No.

SJB5755T

Accident Date

22/02/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJB5755T	China Taiping Insurance (Singapore) Pte. Ltd.	16/01/2019-15/01/2020	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-19-029414

Date of Request:

25/02/2019

Your Ref No:

Online Purchase

Premier Automotive Services Pte Ltd 23 Changi South Ave 2

#01-02

Singapore 486443

Dear Sir/Madam,

Enquiry Date

25/02/2019

Enquiry By

GARY SHI GUO RONG

TP Vehicle No.

SJB5755T

Accident Date

22/02/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En Auton	nobile		
CHI	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI19003	573/K1ea3q2		
	NSON ROAD #16-RINGLEAF TOWER	00 RSINGAPORE 079909	Date: 04-09-2019 Code: CTI			
1.	NIFE MILE	Policy Particula	ars :- THIRD PARTY CLAI	M		
	Insured Veh.	SJB 5755T	Veh. Inspected	SHB 8034U		
	Policy No.	DMPCSN3039981906	Coverage (\$)	0.00		
	Claim No.		Excess (\$)	0.00		
	Assign From		Assign Date	25/02/2019		
2.		Vehicle Pa	articulars & Condition	LEWIS DE MAN		
	Make & Model	KIA OPTIMA	c.c	1685		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	KNAGM414MF5658139	Colour	SILVER		
	Odometer	381126	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	FAIR				
3,		Con	ditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	205/65 R16	MAXXIS	6 mm		
	L/H Front Tyre	205/65 R16	MAXXIS	6 mm		
	R/H Rear Tyre	205/65 R16	MAXXIS	6 mm		
	L/H Rear Tyre	205/65 R16	MAXXIS	6 mm		
,		Descri	ption of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S BODY.			
j.	Driminoto occio		eral Information			
	Accident Date	22/02/2019	Inspection Date	25/02/2019		
	Survey held at	PREMIER AUTOMOTIVE SE	RVICES PTE LTD			
		23 CHANGI SOUTH AVENU	E 2 #01-02 SINGAPORE 486	443		
a.			Remarks			
		ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS				
b.		Estima	ate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8034U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	O/S HEAD LAMP	SERVICEABLE	1,028.00	
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	11000
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	SERVICEABLE	32.00	23
1	FRONT O/S FENDER	DENTED	384.00	384.00
1	FRONT O/S FENDER INNER SHIELD	SERVICEABLE	120.00	92
1	FRONT O/S DOOR	DENTED	791.00	791.00
1	FRONT O/S DOOR REGULATOR	SERVICEABLE	290.00	
2	FRONT O/S DOOR HINGES @\$34.00	SERVICEABLE	68.00	
1	FRONT O/S RIM	SERVICEABLE	246.00	
1	O/S WING MIRROR ASSY	TO REPAIR SEE LABOUR	590.00	
	LESS 10% DISCOUNT		-412.40	-121.90
			3,711.60	1,097.10
	SPECIAL NETT ITEMS			
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	
1	TYRE (SN)	SERVICEABLE	200.00	-
1	O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			456.00	120.00
	LABOUR	1		
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	9
	TO DISMANTLE /REFIT INNER COMPONENTS OF THE FRONT O/S DOOR ONTO NEW SHELL DOOR.	The same of the sa	150.00	50.00
- 1	TO DISMANTLE /REFIT THE INNER GARNISHES .INNER LININGS, INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	12

Report Ref No. CC3/CTI19003573/K1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND O/S WING MIRROR ASSY.		600.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER ,FRONT O/S DOOR ,O/S WING MIRROR COVER.		800.00	590.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			1,960.00	1,090.00
	GRAND TOTAL		6,127.60	2,307.10

RECOMMENDED COST OF LUMP SUM REPAIRS	1,850.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC3/CTI19003573/K1ea3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

1.0

HO LEONG CHUAN

Automotive Assessor