

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 22/02/2019
Vehicle No : SKA553K
Veh Make/Model : Volk. New Golf 1.4 TSI AT
YOM : 2010
Chassis No : WVWZZZ1KZBW145341
Date of Accident : 21/02/2019

No	Qty	Description	Amount \$
		Balance c/f	\$ 8,686.23
		Special Nett Items:-	
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor	\$ 380.00
3	1	Tailgate windscreen glass gum/sealant	\$ 80.00
4	10	Tailgate inner trim board clip	\$ 50.00
5	10	Rear bumper clip	\$ 70.00
6	6	End panel top trim clip	\$ 42.00
		Total - SN Item	\$ 677.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 1,000.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,100.00
3		To apply anti rust treatment.	\$ 120.00
4		To check wiring system & light.	\$ 80.00
5		To remove and reinstall tailgate windscreen glass.	\$ 150.00
6		To transfer tailgate inner compartment, mechanism & assy.	\$ 250.00
7		To check and test tailgate water leaking.	\$ 80.00
8		To remove and replace reverse sensor.	\$ 120.00
9		Computer diagnostic after repair.	\$ 300.00
10		Upholstery details cleaning.	\$ 220.00
		Total - L/C	\$ 3,420.00
		Sub-Total	\$ 12,783.23
		7% GST	\$ 894.83
		Total	\$ 13,678.06

45sn
200sn
40sn
X
✓
✓
700l
?
?
20l
120l
60l
15l
50l
X
X