

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SCR 86Y

B/F

8,979.48

1	1 pc	Tailgate Inner Lock	✓	151.20	✓	151.20	N
2	1 pc	Tailgate Auto Lock Actuator	✓	175.50	?	175.50	N DM
3	1 pc	Tailgate Lock Catch	X	46.20	X	46.20	N
4	1 pc	Tailgate Weatherstrip	✓	185.90	✓	185.90	N
5	2 pcs	Tailgate Hinges	✓	69.10	X	138.20	N
6	2 pcs	Tailgate Absorber	✓	241.80	X	483.60	N
7	1 pc	Rear Windscreen Glass with Moulding	✓	963.00	✓	963.00	N
8	1 pc	Rear Windscreen Inner Seal	✓	53.50	✓	53.50	N
9	2 pcs	Rear Bumper Side Retainers	✓	43.00	✓	86.00	N
10	1 set	Rear Bumper Clips	✓	50.00	✓	50.00	N
11	2 pcs	Rear Bumper Reflectors LH-CRA, RH-NN	✓	58.10	?	116.20	N CRA
12	2 pcs	Taillamps LH-CRA, RH- CMT	✓	358.20	?	716.40	N ✓
13	2 pcs	Taillamps Inner Sealer LH, RH-NN	✓	30.00	?	60.00	N REC
14	2 set	Taillamps Clips	X	25.00	X	50.00	N NN
15	1 pc	End Panel Top Trim	✓	102.50	?	102.50	N CRA
16	1 set	End Panel Top Trim Clips	✓	30.00	✓	30.00	N NN
17	1 pc	Spare Tyre Wheel Nut	X	36.20	X	36.20	N NN
18	1 pc	Rear Key Antena Sensor	X	86.50	?	86.50	N NN
19	2 set	Rear Fender Inner Trim Clips	X	30.00	X	60.00	N NN
20	1 set	Rear Fender Arch Garnish Clips	X	30.00	X	30.00	N NN
21	1 pc	Rear Air Vent RH	✓	62.60	?	62.60	N CRA
22	1 pc	Rear Exhaust Silencer	✓	653.20	X	653.20	N X
23	2 pcs	Rear Exhaust Mountings	✓	38.00	?	76.00	N REC
24	1 pc	Rear Exhaust Gasket	✓	46.00	?	46.00	N REC
25	1 pc	Rear Exhaust Heat Plate	✓	172.10	?	172.10	N DD

4,412.70

Less 10%

441.27

3,971.43

C/F

12,950.91

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SCR 86Y
 Vehicle Model : NISSAN QASHQAI
 Accident Date : 19.12.2016
 Original Reg Date : 28.12.2015

Date : 19.12.2016
 Chassis : SJNFEAJ11U1533022
 TP Ins. : AIG

ESTIMATE

1	1 pc	Tailgate	✓	✓	det	3,542.60	L CP-CRA
2	1 pc	Tailgate Outer Garnish		✓	7	381.50	L CRA
3	1 pc	Tailgate Inner Trim		✓	7	381.10	L CRA
4	1 pc	Rear Bumper	✓	det		823.60	L
5	1 pc	Rear Bumper Reinforcement		✓	2	674.00	L DD
6	2 pcs	Rear Bumper Reinforcement Bracket LH-DD, RH-NN	✓		155.00	310.00	L
7	1 pc	End Panel		✓		619.90	L BUC
8	1 pc	Spare Tyre Panel	X			1,883.20	L
9	2 pcs	Spare Tyre Panel Top Side Box LH-CRA, RH-NN	✓		352.00	704.00	L
10	1 pc	Spare Tyre Panel Top Board (Outer)	✓	det		527.30	L
11	2 pcs	Rear Fender Inner Trim			387.50	X 775.00	L NN
12	2 pcs	Rear Fender Arch Garnish LH-CRA, RH-NN	✓		270.70	X 541.40	L NN
						11,163.60	
						Less 30%	3,349.08
							7,814.52

1	1 pc	Tailgate Badge	✓			we 58.50	N ✓
2	1 pc	Tailgate Emblem Qashqai	✓			we 82.40	N ✓
3	1 set	Tailgate Outer Garnish Clips	✓			we 30.00	N ✓
4	2 pcs	Tailgate Number Plate Lamps	X		72.00	144.00	NX NN
5	2 pcs	Tailgate Lamps LH-CRA, RH-NN	✓		271.20	7 542.40	N
6	2 pcs	Tailgate Lamps Inner Sealer	✓		30.00	7 60.00	N TNEC
7	2 set	Tailgate Lamps Clips	✓		25.00	we 50.00	N TFO
8	2 pcs	Tailgate Stopper	X		18.00	we 36.00	NX
9	1 pc	Tailgate Pocket Handle	X			we 48.30	NX
10	1 set	Tailgate Inner Trim Clips	✓			40.00	N -NEC
11	1 pc	Rear Bumper Sponge	✓			7 173.80	N CRA
12	1 pc	Rear Bumper Tow Cover	✓			29.00	N ds.
						1,294.40	
						Less 10%	129.44
							1,164.96

C/F 8,979.48

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SCR 86Y

B/F

12,950.91

Special Nett

1	1 pc	Rear Windscreen Sealant	✓	40	60.00	
2	1 pc	Rear Number Plate with Cover	✓	40	70.00	
3	1 pc	Reverse Camera	✓	350	450.00	980
4	4 pcs	Reverse Sensor	✓	350	450.00	
5	1 set	Body Panel Joint Sealant	✓	80	120.00	
6	1 set	Rear Floor Panel Insulator Pad	✓	120	150.00	

Labour charge

Panel Beating	1200	1,800.00	1200
Spray painting	1000	1,400.00	1000
Anti rust	80	100.00	80
Check Wiring	30	50.00	30
Remove and install rear windscreen.	120	140.00	120
Remove and install tailgate parts.	60	90.00	60
Remove and install carpet and seat.	60	120.00	60
Remove and install reverse camera.	80	150.00	80
Remove and install reverse sensor.	80	90.00	80
Remove and install rear exhaust.	80	120.00	80
Remove and install petrol tank.	—	120.00	X
		\$ 18,430.91	

Not Authorised
HS Repair
2012/10/16
After repair photo
9 working days