

ASS. REC. BY

REP: es/smo19003639/Tlqdzm

Agent's Instruction

SAI Ver. 01

ASSIGNMENT (Office)

From (Person)

Thelma Cho

of

SMD

Date/Time

26/2/19 @ 12.41pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

SKC 3216D

Insured

FBP1329M

at Workshop m/s

My Car Consultant

Tel

88668832

of

53 ubi Ave 1 #01-33

Policy No.

DIAMTMCO1001104

Claim No.

CMTD1901084

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

23/2/19

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement

Date/Time

330pm 26/2/19

Person Contacted

Hui Qin

Vehicle IN / OUT

OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC 3216D - NA/AIG 19003509/24 DUA: 23/2/19
	FBP1329M - NA/AIG 19003509/24 DUA: 23/2/19
28/2/19 @	3.08pm revised to Thelma Cho via Messenger.
28/3/19 @	5.18pm confirmed with Hui Qin is \$2800, 5 days.
	(Red to 1299.07, 32/10)

Taffin

REF: SMO

ASSISTANT

Date: 27/2/19

On: ☒ W5 / ☐ TP RES / ☐ QD RES / ☐ EVA / ☐ HHV / ☐ MV

To inspect Vehicle No: SKC 3216D

at Work Shop no:

at

Insured

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

Veh No: SKC 3216D Date: 20/11/19

Type: ☒ Car / ☐ MCycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Audi A7

cc: 2995

Colour: Black

Insured / Std / Nil / NA

Sp. Reading: 91287

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/Nr: WAUZZZ4L6BD007557

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / \$Rim / STD A/Rim or

Tyre Size: F: 235/60R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I: 27/2/19 011 am

Survey held at: My car consultant p.c.

Des. of Damages: Frt / Rear / O/S / ☒ UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 1 MAR 2019

Date/Time, File Pass to:

☐ : Preli. Report

1/2/19

☐ : Final Report

Date/Time, File Return to:

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1. S + P: 5

1. Photos

1. Video

1. ...

1. ...

1. ...

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Weekend (\$)

Report Format:

MER-TP

Lump Sum / L.B. (\$)

2800

250
10
260

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 28 Feb 2019

Preliminary Advice

Insured Vehicle No	: FBP1329M	Accident Date	: 23/02/2019
TP Vehicle No	: SKC3216D	Assignment Date	: 26/02/2019
Make	: AUDI Q7	Est. Duration of Repair	: 5.00
Date of Inspection	: 27/02/2019		
Inspection At	: MY CAR CONSULTANT - UBI (HQ) 53 PAYA UBI INDUSTRIAL PARK, #01-33 SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,099.07
Revised Amount	:S\$	3,609.07
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,609.07

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Feb 2019		26 Feb 2019 12:41 Edit Adj Rpt				Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	NUR SHAZRIQAH BINTE ATSANI, ID: S9914594C		
Main Claimant:	WENDY TAN PHAIK SIM, ID: S7568349I		
Vehicle Reg. No.:	SKC3216D	Date of Loss:	23/02/2019 18:00 - :59
Claim Type:	TP / CMTD1901084	Policy/Cover Note No.:	D19MTMC01001104 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	FBP1329M	Policy No. (Claimant):	
		Excess:	
Repairer:	My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33, 408934 Ubi - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 07/03/2019]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: My Car Consultant <admin@mycar.sg>
Sent: Wednesday, 20 March 2019 5:18 PM
To: Shiau Chan (LKKAuto)
Subject: re: FINALISE OF VEHICLE SKC 3216D (DOA: 23/02/2019)

WITHOUT PREJUDICE

Dear Shiau,

I confirm the same for this vehicle :

COR : \$2,800.00
LOR : 05 Days

Thanks & Regards,

Huiqin

My Car Consultant
53 Paya Ubi Industrial Park #01-33 S(408934)
Tel: 88668832

From: "Shiau Chan (LKKAuto)" <siewsc@lkkauto.com>
Sent: Wednesday, March 20, 2019 5:09 PM
To: "admin@mycar.sg" <admin@mycar.sg>
Subject: FINALISE OF VEHICLE SKC 3216D (DOA: 23/02/2019)

Dear Hui Qin,

WITHOUT PREJUDICE

As spoken with you.

Offer Lump Sum \$2,800.00 before GST and 5 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad


Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A



2.68% P.A. Low Interest @ GV
Finance. \$0 Admin Fees. \$2500
Downpayment Monthly \$638
GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted

20 results/page

4 vehicles

Audi Q7

Advanced Search



	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi Q7		Any	Any	2011	Any	Any	Any	Available
		Audi Q7 3.0A TFSI Quattro	\$69,800	\$17,900 /yr	20-Jan-2011	2,995 cc	119,932 km	SUV	Available
Monthly For \$1.6k Only! Other Loan Packages From Bank/In House/Balloon Scheme Available With Most Attractive And 100% Fast Approval Rates! Sporty, Powerful And Comfortable Family 7 Seaters SUV Selling...									
Le Motor Enterprise									
Posted: 21-Feb-2019 Tags: 2011 Audi Q7, 2011 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi									
		Audi Q7 4.2 FSI Quattro S-Line	\$88,000	\$21,770 /yr	10-Mar-2011	4,163 cc	99,000 km	SUV	Available
One And Only 4.2 Powerful V8 Available. Full Air Suspension Just Replaced. Many Parts Replaced. Adaptive Air Suspension System. Best Value.									
Posted: 13-Feb-2019 Tags: 2011 Audi Q7, 2011 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi									
		Audi Q7 3.0A TFSI Quattro	\$68,777	\$16,110 /yr	21-Mar-2011	2,995 cc	-	SUV	Available
Sporty, Powerful And Comfortable Family 7 Seaters SUV Selling At Lowest Depreciation! 100% Accident Free! All Trade In/ Scarp Are Welcome! Hurry Up And Call Us Now!									
Posted: 01-Feb-2019 Tags: 2011 Audi Q7, 2011 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi									
		Audi Q7 3.0A TFSI Quattro S-Line	\$91,800	\$19,450 /yr	23-Dec-2011	2,995 cc	92,000 km	SUV	Available
Best Deal! 7 Seater SUV! Highest ARF! High Paper Value! High Body Value Above \$10K! Guarantee Cheapest In Market! New Road Tax! Best For Short Term! Flexible Loan With Lowest Interest Rate! Extended P...									
Posted: 21-Jan-2019 Tags: 2011 Audi Q7, 2011 audi q7, Audi Q7, audi q7, Audi, Q7, q7, Used Audi									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi Q7, Audi Q7 Singapore, used Audi Q7 Singapore, used Audi Q7, used vehicles Singapore or even buy used Audi Q7 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8349I
Vehicle Details	
Vehicle No.:	SKC3216D
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Feb 2019
Vehicle Make:	AUDI
Vehicle Model:	Q7 3.0 QUATTRO A
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	CJT003528
Chassis No.:	WAUZZZ4L6BD007551
Maximum Power Output:	200.0 kW (268 bhp)
Open Market Value:	\$70,100.00
Original Registration Date:	11 Aug 2011
First Registration Date:	11 Aug 2011
Transfer Count:	0
Actual ARF Paid:	\$70,100.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2021
PARF Rebate Amount:	\$42,060.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$70,117.00
COE Rebate Amount:	\$17,133.00
Total Rebate Amount:	\$59,193.00

The information contained herein is correct as at 28 Feb 2019

OK



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 26 Feb 19
Vehicle: SKC3216D
Make / Model: AUDI/Q7
Chassis: WAUZZZ4L6BD007551

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT LH DOOR	1	\$	1,876.34
2	FRONT LH DOOR FRAME STICKER	1	\$	170.75
3	FRONT LH DOOR HANDLE	1	\$	110.00
4	FRONT LH DOOR HANDLE END SHIELD	1	\$	31.40
				\$ 2,188.49
			Less 5%	\$ 109.42
				\$ 2,079.07
			Parts Total:	\$ 2,079.07
Labour to:				
5	CHECK FRONT WIRING AND LIGHTNING SYSTEM		\$	70.00
6	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW		\$	200.00
7	PANEL BEATING ON AFFECTED AREAS		\$	700.00
8	SPRAY PAINTING ON AFFECTED AREAS		\$	900.00
9	APPLY ANTI RUST ON AFFECTED AREAS		\$	150.00
				\$ 2,020.00
			Grand total:	\$ 4,099.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495747/674/843
WP

27/2/19 @ 11am

Taufik @ lkkauto.com

5 days

lumpsum

Resurvey after repair.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003639/T1QD3N2

Date: 25/03/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTMC01001104
Claimant Vehicle No :	SKC3216D	Insured Vehicle No :	FBP1329M
Date of Loss:	23/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1901084

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC3216D	Engine No:	CJT003528
Make & Model:	AUDI Q7, 3.0 TDI QUATTRO (A)	Chassis No:	WAUZZZ4L6BD007551
Reg. Date:	11/08/2011 (Man. Year: 2010)	Odometer:	91287 km
Colour:	Black		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,079.07	2,079.07	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,530.00	490.00	24.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,099.07	3,609.07	490.00	11.95
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	4,099.07	2,800.00	1,299.07	31.69

INSPECTION

Date of Assignment:	26/02/2019	
Date Inspected:	27/02/2019	Inspected At: My Car Consultant - Ubi (HQ) 53 Paya Ubi Industrial Park, #01-33 Singapore 408934
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2019)
Parts:	M1-SUV	AUDI Q7 3.0 TDI QUATTRO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC3216D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Dented	1,876.34 FL	*1,876.34 FL
2	1		*FRONT LH DOOR FRAME STICKER	Necessary	170.75 FL	*170.75 FL
3	1		*FRONT LH DOOR HANDLE	Cut	110.00 FL	*110.00 FL
4	1		*FRONT LH DOOR HANDLE END SHIELD	Cut	31.40 FL	*31.40 FL
				Sub Total (\$\$)	2,188.49	2,188.49
				- List Item Discount on L Items 5.00/5.00% (\$\$)	109.42	109.42
				Total Parts (\$\$)	2,079.07	2,079.07

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	70.00	30.00
2	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW	New	200.00	60.00
3	PANEL BEATING ON AFFECTED AREAS	New	700.00	600.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	900.00	800.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (S\$)			2,020.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >