



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/04/2019

### Survey Details:

Date of loss	26-Feb-19
Date of appointment	26-Feb-19
Date of survey	27-Feb-19
Location of survey	TORQUE 5 PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SKG 248K
Make and Model	MERCEDES BENZ GLA180 URBAN (R18 LED)
Date of registration	30/4/2018
Excess	
Market Value	\$125,000
Parf Rebate	\$57,424
Nett Loss	\$67,576

### Repair details:

Initial Estimate	\$ 18,358.50
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 8,488.37
Check items (estimate)	\$ -
Labour	\$ 1,570.00
<b>Total</b>	<b>\$ 10,058.37</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 8,000.00</b>

Number of days for repair	<u>4days</u>
---------------------------	--------------



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best.*

**Mandate:**

Liability(TP)		100%
Proposed repair cost	\$	8,560.00
Loss of use	\$	-
Loss of rental	\$	720.00
Loss of income	\$	-
LTA search fees	\$	36.45
Others		
<b>Proposed Total</b>	<b>\$</b>	<b>9,316.45</b>