



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKG248K
 Make & Model : MERCEDES BENZ, GLA180 URBAN (R18 LED), WDC1569422J494496
 Year of Manufacture : 2018

Estimation No. : E19020026
 DOA : 26/02/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>Dis</i>	1.00	0.00 1470.00	0.00 ✓
2	Rear bumper side core (LH) <i>ner</i>	1.00	0.00 125.00	0.00 ✓
3	Rear bumper side core (RH) <i>ner</i>	1.00	0.00 125.00	0.00 ✓
4	Rear bumper centre bracket <i>(ner)</i>	1.00	0.00 210.00	0.00 ✓
5	Rear bumper chrome moulding (LH) <i>exhaust</i> <i>scr</i>	1.00	0.00 485.00	0.00 ✓
6	Rear bumper chrome moulding (RH) <i>exhaust</i> <i>scr</i>	1.00	0.00 485.00	0.00 ✓
7	Reverse sensor <i>shut</i>	1.00	0.00 228.00	0.00 ✓
8	Rear bumper lower garnish <i>grazed</i>	1.00	0.00 295.00	0.00 ✓
9	Rear bumper reinforcement <i>best</i>	1.00	0.00 755.00	0.00 ✓
10	Rear bumper towing cap <i>11 X</i>	1.00	0.00 110.00	0.00 X
11	Rear bumper bracket (LH) <i>on</i>	1.00	0.00 210.00	0.00 ✓
12	Rear bumper bracket (RH) <i>on</i>	1.00	0.00 210.00	0.00 ✓
13	Reverse sensor wiring set <i>Day</i>	1.00	0.00 380.00	0.00 ✓
14	Tailgate <i>12 X</i>	1.00	0.00 2052.00	0.00 X
15	Tailgate lock <i>11 X</i>	1.00	0.00 327.00	0.00 X
16	Tailgate lock switch <i>11 X</i>	1.00	0.00 260.00	0.00 X
17	Tailgate lock sensor <i>11 X</i>	1.00	0.00	0.00 X
18	Tailgate lock catch <i>11 X</i>	1.00	0.00	0.00 X
19	Tailgate emblem - Logo <i>ner</i>	1.00	0.00 180.00	0.00 ✓
20	Tailgate emblem - GLA180 <i>ner</i>	1.00	0.00 110.50	0.00 ✓
21	Tailgate chrome garnish <i>11 X</i>	1.00	0.00 235.00	0.00 X
22	License lamp (LH) <i>11 X</i>	1.00	0.00	0.00 X
23	License lamp (RH) <i>11 X</i>	1.00	0.00	0.00 X
24	Tailgate lamp (LH) <i>11 X</i>	1.00	0.00 598.00	0.00 X
25	Tailgate lamp (RH) <i>11 X</i>	1.00	0.00 598.00	0.00 X
26	Tailgate inner trim board <i>11 X</i>	1.00	0.00	0.00 X

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKG248K
Make & Model : MERCEDES BENZ, GLA180 URBAN (R18 LED), WDC1569422J494496
Year of Manufacture : 2018

Estimation No. : E19020026
DOA : 26/02/2019

No	Description	Qty	U/P	Amt
27	Tailgate inner side garnish (LH) 1 1 X	1.00	0.00	0.00 X
28	Tailgate inner side garnish (RH) 1 1 X	1.00	0.00	0.00 X
29	Tailgate inner centre garnish 1 1 X	1.00	0.00	0.00 X
30	Tailgate wiper motor 1 1 V	1.00	0.00	0.00 X
31	Tailgate wiper arm 1 1 X	1.00	0.00	0.00 X
32	Tailgate rubber beading 1 1 X 274.30	1.00	0.00 274.30	0.00 ✓
33	Tailgate rubber stopper (LH) 1 1 X	1.00	0.00	0.00 X
34	Tailgate rubber stopper (RH) 1 1 X	1.00	0.00	0.00 X
35	Tailgate damper (LH) 1 1 X	1.00	0.00	0.00 X
36	Tailgate damper (RH) 1 1 X	1.00	0.00	0.00 X
37	Tailgate hinge (LH) 1 1 X	1.00	0.00	0.00 X
38	Tailgate hinge (RH) 1 1 X	1.00	0.00	0.00 X
39	Rear windscreen 1 1 X	1.00	0.00	0.00 X
40	Tail lamp (LH) 1 1 X	1.00	0.00 754.00	0.00 ✓
41	Tail lamp (RH) 1 1 X	1.00	0.00 754.00	0.00 X
42	End panel 1 1 X	1.00	0.00 798.00	0.00 ✓
43	End panel top garnish 1 1 X	1.00	0.00 389.00	0.00 ✓
44	Rear floor panel top board 1 1 X	1.00	0.00	0.00 X
45	Rear floor panel 1 1 X	1.00	0.00	0.00 X
46	Rear exhaust muffler 1 1 X	1.00	0.00	0.00 X
47	Rear exhaust mounting 1 1 X	1.00	0.00	0.00 X
48	Rear bumper protection garnish 1 1 X	1.00	0.00 340.00	0.00 ✓
49	Rear fender protector (LH) 1 1 X	1.00	0.00 290.00	0.00 ✓
50	Rear fender protector (RH) 1 1 X	1.00	0.00 290.00	0.00 ✓
51	Rear bumper chrome protector 1 1 X	1.00	0.00 520.00	0.00 ✓

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKG248K
Make & Model : MERCEDES BENZ, GLA180 URBAN (R18 LED), WDC1569422J494496
Year of Manufacture : 2018

Estimation No. : E19020026
DOA : 26/02/2019

No	Description	Qty	U/P	Amt
			Amt	S\$ 0.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 0.00

Section: Special Nett Items

52	Reverse camera	1.00	500.00	500.00	X
53	Rear number plate & casing	1.00	45.00	45.00	X
54	Rear bumper clip set	1.00	50.00	50.00	-
55	Tailgate C&C emblem	1.00	90.00	90.00	60
56	Tailgate inner trim board clip set	1.00	50.00	50.00	X
57	End panel top garnish clip set	1.00	30.00	30.00	X
58	Rear windscreen sealant	1.00	50.00	50.00	X
59	End panel sealant	1.00	50.00	50.00	X

Amt S\$ 865.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 865.00

Section: Labour Items

60	To R&R rear bumper reverse sensor	1.00	80.00	80.00	50
61	To check wiring & lighting system	1.00	100.00	100.00	20
62	To respray undercoating / putty on affected areas	1.00	80.00	80.00	20
63	To supply anti rust treatment on affected areas	1.00	60.00	60.00	
64	To R&R tailgate mechanism	1.00	280.00	280.00	11 X
65	To R&R rear windscreen	1.00	200.00	200.00	11 X
66	To R&R rear exhaust assy	1.00	250.00	250.00	11 X
67	To R&R rear trims, garnish and seats	1.00	250.00	250.00	50
68	To R&R fuel tank to cut & weld	1.00	300.00	300.00	11 X
69	To diagnostic erase fault code memories	1.00	160.00	160.00	11 X
70	To repair, replace and realign damaged areas	1.00	1,400.00	1,400.00	600

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKG248K
Make & Model : MERCEDES BENZ, GLA180 URBAN (R18
LED), WDC1569422J494496
Year of Manufacture : 2018

Estimation No. : E19020026
DOA : 26/02/2019

No	Description	Qty	U/P	Amt
71	To spray painting on affected areas	1.00	1,000.00	1,000.00
72	Sundries	1.00	50.00	50.00

Amt S\$ 4,210.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 4,210.00

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 865.00
Labour Items Subtotal S\$

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SKG248K
Make & Model : MERCEDES BENZ, GLA180 URBAN (R18 LED), WDC1569422J494496
Year of Manufacture : 2018

Estimation No. : E19020029
DOA : 27/02/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Tail lamp bracket RH / one	1.00	0.00 118.00	0.00 ✓
2	Tail lamp bracket LH / one	1.00	0.00 118.00	0.00 ✓
3	Exhaust heat shield / bul 290	1.00	0.00 390.00	0.00 ✓

Amt	S\$ 0.00
Discount (0.00%)	S\$ 0.00
Subtotal	S\$ 0.00

parts = 10923.80 - 10% AAA
= 9831.42

S/N = 110

Labour = 1570

P+S+L = 11511.42 - 20% L/S
= \$ 9200

P-9308.7
107
8378.37
S.N. 110
10hr - 1570
800

List Items Subtotal	S\$ 0.00
Total	S\$ 0.00