

INS. CASE OWNER: Jimmy | CC3, ALH 1900 5648, TI f a34 | IDAC:

Surveyor: MTH | DOI: 11/3/2019 | Date / Time: 26/11/19 | Registered in Merimen: 26/11/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SPT 1411E | Claim No. : \_\_\_\_\_  
 Name of Insured : Sharon Bernedette Wong for Pmg | Policy No. : \_\_\_\_\_  
 Insured Tel No. : \_\_\_\_\_ | HP: \_\_\_\_\_ | Make / Model : \_\_\_\_\_  
 Excess Sec II :SS \_\_\_\_\_ | D.O.A: 15/1/19 | Place of Accident : Rt Panjaya 7 KJE  
 Is driver the owner? ( YES / NO ) | Nature of Accident : \_\_\_\_\_  
 If NO, Driver Name / Age : \_\_\_\_\_ | OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Driver Tel No. : \_\_\_\_\_ | (V/L: YES / NO) | Insured Liability : \_\_\_\_\_ % | Final ? Yes / No \_\_\_\_\_

GLD 4430C → → → → →

INSRS: pml | WSP: \_\_\_\_\_ | Tel: \_\_\_\_\_ | Liability: \_\_\_\_\_ | RMKS: \_\_\_\_\_  
 INSRS: \_\_\_\_\_ | WSP: \_\_\_\_\_ | Tel: \_\_\_\_\_ | Liability: \_\_\_\_\_ | RMKS: \_\_\_\_\_  
 INSRS: \_\_\_\_\_ | WSP: \_\_\_\_\_ | Tel: \_\_\_\_\_ | Liability: \_\_\_\_\_ | RMKS: \_\_\_\_\_  
 INSRS: \_\_\_\_\_ | WSP: \_\_\_\_\_ | Tel: \_\_\_\_\_ | Liability: \_\_\_\_\_ | RMKS: \_\_\_\_\_

| Date/Time        | STAGE                            | DATE / PIC                          |
|------------------|----------------------------------|-------------------------------------|
| <u>20/11</u>     | Non-Reporting ltr (1st)          |                                     |
| <u>20/11</u>     | Non-Reporting ltr (2nd)          |                                     |
| <u>20/11</u>     | Non-Reporting ltr (Final)        |                                     |
| <u>20/11</u>     | Notification ltr (if non-pickup) |                                     |
| <u>11/3/2019</u> | Call OI: <u>11/3/2019</u>        |                                     |
|                  | After call ltr to OI:            |                                     |
|                  | Documentation Check List:        | Handler: _____ Typist: _____        |
|                  | Notification ltr (if non-pickup) | <input type="checkbox"/>            |
|                  | After call ltr to OI:            | <input checked="" type="checkbox"/> |
|                  | Authorisation To Act:            | <input checked="" type="checkbox"/> |
|                  | Release Voucher:                 | <input checked="" type="checkbox"/> |
|                  | Final Repair Bill:               | <input checked="" type="checkbox"/> |
|                  | Car Rental Invoice:              | <input checked="" type="checkbox"/> |
|                  | Towing Invoice                   | <input type="checkbox"/>            |
|                  | LTA / GIA :                      | <input checked="" type="checkbox"/> |
|                  | Medical Bill:                    | <input type="checkbox"/>            |
|                  | PIR:                             | <input type="checkbox"/>            |
|                  | Mandate/Reject Instruction:      | <input type="checkbox"/>            |
|                  | LOD                              | <input checked="" type="checkbox"/> |
|                  | Payment Breakdown Form:          | <input type="checkbox"/>            |
|                  | Post-Repair Photos:              | <input type="checkbox"/>            |
|                  | Others:                          | <input type="checkbox"/>            |

PRELIMINARY ADVICE Date/Time: 11/3/2019 Sent By: Lmk

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_  
 Repair Cost: \$5 4,151.30 ( 4 days) Reduction: 42.35 % Email  Call

FINAL SETTLEMENT Date/Time: 25/11/2019 Confirm with: Lowine Email  Call   
 Final Liability: % 100 ( Agreed / Assessed) BOLA S/N No. : 27 IF NO or B 28, Ass. Lin: Front to rear

Repair Cost: \$5 4,441.89  
 Loss of Rental (LOR): \$5 481.50 ( 4 days) > \$112.50 + 77.94  
 Loss of Use (LOU): \$5 - ( 3 x days)  
 Loss of Income (LOI): \$5 - ( 3 x days)  
 LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]  
 GIA/LTA Search: \$5 2.00  
 Medical: \$5 -  
 Disbursement: \$5 - (e.g. Tow/ Independent)  
 Legal Cost: \$5 -  
 Total: \$5 4,925.39 Global Sum SS: \_\_\_\_\_  
 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format: TP  
 3) Survey fee: \$320.00

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call   
 Payee 1: \$5 4,925.39 Name 1: Performance Motors Limited  
 Payee 2: (Strike if N.A.) \$5 Name 2: \_\_\_\_\_  
 Payee 3: (Strike if N.A.) \$5 Name 3: \_\_\_\_\_

Taufik

ALG.

3248/11

2012-07-11

Year: 2012  
 Make/Model: BMW X1  
 Color: Silver  
 Sp/Reading: 73029  
 Engine: WB4VL92030VL80622  
 Cms: [unclear]  
 Gen. Cond: Good  
 Steering: [unclear]  
 Brake: [unclear]  
 Mod: [unclear]  
 Tyres: 205/60R16  
 BS / DUH / EXNOVA / GY / PS / LIZA / MIC / CHTSU / PIR / SMI / TOYO / YOKO or  
 Front: [unclear]  
 RR04: 6 mm  
 LR04: 6 mm  
 D.O.A.: 11/3/19  
 Garage held at: PML  
 Date: 2012-07-11  
 Person Contacted: Joseph  
 Action/Description: [unclear]

Year: 2012 July  
 Type: [unclear]  
 Truck / Trailer or  
 Make: BMW X1  
 Color: Silver  
 Sp/Reading: 73029  
 Engine: WB4VL92030VL80622  
 Cms: [unclear]  
 Gen. Cond: Good  
 Steering: [unclear]  
 Brake: [unclear]  
 Mod: [unclear]  
 Tyres: 205/60R16  
 BS / DUH / EXNOVA / GY / PS / LIZA / MIC / CHTSU / PIR / SMI / TOYO / YOKO or  
 Front: [unclear]  
 RR04: 6 mm  
 LR04: 6 mm  
 D.O.A.: 11/3/19  
 Garage held at: PML  
 Date of Damages: [unclear]  
 The UIC / Chassis frame / Body Structure: [unclear]



The veh had commenced its repair at the time of inspection.  
 965K.

Est. Imports: 4 days  
 Duration: 181 days  
 CA / BEV / REP / 24 HRS

7,200.00 ... Rebate \$50,529.

P/P1 \$4,151.30 (Redd 3,049.30 / 423,549)

Master File Pass: [ ] Prof. Report  
 [ ] Final Report

Days Of Repair:  
 Resurvey No. of Trip:

Add Fee: [ ] Site Insp: 15  
 [ ] Interview: 15  
 [ ] Report Prep: 15  
 [ ] Report Prod: 15

Garage Fee: [ ]  
 Transportation: [ ]  
 [ ]  
 [ ]  
 [ ]

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 199401559W GST Reg. No M2-0020081-X

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

180, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63445773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

26 FEB 2019

## ESTIMATE

Estimate No. : b1 50256 Page No. : 1 of 5  
Date Estimated : 25/02/2019  
Prepared By : Joseph Yaguel

### - ESTIMATE REPAIR FOR -

Sim Wai Peng Tina  
32 Segar Road  
#10-15

Singapore 677722

### - ACCOUNT - 40000

Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL        | MILEAGE |
|-----------|-------------|------------|--------------|---------|
| SLD4430C  | VL60622     | 27/07/2012 | X1 sDrive20i | 0       |

#### DESCRIPTION

Replacing rear bumper panel and attachment, etc to knock out dents caused by the accident

850 1,700.00

Spray rear bumper

934 1,038.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

plate no. 2451 531.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries

80 150.00

Total Labour 1: 3,596.00

#### DESCRIPTION

| DESCRIPTION                         | QTY | PRIC     | VALUE    |
|-------------------------------------|-----|----------|----------|
| TAILPIPE END PIECE ALU LOOK         | 2   | 107.85   | 215.70   |
| REAR MUFFLER WITH EXHAUST FLAP      | 1   | 1,172.05 | 1,172.05 |
| RR BUMPER CTR GUIDE                 | 1   | 62.85    | 62.85    |
| RR BUMPER CARRIER                   | 1   | 444.50   | 444.50   |
| RR BUMPER LH GUIDE                  | 1   | 58.35    | 58.35    |
| RR BUMPER RH GUIDE                  | 1   | 58.35    | 58.35    |
| RR BUMPER (PRIMED)                  | 1   | 885.80   | 885.80   |
| RR BUMPER BOTTOM (XLINE/PDC)        | 1   | 343.45   | 343.45   |
| DECOUPLING RING PDC TORQUE CONVERTE | 4   | 5.05     | 20.20    |

Total Parts : 3,261.25

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770180, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190525/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**Estimate No. : **b1 50256**  
Date Estimated : **25/02/2019**  
Prepared By : **Joseph Yaguel**Page No. : **2 of 5**

| REGN. NO.       | CHASSIS NO.    | REGN. DATE        | MODEL               | MILEAGE  |
|-----------------|----------------|-------------------|---------------------|----------|
| <b>SLD4430C</b> | <b>VL60622</b> | <b>27/07/2012</b> | <b>X1 sDrive20i</b> | <b>0</b> |

Claims OD / 3rd Party / Uninsured losses / L

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
 Date&Time 11/3/19 @ 11:50 Excess \$  
 Surveyor's Name Taylor Sign Taylor  
 Surveyor's Tel 97495744 Authorized \_\_\_\_\_  
 Authorized Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR (Ref / No. PML)

Surveyor's E-mail taylor@blunders.com  
 No. of Working Days Recommend 3-4 days

**LXX Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts (during/after repair)
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



|                    |   |                 |
|--------------------|---|-----------------|
| Labour 1           | : | <b>3,596.00</b> |
| Parts              | : | <b>3,261.25</b> |
| Labour 2           | : | <b>0.00</b>     |
| Excess             | : | <b>0.00</b>     |
| Total GST @ 7%     | : | <b>480.01</b>   |
| <b>Grand Total</b> | : | <b>7,337.26</b> |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sims Darcy Group  
 Co. Reg. No. 1974011559W, GST Reg. No. M2-0020001-1-1



## SUPPLEMENTARY

Estimate No. : b1 50256  
 Date Estimated : 25/02/2019  
 Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
 Sim Wai Peng Tina  
 32 Segar Road  
 #10-15  
 Singapore 677722

- ACCOUNT - 121  
 AIG Asia Pacific Insurance Pte. Ltd.  
 78 Shenton Way  
 #08-16 Chartis Building  
 Singapore 079120

| REGN NO  | CHASSIS NO | REGN DATE  | MODEL        | M LEAGE |
|----------|------------|------------|--------------|---------|
| SLD4430C | VL60622    | 27/07/2012 | X1 sDrive20i | 0       |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|-------------|----------------|---------|------|
|-------------|----------------|---------|------|

| DESCRIPTION                                  | UNIT PRICE | QTY   | DISC. % | NETT   |
|--|------------|-------|---------|--------|
| # RR EXHAUST RUBBER MOUNTING • <i>bt</i>     | 31.40      | 1.00  |         | 31.40  |
| # TAILPIPE END PIECE ALU LOOK • <i>db</i>    | 110.55     | 1.00  |         | 110.55 |
| # TAILPIPE END PIECE ALU LOOK • <i>db</i>    | 110.55     | 1.00  |         | 110.55 |
| # RR BUMPER TOW HOOK COVER (SET) • <i>de</i> | 63.85      | 1.00  |         | 63.85  |
| # EXPANDING RIVET • <i>Hec</i>               | 1.35       | 20.00 |         | 27.00  |

|                        |        |
|------------------------|--------|
| Total Labour :         |        |
| Total Parts :          | 343.35 |
| Total Labour & Parts : | 343.35 |



## FINAL REPORT

Estimate No. : b1 50256  
Date Estimated : 25/02/2019  
Prepared By : Joseph Yague1

Page No. :

REPAIR FOR -  
Sim Wai Peng Tina  
32 Segar Road  
#10-15  
  
Singapore 677722

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

| REGN. NO | CHASSIS NO | REGN. DATE | MODEL        | M LEAGE |
|----------|------------|------------|--------------|---------|
| SLD4430C | VL60622    | 27/07/2012 | X1 sDrive20i | 0       |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|-------------|----------------|---------|------|
|-------------|----------------|---------|------|

|  |        |  |          |
|--|--------|--|----------|
| To replace rear bumper and attachments include knocking out dents caused by the accident         | 850.00 |  | 850.00   |
| To spray paint rear bumper   | 934.00 |  | 934.00   |
| * To replace tailpipe end piece and attachments include alignment and conducting checks for leak | 100.00 |  | 100.00 ✓ |
| To check electrical wiring systems and lightings at the rear section for proper function         | 150.00 |  | 150.00 ✓ |
| Sundries   | 80.00  |  | 80.00    |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|-------------|------------|-----|---------|------|
|-------------|------------|-----|---------|------|

|                                     |        |       |  |                   |
|-------------------------------------|--------|-------|--|-------------------|
| # RR EXHAUST RUBBER MOUNTING *      | 31.40  | 1.00  |  | 31.40 <i>bt</i>   |
| # TAILPIPE END PIECE ALU LOOK *     | 110.55 | 1.00  |  | 110.55 <i>del</i> |
| # TAILPIPE END PIECE ALU LOOK *     | 110.55 | 1.00  |  | 110.55 <i>del</i> |
| # RR BUMPER TOW HOOK COVER (SET) *  | 63.85  | 1.00  |  | 63.85 <i>del</i>  |
| RR BUMPER CARRIER                   | 444.50 | 1.00  |  | 444.50            |
| RR BUMPER (PRIMED)                  | 885.80 | 1.00  |  | 885.80            |
| RR BUMPER BOTTOM (XLINE/PDC)        | 343.45 | 1.00  |  | 343.45            |
| # EXPANDING RIVET *                 | 1.35   | 20.00 |  | 27.00 <i>NA</i>   |
| DECOUPLING RING PDC TORQUE CONVERTE | 5.05   | 4.00  |  | 20.20             |

### # SUPPLEMENTARY ITEMS

|                                 |            |
|---------------------------------|------------|
| Total Labour :                  | 2,114.00   |
| Total Parts :                   | 2,037.30   |
| Total Labour & Parts :          | 4,151.30 ✓ |
| Deduction for Excess :          | 0.00       |
| Total Repair Costs less Excess: | 4,151.30   |
| GST @7%:                        | 290.59     |
| Grand Total :                   | 4,441.89   |

**Poh Kin (LKKAuto)**

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Monday, 8 April 2019 3:49 PM  
**To:** Taufikh (LKKAuto); Poh Kin (LKKAuto); SUR  
**Subject:** FINAL REPORT / SLD4430C  
**Attachments:** Final Report SLD4430C\_2.pdf; Final Report SLD4430C.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,114.00  
Total Parts : 2,037.30  
Total Labour & Parts : 4,151.30

Repair days: 4

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

**Poh Kin (LKKAuto)**

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Friday, 28 June 2019 6:10 PM  
**To:** 'PBSP'  
**Cc:** Admin A  
**Subject:** RTA involving vehicle nos. SLD4430C and SKT 1411E on 11.03.2019  
  
**Importance:** High

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

**Our Ref:** CC3/AIG19003648/T1fa3  
**Your Ref:** SLD 4430C

Dear Caroline,

We refer to above matter and your letter of demand.

We hereby confirmed settlement as below:

|                           |                            |
|---------------------------|----------------------------|
| 1. Cost of Repair (w/gst) | S\$ 4,441.89               |
| 2. Loss of Rental         | S\$ 481.50                 |
| 3. GIA search fee         | <u>S\$ 2.00</u>            |
|                           | <b><u>S\$ 4,925.39</u></b> |

Signed DV received in your LOD, we will proceed closing this matter for payment processing.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**Poh Kin (LKKAuto)**

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Friday, 1 March 2019 2:56 PM  
**To:** 'PBSP'  
**Cc:** Admin A; assignments  
**Subject:** RE: REQUEST FOR DIRECT SETTLEMENT - SLD4430C & SKT1411E ON 15/02/2019  
\*\*\* LKK REF: CC3/AIG19003648/fa3

**Importance:** High

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

Our Ref: CC3/AIG19003648/fa3  
Your Ref: SLD 4430C

Dear Caroline,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

*"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."*

*In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."*


Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** PBSP [mailto:pml-pbsp@simedarby.com.sg]  
**Sent:** Friday, 1 March 2019 9:31 AM  
**To:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>  
**Cc:** CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Subject:** Re: REQUEST FOR DIRECT SETTLEMENT - SLD4430C & SKT1411E ON 15/02/2019 \*\*\* LKK REF: CC3/AIG19003648/fa3

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Sent:** Tuesday, 26 February 2019 7:38:45 PM  
**To:** PBSP; Poh Kin (LKKAuto)  
**Cc:** CS A Team; 甯珺 @; assignments  
**Subject:** RE: REQUEST FOR DIRECT SETTLEMENT - SLD4430C & SKT1411E ON 15/02/2019 \*\*\* LKK REF: CC3/AIG19003648/fa3

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Caroline,

We refer to the below email.

Please be informed that we are currently **pending for our principal to release OI GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact **Poh Kin at 6841 2132.**

Our respective case handler will look into the matter and revert to you in due course.

**Please arrange for TP survey.**

**To check availability of the case handler, you may contact the undersigned.**

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** PBSP <pml-pbsp@simedarby.com.sg>

**Sent:** Tuesday, 26 February, 2019 8:34 AM

**To:** CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

**Subject:** REQUEST FOR DIRECT SETTLEMENT - SLD4430C & SKT1411E ON 15/02/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008  
(PAYMENT BREAKDOWN)**

|                          |            |               |  |
|--------------------------|------------|---------------|--|
| <b>Vehicle No:</b>       | SLD4430C   | <b>Model:</b> |  |
| <b>Date of Accident:</b> | 15.02.2019 |               |  |

|                        |                              |                             |                                |
|------------------------|------------------------------|-----------------------------|--------------------------------|
| Global Sum Settlement: | <input type="checkbox"/> Yes | <input type="checkbox"/> No |                                |
| Repair Estimate        | : \$                         | 7,337.26                    |                                |
| Final Repair Cost      | : \$                         | 4,441.89                    |                                |
| Loss of Use            | : \$                         | --                          | _____ days at \$ _____ per day |
| Rental (if any)        | : \$                         | 481.50                      | 4 days                         |
| LTA / GIA Search Fee   | : \$                         | 2.00                        |                                |
| Others                 | : \$                         | --                          |                                |
|                        | : \$                         | --                          |                                |
| Final Settlement Sum   | : \$                         | 4,925.39                    |                                |

**Is Third Party Workshop GIA Registered?**  YES  NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No  
BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                           |      |          |
|--|---------------------------|------|----------|
| 1)                                     | Performance Motor Limited | : \$ | 4,441.89 |
| 2)                                     | Performance Motor Limited | : \$ | 2.00     |
| 3)                                     | Sim Wai Peng Tina         | : \$ | 481.50   |

\_\_\_\_\_  
Signed by appointed surveyor

\_\_\_\_\_  
Date

**Please attach all the supporting documents to the form.  
Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;  
Survey Report; Medical Report / Bill (if any)**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC3/AIG19003648/Afb3**

1<sup>st</sup> March 2019

**SHARON BERNADETTE WAN SU PING**

30 Segar Road,  
#06-11,  
Singapore 677721.

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING NOS. SKT 1411E AND SLD 4430C ALONG  
SLIP ROAD OF BUKIT PANJANG ON 15.02.2019**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

I, Sim Wai Peng Ting ("the third party claimant")  
of 32 Seagar Road #10-15 S(677722) (address),  
owner of SLD 4430C (vehicle no.) hereby authorize  
Performance Motors Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SLD 4430C that was  
damaged pursuant to the accident which occurred on 15/2/19 (date) along  
Slip RD of BT Panjang Ring Rd towards BT Panjang Rd (location)  
involving vehicle no/s SKT 1411E ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment furtherto settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 26<sup>th</sup> day of Feb (month) 20 19 (year)

  
\_\_\_\_\_  
Signed by "the third party claimant"  
15 Mar 2019

  
\_\_\_\_\_  
Signed by "the workshop"  
PERFORMANCE MOTORS LIMITED  
303 Alexandra Road  
Darty Performance Co.  
Singapore 159941  
TEL: 63190100 (Sales)  
63190111 (AfterSales)

**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 4441.89 (repair costs), S\$ 481.50 (less of use/rental) S\$ 2.00 (search fees) for vehicle no. SLO4430C that was damaged pursuant to the accident which occurred on 15/2/19 (date) along Skip Rd of BT Pong Rng Rd + sub BT Pong (location) involving vehicle no/s SKT1411E.

This is pursuant to the inspection conducted on 11/3/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Sim Wai Peng Inn ("third party claimant") of vehicle no. SLO4430C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLO4430C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 03 day of 07 (month) 20 19 (year)



MTH

Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"

PERFORMANCE MOTORS LIMITED  
200 Aljunied Road  
Sime Darby Performance Centre  
Singapore 150041  
TEL: 63190100 (Sales)  
63190111 (Admin)

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747771280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190886 (AfterSales)  
Fax. 63449771115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/538 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

(Poh Kin)

27 - A3

## SERVICE TAX INVOICE

Repair Order No. : B1 1343877

Date IN : 11/03/2019

Motor Claim Advisor: Joseph Yaguel

Page No. : 1 of 2

Invoice Number : 2102978 / WSB

Invoice Date : 24/05/2019

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

## - CUSTOMER INFORMATION -

Ms Sim Wai Peng Tina  
32 Segar Road  
#10-15

Singapore 677722

## - INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

| REGN. NO.  | CHASSIS NO. | REGN. DATE | MODEL        | MILEAGE |
|------------|-------------|------------|--------------|---------|
| SLD4430C / | VL60622     | 27/07/2012 | X1 SDRIVE20I | 73029   |

## - - - - LABOUR 1 - - - -

|   | NETT   |
|---|--------|
| To replace rear bumper and attachments including knock out dented area caused by the accident.  | 850.00 |
| To respray rear bumper.   | 934.00 |
| To replace tailpipe end piece and attachments including alignment and conduct checks for leak.  | 100.00 |
| To check electrical wiring systems and lightings at the rear section for proper function.   | 150.00 |
| Sundries.   | 80.00  |
| INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.  | 0.00   |
| DATE OF ACCIDENT : 15.02.2019. 3RD PARTY CAR : SKT1411E.  |        |
| YOUR REF NO : NIL.  |        |
| VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 11.03.2019 AT 11:50PM. AUTHORISED REPAIR BY MR CHONG POH KIN FROM LKK AUTO ON 01.03.2019 VIA EMAIL. |        |
| PROPOSE CAR RENTAL = \$481.50. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.   | 0.00   |
| GIA SEARCH FEE = \$2.00.  | 0.00   |

Total Labour 1: **2,114.00**

## - - - - PARTS - - - -

|                                     | Qty | Retail Price | NETT   |
|-------------------------------------|-----|--------------|--------|
| RR BUMPER (PRIMED)                  | 1   | 885.80       | 885.80 |
| RR BUMPER BOTTOM (XLINE/PDC)        | 1   | 343.45       | 343.45 |
| DECOUPLING RING PDC TORQUE CONVERTE | 4   | 5.05         | 20.20  |
| RR BUMPER CARRIER                   | 1   | 444.50       | 444.50 |
| RR BUMPER TOW HOOK COVER (SET)      | 1   | 63.85        | 63.85  |
| EXPANDING RIVET                     | 20  | 1.35         | 27.00  |
| TAILPIPE END PIECE ALU LOOK         | 1   | 110.55       | 110.55 |
| RR EXHAUST RUBBER MOUNTING          | 1   | 31.40        | 31.40  |
| TAILPIPE END PIECE ALU LOOK         | 1   | 110.55       | 110.55 |

Total Parts : **2,037.30**

303, Alexandra Road  
Sims Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Tampung Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773115, Alexandra Road  
Sims Darby Business Centre  
Singapore 159944  
Tel. 63150528 (AfterSales)  
63150533/330 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1343877**Date IN : **11/03/2019**Motor Claim Advisor: **Joseph Yaguel**Page No. : **2 of 2**Invoice Number : **2102978 / WSB**Invoice Date : **24/05/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Toh Jing Xuan**

|                |            |                                  |                |
|----------------|------------|----------------------------------|----------------|
| Labour Charges | : 2,034.00 | Total Labour & Parts Charges     | : S\$ 4,151.30 |
| Parts Charges  | : 2,037.30 | Less Insurance Excess            | : S\$ 0.00     |
| Lubricant/Misc | : 80.00    | Invoice Total Amount Exclude GST | : S\$ 4,151.30 |
|                |            | GST @ 7%                         | : S\$ 290.59   |
|                |            | Invoice Total Amount Include GST | : S\$ 4,441.89 |

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 4,441.89

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



MISS SIM WAI PENG TINA  
32 SEGAR ROAD #10-15  
67722 SINGAPORE

**SIME DARBY SERVICES PTE LTD**  
Hertz International Licensee  
305 Alexandra Road, #05-05  
Vantage Automotive Centre, Singapore 159942  
p (65) 6447.3388 f (65) 6345.7247  
Email: reservation.hertz@simedarby.com.sg  
Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

INVOICE DATE : 15-MAR 2019

R.A. No. 61012916 / Nur Ezham Omar

|  |   |
|--|---|
| TITLE : MISS                                       | KILOMETER OUT/IN : 63329 / 63446                |
| AUTHORIZED DRIVER : SIM WAI PENG TINA              | KILOMETER DRIVEN : 117                          |
| NRIC/PASSPORT NO. : S6933436I                      | PETROL LEVEL OUT/IN : FULL / FULL               |
| MAKE & MODEL : NISSAN TEANA 2.5CVT                 | DATE & TIME OUT : 11-MAR 2019 08:30             |
| CAR REGISTRATION NO. : SMF2817L / UNIT # : 0002734 | DATE & TIME IN : 15-MAR 2019 09:25              |
| CAR GROUP GIVEN : I                                | CHECK IN LOCATION : SHORT TERM-HQ (SIN61)-HERTZ |
| CAR GROUP CHARGED : G                              | NO. OF DAY(S) CHARGED : 4 DAY(S)                |

| DESCRIPTION                                     | UNIT PRICE (SGD) | UNIT                         | AMOUNT BEFORE GST (SGD) | GST @ 7%     | AMOUNT (SGD)   |
|---|------------------|------------------------------|-------------------------|--------------|----------------|
| <b>SGMYTHID RATES</b>                           |                  |                              |                         |              |                |
| 4 DAY(S) @ \$125.00 / DAY                       |                  |                              | 500.00                  | 35.00        | 535.00         |
| DISCOUNT (CDP) 10% - DISC10                     |                  |                              | -50.00                  | -3.50        | -53.50         |
| LESS 10% DISCOUNT                               |                  |                              |                         |              |                |
| <b>SUB-TOTAL</b>                                |                  |                              | <b>450.00</b>           | <b>31.50</b> | <b>481.50</b>  |
| REMARKS: BMW OWNER: SLD4430C<br>PML CSA: JOSEPH |                  | <b>TOTAL (SGD) :</b>         | <b>450.00</b>           | <b>31.50</b> | <b>481.50</b>  |
| * ITEMS NOT SUBJECT TO GST                      |                  |                              |                         |              |                |
|   |                  | <b>AMEX XXXXXXXXXXXX2003</b> |                         |              | <b>-481.50</b> |
|   |                  | <b>BALANCE DUE</b>           |                         |              | <b>0.00</b>    |

**NOTE:**

I / WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT; ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

Printed on 15-Mar-2019 9:45

Entered by Nur Ezham Omar

**SIME DARBY SERVICES PTE LTD**

Hertz International Licensee

305 Alexandra Road, #05-03

Vantage Automotive Centre, Singapore 159942

p [65] 6447.3388 f [65] 6345.7247

Email: reservation.hertz@simedarby.com.sg

Co. Reg. No. 197501045W GST Reg. No. M2-0021986-4

**TO BE PAID BY**

PAYMENT : AMEX - XXXXXXXXXXXX003

**HIRER'S DETAILS**

TITLE : MISS  
 NAME : SIM WAI PENG TINA  
 ADDRESS : 32 SEGAR ROAD  
 #10-15  
 677722  
 SINGAPORE

NRIC/PASSPORT NO : S6933436i ISSUE: 24/09/1991

ISSUED BY : SINGAPORE

LICENSE : S8933436i EXPIRY: 12/12/2999

ISSUED BY : SINGAPORE

NATIONALITY : SINGAPOREAN D.O.B : 24/09/1969

FREQUENT FLYER NO.

LOCAL CONTACT : 90620999

HOTEL

**COMPANY'S DETAILS**

NAME

ADDRESS

**IMPORTANT NOTICE**

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 day's rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Hertz Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/intoxicants/drugs.
- Vehicles are prohibited to be driven into Thailand.
- Strictly no key-drop services allowed, security deposit will be forfeited.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

  
 \_\_\_\_\_

Hirer

  
 \_\_\_\_\_

Additional Driver

**ADDITIONAL DRIVERS:**

RENTAL AGREEMENT NUMBER : 61012916  
 RENTAL LOCATION : SHORT TERM-HQ (SIN61)-HERTZ

**CHECKOUT**

UNIT # / REGN NO. : 00002734 / SMF2817L  
 MAKE & MODEL : NISSAN NISSAN TEANA 2.5 CVT  
 CAR GROUP GIVEN : I CHARGE : G  
 KILOMETER OUT : 63.329  
 PETROL LEVEL OUT : FULL  
 DATE & TIME OUT : 11/03/2019 08:30  
 DUE DATE & TIME IN : 14/03/2019 08:30  
 CHECKIN LOCATION : SHORT TERM-HQ (SIN61)-HERTZ

**RENTAL RATES**

AS: SGMVTHID RATES  
 DAILY @ S\$ 125.00  
 EXTRA DAY @ S\$ 125.00  
 EXTRA HOUR @ S\$ 125.00

**TOTAL: S\$ 481.50****FOR RATES TO APPLY**

MINIMUM 24 HOURS  
 CAR MUST BE RETURNED TO RENTING LOCATION  
 ON THE DUE DATE

**CORPORATE / PROMOTION PROGRAM**

DISC10 : LESS 10% DISCOUNT

**INSURANCE**

BY INITIALS, THE HIRER  
 INCLUSIVE LDW  
 NON-WAIVERABLE DAMAGE EXCESS: S\$ 2,000.00 (SIN USE)

DECLINES PAI @ S\$ 5.00 PER DAY

DECLINES WSC @ S\$ 5.00 PER DAY

THIS CAR IS FOR SINGAPORE USE ONLY. THERE IS NO INSURANCE  
 COVERAGE FOR USE OUTSIDE SINGAPORE

**OTHER CHARGES**

FUEL SERVICES @ S\$2.70 / LITRE  
 DISCOUNT (CDP) 10 % @ S\$ -50.00

**CASH & CHEQUE DEPOSIT****REMARKS**

BMW OWNER: SLD4430C  
 PML C5A: JOSEPH

**HI RESERVATION**

RES. ID# : H9634728930  
 Nur Ezham Omar

TACOF:  
 REF SRC: HERTZINTL

Printed on : 15-Mar-2019 9:45  
 Entered by: Nur Ezham Omar





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-19-030469

Date of Request: 26/02/2019

Your Ref No:

Online Purchase

Performance Motors Limited  
 303 Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941

Dear Sir/Madam,

Enquiry Date 26/02/2019  
 Enquiry By Melanie Setiawati  
 TP Vehicle No. SKT1411E  
 Accident Date 15/02/2019

**Enquiry Result**

| TP Vehicle No. | Insurer                              | Period of Insurance   | Insurer Tel. No. |
|----------------|--------------------------------------|-----------------------|------------------|
| SKT1411E       | AIG Asia Pacific Insurance Pte. Ltd. | 26/05/2018-25/05/2019 | 65-6419-3000     |

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-19-030469

Date of Request: 26/02/2019

Your Ref No:

Online Purchase

 Performance Motors Limited  
 303 Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941

Dear Sir/Madam,

 Enquiry Date 26/02/2019  
 Enquiry By Melanie Setiawati  
 TP Vehicle No. SKT1411E  
 Accident Date 15/02/2019

| DESCRIPTION                      | AMOUNT (S\$) |
|----------------------------------|--------------|
| TP Insurer Enquiry               | 1.87         |
| GST Amount                       | 0.13         |
| Total Amount Due (GST Inclusive) | 2.00         |

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO  Cash  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |             |   |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 27 Feb 2019<br><a href="#">Edit Reg</a> |               | 11 Mar 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$4,151.30</b><br><a href="#">Edit Estimates</a> | <b>S\$4,151.30</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference  | Claim Details          | Documents  | Show All |         |             |              |            |       |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |  |                        |  |          |         |             |              |            |       |
| Insured:  | <b>Sharon Bernadette Wan Su Ping (Sharon Bernadette Ruan Shubing)</b> , ID: S7503897F  |                        |  |          |         |             |              |            |       |
| Main Claimant:  | <b>SIM WAI PENG TINA</b> , ID: S6933436I   |                        |  |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SLD4430C</b>  | Date of Loss:          | 15/02/2019 07:00 - :59<br>[78 Months and 19 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>TP / 2742862146SG</b>   | Policy/Cover Note No.: | 2100413453 (Comprehensive)<br>Coverage: 26/05/2018 - 25/05/2019              |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>SKT1411E</b>  | Policy No. (Claimant): | PNPV2018-00008760  |          |         |             |              |            |       |
|   |  | Excess:                |  |          |         |             |              |            |       |
| Repairer:   | <b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 |                        |  |          |         |             |              |            |       |
| Handling Insurer:   | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com       |                        |  |          |         |             |              |            |       |
| Claimant's Insurer:   | <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700   |                        |  |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 07/03/2019]   |                        |  |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |  |                        |  |          |         |             |              |            |       |
| There are no mail for this case.  |  |                        |  |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |  |                        |  |          |         |             |              |            |       |
| Due Date  | Priority   | Type                   | Task Group   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |  |                        |  |          |         |             |              |            |       |

## Claim Documents

\*SLD4430C (2742862146SG)  
[SKT1411E]

TP

SIM WAI PENG TINA

Feb 15 2019 7:00AM

[Sharon Bernadette Wan Su Ping (Sharon Bernadette Ruan Shubing)]  
Performance Motors Limited

| Upload Documents               |                 | Upload Photos   |  | Compose New Letter |  | Upload Video |  | Upload Audio |          | View <span style="float: right;">View in Browser</span> |                                     |
|--------------------------------|-----------------|---|--|--------------------|--|--------------|--|--------------|----------|---|-------------------------------------|
| <b>Letters/Correspondences</b> |                 |   |  |                    |  |              |  |              |          | 1 per page  | <input checked="" type="checkbox"/> |
| No                             | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                         |  |                    |  |              |  | Thumbnail    | Print    |   |                                     |
| 1                              | (Draft)         | <b>Third Party Express Settlement - Payment Breakdown</b> |  |                    |  |              |  |              | Edit     |   |                                     |
| <b>Photos/Images</b>           |                 |   |  |                    |  |              |  |              |          | 3 per page  | <input checked="" type="checkbox"/> |
| No                             | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                         |  |                    |  |              |  | Thumbnail    | Print    |   |                                     |
| 1                              | 04/06/19 16:24  | <b>Odometer Reading</b>                                   |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 2                              | 04/06/19 16:24  | <b>Chassis Number</b>                                     |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 3                              | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 4                              | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 5                              | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 6                              | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 7                              | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 8                              | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 9                              | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 10                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 11                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 12                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 13                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 14                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 15                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 16                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 17                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 18                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 19                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 20                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 21                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 22                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 23                             | 04/06/19 16:24  | <b>General View</b>                                       |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 24                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 25                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 26                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 27                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 28                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 29                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 30                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 31                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 32                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 33                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |
| 34                             | 04/06/19 16:25  | <b>Reinspection Photo</b>                                 |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/>                     |                                     |

| Letters/Correspondences |                 |   | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|---|------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail  | Print                               |
|                         |                 |   |            | <input checked="" type="checkbox"/> |
| 35                      | 04/06/19 16:25  | Reinspection Photo                        | Load JPG   | <input checked="" type="checkbox"/> |
| 36                      | 04/06/19 16:25  | Reinspection Photo                        | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation           |                 |   | 1 per page | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail  | Print                               |
| 1                       | 26/02/19 19:37  | TP ESTIMATE + TP GIA REPORT               | Load PDF   |                                     |
| 2                       | 17/03/19 20:24  | TP ESTIMATE - MARKED                      | Load PDF   |                                     |
| 3                       | 03/07/19 14:30  | TP Estimate- revise + Supplementary       | Load PDF   |                                     |
| 4                       | 03/07/19 14:30  | LETTER TO OI                              | Load PDF   |                                     |
| 5                       | 15/07/19 15:13  | WORKSHOP INVOICE                          | Load PDF   |                                     |
| 6                       | 15/07/19 15:14  | AUTHORISATION TO ACT FORM                 | Load PDF   |                                     |
| 7                       | 15/07/19 15:14  | Release Voucher                           | Load PDF   |                                     |
| 8                       | 15/07/19 15:14  | RENTAL RECEIPT                            | Load PDF   |                                     |
| 9                       | 15/07/19 15:14  | GIA SEARCH                                | Load PDF   |                                     |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail  | Print                               |
| 1                       | 27/02/19 12:24  | OI GIA REPORT                             | Load PDF   |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>   |       |      |       |
| <div style="border: 1px solid black; width: 100%; height: 100%;"></div>  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

|                   |                     |        |                          |
|-------------------|---------------------|--------|--------------------------|
| Vehicle No:       | SKT1411E (Insd veh) | Model: | BMW X1 2.0 SDRIVE20I (A) |
|                   | SLD4430C (TP veh)   |        |                          |
| Date of Accident: | 15/02/2019          |        |                          |

|  |     |   |  |
|--|-----|---|--|
| Global Sum Settlement  | :   | <input type="checkbox"/> Yes                        | <input checked="" type="checkbox"/> No |
| Repair Estimate  | :\$ |   | 7,811.64                               |
| Final Repair Cost  | :\$ |   | 4,441.89                               |
| Loss of Use  | :\$ |   | days at \$0.00 per day                 |
| Rental (if any)  | :\$ |   | 481.50    4 days                       |
| LTA / GIA Search Fee   | :\$ |   | 2.00                                   |
| Others:  | :\$ |   | 0.00                                   |
|  | :\$ |   |  |
| Final Settlement Sum   | :\$ |   | 4,925.39                               |
| Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO    (Kindly indicate below) |     |   |  |
| A) For <b>Non GIA Registered Workshop:</b>   |     | Agreed Liability _____(%)                           |  |
| B) For <b>GIA Registered Workshop:</b>   |     | BOLA Applicable: Yes/ No    BOLA Scenario No: _____ |  |
| BOLA Liability: _____100_____(%)   |     | Assessed Liability (*): _____(%)                    |  |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.                                   |     |   |  |
| Remarks _____  |     |   |  |

| Payment Instruction: Payee's Breakdown |                            |     |          |
|--|----------------------------|-----|----------|
| 1)                                     | Performance Motors Limited | :\$ | 4,925.39 |
| 2)                                     |                            | :\$ |          |
| 3)                                     |                            | :\$ |          |

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

15 Jul  
2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19003648/T1FA3Q2  
**Date:** 15/07/2019

#### REFERENCE

|  |                             |  |
|--|-----------------------------|--|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100413453   |
| <b>Claimant Vehicle No :</b> SLD4430C                  | <b>Insured Vehicle No :</b> | SKT1411E   |
| Date of Loss: 15/02/2019                               | Nature of Claim:            | TP <span style="float: right;">Claim No: 2742862146SG</span> |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|  |                               |
|--|-------------------------------|
| Reg No: <b>SLD4430C</b>                              | Engine No: HIDDEN             |
| Make & Model: BMW X1, 2.0 SDRIVE20I (A)              | Chassis No: WBAVL92030VL60622 |
| Reg. Date: 27/07/2012 (Man. Year: 2012)              | Odometer: 73029 km            |
| Colour: Silver                                       |                               |
| Engine Capacity: 1997 cc                             |                               |
| Market Value/New Car Price: N/A                      |                               |
| Sum Insured (S\$): <b>Market Value/New Car Price</b> |                               |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |     |                          |     |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification:    | No  | Pre-accident Condition:  |     |

#### CONDITION OF TYRES

|                                    |                                   |
|------------------------------------|-----------------------------------|
| Front Tyre Size: 205/60 R16        | Rear Tyre Size: 205/60 R16        |
| Front Left Side: Continental 6 mm  | Rear Left Side: Continental 6 mm  |
| Front Right Side: Continental 6 mm | Rear Right Side: Continental 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS  | Repairer's      | Adjuster's      | Difference      | Diff %       |
|---|-----------------|-----------------|-----------------|--------------|
| Parts   | 3,754.60        | 2,117.30        | 1,637.30        | 43.61        |
| Miscellaneous Items   | 0.00            | 0.00            | 0.00            |              |
| Labour  | 3,546.00        | 2,034.00        | 1,512.00        | 42.64        |
| Paintwork Labour  | 0.00            | 0.00            | 0.00            |              |
| Towing  | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>                                    | <b>7,300.60</b> | <b>4,151.30</b> | <b>3,149.30</b> | <b>43.14</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>                               | 511.04          | 290.59          | 220.45          | 43.14        |
| <b>Nett Amount (S\$)</b>                                    | <b>7,811.64</b> | <b>4,441.89</b> | <b>3,369.75</b> | <b>43.14</b> |
| <b>+ Car Rental (4.0 x S\$112.50/day + 7.00% GST) (S\$)</b> |                 | 481.50          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                               |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                                 |                 | <b>4,925.39</b> |                 |              |

#### INSPECTION

|                             |                          |  |
|-----------------------------|--------------------------|--|
| Date of Assignment:         | 11/03/2019               |  |
| Date Inspected:             | 11/03/2019 Inspected At: | Performance Motors Limited (Alexandra)<br>303 Alexandra Road, Sime Darby<br>Performance Centre<br>Singapore 159941 |
| Estimated Period of Repair: | 4.0 days                 |  |

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Chong Poh Kin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's                | Amount          |                 |
|-----|-----|----------|--------------------------------------|---------------|---------------------------|-----------------|-----------------|
| 1   | 1   |          | *SUNDRIES                            | Necessary     | 150.00 FS                 | *80.00 FS       |                 |
| 2   | 2   |          | *TAILPIPE END PIECE ALU LOCK         | Not Necessary | 215.70 FS                 | *- FS           |                 |
| 3   | 1   |          | *REAR MUFFLER WITH EXHAUST FLAP      | Not Necessary | 1,172.05 FS               | *- FS           |                 |
| 4   | 1   |          | *RR BUMPER CTR GUIDE                 | Not Necessary | 62.85 FS                  | *- FS           |                 |
| 5   | 1   |          | *RR BUMPER CARRIER                   | Bent          | 444.50 FS                 | *444.50 FS      |                 |
| 6   | 1   |          | *RR BUMPER LH GUIDE                  | Not Necessary | 58.35 FS                  | *- FS           |                 |
| 7   | 1   |          | *RR BUMPER RH GUIDE                  | Not Necessary | 58.35 FS                  | *- FS           |                 |
| 8   | 1   |          | *RR BUMPER (PRIMED)                  | Deformed      | 885.80 FS                 | *885.80 FS      |                 |
| 9   | 1   |          | *RR BUMPER BOTTOM (XLINE/PDC)        | Deformed      | 343.45 FS                 | *343.45 FS      |                 |
| 10  | 4   |          | *DECOUPLING RING PDC TORQUE CONVERTE | Necessary     | 20.20 FS                  | *20.20 FS       |                 |
| 11  | 1   |          | *RR EXHAUST RUBBER MOUNTING          | Bent          | 31.40 FS                  | *31.40 FS       |                 |
| 12  | 1   |          | *TAILPIPE END PIECE ALU LOCK         | Dented        | 110.55 FS                 | *110.55 FS      |                 |
| 13  | 1   |          | *TAILPIPE END PIECE ALU LOCK         | Dented        | 110.55 FS                 | *110.55 FS      |                 |
| 14  | 1   |          | *SET RR BUMPER TOW HOOK COVER        | Deformed      | 63.85 FS                  | *63.85 FS       |                 |
| 15  | 20  |          | *EXPANDING RIVET                     | Necessary     | 27.00 FS                  | *27.00 FS       |                 |
|     |     |          |                                      |               | <b>Total Parts (\$\$)</b> | <b>3,754.60</b> | <b>2,117.30</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>             |  |          |                 |                 |
| 1                               | REPLACING REAR BUMPER PANEL AND ATTACHMENT ,ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT      | New      | 1,700.00        | 850.00          |
| 2                               | SPRAY REAR BUMPER  | New      | 1,038.00        | 934.00          |
| 3                               | TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK        | New      | 531.00          | 0.00            |
| 4                               | TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION       | New      | 177.00          | 150.00          |
| 5                               | TO REPLACE TAILPIPE END PIECE AND ATTACHMENTS INCLUDE ALIGNMENT AND CONDUCTING CHECKS FOR LEAK | New      | 100.00          | 100.00          |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>3,546.00</b> | <b>2,034.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >