

FBE 582L : 2009 Nov

Yamaha YZF. 559

JYARJISS00000046

TPAXA.

Joy.

Front Wheel Rim. <del>1st</del> new	450	x
Front Fender. Reps	165	x
Headlamp. Cashed	580	✓
Headlamp Casing. Cashed	410	✓
Front Windshield. <del>new</del>	135	x
Speedometer Cashed	980	✓
Front Camera. Dazed	380	✓
Front LH Wing mirror <del>lt</del>	115	✓
Handle Bar LH. Best	105	✓
Handle Bar Centre Bracket. Best	210	✓
Balancer LH. <del>lt</del>	28	✓
Front Fork x 02. <del>1st</del> Best	880 x 2 = 1760	✓
Front Fork Bracket. (lower) Best	195	✓
Front Fork Oil	20 (SN)	✓
Front Fork Oil Seal <del>2</del> <del>from</del>	80 (SN)	✓
Side Fairing Cashed	465	✓
Side Fairing Inner Air Duct. <del>new</del>	65	x
Magneto Casing. <del>lt</del>	215	✓

FBE 582L

Front LH Signal Lamp. <i>could</i>	75 ✓
Front LH Slider	80 (SN) ✓
Clutch Lever	58 ✓
Rear LH Footrest	45 ✓
Rear LH Footrest Bracket <sup>Not new</sup>	95 x.
Rear LH Slider <i>lit</i>	80 (SN) ✓
Rear LH Seat Garnish. <i>could</i>	125 ✓

5746  
5171.40

S-N: 260.

~~Panel Beati~~

Labour

~~350~~ 200

Spray Painting.

~~350~~ 200

Wiring.

~~50~~ 30

470

To straighten chassis member

280 .x.

Towing Fees

~~60~~ 40

total 5901.40

H/S: 47K ✓

05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: