

ASSIGNMENT

From: Merimen

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

64 ~~113~~ days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLX5171M.Yr Regn: 2018 / March.Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6 Avant.

O.C.

1798

Colour:

Gold.

A/C: Insured / Std / NI / NA

Sp. Reading

10188

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2Z24G5JN080941Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / STD / STD A/Rim or

Tyre Size: F:

255/35R20

R:

255/35R20BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

28/02/19

Survey held at

Premium.Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.SLX5171M-X1/3- Report via merimen probi advise.1/3- 16:34pm- Authorize repair by victor kohmv: 4/3 @ 8:33am - email authorize repair to premium excess \$800PV:Nett:

RECEIVED 23 APR 2019

Part by part \$10,797.69 (Red: 14,589.31; 57%)

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prob. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, \$

Photos

Others

TOTAL

Date:

2001121



37/44: Reinspection Photo



38/44: Reinspection Photo



39/44: Reinspection Photo

As the bumper is being thrust backwards, the holding bracket of the lower grille gave way as seen in the highlighted picture.



40/44: Reinspection Photo



41/44: Reinspection Photo



42/44: Reinspection Photo

View Received Message

This mail is associated with :

***SLX5171M (82110173645G)**
OD
Feb 23 2019 3:30PM
[M/S GROZ-BECKERT EAST ASIA LLP]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 30/07/2019 17:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SLX5171M - Claim Handler: Gan, Hunchung

Maintained:Where is the damage of the lower grille which required to be replaced?

38-41

DOCUMENTS SUMMARY

There are no documents.



Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 4 March 2019 8:33 AM
To: Claims Dept; SUR
Subject: RE: OD CLAIM FOR SLX 5171 M

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLX 5171M (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Saturday, 2 March 2019 8:05 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SLX 5171 M

Dear Denise,

Kindly assist repair approval for the above mention case.

Thank You.

Best Regards,
Kelvin Khoo
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 198902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SLX5171M**

OD

Feb 23 2019 3:30PM

[M/S GROZ-BECKERT EAST ASIA LLP]
Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 01/03/2019 16:39 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9668.00) - SLX5171M - Claim Handler: Mohd Zawaye, Norsazani

Approved:9668.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 01 Mar 2019

Preliminary Advice

Vehicle No	: SLX5171M	Accident Date	: 23/02/2019
Make	: AUDI A6 AVANT	Policy No.	: 1800029899
Assignment Date	: 28/02/2019	Excess	: S\$0.00
Date of Inspection	: 28/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,066.00
Revised Amount	:S\$	9,668.00
Check Items (Estimated)	:S\$	1,646.00
Total	:S\$	11,314.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	200,000.00
COE / PARF Rebate	:S\$	83,776.00
Salvage Value	:S\$	
Margin for Repair	:S\$	116,224.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	2066J
Vehicle Details	
Vehicle No.:	SLX5171M
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 AVANT 1.8 TFSI (PI)
Primary Colour:	Beige
Manufacturing Year:	2018
Engine No.:	CYG026148
Chassis No.:	WAUZZZ4G5JN080941
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$46,381.00
Original Registration Date:	28 Mar 2018
First Registration Date:	28 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$56,934.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2028
PARF Rebate Amount:	\$42,700.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$47,390.00
COE Rebate Amount:	\$41,076.00
Total Rebate Amount:	\$83,776.00

The information contained herein is correct as at 01 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2019 20:06
Date Of Accident	23/02/2019 15:30
Exact Location Of Accident	ALONG PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX5171M
Insured/Policyholder	
Name Of Registered Owner	M/S GROZ-BECKERT EAST ASIA LLP
Co Reg No	T10LL2066J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97129811
Alternative Phone No	OFFICE-97129811

Vehicle Particulars

Manufacturer	AUDI
Model	A6 AVANT 1.8 TFSI UL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE CAR
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800029899
Cover Note Number	

Driver

Name of Driver	DIETZ FECKER SILKE
NRIC No	G5393824N
Date Of Birth	11/10/1970
Occupation	INDOOR
Date Of Driving Pass	30/08/2013
Driving Experience	5 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92301660
Fax Number	
Contact Number	OFFICE-92301660
Email Address	SILKEDIEDS@GMX.COM

Address	19 JALAN JAMBU BATU
Postcode	5588738
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - WIFE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : PHILIPP DIETZ GENDER: : MALE
Passenger 2	NAME: : JOE DLLEY GENDER: : MALE
Passenger 3	NAME: : BRENNHEZAG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PIE, STOP AND GO SITUATION, THE CAR IN FRONT OF ME WAS STARTING UP AND SPEEDING UP, SO WAS I. THEN OUT OF A SUDDEN SHE SLAPPED DUE TO THE CAR IN FRONT OF US. I HAD TO BREAK BUT TOO LATE, I MILDLY BUMPED INTO HER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lim Bo Seng
NRIC/FIN No.: 8856267M

SKETCH PLAN



A: SLX 517M
B: SLQ 159V

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Q15, stop and go situation

The car in front of me was starting up and speeding up, so was I. Then all of a sudden she stopped due to the car in front of her. I tried to brake but too late, I mildly bumped into her.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name: *Lim Bee Siang*
NRIC/FIN No.:



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : GROZ-BECKERT EAST ASIA LLP
Period of Insurance : 28 Mar 2018 To 27 Mar 2019
Engine No. : CYG026148
Chassis No. : WAUZZZ4G5JN080941

Vehicle No. : SLX5171M
Policy No. : 1800029899
Endorsement No. : 000000000198999
Issued Date : 07 May 2018

ABOUT THE COVER

Make/Model : AUDI A6 1.8 TFSI AVANT ULTRA
Engine Capacity/Tonnage : 1,798.00 CC Sum Insured : Market Value First Year of Registration : 2018
Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

Any person who is driving on the Policyholder's order or with their permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

null

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6266. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part II of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0904125203

PREMIUM LEASING - KT
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

8/00048

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G5393824N**

Name: **DIETZ FECKER SILKE**

Birth Date: **11 Oct 1970**
 Issue Date: **28 Aug 2018**
 Valid Till: **29/08/2023**

0026392977




REPUBLIC OF SINGAPORE

FIN **G5393824N**

Name: **DIETZ FECKER SILKE**

Date of Birth: **11-10-1970** Sex: **F**

Nationality: **GERMAN**







YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg	30 Aug 2013

NP 428A

Licence No: G5393824N




FA1960353

DEPENDANT'S PASS
Immigration Regulations

FIN **G5393824N**

MULTIPLE JOURNEY VISA ISSUED

Date of Issue: **06-11-2017** Date of Expiry: **21-12-2020**




YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, access liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0256/2019/GW
Date	:	26-Feb-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	M/S Groz-Beckert East Asia Llp
Address	:	159 Kampong Ampat
	:	#05-03A/4
	:	Singapore 368328
Telephone	:	HP +65 97129811
Type of Claim	:	Own Damage Claims
Policy No.	:	1800029899
Vehicle No	:	SLX 5171 M
Model Code	:	Audi A6 AVANT 1.8 UL
Model / Year	:	28/3/2018
Engine No	:	CYG 026148
Chassis No	:	WAUZZZ4G5JN080941
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	23-Feb-19
Place of Accident	:	Along PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 5171 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1000 ✓	✓
3	To respray front bumper and bonnet	\$ 1,700.00 1100 ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>4,822.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 5171 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair Deformed</i>	\$ 2,787.00	X 2229.60
2	FRONT BUMPER LOCKING CLIP <i>Not in</i>	\$ 51.00	+
3	RADIATOR GRILLE <i>Crushed</i>	\$ 1,766.00	✓ 1412.80
4	RADIATOR GRILLE SENSOR SUPPORT LH / RH <i>Not in</i>	2 \$ 122.00	✓ 9669
5	FOAM FILLER PIECE <i>Not Nec</i>	\$ 215.00	?
6	REINFORCEMENT BEAM <i>Not Nec</i>	\$ 754.00	?
7	REINFORCEMENT BEAM SUPPORT LH / RH <i>Not in</i>	2 \$ 23.00	+
8	REINFORCEMENT BEAM COVER <i>Not Nec</i>	\$ 116.00	?
9	HEADLAMP LH <i>Not in</i>	\$ 8,607.00	+
10	HEADLAMP MOUNTING LH <i>Not in</i>	\$ 107.00	+
11	BONNET <i>Dented</i>	\$ 4,965.00	✓ 3972
12	BONNET ATTACHMENT PARTS <i>Not Nec</i>	\$ 161.00	?
13	BONNET CATCH HOOK <i>Not in</i>	\$ 127.00	+
14	AIR COND STICKER <i>Not in</i>	\$ 18.00	✓ 14
15	FRONT NO PLATE <i>Best</i>	S/N \$ 25.00	✓ 25
16	SUNDRIES <i>Not in</i>	\$ 400.00	✓ 20.16
TOTAL SPARE PARTS CHARGES		: \$ 20,244.00	
TOTAL LABOUR CHARGES		: \$ 4,822.00	
GRAND TOTAL		: \$ 25,066.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

25321.44

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin
Surveyed Date : 28/02/15
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parties during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0256/2019/GW

26-Mar-19

Kee Siang

1 of 1

SLX 5171 M

Audi A6 AVANT 1.8 UL

Quantity	Description	Unit Price	Amount
Parts			
1	Front Bumper Lower Grille <i>cracked</i>	\$ 116.00	\$ 92.40 ✓
2	Front Bumper Locking Clip <i>for</i>	\$ 72.00	\$ 57.60 ✓
3	Front Bumper Top Cover <i>cracked</i>	\$ 112.00	\$ 89.20 ✓
4	Outside Temperature Bracket <i>cracked</i>	\$ 21.00	\$ 16.24 ✓
GRAND TOTAL :		\$ 321.00	\$ 255.44

For Premium Automobiles Pte Ltd

Adrian Ling
S.S.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0256/2019/GW
Date	:	26-Feb-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 18 Apr 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	M/S Groz-Beckert East Asia L1p
Address	:	159 Kampong Ampat
	:	#05-03A/4
	:	Singapore 368328
Telephone	:	HP +65 97129811
Type of Claim	:	Own Damage Claims
Policy No.	:	1800029899
Vehicle No	:	SLX 5171 M
Model Code	:	Audi A6 AVANT 1.8 UL
Model / Year	:	28/3/2018
Engine No	:	CYG 026148
Chassis No	:	WAUZZZ4G5JN080941
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	23-Feb-19
Place of Accident	:	Along PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 5171 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 2,450.00	\$ 1,000.00
3	To respray front bumper and bonnet		\$ 1,700.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,822.00	\$ 2,772.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 5171 M

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,787.00	\$ 2,229.60
2	FRONT BUMPER LOCKING CLIP	\$ 51.00	
3	RADIATOR GRILLE	\$ 1,766.00	\$ 1,412.80
4	RADIATOR GRILLE SENSOR SUPPORT LH / RH	2 \$ 122.00	\$ 96.69
5	FOAM FILLER PIECE	\$ 215.00	
6	REINFORCEMENT BEAM	\$ 754.00	
7	REINFORCEMENT BEAM SUPPORT LH / RH	2 \$ 23.00	
8	REINFORCEMENT BEAM COVER	\$ 116.00	
9	HEADLAMP LH	\$ 8,607.00	
10	HEADLAMP MOUNTING LH	\$ 107.00	
11	BONNET	\$ 4,965.00	\$ 3,972.00
12	BONNET ATTACHMENT PARTS	\$ 161.00	
13	BONNET CATCH HOOK	\$ 127.00	
14	AIR COND STICKER	\$ 18.00	\$ 14.00
15	FRONT NO PLATE	S/N \$ 25.00	\$ 25.00
16	<i>Added parts - see attached</i>	\$ 321.00	\$ 255.44
17	SUNDRIES	\$ 400.00	\$ 20.16
	TOTAL SPARE PARTS CHARGES	\$ 20,565.00	\$ 8,025.69
	TOTAL LABOUR CHARGES	\$ 4,822.00	\$ 2,772.00
	GRAND TOTAL	\$ 25,387.00	\$ 10,797.69

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Denise Tay / Motor Claims Dept
Yr Ref: SLX 5171 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0256/2019/KK

20 Sep 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SLX 5171 M, Audi A6 AVANT 1.8 TFSI.

With reference to the above-mentioned vehicle, no. **SLX 5171 M**, claimant, **M/S Groz-Beckert East Asia LLP**, please find the related document per attached.

1. A copy of the Original invoice no. 85014260 – S\$ 10,697.53.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLX 5171 M

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 15:03

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014260 Date: 18/09/2019 Order: SLX5171M Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLX5171M (V 37139) Regn Date: 28/03/2018 Mileage: 11282 WIP No.: 43947

Model: A6 AVANT 1.8 TFSI ULTRA 4GD06G Chassis: WAUZZZ4G5JN080941 Engine: CYG 026148 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4G0853651AET94	GRILLE	Less 020%	1.00	1766.00
X	A4G0807081D	COVER	Less 020%	1.00	111.50
X	A4G0823029A	HOOD	Less 020%	1.00	4965.00
X	A4G0807065ASGRU	COVER	Less 020%	1.00	2787.00
X	A7L5018897A	CLIP	Less 020%	20.00	3.60
X	A8X0867189	CLIP	Less 020%	10.00	0.70
X	A4G0820536B	BRACKET	Less 020%	1.00	20.30
X	A4G0919268K	MOUNTING	Less 020%	1.00	60.26
X	A4G0919267K	MOUNTING	Less 020%	1.00	60.60
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	A4G0010515P	STICKER	Less 020%	1.00	17.50
X	A4G0807683C	GRILLE	Less 020%	1.00	115.50
X	AN 90346302	RIVET	Less 020%	4.00	1.50

Parts 8,000.69
Labour 0.00
Sublet 2,797.00
Menus 0.00
Lubricant 0.00

Sub-Total 9,997.69

7% GST 699.84

Grand Total 10,697.53



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLX 5171 M

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0256/2019/KK
29 February 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 AVANT 1.8 UL
Vehicle Chassis No. : WAUZZZ4G5JN080941
Vehicle Regn No. : SLX 5171 M
Vehicle Mileage : 11282 KM
Vehicle Owner : M/S Groz-Beckert East Asia LIP
Certificate No : 1800029899
Own Damage Excess : \$856.00 (Inclusive 7%GST)
Accident Date : 23/2/2019
Place : Along PIE
Repair Cost : \$ 10,647.53
WIP No. : 43947
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____
Time : _____
Date : 29/3

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Mar 2019 08:59		28 Feb 2019 16:22 Edit Adj Rpt	S\$10,797.69 Edit Estimates	S\$10,797.69 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	M/S GROZ-BECKERT EAST ASIA LLP, Co. Reg. No.: T10LL2066J, Tel: +6597129811		
Vehicle Reg. No.:	SLX5171M	Date of Loss:	23/02/2019 15:00 - :59 [10 Months and 26 Days from LTA Reg Date (Man Yr)]
Claim Type:	OD / 8211017364SG	Policy/Cover Note No.:	1800029899 (Comprehensive) Coverage: 28/03/2018 - 27/03/2019
		Excess:	S\$800.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/03/2019]		
Driver/Custodian:	DIETZ FECKER SILKE (48 / Female), NRIC: G5393824N, Tel: +6592301660 Email: SILKEDIEDS@GMX.COM		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AIG_SG (10/09/2019): Alert - Adj Mandate Approved (S\$10797.69) - SLX5171M - Claim Handler: Gan, Hunch...
- AIG_SG (30/07/2019): Alert - Adj Mandate Maintained - SLX5171M - Claim Handler: Gan, Hunchung
- AIG_SG (01/03/2019): Alert - Adj Mandate Approved (S\$9668.00) - SLX5171M - Claim Handler: Mohd Zawaye...
- AIG_SG (01/03/2019): SLX5171M / OD / 23/02/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX5171M (82110173645G)
 OD
 Feb 23 2019 3:30PM
 [M/S GROZ-BECKERT EAST ASIA LLP]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Assessment Reports													1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	01/03/19 09:00	Adjuster Immediate Advice										1	Load HTM			
Photos/Images													3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
2	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
3	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
4	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
5	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
6	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
7	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
8	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
9	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
10	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
11	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
12	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
13	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
14	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
15	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
16	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
17	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
18	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
19	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
20	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
21	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
22	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
23	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
24	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
25	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
26	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
27	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
28	01/03/19 09:01	General View										1	Load JPG	<input checked="" type="checkbox"/>		
29	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
30	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
31	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
32	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
33	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
34	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
35	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
36	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
37	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
38	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
39	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
40	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		
41	22/04/19 19:01	Reinspection Photo										1	Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
42	22/04/19 19:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	22/04/19 19:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	22/04/19 19:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/03/19 09:01	Singapore Accident Statement		Load PDF	
2	01/03/19 09:06	Certificate of Insurance		Load PDF	
3	01/03/19 09:06	Driver's Driving License and Dependent pass		Load PDF	
4	01/03/19 09:07	Estimate		Load PDF	
5	23/04/19 15:27	ESTIMATE AND SUPPLEMENTARY		Load PDF	
6	23/09/19 15:04	Discharge Voucher		Load PDF	
7	23/09/19 15:04	Workshop Invoice		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/02/19 20:26	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	25/02/19 20:21	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	25/02/19 20:25	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	25/02/19 20:25	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19003784/ATD3E2

Date: 23/09/2019

REFERENCE

Insured/Claimant: M/S GROZ-BECKERT EAST ASIA LLP

Policy No: 1800029899

Date of Loss: 23/02/2019

Nature of Claim: OD

Claim No: 8211017364SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX5171M

Make & Model: AUDI A6 AVANT, 1.8 TFSI S-tronic (C7) facelift (A)

Engine No: CYG026148

Reg. Date: 28/03/2018 (Man. Year: 2018)

Chassis No: WAUZZZ4G5JN080941

Colour: Gold

Odometer: 10188 km

Engine Capacity: 1798 cc

Market Value/New Car Price: S\$200,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R20

Rear Tyre Size: 255/35 R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,499.44	8,025.69	12,473.75	60.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,822.00	2,772.00	2,050.00	42.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,321.44	10,797.69	14,523.75	57.36
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	24,521.44	9,997.69	14,523.75	59.23
+ GST 7.00/7.00% (S\$)	1,716.50	699.84	1,016.66	59.23
Nett Amount (S\$)	26,237.94	10,697.53	15,540.41	59.23

INSPECTION

Date of Assignment: 28/02/2019

Date Inspected: 28/02/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,787.00 FS	*2,229.60 FS
2	1		*FRONT BUMPER LOCKING CLIP	Not Necessary	51.00 FS	*- FS
3	1		*RADIATOR GRILLE	Cracked	1,766.00 FS	*1,412.80 FS
4	1		*RADIATOR GRILLE SENSOR SUPPORT LH/RH (2PCS)	Necessary	122.00 FS	*96.69 FS
5	1		*FOAM FILLER PIECE	Not Necessary	215.00 FS	*- FS
6	1		*REINFORCEMENT BEAM	Not Necessary	754.00 FS	*- FS
7	2		*REINFORCEMENT BEAM SUPPORT LH/RH	Not Necessary	23.00 FS	*- FS
8	1		*REINFORCEMENT BEAM COVER	Not Necessary	116.00 FS	*- FS
9	1		*HEADLAMP LH	Not Necessary	8,607.00 FS	*- FS
10	1		*HEADLAMP MOUNTING LH	Not Necessary	107.00 FS	*- FS
11	1		*BONNET	Dented	4,965.00 FS	*3,972.00 FS
12	1		*BONNET ATTACHMENT PARTS	Not Necessary	161.00 FS	*- FS
13	1		*BONNET CATCH HOOK	Not Necessary	127.00 FS	*- FS
14	1		*AIR COND STICKER	Necessary	18.00 FS	*14.00 FS
15	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
16	1		*SUNDRIES	Necessary	400.00 FS	*20.16 FS
17	1		*FRONT BUMPER LOWER GRILLE	Cracked	92.40 FS	*92.40 FS
18	1		*FRONT BUMPER LOCKING CLIP	Necessary	57.60 FS	*57.60 FS
19	1		*FRONT BUMPER TOP COVER	Cracked	89.20 FS	*89.20 FS
20	1		*OUTSIDE TEMPERATURE BRACKET	Cracked	16.24 FS	*16.24 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **20,499.44** **8,025.69**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,700.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,822.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >