

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: FILE AXA 144
Version: 1810
Date calculated: 04/17/2019 11:09 AM

Full Report
Registration: SLU8379C
Printed: 17/04/2019 11:09 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-25
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	AUDI
Model:	A8 (4H)
Sub Model:	L
Model Sheet Number:	00 48 02
Registration:	SLU8379C
VIN number:	WAUZZZ4H1BN006121
Odometer:	

Model Specs

FROM 10/2010	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	LAUNCH ASSIST
LEATHER/WOOD S/WHEEL	CHROME BADGE	AIR CON AUTO 4-ZONES	ALARM SYSTEM
KEYLESS ENTRY/SAFE	MULTIMEDIA INTERFACE	RADIO SYSTEM HIGH	DIPPING DOOR MIRROR
MULTIMEDIA SYSTEM	DVD CHANGER	SOUND SYSTEM BOSE	NAVIGATION SYSTEM
PARKING AID/CAMERA	AUTO BOOTLID	DOOR POWER CLOSING	S/CVR VALCONA LEATH
FRT/RR HEATED SEATS	REAR SINGLE SEATS	TRIM PART LEATHER	FR/RR SEATS VENTILAT
RR HEADRESTS COMFORT	INTERIOR LAMP PACK	ELEC COMFORT SEATS	MEMORY CONTROL
CTR ARMREST COMFORT	HD COOLING	3.0 LTR 213KW	EMISSION STD EURO 5
TIPTRONIC	QUATTRO	TYRES 255/45 YR 19	WHEELS 9J X 19 ALLOY
SPACE SAVER SP-WHEEL	ALU PACKAGE	WOOD TRIM ASH TREE	ELECTRIC SUNROOF
RR EL ROLLER SUN VIS	RR ILLUM VANITY MIRR	TWO COAT METALLIC	ALUMINUM DESIGN

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: FILE AXA 144
Version: 1810
Date calculated: 04/17/2019 11:09 AM

Full Report
Registration: SLU8379C
Printed: 17/04/2019 11:09 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☒



Labour

Code	Description	Time Base 10 WU/h	Price = 70.00 SGD/h	
			WU	Price SGD
01 50 00 ZAX	GFS CONTROLLED FUNCTION INCLUDES: READ OUT FAULT MEMORY		2.0	14.00
63 29 19 00	R + R FRONT BUMPER COVER		11.0	77.00
94 15 19 00	R + R R/HEADLAMP INCLUDES: DISCONNECT AND CONNECT BATTERY		4.0	28.00
50 55 19 52)	R + R R/F WING (BUMPER COVER AND HEADLAMP REMOVED) INCLUDES: R + R WHEELHOUSE LINER AND WASHER RESERVOIR		9.0	63.00
50 55 55 50	RENEW R/F WING INCLUDES: R + R PROTECTIVE MOULDING		1.0	7.00
55 33 19 00	R + R FRT BONNET SEAL		3.0	21.00
92 25 20 00	REMOVE/REFIT WINDSCREEN WIPER ARMS INCLUDES: WIPER BLADES		2.0	14.00
85 22 19 00)	R + R COWL-/WATER BOX TRIM (WIPER ARMS REMOVED)		5.0	35.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: FILE AXA 144
Version: 1810
Date calculated: 04/17/2019 11:09 AM

Full Report
Registration: SLU8379C
Printed: 17/04/2019 11:09 AM

Code	Description	WU	Price SGD
57 51 19 00	R + R RIGHT FRONT DOOR INCLUDES: ADJUST DOOR	4.0	28.00
57 29 55 50	RENEW RIGHT FRONT DOOR (DOOR REMOVED) INCLUDES: R + R ALL PARTS	29.0	203.00
50 69 19 00)	R + R CROSS BRACE	2.0	14.00
43 31 19 50)	DETACH + REFIT R/F AIR SUSPENSION SHOCK ABSORBER INCLUDES: DETACH + REFIT UPPER AXLE RADIUS ARM AND UPPER GUIDE ARM	4.0	28.00
43 31 19 50)	R + R R/F AIR SUSPENSION SHOCK ABSORBER (WHEEL REMOVED)(SHOCK ABSORBER DETACHED) DOES NOT INCLUDE: PROGRAM CONTROL UNIT	2.0	14.00
43 31 55 50	RENEW R/F AIR SPRING DAMPER	2.0	14.00
43 16 25 ZAX	PROGRAM AIR SUSPENSION CONTROL UNIT DOES NOT INCLUDE: READ ERROR MEMORY	1.0	7.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		8.10	81.0
Total of Labour			567.00

Paint

Paint Work		Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
50 55 61 00	R/F WING NEW PART PAINTING S1	9.0	63.00
57 29 61 00	RIGHT FRONT DOOR NEW PART PAINTING S1	16.0	112.00
51 01 71 13	PAINTING PREPARATION WORK NEW PART S1 METAL (PART/S FITTED)	19.0	133.00
Total Paint		Hrs 4.40	WU 44.0
			Price SGD 308.00

Spare Parts

				prices as at 2015-09-02/23
Code	Description	Part Number	Supplier	Price SGD
0742	R/F WING	4H0 821 106 B		900.00
0790	R/F WING CLAMP KIT	4H0 098 625		100.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: FILE AXA 144

Version: 1810

Date calculated: 04/17/2019 11:09 AM

Full Report

Registration: SLU8379C

Printed: 17/04/2019 11:09 AM

Code	Description	Part Number	Supplier	Price SGD
0792	R/MOUNTING KIT	4H0 098 629		60.00
1482	RIGHT FRONT DOOR	4H0 831 052 B		3,500.00
7086	R/F AIR SUSP ABSORB	4H0 616 039 AP		3,700.00
7204	R/F TYRE PRESS VALVE	311 601 361		60.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 8,320.00
u: Used parts				Addition(+10.00%) 832.00
Total				9,152.00

Final Calculation

	SGD	SGD
Parts	8,320.00	
Addition(+10.00%)	832.00	
Total Parts		9,152.00
Labour Time Base 10 WU/h		
Total 81.0 WU X 70.00 SGD/h	567.00	
Total of Labour		567.00
Paint Work Time Base 10 WU/h		
Labour Cost 44.0 WU X 70.00 SGD/h	308.00	
Total Paint Including Material		308.00
Repair Cost Excludes GST		10,027.00
GST (+7.0%)		701.89
Repair Cost Included GST		10,728.89

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS