Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:Tuesday, 5 March 2019 10:08 AMTo:'Sebastian Kong'; 'Jacob Ang'Cc:SUR; Admin-D (LKKAuto)

Subject: RE: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Dear All,

As instructed by our client, please proceed at repair cost not exceeding \$9,000.00 (inclusive supplementary) to repair the insured vehicle

SKF 9503U (Excess \$ 300/-) on part by part basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sebastian Kong [mailto:sebastian@smemotor.com.sg]

Sent: Tuesday, 5 March 2019 10:02 AM

To: ShirleyHiew@lkkauto.com; admin-d@lkkauto.com

Cc: sur@lkkauto.com; Jacob Ang <jacob.ang@smemotor.com.sg> Subject: Fw: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Hi Shirley,

Please kindly assist

Best Regards

Sebastian SME MOTOR PTE LTD 1 Kaki Bukit Ave 6 Blk D, #02-15/16/17/18 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6747 6106 (6 lines) Fax: 6744 2368 From: Jacob Ang

Sent: Monday, March 4, 2019 1:07 PM

To: Shirley Hiew (LKK Auto)

Cc: SUR

Subject: Re: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Hi Shirley,

We are able to undertake the repair at limit \$9000 (before GST and Excess) on part by part basis. Please kindly advise authorisation.

Best Regards

Jacob Ang SME MOTOR PTE LTD 1 Kaki Bukit Ave 6 Blk D, #02-15/16/17/18 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6747 6106 (6 lines) Fax: 6744 2368

From: Shirley Hiew (LKK Auto)

Sent: Monday, March 4, 2019 11:43 AM

To: jacob.ang@smemotor.com.sg

Cc: SUR

Subject: ***SPAM*** SKF 9503U OD (EQI) DOA 26/02/2019

Dear Sir/Madam,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 9,000.00 on part by part basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)