

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not authorized
HLL
28/2/19
4/5 = 10,500
1427

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

VEHICLE NO:JPW 5390

QTY	PARTICULAR		
1 PCS	REAR WINDSCREEN		Deep cut \$1,025.30 ✓
1 PCS	REAR WINDSCREEN MOULDING	105.30	ner \$145.80 ✓
1 PCS	BOOTLID	655.20	Buc \$841.20 ✓
1 PCS	BOOTLID 'H' LOGO		ner \$42.00 ✓
1 PCS	BOOTLID 'CITY' EMBLEM		ner \$48.00 ✓
1 PCS	BOOTLID 'IVTEC' EMBLEM		ner \$48.00 ✓
1 PCS	BOOTLID OUTER CHROME MOULDING	184.20	but/ner \$325.00 ✓
2 PCS	BOOTLID HINGES @\$165.00		but/ner \$330.00 ✓
1 PCS	BOOTLID INNER LOCK		ner \$195.30 ✓
1 PCS	BOOTLID WEATHERSTRIP	185.20	Torn \$197.20 ✓
1 PCS	BOOTLID INNER TRIM		De \$288.30 ✓
1 SET	BOOTLID INNER TRIM CLIPS		ner \$50.00 ✓
2 PCS	BOOTLID LICENCE LAMPS @\$65.00	62.00	one \$130.00 1pc
1 PCS	REAR BUMPER	463.70	ner \$745.20 ✓
1 PCS	REAR BUMPER LOWER GARNISH	280.00	ner \$310.30 ✓
2 PCS	REAR BUMPER REFLECTORS @\$95.00		ner \$190.00 X
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20		but/ner \$70.40 ✓
1 SET	REAR BUMPER CLIPS		ner \$50.00 ✓
1 PCS	REAR END PANEL		but/ner \$605.00 ✓
1 PCS	REAR END PANEL TOP GARNISH	182.50	ner \$320.00 ✓
1 PCS	REAR FLOOR PANEL	766.20	crumpled/buc \$1,145.20 ✓
1 PCS	REAR FLOOR PANEL TOP BOARD	295.20	Torn \$485.00 ✓
2 PCS	REAR FENDERS @\$1105.00	745.20 x 2 = 1490.40	but/ner \$2,210.00 ✓
2 PCS	REAR FENDER INNER TRIMS @\$480.00	282.50 x 2 = 565	but/ner \$960.00 ✓
1 SET	REAR FENDER INNER TRIM CLIPS		ner \$50.00 ✓
2 PCS	REAR FENDER WHEEL HOUSING PANELS @\$405.00		ner \$810.00 1pc
1 PCS	REAR AIR VENT	85	ner \$105.00 ✓
1 PCS	REAR EXHAUST		ner \$588.20 X
2 PCS	REAR EXHAUST MOUNTINGS @\$60.00		ner \$120.00 X
1 PCS	REAR EXHAUST HEAT SHIELD		but \$185.00 ✓
2 PCS	TAILLAMPS @\$450.00	385 x 2 = 770	ner \$900.00 ✓
2 PCS	TAILLAMP INNER GASKETS @\$25.00		but/ner \$50.00 ✓
2 PCS	REAR CHASSIS MEMBERS @\$545.00		ner \$1,090.00 X
2 PCS	TAILLAMP HOUSING PANELS @\$255.00		but/ner \$510.00 ✓
			\$15,165.40
	S.NETT		
1SET	REAR BUMPER REVERSE SENSOR		shild \$280.00 200
1 PCS	REAR END PANEL SEALANT		ner \$50.00 ✓
1 SET	REAR FLOOR PANEL INSULATOR		ner \$220.00 X
1 PCS	REAR LICENCE PLATE		ner \$20.00 14
1 PCS	REAR WINDSCREEN SOLAR FILM		ner \$280.00 150
1 PCS	REAR WINDSCREEN SEALANT		ner \$50.00 40
	LABOUR CHARGES:		
	TO CHECK WIRING		\$80.00 30

2070
100422
803376

	TO DISMANTLE & REFIX REVERSE SENSOR				\$80.00	50
	TO DISMANTLE & REFIX BOOTLID MECHANISM				\$80.00	60
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY				\$120.00	100
	TO DISMANTLE & REFIX REAR EXHAUST				\$100.00	60
	TO DISMANTLE & REFIX FUEL TANK				\$100.00	60
	TO MOUNT VEHICLE ON CAR O-LINER				\$380.00	250
	TO SPRAY RUST PROOFING				\$250.00	150
	LABOUR FOR PANEL BEATING & REPLACING PARTS				\$2,800.00	2400
	TO PUTTY & SPRAY PAINTING				\$2,000.00	1500
					TO \$22,055.40	

13147.26