



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD	Ref : CS/AIG19003815/Gqd3s2
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120	Date : 09-04-2019
ATTN: LEE MING YAO	Code : AIG



1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SJM 9747H	Veh. Inspected	SLL 2906T
Policy No.	1800075124	Coverage (\$)	0.00
Claim No.	7981615052SG-003	Excess (\$)	0.00
Assign From	LEE MING YAO	Assign Date	20/02/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0140802	Colour	BLUE
Odometer	131142	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60R16	YOKOHAMA	6 mm

4. Description of Damages

	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--	--

5. General Information

Accident Date	16/08/2018	Inspection Date	04/04/2019
Survey held at	385 SIN MING DRIVE #01-02		
Repairer	TEAM AUTOPRO PTE LTD		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-------------------------------------	-----------------------