

Steve (LKK)
8322 8813
sterechen@lkkauto.com

with machine 18/3/19
5 days
P/P
Reg before my

SERVICE ESTIMATE

86020 - C00001 SL: SERVICE SALES - PC

Mr Ng Pui Guan
632, Veerasamy Road
#22-100

Singapore 200632

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 28/02/2019

WIP No. : 56197

Veh.In/Out:

*Tel.No. : Mobile: 96822965

Reg.No. : SLE7148T

Reg.date : 29/07/2016

Mileage : 0

Chassis No: SAJBB4AG5HCY25887

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Ng Pui Guan

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, 900	0	2700.00	0		2,700.00 S	1800
	REAR VALANCE, REAR BOOTLID, ETC						
800	TO PUTTY SPRAYPAINT ON 800	0	2400.00	0		2,400.00 S	1600
	REAR BUMPER, REAR BOOTLID, ETC						
802	TO REPLACE REAR EXHAUST ASSY	0	1800.00	0		1,800.00 S	900
802	TO REMOVE & REFIT	0	500.00	0		500.00 S	X
	REAR BOOTLID PARTS						
R06	REAR NUMBER PLATE & HOLDER	0	60.00	0		60.00 S	X
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	/
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	JT2H4208LML/COVER-BU	1.0 EA	1393.80			1,393.80 S	
	PANEL-VALANC (100) CAT	1.0 EA	567.70			567.70 S	
	BRACKET-BUMP ?	1.0 EA	127.30			127.30 S	
	BRACKET-BUMP ?	1.0 EA	127.40			127.40 S	
	MOUNTING-BRA ?	1.0 EA	66.50			66.50 S	
	MOUNTING-BRA ?	1.0 EA	66.50			66.50 S	

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**SERVICE ESTIMATE**

86020 - C00001
Mr Ng Pui Guan
632, Veerasamy Road
#22-100

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 28/02/2019

WIP No. : 56197

Veh.In/Out:

*Tel.No. : Mobile: 96822965

Reg.No. : SLE7148T

Reg.date. : 29/07/2016

Mileage : 0

Chassis No: SAJBB4AG5HCY25887

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Ng Pui Guan

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	BRACKET REAR BUMPER ?	1.0	EA	68.40			68.40	S
	UNDERTRAY x NM	1.0	EA	322.30			322.30	S
	COVER-TOWING x NM	1.0	EA	31.40			31.40	S
	PANEL-TRUNK x R	1.0	EA	2097.70			2,097.70	S
	BADGE - NEC	1.0	EA	87.40			87.40	S
	JT4N7586/BADGE - NEC	1.0	EA	199.90			199.90	S
	BADGE - NEC	1.0	EA	105.00			105.00	S
	JT2H6457/SILENCER-EX LM - DO	1.0	EA	1660.90			1,660.90	S
	SILENCER-EXH RR ASSY RM - DO	1.0	EA	1660.90			1,660.90	S
	CLAMP-EXHAUST - NEC	2.0	EA	50.30			100.60	S
	BEAM-BUMPER ?	1.0	EA	592.90			592.90	S
	ADHESIVE SEALER FL2 NEC	1.0	EA	549.10			549.10	S

Gross Total. 17,771.70

Labour Total 7,946.00
Parts Total 9,825.70
Package Total 0.00

Net..... 17,771.70
GST @ 7.0% 1,244.02
Total..... 19,015.70
Paid..... 0.00
Please Pay.. 19,015.70

GST: 3=StdRated; 0=OutOfScope; Z=ZeroRated