

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

(3rd party claim against EQ Insured SGM1773U)

Estimate repair

Vehicle No. : SLG3225U
 Make & Model : AXIO Hybrid
 Chassis No. : 1.5G CVT
 Date of survey : _____

Submitted by : Bm
 COE expiry : 26-09-2026
 Engine No. : _____

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01.	Rear bumper X repair.	01	\$912.00		
02	RH retainers X NN	01	\$75.00		
	Special net				
01	Clips / retainers X NN	01	\$25.00		
	\$25 / pzt.				
	Labour Description				
01	Disassemble / Assembly of bumper	01	\$200.00	150	
02	Spray painting of rear bumper (pearl white)	01	\$260.00	200	
				350	
	2 Days.				
	put by pzt.				
	After take paint photos				
	Gmo Corp				
	11/3/19				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.