

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 4 March 2019 9:19 AM
To: 'Justin Ee'; SUR
Cc: Admin-D (LKKAuto)
Subject: RE: SLU 9234 E - Own Damage - FWD

Dear Justin,

As instructed by our client, please proceed to repair the insured vehicle **SLU 9234E** (Excess \$ 500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Justin Ee [mailto:justin_ee@bw.com.sg]
Sent: Friday, 1 March 2019 5:06 PM
To: sur@lkkauto.com
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: SLU 9234 E - Own Damage - FWD

Hi all,

Kindly refer to our attach file of SLU 9234 E - Estimate.

Thank you.

Best regards,
Justin Ee
BW Workshop Services Pte Ltd
30 Ubi Road 4 Singapore 408615
Main: 6289 8800 / Direct Line : 6692 0139 /
Fax: 6858 2120 / HP : 9731 8883 Email justin_ee@bw.com.sg