

**BW WORKSHOP SERVICES PTE LTD**

30 UBI ROAD 4

Singapore 408615

6289 8800

workshop\_admin@bw.com.sg

GST Registration No. : 201504834E

Company Registration No. 201504834E



## Sales Invoice

**INVOICE TO**

FWD INSURANCE

6 TEMASEK BLVD, #18-01

SUNTEC TOWER FOUR,

SINGAPORE

038986

**INVOICE NO. 9886****DATE 31/05/2019****VIN NUMBER**

SLU9234E/GP71121313

**MAKE & MODEL**

HONDA SHUTTLE HYBRID 1.5

ACTIVITY	QTY	RATE	AMOUNT
DOOR RR LH DOOR RR LH	1	648.00	648.00
SPACER LH- HONDA SHUTTLE SPACER LH	1	28.40	28.40
BUMPER RR *NH788P* -HONDA SHUTTLE BUMPER RR *NH823M* -HONDA SHUTTLE	1	796.00	796.00
Labour Charges STD WHEEL CAP COVER	1	80.00	80.00
Labour Charges STD -TO REMOVE ,CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING ,ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	1	750.00	750.00
Labour Charges STD - TO PUTTY AND RESPRAY ON AFFECTED PORTION	1	800.00	800.00
Labour Charges STD - TO DISCONNECT AND CHECK ELECTRICAL WIRING ,HARNES, WIRE SOCKETS, ETC. REMOVE AND REINSTAL DAMAGED PARTS,TEST AND RECTIFY FOR PROPER FUNCTIONAL - TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING ,SEATS.	1	90.00	90.00
Labour Charges STD - TO REMOVE DOOR'S FITTING - TO CONDUCT TYRE BALANCING - TO REMOVE AND REPLACE BUMPER SENSOR - TO CONDUCT TYRE BALANCING	1	170.00	170.00
Excess Fee Excess Fee	1	500.00	-500.00

Thank you for your business!  
We look forward to serving you again.

**SUBTOTAL****2,862.40**

Payment method :  
**CREDIT CARD & NETS ONLY**

BW WORKSHOP SERVICES PTE LTD

GST TOTAL  
TOTAL  
BALANCE DUE

200.37  
3,062.77

**SGD 3,062.77**

Payment method :  
CREDIT CARD & NETS ONLY