

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 10:10

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014854 Date : 18/02/2020 Order : SME4665A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SME4665A (V 39465)	Regn Date: 28/09/2018	Mileage: 14938	WIP No.: 44250
Model: A5 SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF59JA134244	Engine: CVK 068790	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION.	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	300.00	1.00	300.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS FRONT AND REAR DOOR'S MULTI LOCL SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGE	560.00	1.00	560.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT,BACK REST, HAT TRAY,ABCD PILLAR TRIM,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER,REAR LID,RHS SILL PANEL, RHS REAR OUTER WHEEL HOUSING,RHS REAR CONNECTING PLATE,REAR BOTTOM PLATE,RHS B PILLAR AND SILL PANE RENEW REAR BUMPER,RHS FRONT DOOR,RHS WING MIRROR ASSY,RHS REAR DOOR AND SILL PANEL.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	6000.00	1.00	6,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,RHS FRONT DOOR,RHS REAR DOOR,RHS REAR FENDER,RHS WING MIRROR COVER,RHS REAR OUTER WHEEL HOUSING,RHS REAR CONNECTING PLATE,RHS REAR BOTTOM PLATE,RHS B PILLAR,RHS SILL PANEL AND RHS SILL PANEL TRIM.TO CARRY	5000.00	1.00	5,000.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 10:10

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014854	Account: A0006 (T 0)		AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
		Date : 18/02/2020				
		Order : SME4665A				
		Term : 30				

Regn No: SME4665A (V 39465)		Regn Date: 28/09/2018		Mileage: 14938		WIP No.: 44250	
Model: A5 SPORTBACK 2.0 TFSI S tronic		Chassis: WAUZZZF59JA134244		Engine: CVK 068790		Dept: U	
You have been assisted by :- UB-Tony Foong (33)							

		Details	Qty	Unit Price	Amount
S	BODYWORK	OUT STONE CHIP TREATMENT AND JOINT SEALER WORK M: TO RENEW RHS REAR RIM AND TYRE. TO CARRY OUT WHEEL ALIGNMENT AND INSPECT RHS REAR SUSPENSION FOR FURTHER DAMAGES	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
S	BODYWORK	M: TO SUPPLY ACRYLIC SEALANT,CAVITY WAX, STONE CHIP,METAL FILLER POWDER AND 1/4 GLASS SEALANT	880.00	1.00	880.00
S	BODYWORK	M: TO PLACE VEHICLE ON CELLETE BENCH	1200.00	1.00	1,200.00
X	A8W8810076	(A) (G) FRAME 07/03/19	Less 020%	1.00	3432.00
X	A8W8845298F NVB	SIDE WINDO	Less 020%	1.00	653.00
X	A8W0802090A	(V) (G) FLOOR PAN 07/0	Less 020%	1.00	438.50
X	A8W6809410TA	(V) (G) HOUSING 08/03/	Less 020%	1.00	574.00
X	A8W6809424	(V) (G) PLATE 07/03/19	Less 020%	1.00	132.50
X	A8W8831052F	DOOR	Less 020%	1.00	2829.00
X	A8W8837911	SEAL	Less 020%	1.00	201.00
X	AWHT003237	BOLT	Less 020%	2.00	1.00
X	AWHT003497	BOLT	Less 020%	1.00	2.10
X	A8W2837240D GRU	TRIM	Less 020%	1.00	79.40
X	A8W0837206	HANDLE	Less 020%	1.00	34.40
X	A8W2837812A	(A) (G) SUPPORT 07/03/	Less 020%	1.00	148.50
X	A8W0927754	(A) (SK) SENSOR 07/03/	Less 020%	2.00	208.00
X	A8W0947134	LIGHT	Less 020%	1.00	65.90
X	A8W6853604A PUZ	TRIM	Less 020%	1.00	144.50
X	A8W8857410M 9B9	MOUNTING	Less 020%	1.00	999.00
X	A8W0857528 GRU	CAP	Less 020%	1.00	219.50
X	A8W0857536H	(A) (SK) MIRROR 07/03/	Less 020%	1.00	1553.00
X	A8W8853284 2ZZ	(A) (G) WINDOW SLO 07/	Less 020%	1.00	364.00
X	A8W8833052J	DOOR	Less 020%	1.00	2829.00
X	A8W8839912	SEAL	Less 020%	1.00	201.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 10:10

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014854 Date : 18/02/2020 Order : SME4665A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SME4665A (V 39465)	Regn Date: 28/09/2018	Mileage: 14938	WIP No.: 44250
Model: A5 SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF59JA134244	Engine: CVK 068790	Dept: u
You have been assisted by :- UB-Tony Foong (33)			

		Details		Qty	Unit Price	Amount
X	A8W8839249	CHECK ROD	Less 020%	1.00	109.00	87.20
X	A8X4833408A	(A) (SK)HINGE 07/03/1	Less 020%	1.00	40.10	32.08
X	A8W0833406A	(A) (SK)HINGE 07/03/1	Less 020%	1.00	41.30	33.04
X	A8W0831404A	(A) (G)HINGE 07/03/19	Less 020%	1.00	41.30	33.04
X	A8W8833404A	(A) (G)HINGE 07/03/19	Less 020%	1.00	67.80	54.24
X	A8W0837240B GRU	TRIM	Less 020%	1.00	79.40	63.52
X	A8W0837167	HOUSING	Less 020%	1.00	6.70	5.36
X	A8W0837878	COVER	Less 020%	1.00	5.10	4.08
X	A8W0837206	(A) (SK)HANDLE 07/03/	Less 020%	1.00	34.40	27.52
X	A8W0837900A	TRIM	Less 020%	1.00	123.50	98.80
X	A8W0837812A	SUPPORT	Less 020%	1.00	148.50	118.80
X	A8W8839462	REGULATOR	Less 020%	1.00	320.00	256.00
X	A4G0839016H	LATCH	Less 020%	1.00	603.50	482.80
X	A8W8853764 2ZZ	(V) (SK)WINDOW SLO 26	Less 020%	1.00	334.50	267.60
X	A8W0601025AL	RIM 18" V85	Less 020%	1.00	943.00	754.40
X	A8W6810172A	(A) (SK)WHEEL HOUS 07	Less 020%	1.00	256.00	204.80
X	A8W6807067AAGRU	(A) (SK)COVER 07/03/1	Less 020%	1.00	2491.00	1,992.80
X	A8W6807900	(A) (G)STRIP 07/03/19	Less 020%	1.00	203.00	162.40
X	A8W6807838	(A) (SK)TRIM 07/03/19	Less 020%	1.00	36.20	28.96
X	A8W6945106B	(A) (SK)REFLECTOR 07/	Less 020%	1.00	37.10	29.68
X	A8W6807890	GUIDE	Less 020%	1.00	19.90	15.92
X	A8W8853856A GRU	TRIM	Less 020%	1.00	793.50	634.80
X	A8W6898909	SECUR.SET	Less 020%	1.00	117.50	94.00
X	A8W6898909A	ADHES.TAPE	Less 020%	1.00	191.50	153.20
X	ZC245/40R18CSC5	CONTI SPORT CONTACT		1.00	510.00	510.00

Parts 18,399.68
Labour 0.00
Sublet 17,764.00
Menus 0.00
Lubricant 0.00

Sub-Total 35,363.68

7% GST 2,475.46

Grand Total 37,839.14



Received by

For & on behalf of
Premium Automobiles Pte Ltd