

ASS. REC. BY:

REF:

CS/AG119003974/11/13/12

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Justin Wong

of

AGI

Date/Time:

04/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 6777T

Insured:

SLH 7736E

at Workshop m/s

FASTECH

Tel:

of

Policy No:

Claim No:

C10002730

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/3/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SMA 6777T

NA/UPC 19003908/24 DOR: 02/3/19

SLH 7736E

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.:

Yes or No

Lum Sum:

20 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Inspected 1-7-2019 LIA 8567 Yeh.
 not yet 33

20/3/19 1/5 @ 5000 confirmed with Alan. (Red to 19523.10, 80%)

RECEIVED 21 MAR 2019

Date/Time, File Pass to?

1) 21/3/19

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

TOTAL

450

Nivitha (LKK Auto)

From: Justin Wong <justin.wong@budgetdirect.com.sg>
Sent: Monday, 4 March 2019 12:20 PM
To: assignments
Cc: SUR
Subject: Appoint LKK to conduct TP survey (SMA6777T) | Our Ref: C10002730 (SLH7736E)

Hi Team,

Please accept survey assignment and liaise with TP workshop.

Mr. Marcus Chua was chosen.

Thank you.

Regards,

Justin Wong
Executive, Claims

T +65 6540 2184
F +65 6725 0853
E Justin.wong@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Nancy Lam <nancy.lam@fastechauto.com.sg>
Sent: Monday, 4 March 2019 12:12 PM

To: Justin Wong <justin.wong@budgetdirect.com.sg>

Subject: RE: Request for prs SMA 6777T | Our Ref: C10002730

Hi Justin

Please arrange Marcus Chua LKK Auto Consultants Pte Ltd to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Justin Wong [<mailto:justin.wong@budgetdirect.com.sg>]

Sent: Monday, March 4, 2019 11:59 AM

To: Nancy Lam <nancy.lam@fastechnote.com.sg>

Subject: RE: Request for prs SMA 6777T | Our Ref: C10002730

Hi Nancy,

We refer to your pre-repair inspection request on even date.

We propose to use one of the motor surveyors named in the list below to conduct the pre-repair survey.

1. Calvin Ang LKK Auto Consultant Pte Ltd
2. Bryan Ang LKK Auto Consultant Pte Ltd
3. Xing Guo Qiang LKK Auto Consultant Pte Ltd
4. Kenneth Kong LKK Auto Consultants Pte Ltd
5. Mohamad Taufihk LKK Auto Consultants Pte Ltd
6. Marcus Chua LKK Auto Consultants Pte Ltd
7. Pang Kiah Keen (Frankie) FormTeam Adjusters Pte Ltd
8. Chua Soo Teck (Benjamin) FormTeam Adjusters Pte Ltd
9. Lim Say Koon FormTeam Adjusters Pte Ltd
10. Ng You Han FormTeam Adjusters Pte Ltd
11. Soon HanXin (Gary) FormTeam Adjusters Pte Ltd
12. Kenji Tan FormTeam Adjusters Pte Ltd
13. Derrick Quok – In house Surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thank you.

Justin Wong
Executive, Claims

T +65 6540 2184

F +65 6725 0853

E justin.wong@budgetdirect.com.sg



Customer Care +65 6221 2111

Claims +65 6221 2199

Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore

239924

budgetdirect.com.sg



Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Nancy Lam <nancy.lam@fastechauto.com.sg>

Sent: Monday, 4 March 2019 11:32 AM

To: Claims <claims@budgetdirect.com.sg>

Subject: Request for prs SMA 6777T

Hi Sir

My client claiming your insured SLH 7736E.

Please kindly arrange PRS for SMA 6777T.

Date of accident 02.03.2019

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email)

reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Pan Pacific Singapore

\$573

Hotels.com

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A



2.68%P.A Low Interest@Gv
Finance. \$0 Admin Fees. \$3800
Downpayment Monthly \$738
GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING

(CHONG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

10 vehicles

Mazda 2

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

Search Selection

Mazda 2		Any	Any	2009	Any	Any	Any	Available
---------	--	-----	-----	------	-----	-----	-----	-----------

Mazda 2 HB 1.5A V (OPC)
(New 5-yr COE)

\$23,888

\$4,770 /yr

17-Mar-2009

1,498 cc

134,996 km

Hatchback

Available

(100% Showroom Condition!) 1st Owner Unit. Drive With Assurance From CaseTrust Accredited Dealer. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance. STA/VICO...

Sincere Motorring

Posted: 04-Mar-2019 Tags: 2009 Mazda 2, 2009 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda

Mazda 2 HB 1.5A R (New 5-yr
COE)

\$24,333

\$4,860 /yr

14-Apr-2009

1,498 cc

99,800 km

Hatchback

Available

1 Owner, New Arrival! Sporty Light Blue In Black Mazda 2 1.5A R Grade Model! Very Well Maintained By Careful Owner And 100% Accident Free. Low Mileage 99800Km Done Only And Fully Maintain By Careful O...

Posted: 02-Mar-2019 Tags: 2009 Mazda 2, 2009 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda

Mazda 2 HB 1.5A R (COE till
01/2024)

\$25,000

\$5,160 /yr

07-Jan-2009

1,498 cc

99,000 km

Hatchback

Available

New 5 Years COE, Well Maintained, Clean Interior And Exterior, Attractive Interest Rate Of 2.28% Available, High Loan/Trade In Welcome, Contact Us For An Appointment Now!

Posted: 01-Mar-2019 Tags: 2009 Mazda 2, 2009 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda

Mazda 2 HB 1.5A R (COE till
02/2024)

\$25,800

\$5,170 /yr

19-Mar-2009

1,498 cc

59,000 km

Hatchback

Available

1 Owner Only! Well Maintained By Previous Owner! Low Mileage! No Repair Needed! \$3000 Drive Away! (Include 1st Month Installment And Insurance). Trade In Welcome! Call Me Now Before It's Sold!

Viking Motor Pte Ltd

Posted: 28-Feb-2019 Tags: 2009 Mazda 2, 2009 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.

Mazda 2 HB 1.5A R (New 5-yr
COE)

\$25,388

\$5,070 /yr

12-Feb-2009

1,498 cc

95,208 km

Hatchback

Available

10 Year COE At \$39588. 100% Accident Free! Clean And Neat Interior. Beautiful And Pristine Condition! All Our Cars Have Gone Through Complete Checks And All Necessary Repairs Done With Glossy New Pain...

MV Auto

Posted: 26-Feb-2019 Tags: 2009 Mazda 2, 2009 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda

Mazda 2 HB 1.5A R (New 5-yr
COE)

\$24,800

\$4,950 /yr

19-Mar-2009

1,498 cc

130,000 km

Hatchback

Available

Original Condition. Call For Appointment To View Now!

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	7523A

Vehicle Details

Vehicle No.:	SMA6777T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 AT R
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	ZY519982
Chassis No.:	JM0DE10Y190130554
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$16,304.00
Original Registration Date:	02 Jul 2009
First Registration Date:	02 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$16,304.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jul 2019
PARF Rebate Amount:	\$8,152.00

Intended COE Rebate Details

COE Expiry Date:	01 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$415.00
Total Rebate Amount:	\$8,567.00

The information contained herein is correct as at 04 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/03/2019 15:28
Date Of Accident	02/03/2019 12:55
Exact Location Of Accident	SLIP RD PIE (TUAS) TWDS BEDOK NORTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA6777T
Insured/Policyholder	
Name Of Registered Owner	MAISARA BINTE ISMAIL
NRIC No	S9047523A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97374783
Alternative Phone No	OFFICE-97374783

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA2 AT R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05019231
Cover Note Number	

Driver

Name of Driver	MAISARA BINTE ISMAIL
NRIC No	S9047523A
Date Of Birth	12/12/1990
Occupation	INDOOR
Date Of Driving Pass	28/09/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97374783
Fax Number	
Contact Number	OFFICE-97374783
Email Address	NOEMAIL

Address	BLK 151 SIMEI STREET 1 #07-27
Postcode	520151
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG THE STATED VENUE AS THERE WAS INCOMING VEHICLES TRAVELLING ALONG THE MAIN RD. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH7736E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	THERN SIEW KEOW
NRIC/Passport Number	S1442241B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: ;

GENDER: ;

Accident Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Pole 1st 1st 1st

A 1st 1st 1st

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pole 1st 1st 1st

A 1st 1st 1st

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Added
Ha4/3 = 5000
5 day.
4/3/19

Qty Particular SMA 6777T

Amount S\$

List Item:

1PCS REAR WINDSCREEN MOULDING		111	\$110.80 ✓
1PCS TAILGATE	1184.20	Bodly 00	\$1480.20 ✓
1PCS TAILGATE INNER LOCK	309.10	Tw/shole	\$392.10 ✓
1PCS TAILGATE INNER TRIM BOARD		11	\$485.00 X
1SET TAILGATE INNER TRIM BOARD CLIPS		11	\$50.00 X
2PCS TAILGATE REFLECTORS @\$480.00		NT	\$960.00 X
1PCS TAILGATE WEATHERSTRIP	215	Tw	\$220.00 ✓
2PCS TAILGATE DAMPERS @\$300.00		11	\$600.00 X
1PCS TAILGATE REAR LOGO	60.00	M	\$80.00 ✓
1PCS TAILGATE 'MAZDA'2 EMBLEM		M	\$35.00 ✓
1PCS TAILGATE 'SKYACTIV' EMBLEM		NT	\$48.00 X
1PCS TAILGATE REAR WIPER MOTOR		11	\$560.00 X
1PCS REAR BUMPER	984	DD/OE	\$1280.00 ✓
1PCS REAR BUMPER REINFORCEMENT		Bent	\$385.00 ✓
2PCS REAR BUMPER SIDE RETAINERS @\$45.00		Bent	\$90.00 ✓
1SET REAR BUMPER CLIPS		M	\$50.00 ✓
2PCS REAR BUMPER LICENCE PLATE LAMPS @\$110.00		11	\$220.00 X
1PCS REAR END PANEL	445.00	DD/Bent	\$630.00 ✓
1PCS REAR END PANEL TOP GARNISH		Tw	\$289.00 ✓
1PCS REAR FLOOR PANEL		R	\$1500.00 X
1PCS REAR FLOOR PANEL TOP BOARD		11	\$685.00 X
1PCS REAR FLOOR PANEL TOOLS SPONGE		11	\$320.00 X
2PCS TAILLAMPS @\$850.00	545.90 x 2 = 1091.80	Cr	\$1700.00 ✓

(20%)

6340.7

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular	Amount S\$
<u>List Item:</u>		
2PCS	TAILLAMP HOUSING PANELS @\$330.00	2 \$660.00 X
2PCS	REAR FENDERS @\$1150.00	2 \$2300.00 X
2PCS	REAR FENDER INNER TRIM BOARDS @\$690.00	11 \$1380.00 X
1PCS	REAR EXHAUST	2 \$665.00 X
2PCS	REAR EXHAUST MOUNTINGS @\$30.00	11 \$60.00 X
1PCS	REAR EXHAUST HEAT SHIELD	11 \$118.00 X
1PCS	REAR BUMPER SPLASH SHIELD O/S	11 \$60.00 X
List Item Total:		\$17,413.10

Special Nett Item:

1PCS	REAR WINDSCREEN SEALANT	20 \$50.00 40
1PCS	REAR LICENCE PLATE W/HOLDER	10 \$50.00 40
1SET	REAR REVERSE CAMERA	11 \$680.00 X
1PCS	REAR END PANEL SEALANT	20 \$50.00 ✓
1SET	REAR FLOOR PANEL INSULATOR	11 \$300.00 X
1SET	REAR BUMPER REVERSE SENSOR	shuff \$280.00 200
Special Nett Total:		\$1,410.00

Labour Charge:

TO CHECK WIRING.	\$80.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR.	\$80.00 50
TO DISMANTLE & REFIX REAR WINDSCREEN.	\$150.00 120
TO TRANSFER TAILGATE MECHANISM.	\$100.00 60

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Labour Charge:

TO DISMANTLE & REPLACING REAR EXHAUST.

\$100.00 60

TO DISMANTLE & REFIX PETROL TANK.

11 \$100.00 X

TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.

\$180.00 80

TO RESET & REPLACING REVERSE CAMERA.

11 \$280.00 X

TO MOUNT VEHICLE ON CAR O-LINER.

11 \$380.00 X

TO SPRAY RUST PROOFING.

\$150.00 60

TO CONDUCT WHEEL ALIGNMENT.

11 \$100.00 X

LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN &REPLACING PARTS.

\$2000.00 600

TO PUTTY & SPRAY PAINTING.

\$2000.00 1080

Labour Charge Total:

\$5700.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$24,523.10

7542.58

6034

Let Fastech Auto Pte Ltd notify

the Repairer of the following:

- To use Fastech Auto Pte Ltd as the repairer
- To ensure that the repair is carried out
- To ensure that the repair is carried out
- To ensure that the repair is carried out
- To ensure that the repair is carried out
- To ensure that the repair is carried out
- To ensure that the repair is carried out
- To ensure that the repair is carried out

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19003974/Uqd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 26-03-2019



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 7736E	Veh. Inspected	SMA 6777T
Policy No.		Coverage (\$)	0.00
Claim No.	C10002730	Excess (\$)	0.00
Assign From	JUSTIN WONG	Assign Date	04/03/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 2 (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JM0DE10Y190130554	Colour	BLUE
Odometer	33008	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/45 R16	YOKOHAMA	6 mm
L/H Front Tyre	195/45 R16	YOKOHAMA	6 mm
R/H Rear Tyre	195/45 R16	YOKOHAMA	6 mm
L/H Rear Tyre	195/45 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/03/2019	Inspection Date	04/03/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 6777T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	110.80	110.80
1	TAILGATE	BADLY DENTED	1,480.20	1,184.20
1	TAILGATE INNER LOCK	TWISTED / SHORTED	392.10	309.10
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	485.00	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
2	TAILGATE REFLECTORS @\$480.00	NOT FITTED	960.00	-
1	TAILGATE WEATHERSTIP	TWISTED	220.00	215.00
2	TAILGATE DAMPERS @\$300.00	NOT NECESSARY	600.00	-
1	TAILGATE REAR LOGO	NECESSARY	80.00	60.00
1	TAILGATE "MAZDA 2" EMBLEM	NECESSARY	35.00	35.00
1	TAILGATE "SKYACTIV" EMBLEM	NOT FITTED	48.00	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	560.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,280.00	984.00
1	REAR BUMPER REINFORCEMENT	BENT	385.00	385.00
2	REAR BUMPER SIDE RETAINERS @\$45.00	BENT	90.00	90.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER LICENCE PLATE LAMPS @\$110.00	NOT NECESSARY	220.00	-
1	REAR END PANEL	DENTED / BENT	630.00	445.00
1	REAR END PANEL TOP GARNISH	TWISTED	289.00	289.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,500.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	685.00	-
1	REAR FLOOR PANEL TOOLS SPONGE	NOT NECESSARY	320.00	-
2	TAILLAMPS @\$850.00	CRACKED	1,700.00	1,091.80
2	TAILLAMP HOUSING PANELS @\$330.00	TO REPAIR SEE LABOUR	660.00	-
2	REAR FENDERS @\$1150.00	TO REPAIR SEE LABOUR	2,300.00	-
2	REAR FENDER INNER TRIM BOARDS @\$690.00	NOT NECESSARY	1,380.00	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	665.00	-
2	REAR EXHAUST MOUNTINGS @\$30.00	NOT NECESSARY	60.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	118.00	-
1	REAR BUMPER SPLASH SHIELD O/S	NOT NECESSARY	60.00	-

Report Ref No. CS/AGI19003974/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-1,049.78
			17,413.10	4,199.12
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR LICENCE PLATE W/HOLDER (SN)	CRACKED	50.00	40.00
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	680.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	300.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			1,410.00	330.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO DISMANTLE & REPLACING REAR EXHAUST.		100.00	60.00
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		180.00	80.00
	TO RESET & REPLACING REVERSE CAMERA.	NOT NECESSARY	280.00	-
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO SPRAY RUST PROOFING.		150.00	60.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,TAILLAMP HOUSING PANELS,REAR FENDERS AND REAR EXHAUST.		2,000.00	600.00
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,080.00
			5,700.00	2,140.00
	GRAND TOTAL		24,523.10	6,669.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CS/AGI19003974/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.