



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883
ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No:

4246572

Customer

Estimate

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Date:

04-03-19

Vehicle No: YP4657Z

Model/Make: Mitsubishi Fuso
FK62FMZiRDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Step Bracket Sliding Railing and Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc To putty & spray painting & including touch up paint on accident affected areas	\$ 520.00 \$ 600.00 \$ 500.00	SN ✓ 400 350

Total Parts & Labour of estimate for damaged vehicle

\$ 1,620.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

No of Attachments
here

1270

2/5 @ 1000
2000

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: