

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014321 Date : 04/10/2019 Order : SLX8692G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLX8692G (V 37114)	Regn Date: 14/04/2018	Mileage: 25002	WIP No.: 44425
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG	Chassis: WAUZZZ8V3JA087063	Engine: CHZ 678168	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	SUBLET	M: TO REPLACE FRONT WINDSCREEN.	400.00	1.00	400.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER,RADIATOR AND ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE CENTER CONSOLE,INSTRUMENT PANEL AND CLUSTER.RENEW DASHBOARD,BOTH FRONTAL AIRBAG, SLIP RING.TRANSFER OLD FITTINGS.RENEW SEAT BELTS AND CONTROL UNIT,PILLAR TRIMS,ROOF LINING, BOTH CURTAIN AIRBAG AND KNEE AIRBAG	3600.00	1.00	3,600.00
S	BODYWORK	M: TO RENEW FRONT WINDSCREEN	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOT FRONT FENDERS AND BOTH HEADLIGHT.CUT OUT AND WELD FENDER SUPPORT AND CLOSING ELEMENT.ALIGN BOTH FRON CHASSIS FRAMES TO SPECIFICATION OF ORIGIN.RENEW FR LOCK CARRIER TO POSITION.REORGANISE CRASH MANAGEME COMPONENTS.REINSTALL ALL PARTS REMOVED	4500.00	1.00	4,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BOTH FRONT FENDERS, BONNET,HINGES,BOTH UPPER A PILLAR,LHS FENDER	4875.00	1.00	4,875.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 2 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014321 Date : 04/10/2019 Order : SLX8692G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLX8692G (V 37114)	Regn Date: 14/04/2018	Mileage: 25002	WIP No.: 44425
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG	Chassis: WAUZZZ8V3JA087063	Engine: CHZ 678168	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	TOP SUPPORT AND BOTH FRONT DOORS.TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT M:	384.00	1.00	384.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	200.00	1.00	200.00
S	BODYWORK	TO SUPPLY FRONT WINDSCREEN SEALANT M:	600.00	1.00	600.00
S	BODYWORK	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING FOR BOTH FRONT DOOR M:	900.00	1.00	900.00
X	A8V0823723	TO REMOVE AND RENEW INTAKE MANIFOLD AND OTHER DAMAGED ENGINE COMPONENTS.			
X	A04C129601G	(A) (G) SEAL 11/03/19	Less 020%	1.00	52.40
X	A8V4867505B YX7	(A) (SK) AIRCLEANER 18	Less 020%	1.00	251.50
X	A0AM911024A	(A) (Ger) ROOFLINING 1	Less 020%	1.00	1809.00
X	A04C129709E	(V) (Ger) STARTER 18/0	Less 020%	1.00	1443.00
X	A8V2819635D 6PS	(V) (Ger) MANIFOLD 18/	Less 020%	1.00	587.50
X	A8V2857367B 6PS	(V) (Ger) AIR VENT 26/	Less 020%	1.00	137.50
X	A8P0971848D	(V) (Ger) COVER 26/3/1	Less 020%	1.00	85.20
X	A8V3853651AA3FZ	HOLDER (V) 29/03/19	Less 020%	2.00	5.40
X	A8V0867233 VU6	GRILLE	Less 020%	1.00	1301.00
X	A8V0867234 VU6	(V) (Ger) LINING 26/3/	Less 020%	1.00	146.50
X	A8V0941773D	(V) (Ger) LINING 26/3/	Less 020%	1.00	146.50
X	A8V0941774D	HEADLIGHT	Less 020%	1.00	5029.00
X	A8V0821105L	HEADLIGHT	Less 020%	1.00	5029.00
X	A8V0821106L	FENDER	Less 020%	1.00	777.50
X	A8V2819401 9B9	FENDER	Less 020%	1.00	777.50
X	A8V0863825	COVER	Less 020%	1.00	163.50
X	A8V0880201DN6PS	(A) (SK) SILENCER 11/0	Less 020%	1.00	201.00
X	A8V0880204J	(A) (G) AIRBAG 11/03/1	Less 020%	1.00	3141.00
X	A8V4880741F	(A) (SK) AIRBAG 11/03/	Less 020%	1.00	4238.00
X		(A) (G) AIRBAG 11/03/1	Less 020%	1.00	1708.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 3 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014321	Account: A0006 (T 0)
		Date : 04/10/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
		Order : SLX8692G	
		Term : 30	

Regn No: SLX8692G (V 37114)	Regn Date: 14/04/2018	Mileage: 25002	WIP No.: 44425
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG	Chassis: WAUZZZ8V3JA087063	Engine: CHZ 678168	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details		Qty	Unit Price	Amount
X	A8V4880742F	(A) (G)AIRBAG 11/03/1	Less 020%	1.00	1708.00	1,366.40
X	A8V2880841D	(A) (SK)AIRBAG 11/03/	Less 020%	1.00	1708.00	1,366.40
X	A5Q0816411AS	(V) (G)CONDENSER 11/0	Less 020%	1.00	502.50	402.00
X	A5Q0121251GD	RADIATOR	Less 020%	1.00	878.00	702.40
X	A5Q0121251HS	RADIATOR	Less 020%	1.00	837.00	669.60
X	A8V3807233B	PLATE	Less 020%	1.00	270.00	216.00
X	A8V0805588A	(A) (SK)CARRIER 11/03	Less 020%	1.00	663.00	530.40
X	A5Q0121203DA	ELECTRIC F	Less 020%	1.00	1483.00	1,186.40
X	A8V0807550A	FOAM INSER	Less 020%	1.00	172.00	137.60
X	A8V4807109E	BEAM	Less 020%	1.00	659.50	527.60
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	21.00	67.20
X	A8V3845099S NVE	(A) (SK)WINDSHIELD 11	Less 020%	1.00	987.50	790.00
X	A8V0807065R GRU	COVER	Less 020%	1.00	1698.00	1,358.40
X	A8V0823029D	HOOD	Less 020%	1.00	2501.00	2,000.80
X	A8V2857001J 24A	(A) (SK)DASHBOARD 11/	Less 020%	1.00	3887.00	3,109.60
X	A4G0063511L	UTR ADHESIVE PADS	Less 020%	1.00	26.00	20.80
X	A8V0098615	ATT.PARTS	Less 020%	1.00	149.00	119.20
X	A04E145757	GASKET	Less 020%	1.00	12.60	10.08
X	A5Q0121367F	(A) (SK)BRACKET 18/03	Less 020%	2.00	38.30	61.28
X	A8V0121285A	AIR DUCT	Less 020%	1.00	10.40	8.32
X	A04C145749A	(A) (SK-Last)COOLER 1	Less 020%	1.00	691.50	553.20
X	A8V0823126B	EDGING	Less 020%	1.00	24.90	19.92
X	A8V0807217A	COVER	Less 020%	1.00	111.00	88.80
X	A8V3807319	PLATE	Less 020%	1.00	270.00	216.00
X	A8V3807320	PLATE	Less 020%	1.00	270.00	216.00
X	A5Q0820769	(A) (SK)BRACKET 18/03	Less 020%	1.00	24.50	19.60
X	A8V0821092C	PLATE	Less 020%	1.00	55.30	44.24
X	A8V0821468E	BRACKET	Less 020%	1.00	42.60	34.08
X	A8V0821135A	SUPPORT	Less 020%	1.00	87.30	69.84
X	A8V0821136A	SUPPORT	Less 020%	1.00	87.30	69.84
X	A8V3807183B	GUIDE	Less 020%	1.00	34.40	27.52
X	A8V3807184B	GUIDE	Less 020%	1.00	34.40	27.52
X	A8V0823301G	HINGE	Less 020%	1.00	55.30	44.24
X	A8V0823302G	(SK)HINGE	Less 020%	1.00	55.30	44.24

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 4 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014321 Date : 04/10/2019 Order : SLX8692G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLX8692G (V 37114) Regn Date: 14/04/2018 Mileage: 25002 WIP No.: 44425

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V3JA087063 Engine: CHZ 678168 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	A5Q0122291BD	(A) (SK) COUPLPIECE 18	Less 020%	1.00	21.60	17.28
X	A5Q0129621B	AIR DUCT	Less 020%	1.00	18.10	14.48
X	A5Q0129637B	(A) (SK) HOSE 18/03/19	Less 020%	1.00	30.60	24.48
X	A8V0121230	SEAL	Less 020%	1.00	7.10	5.68
X	A1K0121367F	MOUNTING	Less 020%	2.00	8.90	14.24
X	A8V0820536	BRACKET	Less 020%	1.00	16.30	13.04
X	A8V0823185C	CATCH	Less 020%	1.00	99.40	79.52
X	A8V0857819	ADJUSTER	Less 020%	1.00	180.50	144.40
X	A8V0823186C	CATCH	Less 020%	1.00	99.40	79.52
X	A8V0821467E	BRACKET	Less 020%	1.00	42.60	34.08
X	A4H0823543	COVER	Less 020%	1.00	8.90	7.12
X	A8V0821091C	PLATE	Less 020%	1.00	55.30	44.24
X	A8Z0820535A	TEMP.SENS.	Less 020%	1.00	53.70	42.96
X	A8V4823485C	HOOK	Less 020%	1.00	57.20	45.76
X	A4D0260749B	WASHER	Less 020%	1.00	3.00	2.40
X	A3D0260749C	WASHER	Less 020%	1.00	4.00	3.20
X	A5Q0820741B	(V) (SK) COOLANTPIIP 25	Less 020%	1.00	600.50	480.40
X	A8V0823480A	HOOK	Less 020%	1.00	80.90	64.72
X	A4H0823188	(A) (G) COVER 11/03/19	Less 020%	2.00	3.20	5.12
X	A8V0823509A	LOCK	Less 020%	2.00	183.50	293.60
X	A8V0419091CHINU	(V) (Ger) STEERINGWH 2	Less 020%	1.00	2169.00	1,735.20
X	A8V0857608 MG6	(V) (Ger) HANDLE 26/3/	Less 020%	1.00	129.00	103.20
X	A8V0857607A MG6	(V) (Ger) HANDLE 26/3/	Less 020%	1.00	129.00	103.20
X	A8V5857705E V04	(A) (SK) SEAT BELT 11/	Less 020%	1.00	1005.00	804.00
X	A8V5857706E V04	(A) (SK) SEAT BELT 11/	Less 020%	1.00	1005.00	804.00
X	A8V0857607 MG6	(A) (SK) HANDLE 26/3/1	Less 020%	2.00	129.00	206.40
X	A8V2823535B	CABLE	Less 020%	1.00	66.70	53.36
X	A8V0823531A	BOWD CABLE	Less 020%	1.00	52.10	41.68
X	A5Q0820743K	(V) (Ger) COOLANTPIIP 1	Less 020%	1.00	461.00	368.80
X	A8U0955609	FILM	Less 020%	1.00	128.00	102.40
X	A7L0973812	(A) (SK) HOUSING 26/3/	Less 020%	1.00	15.30	12.24
X	A5Q0959651B	(A) (SK) SENSOR 11/03/	Less 020%	3.00	381.50	915.60
X	A1J0955751D	TUBING	Less 020%	1.00	74.90	59.92
X	A431955465A	GASKET	Less 020%	1.00	6.90	5.52

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 5 14:37

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014321 Date : 04/10/2019 Order : SLX8692G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLX8692G (V 37114)	Regn Date: 14/04/2018	Mileage: 25002	WIP No.: 44425
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG	Chassis: WAUZZZ8V3JA087063	Engine: CHZ 678168	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
X	A443955465	GASKET	Less 020%	1.00	2.90
X	A000979940	CONNECTOR (WHITE)	Less 020%	5.00	9.60
X	A000979020EA	WIRES	Less 020%	2.00	21.40
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	AD 00920002	PRIMER (DG)	Less 020%	1.00	18.60
X	A5Q0959655BJ	(A) (SK)MODULE 11/03/	Less 020%	1.00	1606.00
X	A8V0951210D	HORN	Less 020%	1.00	182.00
X	A5Q0129254B	AIR DUCT	Less 020%	1.00	52.30
X	A8V0121284K	AIR DUCT	Less 020%	1.00	21.40
X	A8V0121283K	AIR DUCT	Less 020%	1.00	21.40
X	A8V3853949	(A) (SK) PLATE 11/03/1	Less 020%	1.00	173.50
X	A5Q0955453R	WATER RES.	Less 020%	1.00	185.50
X	A8V0998474A	LED	Less 020%	1.00	665.50
X	A7PP941572AC	POWER MOD	Less 020%	2.00	692.50
X	A8S0907397D	CTRL UNIT	Less 020%	2.00	507.50
X	A8V0998473A	LED	Less 020%	1.00	665.50
X	AN 0161857	POP-RIVET	Less 020%	16.00	3.00
X	AN 10721501	BOLT	Less 020%	1.00	7.40
X	AN 90653901	(A) (SK)CLIP 18/03/19	Less 020%	1.00	1.30
X	AWHT005551A	BOLT	Less 020%	8.00	2.10
X	AN 90827102	BOLT	Less 020%	1.00	23.10
X	AN 10507201	SCREW	Less 020%	2.00	0.90
X	AN 91141501	RIVET	Less 020%	1.00	2.20
X	A5Q0129954	COVER	Less 020%	1.00	26.70

Parts 49,470.64
Labour 0.00
Sublet 17,524.00
Menus 0.00
Lubricant 0.00

Sub-Total 66,394.64

7% GST 4,647.62

Grand Total 71,042.26



Received by

For & on behalf of
Premium Automobiles Pte Ltd