25/03/2002 ASS. REC. BY:	REF: 03/07/1900/4013/49930V Special Instruction:
Surveyor: M	ASSIGNMENT (Office)
From (Person):	hong Boon Sen of CII Date/Time: 05 3/19
Estimated Cost: _	
OD TP/WS/T	PRES/OD RES/EVA/INV/MV/CS .
To Inspect Vehicle	e No: 40 3802C Insured:
at Workshop m/s	Fin Muso Tel: 6289 8126
of	behi Ceur
Policy No:	DMCV9N1647281802 Claim No: SNM19D70102201/2
Sum Insured:	1/ -
Make of Veh: (Client's Record)	D.O.A. 01 3/19
	EP. / REV 24 HRS H.O.D. Endorsement:
D. Ari	Person Contacted: Vehicle IN AOUT
Date/Time A	ction/Instruction ( ) Estimate
	18 3807C x
7/3/2019-	Revert via merimen
	320 Mfred in Brand c/ 8 tx; \$550 Wa Meinen.
1/1/2/10/10	12an Informed Jours C/A on 15 bases & ex: \$550 by end

(08/11/13) wef	REF:	
ASS. REC. BY: MCrous		
	<u>A</u>	SSIGNMENT
From:	Date:	Veh No: 423802 C Yr Regn: \$ , 16
Estimated Cost:	40.140	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD I TP I WS I TP RES I OD	RES / EVA / INV / MV	Truck / Trailer or M
To Inspect Vehicle No:	1/73802	Make: Mit conter c.c 2998
at Workshop m/s	Ju Are	Colour W. C A/C: Insured / Std / NI / NA
of		Sp.Reading 23 241 T/Radio: Insured / Std / NI / NA
Insured:		Eng/No:
Policy No.	1	C/No: FEB21EA20.909
Claims No.		Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured:	Excess: 500	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	-3	Brake: Ingrater / Jammed / Leaked / Burnt or
Make of Veh:		Modi: Nil / \$/Rim / STD A/Rim or
		Tyre Size: F: 185 N/T
(Policy Condition)		m R: 190/ funct
Remark: The veh had comm	nenced its N/S O/	
repair at the time	of inspection.	TOYO / YOKO or
Bal. or Market Value:	56k.	Front Rear
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6/6 mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. / mm L/Bal. 6/6 mm
Est. Repairs: 7	days Res.: Yes or No	D.O.A. 1/3/18 D.O.I. 6/3/18
Lum Sum: 20	% 3 Val.: Yes or No	Survey held at
CA / DEV / DED / 2	4 HRS OFO	Des. of Damages : Frt   Rear   O/S   N/S   U/C   Rooftop or
CA / REV / REP. / 2	Vehicle: IN / O	
Date: Perso	on Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
7/3/19 4/5	7A16245	1 rule Jones. (Red 86040, 40%)
Date/Time, File Pass to?	7. Proli Ponert	Davis Of Banata 7
1179/2 tumbr	: Preli. Report	Days Of Repair:
Date/Time, File Return to?	1. Piliai Report	Resurvey No. of Trip: Survey Fee: 220 Transportation:
2)	Add F	
e early	n a=1-11 f	: Interview (\$ ) Photos
Report Format :	MER-OD	: Tech. Invs (\$ ) Others
Lump Sum / I.B.I: (\$	9000	:Weekend (\$
		TOTAL 220
		TOTAL

# ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

ALL ASSOCIATED TASKS

Priority Type

Task Group

Subject

Due Date

No results.

	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	Submitted	Ins Auth'ed	Gr.	atus
	04 Mar 2019 10:01 Sendback Est	05 Mar 2019 10:05 <b>S\$12,140.00</b>	05 Mar 2019 11:51 Assign				and Addition	Ne	w Assignment
M	tain	Referen	nce	Claim Deta	ils		Documents		Show All
CLAIM SUE	FOLDER DETAI	ILS	Name of Street, or other				IN THE RESERVED		
Insured:		0.110.00	L. Co Reg No.	. 2012009000					
Vehicle Reg. No.:	MSK STAR ENGINEERING PTE L, Co. Reg. No.: 201200800G  9. YP3802C Date of Loss: 01/03/2019 16:00 - :59 [30 Months and 6 Days From LTA Reg Date (Mar						Data (Man Vel)		
Claim Type:	OD		Policy/Cover Note No.: DMCVSN1657281802 (Comprehensive)						
Repairer:	lin Auto Sand	isos Bto Ltd (D.S.	3 700 14 7 7	Excess:		S\$550.00			
Handling Insurer:	China Taiping	ices Pte Ltd (Defu Insurance (Singa	apore) Pte. Ltd	ane 10, #01-410/4 . (HQ) - Tel: 6389	12, 5 6111	39195 Defu L L [Handled	ane - Tel: 6289 81 by Chong Boon S	26 en1	
Adjuster:									
Driver/Custo dian:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 14/03/2019]  KUMARAPPAN BALACHANDAR ( / Male) , NRIC: G2538574H Email:							
Adj Asg. Remarks:	SURVEY REVER	ST.	7						
ASSOCIATE	D MAIL RECEI	VED					View	All I	Compare Care Hal
There are no	mail for this case						View	All	Compose Case Ma

Handler

Assigned By



Search Tasks | Create New Task | Complete

Created On

Done?

# Claim Audit

No.	On	Audit	Remarks	Ву
	04 Mar 2019		(205018) MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M).	[R] JOUIS
	09:53	Cim ven Model Changed	(203016) MITSUBISHI CANTER 3.0 D FEB21ER33DEB (CBO) (M).	SEOW
	04 Mar 2019 09:53	Clm Created	Reg No: YP3802C. Policy No: DMCVSN1657281802. Acct Date: 2019/03/01. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Jin Auto Services Pte Ltd (Defu)	[R] JOUIS SEOW
	05 Mar 2019 10:05	Clm Submitted	12140.00.	[R] JOUIS SEOW
	05 Mar 2019 11:51	Clm Registration Modified	Excess: -> 550.00.	<ul><li>[I] Chong</li><li>Boon Sen</li></ul>
	05 Mar 2019 11:51	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
	05 Mar 2019 11:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/14	[I] Chong Boon Sen
	05 Mar 2019 11:51	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
~	05 Mar 2019 13:41	Assignment 1st Accessed		[A] SHIAL CHAN
	05 Mar 2019 17:54	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] SHIAU CHAN
	07 Mar 2019 11:49	Adj Rpt Initiated		[A] DENIS TAY KWE CHENG
.1	07 Mar 2019 11:57	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/14	[A] DENIS TAY KWEI CHENG
	07 Mar 2019 11:57	Adj Mandate Request	Cur.Req:7650.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENIS TAY KWEE CHENG
.3	12 Mar 2019 11:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/14. Mandate Remarks: Please proceed to authorize repairs at \$7,650.00 BEFORE Excess of \$550.00	[I] Alfred T
	12 Mar 2019 11:32	Adj Mandate Set	Approved:7650.00:Please proceed to authorize repairs at \$7,650.00 BEFORE Exces s of \$550.00Reinsp:Adj decides.	[I] Alfred T
.5	14 Mar 2019 10:31	Clm Supp Created (S:802006)		[R] JOUIS
.0	14 Mar 2019 10:33	(S:802006)	1700.00.	[R] JOUIS
.,	14 Mar 2019 10:33	(S:802006)	LKK Auto Consultants Pte Ltd (HQ):	[I] Merime Administrat
.0	26 Mar 2019 17:14	Supp Combined (S:802006)		[A] SHIAL
.9	28 Mar 2019 09:32	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/14	[A] SHIAL
	28 Mar 2019 09:33	Adj Mandate Request	Cur.Req:9000.00:KINDLY APPROVE REPAIR COST OF LUMP SUM \$9,000.00 INCLUS IVE OF SUPPLEMENTARY AND CHECK ITEMS.	[A] SHIAU
	29 Mar 2019 09:31	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/03/14. Mandate Remarks: Please proceed to authorize repairs at \$7,650.00 BEFORE Excess of \$550.00	Boon Sen
	29 Mar 2019 09:31	Adj Mandate Set	Approved:9000.00:Please proceed to authorize repairs at \$7,650.00 BEFORE Exces s of \$550.00	[I] Chong Boon Sen

■ Date To ▲ ■ ► Audit Type None ▼ Go **Date From** 

ACTIVITY No record

07/03/2019 11:49

Merimen Billin	g for this case -	Transaction H	istory				
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2074408	04/03/2019 09:53	Motor	Jin Auto Services Pte Ltd	Jin Auto Services Pte Ltd (Defu)	YP3802C		xx.xx
2078448	07/03/2019	Motor	LKK Auto Consultants Pte	LKK Auto Consultants Pte	YP3802C		10.70

Ltd (HQ)

Consultants Pte Ltd

#### Note: This document has not been finalised.

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Chong Boon Sen

Date: 28 Mar 2019

# **Preliminary Advice**

Vehicle No

: YP3802C

Accident Date

: 01/03/2019

Make

: MITSUBISHI CANTER

Policy No.

: DMCVSN1657281802

Assignment Date

: 05/03/2019

Excess

: S\$550.00

Date of Inspection : 06/03/2019

Est. Duration of Repair

: 7.00

Inspection At

: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412

SINGAPORE 539195

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	(ESTIMATE \$13,340.00 + 15,040.00 SUPPLEMENTARY \$1,700.00)	
Revised Amount	:S\$	11,250.00	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,250.00	
Lump Sum Repair	:S\$	9,000.00	
Total Loss Consideration			
New for Old Value	:S\$		
Pre-Accident Value	:S\$	56,000.00	
COE / PARF Rebate	:S\$	16,245.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	39,755.00	

#### Remarks

(	X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	ly
		let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments: KINDLY APPROVE ON REPAIR COST OF LUMP SUM \$9,000.00.

#### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 13 March 2019 9:12 AM

To:

jouis@jinauto.com.sg

Cc:

SUR

Subject:

OD VEHICLE YP 3802C (DOA: 01/03/2019)

Dear Jouis,

As instructed by our client, please proceed to repair the insured vehicle **YP 3802C at repair cost on Lump Sum Basis** (Excess \$550/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# Claim Audit

1	AUDIT TRAIL			733
lo.	On	Audit	Remarks	Ву
	04 Mar 2019 09:53	Clm Veh Model Changed	(205018) MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M).	JOUI SEO
	04 Mar 2019 09:53	Clm Created	Reg No: YP3802C. Policy No: DMCVSN1657281802. Acct Date: 2019/03/01. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Jin Auto Services Pte Ltd (Defu)	JOU! SEO
3	05 Mar 2019 10:05	Clm Submitted	12140.00.	JOU! SEO
	05 Mar 2019 11:51	Clm Registration Modified	Excess: -> 550.00.	[I] Chor Boo Ser
	05 Mar 2019 11:51	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chor Boo Ser
6	05 Mar 2019 11:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/14	[I] Chor Boo Ser
7	05 Mar 2019 11:51	Adj Mandate Set	Approved:0.00.	Chor Boo Ser
8	05 Mar 2019 13:41	Assignment 1st Accessed		[A] SHIA CHA
9	05 Mar 2019 17:54	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] SHIA CHA
10	07 Mar 2019 11:49	Adj Rpt Initiated		DENI TAY KWE
11	07 Mar 2019 11:57	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/03/14	DENI TAY KWE CHEI
12	07 Mar 2019 11:57	Adj Mandate Request	Cur.Req:7650.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	DENI TAY KWE
13	12 Mar 2019 11:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/03/14. Mandate Remarks: Please proceed to authoriz e repairs at \$7,650.00 BEFORE Excess of \$550.00	[I] Alfre Toh
14	12 Mar 2019 11:32	Adj Mandate Set	Approved:7650.00:Please proceed to authorize repairs at \$7,650.00 BEFORE Excess of \$550.00Reinsp:Adj decides.	[I] Alfre Toh

**▲** ■ ▶ Date To ▲ ■ ► Audit Type None ▼ Go **Date From** 

ACTIVITY	
No record	

Bill Ref No	g for this case -	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2074408	04/03/2019 09:53	Motor	Jin Auto Services Pte Ltd	Jin Auto Services Pte Ltd (Defu)	YP3802C		xx.xx
2078448	07/03/2019 11:49	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	YP3802C		10.70

#### 3/7/2019

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Chong Boon Sen

Date:

07 Mar 2019

# **Preliminary Advice**

Vehicle No

· YP3802C

Accident Date

: 01/03/2019

Make

: MITSUBISHI CANTER

Policy No.

: DMCVSN1657281802

Assignment Date

: 05/03/2019

Excess

: \$\$550.00

Date of Inspection

: 06/03/2019

Est. Duration of Repair

Inspection At

: JIN AUTO SERVICES PTE LTD (DEFU) BLK 14 DEFU LANE 10, #01-410/412

SINGAPORE 539195

: 7.00

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,140.00
Revised Amount	:S\$	6,145.00
Check Items (Estimated)	:S\$	3,425.00
Total	:S\$	9,570.00
Lump Sum Repair	:S\$	7,650.00

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	16,245.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,755.00

#### Remarks

( x )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	lly
	let us have your authorisation.	

) The vehicle is uneconomical to be repaired	you are advised to invite tender for the wreck
--	--

Other comments:

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

IDT	
Owner ID Type:	Company
Owner ID: /ehicle Details	0800G
'ehicle No.:	YP3802C
ehicle to be Exported:	No
ntended Deregistration Date:	06 Mar 2019
ehicle Make:	MITSUBISHI
ehicle Model:	CANTER FEB21ER4SDEB (CBU)
rimary Colour:	White
Nanufacturing Year:	2016
ngine No.:	4P10C34976
hassis No.:	FEB21EA20909
laximum Power Output:	-
Open Market Value:	\$34,117.00
Original Registration Date:	23 Aug 2016
irst Registration Date:	23 Aug 2016
ransfer Count:	0
actual ARF Paid: ntended PARF Rebate Details	\$1,706.00
ARF Eligibility:	No
ARF Eligibility Expiry Date:	-
ARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
COE Expiry Date:	22 Aug 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$21,778.00
OE Rebate Amount:	\$16,245.00
otal Rebate Amount:	\$16,245.00

The information contained herein is correct as at 06 Mar 2019

ОК

#### SGCARMART COM

Login Sign up

**New Cars** 

**Used Cars** 

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

# FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

2 units BMW X2 sDrive20i M-Sport for sales.



PML 3 Years Warranty! Super Low Mileage At 3800km, high trade in. Call us now! Speedo Motoring StarAd



Browse by Category ~

Post an Ad

Advertiser Login

Make

Ways of Selling

Mitsubishi FFh21

Model

Depreciation

Reg Date

Eng Cap

Sort by Date Posted

Advanced Search 🗽

Veh Type

Submit (

Status Available

✓ 20 results/page ✓

Search Selection

5 vehicles

Mitsubishi FEb21

23-Sep-2016

2016

2.998 cc

Truck

Available

Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel

\$59,800

\$7,920 /vr

Any

No VPC Required, Class 3 Licence Can Drive. 1 Owner Only, Very Suitable For Ferry Workers, No Repair Needed. Very Good Condition. Can Carry Up To 2.6 Ton. High Loan And High Trade In Available. Call U...

ABWIN (1994) Pte Ltd

Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Posted: 06-Mar-2019 Used Mitsubishi

14-Nov-2016

2,998 cc

Available

Mitsubishi Fuso Canter FEB21 Fuel Type: Diesel

\$55,800

\$7,250 /yr

New Arrival, 100% No Gimmick, Nice Bidding Number Plate Go With The Truck. Low Mileage, Full Canopy. Class 3 Can Drive. Original Condition, Road Tax Utill Nov 2019. Well Kept Stunning Condition, 6 Alm...

Posted: 05-Mar-2019

Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubi



Mitsubishi Fuso Canter FEB21

\$58,800

\$8,520 /yr

27-Jan-2016

2,998 cc

Truck

Available

Fuel Type: Diesel

1 Owner Only. 15 Feet Wooden Deck With Full Length Canopy, Can Drive With Class 3 Licence. No VPC Required. High COE Value Of \$42,036.

Posted: 04-Mar-2019

Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi



Mitsubishi Fuso Canter FEB21

\$61,800

\$8,170 /yr

28-Sep-2016

2,998 cc

Truck

Available

Fuel Type: Diesel

As Good As New, With New Canopy, High Trade In, Low Interest, Door Step View, Call Now For Appointment!

ABWIN (1994) Pte Ltd

Posted: 03-Mar-2019

Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi Fuso, fuso, Used Mitsubishi



Key Chain (Mitsubishi)

Universal Key Chain (Mitsubishi)

More info about this product



Mitsubishi Fuso Canter FEB21

\$57,800

\$8,440 /yr

08-Jan-2016

2,998 cc

Truck

Available

Why Go Still For Rental ? 90% Loan And Monthly Installment Only Pay \$856, No Need Guarantor! Come With LTA Approved High Box And Low Deck Easy For Loading Of Goods! Free New Paintwork Can Choose Your ...

ABWIN (1994) Pte Ltd

Posted: 11-Feb-2019

Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso,

Used Mitsubishi

Save this search criteria, to get email alerts whenever a match is found.

Compare

Depreciation

Reg Date

Eng Cap

Mileage

https://www.sgcarmart.com/used\_cars/listing.php?RGD=2016&MOD=Mitsubishi FEb21&RPG=20&V... 06-Mar-19

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

atoresaid.	
	ACCIDENT STATEMENT
Date Of Report	02/03/2019 11:09
Date Of Accident	01/03/2019 16:40
Exact Location Of Accident	ECP TOWARDS CHANGI AFTER BEDOK EXIT
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	YP3802C
Insured/Policyholder	
Name Of Registered Owner	MSK STAR ENGINEERING PTE LTD
Co Reg No	201200800G
Email Address	MSKSTARENGG@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90091425
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEB (CBU)
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1657281802
Cover Note Number	
Driver	
Name of Driver	KUMARAPPAN BALACHANDAR
Passport No/FIN	G2538574H
Date Of Birth	24/05/1989
Occupation	OUTDOOR
Date Of Driving Pass	30/01/2015
Driving Experience	4 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84044557
Fax Number	
Contact Number	

NOEMAIL

5 YISHUN INDUSTRIAL STREET 1 #04-07 NORTH SPRING BIZHUB Address

SINGAPORE

768161 Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

NO Was any body injured in the Accident?

Was any injured conveyed to hospital by NO

ambulance?

YES

2

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING ALONG ECP TOWARDS CHANGI, WHEN THE FRONT VEHICLE B SUDDENLY STOPPED, I CANNOT STOP IN TIME AND HAD COLLIDED ONTO VEHICLE B REAR PORTION, NO ONE WAS INJURED, THE VEHICLE B JUST LEAVE THE SCENE AFTER ACCIDENT HAPPEN, SO I CANNOT GET ANY PARTICULAR FROM DRIVER AND THE VEHICLE B VEHICLE NUMBER.

#### Attachment(s)

Are accident photos available for attachment? YES NO Was there any video captured by Car Camera? NO Was there any audio recorded?

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Accident Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (lii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

nature

Date & Time:

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

#### Accident Sketch Plan

SKETCH PLAN					
		- 1 - 1			DOH D1/03/201
		8			A : YP3802 C
					B: Unknown
		AII			
		1 1			
		1 1			
ESCRIBE CIRCUM	MSTANCES OF 1	THE ACCIDENT			
I was	travelling	along ECP	towards	Changi Est	, When
the from	t vehicle	B Suddenly	stopped,	I cannot	rtop in tin
and led	callidad	suf- v	lite B	race partial	no one was
- B	COLLIGES	20010	MICIE	rear portion	no one mus
injured, -	the de	vehicle B	just lead	re the so	ine after
, ,	, ,				
the accid	eut ha	ppen iso	1 cannot	get any	parti-cular
of briver	and	the veh	icle B no	umber a	
ECLARATION	estalina nastleulare	are true in every respe	et	/	1 ATE DA
ve deciare the roll	egoing particulars	. D. A.	51	12	40
olicyholde Signatu	*	Driver's alghature	Por haddeek		ersonnel's Signature
ate & Time:		(If driver is not the po Date & Time:	ucyroider)	Name: NRIC/FIN No.:	

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-410/412 Singapore 539195

Tel: 6289 8126 Fax: 6287 0590 Email: Jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg.No: 200704370C

LKK.

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

P	Δ	B.	TI	CI	Ш	Ι Δ	RS	0	F	CI	Δ	M
	_					ᅳᅳ				~_		

Claim Type:

OD (OWN DAMAGE) DMCVSN1657281802 Ref. No:

YP3802C

Policy No:

YP3802C

Date of Loss: Driveable?

01/03/2019

Vehicle Reg. No.: Driver Age/Info:

/ MALE

UNKNOWN

TP Injury Involved?

Party At Fault:

NO

Insured/Claimant:

MSK STAR ENGINEERING PTE L

KUMARAPPAN BALACHANDAR

Third Party Involved? YES

Driver:

MITSUBISHI CANTER, 3.0 D

Vehicle Reg. Date:

23/08/2016

Vehicle Colour:

Make/Model:

FEB21ER3SDEB (CBU) (M) WHITE

Engine No:

4P10C34976

1 KM

Chassis No:

FEB21EA20909

Odometer:

Paint Type:

Total Loss?

NO

14

Est. Duration of Repair (day)

I WAS TRAVELLING ALONG ECP TOWARDS CHANGI, WHEN THE FRONT VEHICLE B SUDDENLY STOPPED , I CANNOT STOP IN TIME AND HAD

COLLIDED ONTO VEHICLE B REAR PORTION, NO ONE WAS INJURED, THE VEHICLE B JUST LEAVE THE SCENE AFTER ACCIDENT HAPPEN, SO I CANNOT GET ANY PARTICULAR FROM DRIVER AND THE VEHICLE B

VEHICLE NUMBER.

Present Location:

Description of

Accident/Loss

JIN AUTO SERVICES PTE LTD (DEFU)

	400	Nett Amount (S\$)	12,989.80
	Signature: Date:	+ GST 7.00% (S\$)	849.80
	Acknowledged by Repairer	Gross Total (S\$)	12,140.00
Towing	<ul> <li>Supplementary named must us is subject to fir all approval from</li> </ul>	e resurveyed and in insurance Company	0.00
Paintwork Labour	<ul> <li>No illegui medilicalloggi lyali</li> </ul>	0.00	
Labour	Trico party survey is on a 'Will		2,940.00
Miscellaneous Items	<ul> <li>To display damaged panish the</li> <li>Parts recessive addient to con</li> </ul>		0.00
Parts	* To resulting beforelatter spray		9,200.00
COST OF CLAIMS	the Repairer of the follow	ng:	Amount
	LKK Auto Consultants he	nce notify	

This claim is handled by: JOUIS SEOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

#### REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 05 Mar 2019)

Parts:

MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: Jin Auto Services Pte Ltd/YP3802C/05/03/2019 10:05

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

Vo.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN SNO	0.00	0.00	*700.00 F
2	1		*FRONT WINDSCREEN RUBBER 744	0.00	0.00	*200.00 F
}	1		*WIPER PANEL P9	0.00	0.00	*190.00 F
	1		*LH WIPER ARM 34	0.00	0.00	*70.00 F
5	1		*LH WIPER BLADE	0.00	0.00	*10.00 F
	1		*FRONT PANEL 5.45.00	0.00	0.00	*980.00 F
	1		*FRONT PANEL FUSO EMBLEM PMC	0.00	0.00	*40.00 F
	1		*GRILLE CMO	0.00	0.00	*480.00 F
	1		*FRONT LH CORNERPANEL DO/cre -	0.00	0.00	*240.00 F
0	1		*FRONT LH SIGNAL LAMP	0.00	0.00	*100.00 F
1	1		*FRONT LH SIDE MIRROR STAND Bullar	0.00	0.00	*200.00 F
2	1		*FRONT BUMPER	0.00	0.00	*480.00 F
3	1		*FRONT BUMPER LH SIDE RUBBER De -	0.00	0.00	*170.00 F
4	1		*FRONT LH DOOR	0.00	0.00	*900.00 F
5	1		*FRONT LH DOOR HINGE ATX	0.00	0.00	*40.00 F
6	1		*FRONT LH DOOR TRIM	0.00	0.00	*280.00 F
7	1		*FRONT LH DOOR PILLAR BOLS TO	0.00	0.00	*680.00 F
8	1		*FRONT LH DOOR GLASS REGILATOR JM/	Stules - 0.00	0.00	*480.00 F
9	1	NO STOCK BY AIR	*DASHBOARD PANEL	0.00	0.00	*1,000.00 F
0	1	NO STOCK BY AIR	*DASHBOARD PANEL LH COVER	0.00	0.00	*350.00 F.
1	1		*WIPER TANK Be	0.00	0.00	*95.00 F
2	1		*AIRCON BLOWER CASING THE	0.00	0.00	*1,050.00 F
3	1		*AIRCON EVAPORATOR TO	0.00	0.00	1200 *-F
4	1		*VENTILATOR CASING	0.00	0.00	*450.00 F
5	1		*IU BRACKET ALL	0.00	0.00	*15.00 F
Fra	nchise	part.	Total D.	arts (S\$)		9,200.00

Jin Auto Services Pte Ltd/YP3802C/05/03/2019 10:05. Not valid without Reference section. Generated using Merimen e-Claims IEAS

9010

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-410/412 Singapore 539195

Tel: 6289 8126 Fax: 6287 0590 Email: Jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg.No: 200704370C

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

Ref. No: Date of Loss: YP3802C

Policy No:

DMCVSN1657281802 YP3802C

Driveable?

01/03/2019

Vehicle Reg. No.: Driver Age/Info:

Party At Fault:

**UNKNOWN** 

TP Injury Involved?

/ MALE

NO

Third Party Involved? YES

Insured/Claimant:

MSK STAR ENGINEERING PTE L KUMARAPPAN BALACHANDAR

Driver:

MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)

Vehicle Reg. Date:

23/08/2016

Vehicle Colour:

Make/Model:

4P10C34976

WHITE

Chassis No:

FEB21EA20909

Engine No: Odometer:

1 KM

Paint Type:

Total Loss?

NO

Est. Duration of Repair

(day)

14

I WAS TRAVELLING ALONG ECP TOWARDS CHANGI, WHEN THE FRONT

VEHICLE B SUDDENLY STOPPED, I CANNOT STOP IN TIME AND HAD

Description of Accident/Loss COLLIDED ONTO VEHICLE B REAR PORTION, NO ONE WAS INJURED, THE VEHICLE B JUST LEAVE THE SCENE AFTER ACCIDENT HAPPEN, SO I CANNOT GET ANY PARTICULAR FROM DRIVER AND THE VEHICLE B

VEHICLE NUMBER.

Present Location:

JIN AUTO SERVICES PTE LTD (DEFU)

COST OF CLAIMS		Amount
Parts		9,200.00
Miscellaneous Items		0.00
Labour		2,940.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	12,140.00
	+ GST 7.00% (S\$)	849.80
	Nett Amount (S\$)	12,989.80

This claim is handled by: JOUIS SEOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

-4	:			l = l= =
EST	ıma	ies.	on	Labour

No	Particulars	Lab, Type		Amount
Lab	our Items			
1	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	New	.0	80.00
2	TO REMOVE AND RENEW FRONT DASHBOARD	New	180	320.00
3	TO REMOVE AND RENEW AIRCON PART	New	100	180.00
4	TOP UP FREON GAS	New		100.00
5	SPRAY PAINTING FOR 6 PORTION	New	800	980.00
6	LABOUR CHARGE	New	1050	1,100.00
7	REMOVE AND CHECK HARNESS	New	30	180.00
		Gross Labour Cost (S\$)		2,940.00

Jin Auto Services Pte Ltd/YP3802C/05/03/2019 10:05. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 14 Mar 2019)

Parts:

N/A

MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not

available in database)

Labour:

Repairer's (Price-denominated Standard List)

Print Code:

Jin Auto Services Pte Ltd/YP3802C/14/03/2019 10:33

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last

estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIRXON HEATER ASSY	0.00	eul 0.00	*1,200.00 FX
2	1		*AIRCON DUCTING INTAKE		graf 0.00	*500.00 F
F=Fr	anchise	part.	Total Parts (S\$)			1,700.00

Jin Auto Services Pte Ltd/YP3802C/14/03/2019 10:33. Not valid without Reference section. Generated using Merimen e-Claims IEAS

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	dj Submitted	Ins Auth'ed	Pending for Survey Report Cancel Case			
Main	04 Mar 2019 Sendback Est	05 Mar 2019 10:05 <b>\$\$12,140.00</b>	05 Mar 2019 11:51 Edit Adj Rpt	S\$9,000.00 Edit Estimates		\$9,000.00 View Rpt					
Supp #1	14 Mar 2019 10:31	14 Mar 2019 10:33 <b>S\$1,700.00</b>	14 Mar 2019 10:33				(Combined)	Combined with Mair Uncombine Suppl.			
	Main	Refer	ence	Claim Detai	ils		Documents	St	l IIA wo		
Insured: Vehicle Reg No.:		IGINEERING PT	L, Co. Reg. No.:	201200800G Date of Lo	oss:	01/03/2019 1 [ <b>30</b> Months a	6:00 - :59 nd <b>6</b> Days From L	TA Reg Date (Mar	Yr)]		
No.: Claim Type	5.00/2-5-5-5-5-5	19D201022C01/2		<b>OD</b> / SNM19D201022C01/3		Policy/Cov Note No.:	/er	1	nd 6 Days From L 281802 (Compre		1 Yr)]
				Excess: S\$550.00							
Repairer:	Jin Auto Serv	rices Pte Ltd (De	fu) Blk 14 Defu La	ne 10, #01-410/41	2, 53	1 1	ne - Tel: 6289 812	26			
Handling Insurer:		•		. (HQ) - Tel: 6389							
Adjuster:	LKK Auto Cor	sultants Pte Ltd	(HQ) - Tel: 6256	-3561 [Handled I	by M	ARCUS CHUA	] [Final Rpt	due 14/03/20:	19]		
Driver/Cust	0	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Handled by MARCUS CHUA] [Final Rpt due 14/03/2019]  KUMARAPPAN BALACHANDAR ( / Male) , NRIC: G2538574H Email:									
dian:	KUMARAPPAN	BALACHANDAR (	(Male), NRIC: 0	32538574H Email:							

#### ASSOCIATED MAIL RECEIVED

SURVEY REVERT

- CHINA\_TAIPING (29/03/2019): Alert Adj Mandate Approved (\$\$9000.00) YP3802C Claim Handler: Chong Boon S...
   CHINA\_TAIPING (12/03/2019): Alert Adj Mandate Approved (\$\$7650.00) YP3802C Claim Handler: Chong Boon S...

# ALL ASSOCIATED TASKS□

Adj Asg.

**Due Date** Priority Type **Task Group** Subject Handler Assigned By Completed On Created On Done? No results.

View All

Search Tasks

Create New Task

Complete

## **Claim Documents**

# YP3802C (SNM19D201022C01/2) OD Mar 1 2019 4:00PM [MSK STAR ENGINEERING PTE L] Jin Auto Services Pte Ltd

Ass	essment Reports		1 per page	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbna	4
1	05/03/19 10:05	Repairer Estimates	■ Load HTM	
2	14/03/19 10:33	Repairer Estimates Suppl. #1	■ Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	
1	07/03/19 11:57	Adjuster Immediate Advice	1 Load HTM	_
2	28/03/19 09:32	Adjuster Immediate Advice	■ Load HTM	
Pho	otos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbna	il Print
1	07/03/19 11:43	General View	Load JPG	<b>Y</b>
2	07/03/19 11:43	General View	1 Load JPG	V
3	07/03/19 11:43	General View	1 Load JPG	<b>✓</b>
4	07/03/19 11:43	General View	1 Load JPG	V
5	07/03/19 11:43	General View	1 Load JPG	V
6	07/03/19 11:43	General View	■ Load JPG	4
7	07/03/19 11:43	General View	1 Load JPG	V
8	07/03/19 11:43	General View	1 Load JPG	~
9	07/03/19 11:43	General View	Load JPG	V
10	07/03/19 11:43	General View	1 Load JPG	~
11	07/03/19 11:43	General View	1 Load JPG	V
12	07/03/19 11:43	General View	1 Load JPG	<b>✓</b>
13	07/03/19 11:43	General View	1 Load JPG	V
14	07/03/19 11:43	General View	1 Load JPG	V
15	07/03/19 11:43	General View	■ Load JPG	<b>✓</b>
16	07/03/19 11:43	General View	Load JPG	V
17	07/03/19 11:43	General View	■ Load JPG	V
18	07/03/19 11:43	General View	■ Load JPG	V
19	07/03/19 11:43	General View	Load JPG	V
20	07/03/19 11:43	General View	■ Load JPG	~
21	07/03/19 11:43	General View	6 Load JPG	<b>✓</b>
22	07/03/19 11:43	General View	1 Load JPG	~
23	07/03/19 11:43	General View	1 Load JPG	V
24	07/03/19 11:43	General View	1 Load JPG	<b>✓</b>
25	07/03/19 11:43	General View	1 Load JPG	V
26	07/03/19 11:43	General View	1 Load JPG	V
27	07/03/19 11:43	General View	1 Load JPG	~
28	07/03/19 11:43	General View	1 Load JPG	V
29	07/03/19 11:43	General View	1 Load JPG	V
30	07/03/19 11:43	General View	1 Load JPG	
31	07/03/19 11:43	General View	1 Load JPG	-
32	07/03/19 11:43	General View	■ Load JPG	~

A5S	essment Reports		1 per page	<u>~</u> [
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbn	
33	07/03/19 11:43	General View	1 Load JP	G [
34	07/03/19 11:43	General View	<b>⑥</b> Load JP	G 5
35	07/03/19 11:43	General View	1 Load JP	G 5
36	07/03/19 11:43	General View	■ Load JP	G G
37	07/03/19 11:43	General View	1 Load JP	G 5
38	07/03/19 11:43	General View	1 Load JP	G G
39	07/03/19 11:43	General View	€ Load JP	G 5
40	07/03/19 11:43	General View	■ Load JP	G 5
41	07/03/19 11:43	General View	6 Load JP	-
42	07/03/19 11:43	General View	Load JP	G 5
43	07/03/19 11:43	General View	Load JP	-
44	07/03/19 11:43	General View	1 Load JP	-
45	07/03/19 11:43	General View	1 Load JP	-
46	07/03/19 11:43	General View	1 Load JP	-
47				
	07/03/19 11:43	General View	1 Load JP	-
48	07/03/19 11:43	General View	1 Load JP	-
49	07/03/19 11:43	General View	1 Load JP	_
50	07/03/19 11:43	General View	1 Load JP	
51	07/03/19 11:43	General View	1 Load JP	-
52	07/03/19 11:43	General View	1 Load JP	-
53	07/03/19 11:43	General View	1 Load JP	_
54	07/03/19 11:43	General View	1 Load JP	G G
55	07/03/19 11:43	General View	■ Load JP	G 5
56	07/03/19 11:43	General View	1 Load JP	G 5
57	07/03/19 11:43	General View	Load JP	G G
58	07/03/19 11:43	General View	Load JP	G 5
59	07/03/19 11:43	General View	Load JP	G 5
50	07/03/19 11:43	General View	1 Load JP	G 5
51	07/03/19 11:43	General View	1 Load JP	G 5
52	07/03/19 11:43	General View	Load JP	G G
53	07/03/19 11:43	General View	Load JP	G 5
54	07/03/19 11:43	General View	■ Load JP	G 5
65	07/03/19 11:43	General View	■ Load JP	-
56	07/03/19 11:43	General View	Load JP	
57	07/03/19 11:43	General View	■ Load 3P	
58	07/03/19 11:43	General View	Load JP	-
	The state of the s		1 Load JP	-
59	07/03/19 11:43	General View	1 Load JP	-
70	07/03/19 11:43	General View		
71	07/03/19 11:43	General View	1 Load JP	-
72	28/03/19 11:04	Reinspection Photo	Load JP	-
73	28/03/19 11:04	Reinspection Photo	1 Load JP	_
74	28/03/19 11:04	Reinspection Photo	1 Load JP	-
75	28/03/19 11:04	Reinspection Photo	1 Load JP	
76	28/03/19 11:04	Reinspection Photo	1 Load JP	
77	28/03/19 11:04	Reinspection Photo	1 Load JP	
78	28/03/19 11:04	Reinspection Photo	1 Load JP	_
79	28/03/19 11:04	Reinspection Photo	1 Load JP	_
30	28/03/19 11:04	Reinspection Photo	1 Load JP	_
31	28/03/19 11:04	Reinspection Photo	1 Load JP	G E
82	28/03/19 11:04	Reinspection Photo	■ Load JP	G G

Ass	essment Reports		1 per page	√ <b>√</b>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbna	
83	28/03/19 11:04	Reinspection Photo	1 Load JPC	G 🗸
84	28/03/19 11:04	Reinspection Photo	1 Load JPC	G 🔽
85	28/03/19 11:04	Reinspection Photo	1 Load JPC	G <b>✓</b>
86	28/03/19 11:04	Reinspection Photo	€ Load JPC	G 🗸
87	28/03/19 11:04	Reinspection Photo	■ Load JPC	G 🗹
88	28/03/19 11:04	Reinspection Photo	■ Load JPC	G 🗸
89	28/03/19 11:04	Reinspection Photo	■ Load JPC	G 🔽
90	28/03/19 11:04	Reinspection Photo	1 Load JPC	G 🗸
91	28/03/19 11:04	Reinspection Photo	Load JPC	G 🔽
92	28/03/19 11:04	Reinspection Photo	1 Load JPC	3 <b></b>
93	28/03/19 11:04	Reinspection Photo	1 Load JPC	G 🗸
94	28/03/19 11:04	Reinspection Photo	■ Load JPC	3 <b>V</b>
95	28/03/19 11:04	Reinspection Photo	1 Load JPC	3 <b>V</b>
96	28/03/19 11:04	Reinspection Photo	1 Load JPG	
97	28/03/19 11:04	Reinspection Photo	1 Load JPG	3 <b>V</b>
98	28/03/19 11:04	Reinspection Photo	■ Load JPG	_
99	28/03/19 11:04	Reinspection Photo	■ Load JPC	
100	28/03/19 11:04	Reinspection Photo	1 Load JPG	
101	28/03/19 11:04	Reinspection Photo	1 Load JPC	
102	28/03/19 11:04	Reinspection Photo	1 Load JPC	
103	28/03/19 11:04	Reinspection Photo	■ Load JPC	-
103	28/03/19 11:04	Reinspection Photo	1 Load JPC	
			■ Load JPC	
105	28/03/19 11:04	Reinspection Photo		
106	28/03/19 11:04	Reinspection Photo		_
107	28/03/19 11:04	Reinspection Photo	O Load JPC	-
108	28/03/19 11:04	Reinspection Photo	Load JPC	
109	28/03/19 11:04	Reinspection Photo	■ Load JPC	-
110	28/03/19 11:04	Reinspection Photo	1 Load JPC	
111	28/03/19 11:04	Reinspection Photo	1 Load JPC	
112	28/03/19 11:04	Reinspection Photo	1 Load JPC	-
113	28/03/19 11:04	Reinspection Photo	1 Load JPC	
114	28/03/19 11:04	Reinspection Photo	1 Load JPC	
115	28/03/19 11:04	Reinspection Photo	1 Load JPC	
116	28/03/19 11:04	Reinspection Photo	1 Load JPC	_
117	28/03/19 11:04	Reinspection Photo	1 Load JPC	-
118	28/03/19 11:04	Reinspection Photo	1 Load JPC	_
119	28/03/19 11:04	Reinspection Photo	1 Load JPC	
120	28/03/19 11:04	Reinspection Photo	1 Load JPC	
121	28/03/19 11:04	Reinspection Photo	1 Load JPC	3 <b>V</b>
122	28/03/19 11:04	Reinspection Photo	1 Load JPC	G 🗸
123	28/03/19 11:04	Reinspection Photo	1 Load JPC	G <b>✓</b>
124	28/03/19 11:04	Reinspection Photo	1 Load JPC	G ✓
125	28/03/19 11:04	Reinspection Photo	Load JPC	G <b>✓</b>
126	28/03/19 11:04	Reinspection Photo	1 Load JPC	G <b></b> ✓
				mg I
Doc	umentation		TORNIA SALES	<u> </u>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbna Load PD	
1 No	04/03/19 10:02 Relabel/Reorder	E-FILE GIA REPORT  LKK Auto Consultants Pte Ltd (HQ)	Thumbna	
1	07/03/19 11:42	ESTIMATE	1 Load PD	

# **Documents Checklist**

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909

Our File No:

CS/CTI19004013/UQD3E2

Date:

02/04/2019

REFERENCE

Date of Loss:

Insured/Claimant: MSK STAR ENGINEERING PTE L Policy No:

01/03/2019

DMCVSN1657281802

Nature of Claim: OD

Claim No: SNM19D201022C01/2

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

YP3802C

Make & Model:

MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU)

23/08/2016 (Man. Year: 2016)

Engine No: Chassis No:

4P10C34976

Reg. Date: Colour:

White

Odometer:

FEB21EA20909 238255 km

Engine Capacity:

2998 cc

Sum Insured (S\$):

S\$56,000.00

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Market Value/New Car Price:

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195 R15

Rear Tyre Size:

195/85 R15 (D)

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm

Rear Left Side: Rear Right Side: Bridgestone 6/6 mm Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,900.00	9,010.00	1,890.00	17.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	2,240.00	700.00	23.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,840.00	11,250.00	2,590.00	18.71
Approved Total (Overridden) (S\$)		9,000.00		
- Excess (S\$)	0.00	550.00	-550.00	
(S\$)	13,840.00	8,450.00	5,390.00	38.95
+ GST 7.00/7.00% (S\$)	968.80	591.50	377.30	38.95
Nett Amount (S\$)	14,808.80	9,041.50	5,767.30	38.95

INSPECTION

Date Inspected:

Date of Assignment:

05/03/2019 06/03/2019

Present Location:

Inspected At:

Jin Auto Services Pte Ltd (Defu) Jin Auto Services Pte Ltd (Defu)

Singapore 539195

Blk 14 Defu Lane 10, #01-410/412

Estimated Period of Repair:

7.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_p... 2/4/2019

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Referen	ce	
Part Source	:	(Last Synchronised: 02 Apr 2019)
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	d, no print-code for YP3802C)
Validity:		ates are valid only if they contain the print code (above) on all estimate pages, running page in the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Broken	700.00 F	*700.00 F
2	1		*FRONT WINDSCREEN RUBBER	Twisted	200.00 F	*200.00 F
3	1		*WIPER PANEL	Dented	190.00 F	*190.00 F
4	1		*LH WIPER ARM	Bent	70.00 F	*70.00 F
5	1		*LH WIPER BLADE	Bent	10.00 F	*10.00 F
6	1		*FRONT PANEL	Badly Dented	980.00 F	*980.00 F
7	1		*FRONT PANEL FUSO EMBLEM	Necessary	40.00 F	*40.00 F
8	1		*GRILLE	Cracked	480.00 F	*480.00 F
9	1		*FRONT LH CORNERPANEL	Dented / Cracked	240.00 F	*240.00 F
10	1		*FRONT LH SIGNAL LAMP	Cracked	100.00 F	*100.00 F
11	1		*FRONT LH SIDE MIRROR STAND	Bent / Cracked	200.00 F	*200.00 F
12	1		*FRONT BUMPER	Dented	480.00 F	*480.00 F
13	1		*FRONT BUMPER LH SIDE RUBBER	Deformed	170.00 F	*170.00 F
14	1		*FRONT LH DOOR	Repair	900.00 F	*- F
15	1		*FRONT LH DOOR HINGE	Not Necessary	40.00 F	*- F
16	1		*FRONT LH DOOR TRIM	Cracked	280.00 F	*280.00 F
17	1		*FRONT LH DOOR PILLAR	Badly Dented	680.00 F	*680.00 F
18	1		*FRONT LH DOOR GLASS REGILATOR	Jammed / Shorted	480.00 F	*480.00 F
19	1	NO STOCK BY AIR	*DASHBOARD PANEL	Cracked	1,000.00 F	*1,000.00 F
20	1	NO STOCK BY AIR	*DASHBOARD PANEL LH COVER	Cracked	350.00 F	*350.00 F
21	1		*WIPER TANK	Deformed	95.00 F	*95.00 F
22	1		*AIRCON BLOWER CASING	Cracked	1,050.00 F	*1,050.00 F
23	1		*AIRCON EVAPORATOR	Cracked	0.00 F	*1,200.00 F
24	1		*VENTILATOR CASING	Not Necessary	450.00 F	*-F
25	1		*IU BRACKET	Necessary	15.00 F	*15.00 F
Sup	pleme	entary #1				
26	1		*AIRXON HEATER ASSY	Repeated	1,200.00 F	*- F
27	1	4	*AIRCON DUCTING INTAKE	Repeated	500.00 F	*- F
F=Fra	anchise	e part.		Total Parts (S\$)	10,900.00	9,010.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	New	80.00	80.00
2	TO REMOVE AND RENEW FRONT DASHBOARD	New	320.00	180.00
3	TO REMOVE AND RENEW AIRCON PART	New	180.00	100.00
4	TOP UP FREON GAS	New	100.00	0.00
5	SPRAY PAINTING FOR 6 PORTION	New	980.00	800.00
6	LABOUR CHARGE	New	1,100.00	1,050.00
7	REMOVE AND CHECK HARNESS	New	180.00	30.00
	Gross L	abour Cost (S\$)	2,940.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >